
INSTALLATION OF GROUNDWATER MONITORING WELLS, GAS PROBE AND STAFF GAUGES FOR "CENTRAL COUNTY SOLID WASTE DISPOSAL COMPLEX, PHASE II," KNIGHTS TRAIL ROAD, SARASOTA COUNTY, FLORIDA FDEP PERMIT NO. 130542-006-SC/01

> PROVIDED AS ATTACARDOST F OF THE PHISE I CONTRAINED OF CONSTINUOUS COMPLETION ROBINISTAL





Orlando, 8008 S. Orange Avenue, Orlando, Florida 32809, Phone (407) 855-3860 Bartow, 1525 Centennial Drive, Bartow, Florida 33830, Phone (863) 533-0858 Cocoa, 1300 N. Cocoa Boulevard, Cocoa, Florida 32922, Phone (321) 632-2503 Fort Lauderdale, 3665 Park Central Boulevard North, Pompano Beach, Florida 33064, Phone (954) 969-8788 Fort Myers, 9970 Bavaria Road, Fort Myers, Florida 33913, Phone (239) 768-6600 Miami, 2608 W. 84th Street, Hialeah, Florida 33016, Phone (305) 825-2683 Port Charlotte, 740 Tamiami Trail, Unit 3, Port Charlotte, Florida 33954, Phone (941) 624-3393 Port St. Lucie, 460 NW Concourse Place Unit #1, Port St. Lucie, Florida 34986-2248, Phone (772) 878-0072 Sarasota, 78 Sarasota Center Blvd., Sarasota, Florida 34240, Phone (941) 922-3526 Tallahassee, 3175 West Tharpe Street, Tallahassee, Florida 32303, Phone (850) 576-6131 Tampa, 3925 Coconut Palm Drive, Suite 115, Tampa, Florida 33619, Phone (813) 620-3389 West Palm Beach, 2511 Westgate Avenue, Suite 10, West Palm Beach, Florida 33409, Phone (561) 687-8200

A.S.F.E. American Concrete Institute American Society for Testing and Materials Florida Institute of Consulting Engineers

DEP Form # 62-522.900(3)	
Form Title MONITOR WELL COM	PLETION REPORT
Effective Date	
DEP Application No	
(Filled in by F	VED)

Florida Department of Environmental Protection Twin Towers Office Bldg. 2600 Blair Stone Road Tallahassee, Florida 32399-2400

MONITOR WELL COMPLETION REPORT

	DATE: 8/13/09			
Mention	INSTALLATION NAME: Central County Solid Waste Disposal Complex, Phase II			
	DEP PERMIT NUMBER:_130542-006-SC/01	GMS NUMBER: WACS No. SWI	0/58/51614	
	WELL NUMBER: GP-09	WELL NAME: Gas Probe		
3	DESIGNATION: Background	Immediate	Compliance	
	LATITUDE/LONGITUDE: 27 12.191/82 23.769			
	AQUIFER MONITORED: NA			
	INSTALLATION METHOD: Hollow-stem auger			
i	INSTALLED BY: Daniel Peace			
	TOTAL DEPTH: 14.0'			
	SCREEN LENGTH: 12.0'	(bls) SCREEN SLOT SIZE: 0.010"	SCREEN TYPE: PVC SCH 80 slotted	
	CASING DIAMETER: 1"	CASING TYPE: PVC SCH 80		
LENGTH OF CASING: 5.0' (3.0' above grade)		FILTER PACK MATERIAL: Pea	gravel	
	TOP OF CASING ELEVATION (MSL): 23.75'			
	GROUND SURFACE ELEVATION (MSL): 20.75'			
	COMPLETION DATE: 7/15/09			
	DESCRIBE WELL DEVELOPMENT: NA			
	POST DEVELOPMENT WATER LEVER ELEVATION (MSL) <u>:</u> NA		
	DATE AND TIME MEASURED: NA			
	REMARKS: (soils information, stratigraphy, etc.) :See attact	hed soil boring log		
	REPORT PREPARED BY: Ashby Hoover, P.E. (Ardaman &			
		(name, company, phone number)		

(bls)= Below Land Surface

NOTE: PLEASE ATTACH BORING LOG.

BORING LOCATION: See report CLIENT: Sara: County Government PROJECT: CCSWDC, Ph 2, gas well DATE DRILLED: 7/15/09 START: FINISH: LOCATION: See report GROUND SURFACE ELEVATION: 20.75 WATER TABLE DEPTH: 5.2' DATE: 6/23/09 DRILL CREW: Dan & Mark LOGGED BY: Mark O. DRILL MAKE & MODEL: CME 45 BIT: fishtail **DRILLING RODS:** DRILLING METHOD: hollow-stem auger **WEATHER CONDITIONS:** SPT N-VALUE GRAPHIC LOG WATER CONTENT (%) SAMPLE NO. PLAST. INDEX ᇤ LIQUID LIMIT ORGANIC PERCENT FINES DEPTH, SOIL DESCRIPTION 0 SP-SM mixed brown fine sand w/silt (fill) 2 SP gray fine sand w/orange streaks SP pale brown fine sand w/orange streaks SP pale brown fine sand SP pale brown fine sand w/orange streaks SP-SM yellow-brown fine sand with silt SP gray fine sand SP-SC gray fine sand with clay SC gray clayey fine sand 8 SP-SM brown fine sand w/silt, trace clay 10 12 ML gray slightly cemented silt w/phosphate End of boring 14 PAGE __1_ OF __ Ardaman & Associates, Inc. Geotechnical, Environmental and Materials Consultante REVIEWED BY: Craig Obrecht, P.E. FILE NO: 09-8647

BORING NO.: GP-09





May 11, 2007

Susan Pelz, P.E. 25 23
Florida Department of Environmental Protection
13051 N. Telcom Parkway
Temple Terrace, Fl 33637-0926

NUMBER OF STREET OF NVIRONMENTAL PROTECTION

MAY 21 2007

SOUTHWEST DISTRICT
TAMPA

Subject:

Central County Solid Waste Disposal Complex

Permit Number 130542-002-SO/01

Second Quarter 2007 - Landfill Gas Migration Monitoring Report

Dear Ms. Pelz:

Attached in accordance with Specific Condition Number Part F C of the operating permit are the 2nd quarter landfill gas migration monitoring readings for the Central County Solid Waste Disposal Complex.

Please contact me if you have any questions at (941) 650-2078.

Sincerely,

Paul A.Wingler P.E. Solid Waste Operations



LANDFILL GAS MIGRATION MONITORING REPORT CENTRAL COUNTY SOLID WASTE DISPOSAL COMPLEX

Permit Number 130542-002-SO/01

Monitoring	% LEL		
Location	(Methane in air)	Date	Observer
GP 1	0	5/10/07	T. Foxworthy
GP 2	0	5/10/07	T. Foxworthy
GP 3	0	5/10/07	T. Foxworthy
GP 4	0	5/10/07	T. Foxworthy
GP 5	0	5/10/07	T. Foxworthy
GP 6	0	5/10/07	T. Foxworthy
GM-1	0	5/10/07	T. Foxworthy
GM-2	0	5/10/07	T. Foxworthy
GM-3	0	5/10/07	T. Foxworthy
GM-4	0	5/10/07	T. Foxworthy
GM-5	0	5/10/07	T. Foxworthy
GM-6	0	5/10/07	T. Foxworthy
GM-7	0	5/10/07	T. Foxworthy

- 1. GP 1-6 = Landfill gas migration monitoring probes
- 2. GM-1 = Maintenance building, contractor operations
- 3. GM-2 = MRF office trailer
- 4. GM-3 = Maintenance building, County operations
- 5. GM-4 = Administration building
- 6. GM-5 = Scale house
- 7. GM-6 = Control booth
- 8. GM-7 = Electric panel at leachate tank



Dept. of Environmental Protection

MAR 16 2007

March 5, 2007

Southwest District

Susan Pelz, P.E. Florida Department of Environmental Protection 13051 N. Telcom Parkway Temple Terrace, Fl 33637-0926

Subject:

Central County Solid Waste Disposal Complex

Permit Number 130542-002-SO/01

First Quarter 2007 - Landfill Gas Migration Monitoring Report

Dear Ms. Pelz:

Attached in accordance with Specific Condition Number Part F C of the operating permit are the 1st quarter landfill gas migration monitoring readings for the Central County Solid Waste Disposal Complex.

Please contact me if you have any questions at (941) 861-1578.

Sincerely,

Paul Wingler

Solid Waste Operations

P allinger


a

LANDFILL GAS MIGRATION MONITORING REPORT CENTRAL COUNTY SOLID WASTE DISPOSAL COMPLEX

Permit Number 130542-002-SO/01

Monitoring	% LEL		
Location	(Methane in air)	Date	Observer
GP 1	0	1/17/06	T. Foxworthy
GP 2	0	1/17/06	T. Foxworthy
GP 3	0	1/17/06	T. Foxworthy
GP 4	0	1/17/06	T. Foxworthy
GP 5	0	1/17/06	T. Foxworthy
GP 6	0	1/17/06	T. Foxworthy
GM-1	0	1/17/06	T. Foxworthy
GM-2	0	1/17/06	T. Foxworthy
GM-3	0	1/17/06	T. Foxworthy
GM-4	0	1/17/06	T. Foxworthy
GM-5	0	1/17/06	T. Foxworthy
GM-6	0	1/17/06	T. Foxworthy
GM-7	0	1/17/06	T. Foxworthy

- 1. GP 1-6 = Landfill gas migration monitoring probes
- 2. GM-1 = Maintenance building, contractor operations
- 3. GM-2 = MRF office trailer
- 4. GM-3 = Maintenance building, County operations
- 5. GM-4 = Administration building
- 6. GM-5 = Scale house
- 7. GM-6 = Control booth
- 8. GM-7 = Electric panel at leachate tank





Dept. of Environmental Protection

NOV 17 2006

November 17, 2006

Susan Pelz, P.E. Florida Department of Environmental Protection 13051 N. Telcom Parkway Temple Terrace, Fl 33637-0926

Southwest District

Subject:

Central County Solid Waste Disposal Complex

Permit Number 130542-002-so/01

Fourth Quarter 2006 - Landfill Gas Migration Monitoring Report

Dear Ms. Pelz:

Attached in accordance with Specific Condition Number 18 of the operating permit are the 4th quarter landfill gas migration monitoring readings for the Central County Solid Waste Disposal Complex.

Please contact me if you have any questions at (941) 861-1578

Sincerely,

Paul Wingler P. E Solid Waste Operations

a

Monitoring	% LEL		
Location	(Methane in air)	Date	Observer
GP 1	0	11/09/06	T. Foxworthy
GP 2	0	11/09/06	T. Foxworthy
GP 3	0	11/09/06	T. Foxworthy
GP 4	0	11/09/06	T. Foxworthy
GP 5	0	11/09/06	T. Foxworthy
GP 6	0	11/09/06	T. Foxworthy
GM-1	0	11/09/06	T. Foxworthy
GM-2	0	11/09/06	T. Foxworthy
GM-3	0	11/09/06	T. Foxworthy
GM-4	0	11/09/06	T. Foxworthy
GM-5	0	11/09/06	T. Foxworthy
GM-6	0	11/09/06	T. Foxworthy
GM-7	0	11/09/06	T. Foxworthy



- 1. GP 1-6 = Landfill gas migration monitoring probes
- 2. GM-1 = Maintenance building, contractor operations
- 3. GM-2 = MRF office trailer
- 4. GM-3 = Maintenance building, County operations
- 5. GM-4 = Administration building
- 6. GM-5 = Scale house
- 7. GM-6 = Control booth
- 8. GM-7 = Electric panel at leachate tank







August 22, 2006

Susan Pelz, P.E. Florida Department of Environmental Protection 13051 N. Telcom Parkway Temple Terrace, Fl 33637-0926

Subject:

Central County Solid Waste Disposal Complex

Permit Number 130542-002-so/01

Third Quarter 2006 - Landfill Gas Migration Monitoring Report

Dear Ms. Pelz:

Attached in accordance with Specific Condition Number 18 of the operating permit are the 2nd quarter landfill gas migration monitoring readings for the Central County Solid Waste Disposal Complex.

Please contact me if you have any questions at (941) 650-2072.

Sincerely,

Don Shaulis

Solid Waste Operations



LANDFILL GAS MIGRATION MONITORING REPORT CENTRAL COUNTY SOLID WASTE DISPOSAL COMPLEX

Permit Number 130542-002-so/01

Monitoring	% LEL		
Location	(Methane in air)	Date	Observer
GP 1	0	8/22/06	T. Foxworthy
GP 2	0	8/22/06	T. Foxworthy
GP 3	0	8/22/06	T. Foxworthy
GP 4	0	8/22/06	T. Foxworthy
GP 5	0	8/22/06	T. Foxworthy
GP 6	0	8/22/06	T. Foxworthy
GM-1	0	8/22/06	T. Foxworthy
GM-2	0	8/22/06	T. Foxworthy
GM-3	0	8/22/06	T. Foxworthy
GM-4	0	8/22/06	T. Foxworthy
GM-5	0	8/22/06	T. Foxworthy
GM-6	0	8/22/06	T. Foxworthy
GM-7	0	8/22/06	T. Foxworthy

Notes:

- 1. GP 1-6 = Landfill gas migration monitoring probes
- 2. GM-1 = Maintenance building, contractor operations
- 3. GM-2 = MRF office trailer
- 4. GM-3 = Maintenance building, County operations
- 5. GM-4 = Administration building
- 6. GM-5 = Scale house
- 7. GM-6 = Control booth
- 8. GM-7 = Electric panel at leachate tank

ENVIRONMENTAL PROTECTION

AUG 25 2008

SOUTHWEST DISTRICT



SARASOTA COUNTY

"Dedicated to Quality Service"

Dept. of Environmental Protection

MAY 12 2006

May 10, 2006

Southwest District

Susan Pelz, P.E. Florida Department of Environmental Protection 13051 N. Telcom Parkway Temple Terrace, Fl 33637-0926

Subject:

Central County Solid Waste Disposal Complex

Permit Number S058-299180

Second Quarter 2006 - Landfill Gas Migration Monitoring Report

Dear Ms. Pelz:

Attached in accordance with Specific Condition Number 18 of the operating permit are the 2nd quarter landfill gas migration monitoring readings for the Central County Solid Waste Disposal Complex.

Please contact me if you have any questions at (941) 650-2072.

Sincerely,

Don Shaulis

Solid Waste Operations

Don Shaulis

0

Monitoring	% LEL		
Location	(Methane in air)	Date	Observer
GP 1	0	5/08//06	T. Foxworthy
GP 2	0	5/08//06	T. Foxworthy
GP 3	0	5/08//06	T. Foxworthy
GP 4	0	5/08//06	T. Foxworthy
GP 5	0	5/08//06	T. Foxworthy
GP 6	0	5/08//06	T. Foxworthy
GM-1	0	5/08//06	T. Foxworthy
GM-2	0	5/08//06	T. Foxworthy
GM-3	0	5/08//06	T. Foxworthy
GM-4	0	5/08//06	T. Foxworthy
GM-5	0	5/08//06	T. Foxworthy
GM-6	0	5/08//06	T. Foxworthy
GM-7	0	5/08//06	T. Foxworthy

- 1. GP 1-6 = Landfill gas migration monitoring probes
- 2. GM-1 = Maintenance building, contractor operations
- 3. GM-2 = MRF office trailer
- 4. GM-3 = Maintenance building, County operations
- 5. GM-4 = Administration building
- 6. GM-5 = Scale house
- 7. GM-6 = Control booth
- 8. GM-7 = Electric panel at leachate tank



November 1, 2005

Susan Pelz, P.E. Florida Department of Environmental Protection 3804 Coconut Palm Drive Tampa, Florida 33619-8318

Subject:

Central County Solid Waste Disposal Complex

Permit Number 130542-002-so/01

Fourth Quarter 2005 - Landfill Gas Migration Monitoring Report

Dear Ms. Pelz:

Attached in accordance with Specific Condition Number part F-3 of the operating permit are the Fourth quarter landfill gas migration monitoring readings for the Central County Solid Waste Disposal Complex.

Please contact me if you have any questions at (941) 650-2072.

Sincerely,

Don Shaulis

Solid Waste Operations

on Shaulis

Monitoring	% LEL		
Location	(Methane in air)	Date	Observer
GP 1	0%	10/26/05	T. Foxworthy
GP 2	0%	10/26/05	T. Foxworthy
GP 3	0%	10/26/05	T. Foxworthy
GP 4	0%	10/26/05	T. Foxworthy
GP 5	0%	10/26/05	T. Foxworthy
GP 6	0%	10/26/05	T. Foxworthy
GM-1	0%	10/26/05	T. Foxworthy
GM-2	0%	10/26/05	T. Foxworthy
GM-3	0%	10/26/05	T. Foxworthy
GM-4	0%	10/26/05	T. Foxworthy
GM-5	0%	10/26/05	T. Foxworthy
GM-6	0%	10/26/05	T. Foxworthy
GM-7	0%	10/26/05	T. Foxworthy

- 1. GP 1-6 = Landfill gas migration monitoring probes
- 2. GM-1 = Maintenance building, contractor operations
- 3. GM-2 = MRF office trailer
- 4. GM-3 = Maintenance building, County operations
- 5. GM-4 = Administration building
- 6. GM-5 = Scale house
- 7. GM-6 = Control booth
- 8. GM-7 = Electric panel at leachate tank







August 5, 2005

Susan Pelz, P.E.

Florida Department of Environmental Protection 3804 Coconut Palm Drive Tampa, Florida 33619-8318

Subject:

Central County Solid Waste Disposal Complex

Permit Number 130542-002-so/01

Third Quarter 2005 - Landfill Gas Migration Monitoring Report

Dear Ms. Pelz:

Attached in accordance with Specific Condition Number part F-3 of the operating permit are the Third quarter landfill gas migration monitoring readings for the Central County Solid Waste Disposal Complex.

Please contact me if you have any questions at (941) 650-2072.

Sincerely,

Don Shaulis

Solid Waste Operations

Monitoring	% LEL		
Location	(Methane in air)	Date	Observer
GP 1	0%	8/4/05	T. Foxworthy
GP 2	0%	8/4/05	T. Foxworthy
GP 3	0%	8/4/05	T. Foxworthy
GP 4	0%	8/4/05	T. Foxworthy
GP 5	0%	8/4/05	T. Foxworthy
GP 6	0%	8/4/05	T. Foxworthy
GM-1	0%	8/4/05	T. Foxworthy
GM-2	0%	8/4/05	T. Foxworthy
GM-3	0%	8/4/05	T. Foxworthy
GM-4	0%	8/4/05	T. Foxworthy
GM-5	0%	8/4/05	T. Foxworthy
GM-6	0%	8/4/05	T. Foxworthy
GM-7	0%	8/4/05	T. Foxworthy

- 1. GP 1-6 = Landfill gas migration monitoring probes
- 2. GM-1 = Maintenance building, contractor operations
- 3. GM-2 = MRF office trailer
- 4. GM-3 = Maintenance building, County operations
- 5. GM-4 = Administration building
- 6. GM-5 = Scale house
- 7. GM-6 = Control booth
- 8. GM-7 = Electric panel at leachate tank



January 19, 2006

FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

JAN 23 2006

SOUTHWEST DISTRICT TAMPA

Susan Pelz, P.E. Florida Department of Environmental Protection 13051 N. Telcom Parkway Temple Terrace, Fl 33637-0926

Subject:

Central County Solid Waste Disposal Complex

Permit Number S058-299180

First Quarter 2006 - Landfill Gas Migration Monitoring Report

Dear Ms. Pelz:

Attached in accordance with Specific Condition Number 18 of the operating permit are the 1st quarter landfill gas migration monitoring readings for the Central County Solid Waste Disposal Complex.

Please contact me if you have any questions at (941) 650-2072.

Sincerely,

Don Shaulis

Solid Waste Operations

Don Shaulis

10

Monitoring	% LEL		
Location	(Methane in air)	Date	Observer
GP 1	0	1/17/06	T. Foxworthy
GP 2	0	1/17/06	T. Foxworthy
GP 3	0	1/17/06	T. Foxworthy
GP 4	0	1/17/06	T. Foxworthy
GP 5	0	1/17/06	T. Foxworthy
GP 6	0	1/17/06	T. Foxworthy
GM-1	0	1/17/06	T. Foxworthy
GM-2	0	1/17/06	T. Foxworthy
GM-3	0	1/17/06	T. Foxworthy
GM-4	0	1/17/06	T. Foxworthy
GM-5	0	1/17/06	T. Foxworthy
GM-6	0	1/17/06	T. Foxworthy
GM-7	0	1/17/06	T. Foxworthy

- 1. GP 1-6 = Landfill gas migration monitoring probes
- 2. GM-1 = Maintenance building, contractor operations
- 3. GM-2 = MRF office trailer
- 4. GM-3 = Maintenance building, County operations
- 5. GM-4 = Administration building
- 6. GM-5 = Scale house
- 7. GM-6 = Control booth
- 8. GM-7 = Electric panel at leachate tank







June 23, 2005

Susan Pelz, P.E. Florida Department of Environmental Protection 3804 Coconut Palm Drive Tampa, Florida 33619-8318

Subject:

Central County Solid Waste Disposal Complex

Permit Number S058-299180

Second Quarter 2005 - Landfill Gas Migration Monitoring Report

Dear Ms. Pelz:

Attached in accordance with Specific Condition Number 18 of the operating permit are the 2nd quarter landfill gas migration monitoring readings for the Central County Solid Waste Disposal Complex.

Please contact me if you have any questions at (941) 650-2072.

Sincerely,

Don Shaulis

Solid Waste Operations

0

Monitoring	% LEL		
Location	(Methane in air)	Date	Observer
GP 1	0	6/13/05	T.F.
GP 2	0	6/13/05	T.F.
GP 3	0	6/13/05	T.F.
GP 4	0	6/13/05	T.F.
GP 5	0	6/13/05	T.F.
GP 6	0	6/13/05	T.F.
GM-1	0	6/13/05	T.F.
GM-2	0	6/13/05	T.F.
GM-3	0	6/13/05	T.F.
GM-4	0	6/13/05	T.F.
GM-5	0	6/13/05	T.F.
GM-6	0	6/13/05	T.F.
GM-7	0	6/13/05	T.F.

- 1. GP 1-6 = Landfill gas migration monitoring probes
- 2. GM-1 = Maintenance building, contractor operations
- 3. GM-2 = MRF office trailer
- 4. GM-3 = Maintenance building, County operations
- 5. GM-4 = Administration building
- 6. GM-5 = Scale house
- 7. GM-6 = Control booth
- 8. GM-7 = Electric panel at leachate tank







April 5, 2005

Susan Pelz, P.E. State of Environmental Protection 3804 Coconut Palm Drive Tampa, Florida 33619-8318

Shaulis

Subject:

Central County Solid Waste Disposal Complex

Permit Number S058-299180

First Quarter 2005 - Landfill Gas Migration Monitoring Report

Dear Ms. Pelz:

Attached in accordance with Specific Condition Number 18 of the operating permit are the 1st quarter landfill gas migration monitoring readings for the Central County Solid Waste Disposal Complex.

Please contact me if you have any questions at (941) 650-2072.

Sincerely,

Don Shaulis

Solid Waste Operations

70			
Monitoring	% LEL		
Location	(Methane in air)	Date	Observer
GP 1	0	3/29/05	T.F.
GP 2	0	3/29/05	T.F.
GP 3	0	3/29/05	T.F.
GP 4	0	3/29/05	T.F.
GP 5	0	3/29/05	T.F.
GP 6	0	3/29/05	T.F.
GM-1	0	3/29/05	T.F.
GM-2	0	3/29/05	T.F.
GM-3	0	3/29/05	T.F.
GM-4	0	3/29/05	T.F.
GM-5	0	3/29/05	T.F.
GM-6	0	3/29/05	T.F.
GM-7	0	3/29/05	T.F.



- 1. GP 1-6 = Landfill gas migration monitoring probes
- 2. GM-1 = Maintenance building, contractor operations
- 3. GM-2 = MRF office trailer
- 4. GM-3 = Maintenance building, County operations
- 5. GM-4 = Administration building
- 6. GM-5 = Scale house
- 7. GM-6 = Control booth
- 8. GM-7 = Electric panel at leachate tank





July 1, 2004

John Morris, P. G. Florida Department of Environmental Protection 3804 Coconut Palm Drive Tampa, Florida 33619-8318

Subject:

Central County Solid Waste Disposal Complex

Permit Number S058-299180

Third Quarter 2004 - Landfill Gas Migration Monitoring Report

Dear Mr. Morris:

Attached in accordance with Specific Condition Number 18 of the operating permit are the 3rd quarter landfill gas migration monitoring readings for the Central County Solid Waste Disposal Complex.

Please contact me if you have any questions.

Sincerely,

Don Shaulis

Solid Waste Operations

m Shaulis


Enclosure

C: Susan Pelz, P.E. FDEP -- (w/o enclosure)




Monitoring	% LEL		
Location	(Methane in air)	Date	Observer
GP 1	0%	7/1/04	T.F.
GP 2	0%	7/1/04	T.F.
GP 3	0%	7/1/04	T.F.
GP 4	0%	7/1/04	T.F.
GP 5	0%	7/1/04	T.F.
GP 6	0%	7/1/04	T.F.
GM-1	0%	7/1/04	T.F.
GM-2	0%	7/1/04	T.F.
GM-3	0%	7/1/04	T.F.
GM-4	0%	7/1/04	T.F.
GM-5	0%	7/1/04	T.F.
GM-6	0%	7/1/04	T.F.
GM-7	0%	7/1/04	T.F.

- 1. GP 1-6 = Landfill gas migration monitoring probes
- 2. GM-1 = Maintenance building, contractor operations
- 3. GM-2 = MRF office trailer
- 4. GM-3 = Maintenance building, County operations
- 5. GM-4 = Administration building
- 6. GM-5 = Scale house
- 7. GM-6 = Control booth
- 8. GM-7 = Electric panel at leachate tank







May 12, 2004

John Morris, P. G. Florida Department of Environmental Protection 3804 Coconut Palm Drive Tampa, Florida 33619-8318

Subject:

Central County Solid Waste Disposal Complex

Permit Number S058-299180

Second Quarter 2004 - Landfill Gas Migration Monitoring Report

Dear Mr. Morris:

Attached in accordance with Specific Condition Number 18 of the operating permit are the 2nd quarter landfill gas migration monitoring readings for the Central County Solid Waste Disposal Complex.

Please contact me if you have any questions at (941) 861-1577.

Sincerely,

Don Shaulis

Solid Waste Operations

Attachment

C: Susan J. Pelz, P.E. FDEP Tampa

I:\projects\Central County Solid Waste Disposal Complex\Landfill Gas\2004 reports\2nd qtr 04 gas migration.doc



N4	0/ 1 121		
Monitoring	% LEL		
Location	(Methane in air)	Date	Observer
GP 1	0	4/29/04	T.F.
GP 2	0	4/29/04	T.F.
GP 3	0	4/29/04	T.F.
GP 4	0	4/29/04	T.F.
GP 5	0	4/29/04	T.F.
GP 6	0	4/29/04	T.F.
GM-1	0	4/29/04	T.F.
GM-2	0	4/29/04	T.F.
GM-3	0	4/29/04	T.F.
GM-4	0	4/29/04	T.F.
GM-5	0	4/29/04	T.F.
GM-6	0	4/29/04	T.F.
GM-7	0	4/29/04	T.F.
GM-8	0	4/29/04	T.F.

- 1. GP 1-6 = Landfill gas migration monitoring probes
- 2. GM-1 = Maintenance building, contractor operations
- 3. GM-2 = MRF office trailer
- 4. GM-3 = Maintenance building, County operations
- 5. GM-4 = Administration building
- 6. GM-5 = Scale house
- 7. GM-6 = Control booth
- 8. GM-7 = Electric panel at leachate tank





February 25, 2004

John Morris, P. G. Florida Department of Environmental Protection 3804 Coconut Palm Drive Tampa, Florida 33619-8318

Subject:

Central County Solid Waste Disposal Complex

Permit Number S058-299180

First Quarter 2004 - Landfill Gas Migration Monitoring Report

Dear Mr. Morris:

Attached in accordance with Specific Condition Number 18 of the operating permit are the 1st quarter landfill gas migration monitoring readings for the Central County Solid Waste Disposal Complex.

Please contact me if you have any questions at (941) 861-1577.

Sincerely,

Don Shaulis

Solid Waste Operations

Attachment

C: Susan J. Pelz P.E. FDEP Tampa (w/o attachments)



Monitoring	% LEL		
Location	(Methane in air)	Date	Observer
GP 1	0	2/24/04	T.F.
GP 2	0	2/24/04	T.F.
GP 3	0	2/24/04	T.F.
GP 4	0	2/24/04	T.F.
GP 5	0	2/24/04	T.F.
GP 6	0	2/24/04	T.F.
GM-1	0	2/24/04	T.F.
GM-2	0	2/24/04	T.F.
GM-3	0	2/24/04	T.F.
GM-4	0	2/24/04	T.F.
GM-5	0	2/24/04	T.F.
GM-6	0	2/24/04	T.F.
GM-7	0	2/24/04	T.F.
GM-8	0	2/24/04	T.F.

- 1. GP 1-6 = Landfill gas migration monitoring probes
- 2. GM-1 = Maintenance building, contractor operations
- 3. GM-2 = MRF office trailer
- 4. GM-3 = Maintenance building, County operations
- 5. GM-4 = Administration building
- 6. GM-5 = Scale house
- 7. GM-6 = Control booth
- 8. GM-7 = Electric panel at leachate tank







December 3, 2003

John Morris, P. G. Florida Department of Environmental Protection 3804 Coconut Palm Drive Tampa, Florida 33619-8318

Subject:

Central County Solid Waste Disposal Complex

Permit Number S058-299180

Fourth Quarter 2003 - Landfill Gas Migration Monitoring Report

Dear Mr. Morris:

Attached in accordance with Specific Condition Number 18 of the operating permit are the 4th quarter landfill gas migration monitoring readings for the Central County Solid Waste Disposal Complex.

Please contact me if you have any questions.

Shaulis

Sincerely,

Don Shaulis

Solid Waste Operations


Attachment

C: Susan Pelz, P.E. FDEP- (w/o enclosure)

I-\projects\Central County Solid Waste Disposal Complex\Landfill Gas\2003 reports\4th qtr 03 gas migration.doc

Monitoring	% LEL	1	
Location	(Methane in air)	Date	Observer
GP 1	0 %	12/1/03	T.F.
GP 2	0 %	12/1/03	T.F.
GP 3	0 %	12/1/03	T.F.
GP 4	0 %	12/1/03	T.F.
GP 5	0 %	12/1/03	T.F.
GP 6	0 %	12/1/03	T.F.
GM-1	0 %	12/1/03	T.F.
GM-2	0 %	12/1/03	T.F.
GM-3	0 %	12/1/03	T.F.
GM-4	0 %	12/1/03	T.F.
GM-5	0 %	12/1/03	T.F.
GM-6	0 %	12/1/03	T.F.
GM-7	0 %	12/1/03	T.F.

- 1. GP 1-6 = Landfill gas migration monitoring probes
- 2. GM-1 = Maintenance building, contractor operations
- 3. GM-2 = MRF office trailer
- 4. GM-3 = Maintenance building, County operations
- 5. GM-4 = Administration building
- 6. GM-5 = Scale house
- 7. GM-6 = Control booth
- 8. GM-7 = Electric panel at leachate tank







September 2, 2003

John Morris, P. G. Florida Department of Environmental Protection 3804 Coconut Palm Drive Tampa, Florida 33619-8318

Subject:

Central County Solid Waste Disposal Complex

Permit Number S058-299180

Third Quarter 2003 - Landfill Gas Migration Monitoring Report

Dear Mr. Morris:

Attached in accordance with Specific Condition Number 18 of the operating permit are the 3rd quarter landfill gas migration monitoring readings for the Central County Solid Waste Disposal Complex.

Please contact me if you have any questions.

Don Shaulis

Sincerely,

Don Shaulis

Solid Waste Operations

Enclosure

C: Susan Pelz, P.E. FDEP – (w/o enclosure)

I:\projects\Central County Solid Waste Disposal Complex\Landfill Gas\2003 reports\3rd qtr 03 gas migration.doc



Monitoring	% LEL		
Location	(Methane in air)	Date	Observer
GP 1	0%	8/19/03	T.F.
GP 2	0%	8/19/03	T.F.
GP 3	0%	8/19/03	T.F.
GP 4	0%	8/19/03	T.F.
GP 5	0%	8/19/03	T.F.
GP 6	0%	8/19/03	T.F.
GM-1	0%	8/19/03	T.F.
GM-2	0%	8/19/03	T.F.
GM-3	0%	8/19/03	T.F.
GM-4	0%	8/19/03	T.F.
GM-5	0%	8/19/03	T.F.
GM-6	0%	8/19/03	T.F.
GM-7	0%	8/19/03	T.F.

- 1. GP 1-6 = Landfill gas migration monitoring probes
- 2. GM-1 = Maintenance building, contractor operations
- 3. GM-2 = MRF office trailer
- 4. GM-3 = Maintenance building, County operations
- 5. GM-4 = Administration building
- 6. GM-5 = Scale house
- 7. GM-6 = Control booth
- 8. GM-7 = Electric panel at leachate tank



June 24, 2003

John Morris, P. G. Florida Department of Environmental Protection 3804 Coconut Palm Drive Tampa, Florida 33619-8318

Subject:

Central County Solid Waste Disposal Complex

Permit Number S058-299180

Second Quarter 2003 - Landfill Gas Migration Monitoring Report

Dear Mr. Morris:

Attached in accordance with Specific Condition Number 18 of the operating permit are the 2nd quarter landfill gas migration monitoring readings for the Central County Solid Waste Disposal Complex.

Please contact me if you have any questions at (941) 861-1577.

Sincerely,

Don Shaulis

Solid Waste Operations

Attachment

C: Susan J. Pelz P.E. FDEP Tampa (w/o attachments)

Monitoring	% LEL		
Location	(Methane in air)	Date	Observer
GP 1	0	6/24/03	T.F.
GP 2	0	6/24/03	T.F.
GP 3	0	6/24/03	T.F.
GP 4	0	6/24/03	T.F.
GP 5	0	6/24/03	T.F.
GP 6	0	6/24/03	T.F.
GM-1	0	6/24/03	T.F.
GM-2	0	6/24/03	T.F.
GM-3	0	6/24/03	T.F.
GM-4	0	6/24/03	T.F.
GM-5	0	6/24/03	T.F.
GM-6	0	6/24/03	T.F.
GM-7	0	6/24/03	T.F.
GM-8	0	6/24/03	T.F.

- 1. GP 1-6 = Landfill gas migration monitoring probes
- 2. GM-1 = Maintenance building, contractor operations
- 3. GM-2 = MRF office trailer
- 4. GM-3 = Maintenance building, County operations
- 5. GM-4 = Administration building
- 6. GM-5 = Scale house
- 7. GM-6 = Control booth
- 8. GM-7 = Electric panel at leachate tank





March 24, 2003

John Morris, P. G. Florida Department of Environmental Protection 3804 Coconut Palm Drive Tampa, Florida 33619-8318

Subject:

Central County Solid Waste Disposal Complex

Permit Number S058-299180

First Quarter 2003 - Landfill Gas Migration Monitoring Report

Dear Mr. Morris:

Attached in accordance with Specific Condition Number 18 of the operating permit are the 1st quarter landfill gas migration monitoring readings for the Central County Solid Waste Disposal Complex.

Please contact me if you have any questions at (941) 861-1577.

Sincerely,

Don Shaulis

Solid Waste Operations

Attachment

C: Susan J Pelz, P.E. FDEP

FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

MAR 2 6 2003

SOUTHWEST DISTRICT TAMPA

LANDFILL GAS MIGRATION MONITORING REPORT CENTRAL COUNTY SOLID WASTE DISPOSAL COMPLEX Permit Number SO58-299180

Monitoring	% LEL		
Location	(Methane in air)	Date	Observer
GP 1	0	3/24/03	T.F.
GP 2	0	3/24/03	T.F.
GP 3	0	3/24/03	T.F.
GP 4	0	3/24/03	T.F.
GP 5	0	3/24/03	T.F.
GP 6	0	3/24/03	T.F.
GM-1	0	3/24/03	T.F.
GM-2	0	3/24/03	T.F.
GM-3	0	3/24/03	T.F.
GM-4	0	3/24/03	T.F.
GM-5	0	3/24/03	T.F.
GM-6	0	3/24/03	T.F.
GM-7	0	3/24/03	T.F.
GM-8	0	3/24/03	T.F.

- 1. GP 1-6 = Landfill gas migration monitoring probes
- 2. GM-1 = Maintenance building, contractor operations
- 3. GM-2 = MRF office trailer
- 4. GM-3 = Maintenance building, County operations
- 5. GM-4 = Administration building
- 6. GM-5 = Scale house
- 7. GM-6 = Control booth
- 8. GM-7 = Electric panel at leachate tank





November 29, 2002

John Morris, P. G. Florida Department of Environmental Protection 3804 Coconut Palm Drive Tampa, Florida 33619-8318

Subject:

Central County Solid Waste Disposal Complex

Permit Number S058-299180

Fourth Quarter 2002 - Landfill Gas Migration Monitoring Report

Dear Mr. Morris:

Attached in accordance with Specific Condition Number 18 of the operating permit are the 4th quarter landfill gas migration monitoring readings for the Central County Solid Waste Disposal Complex.

Please contact me if you have any questions.

Sincerely,

Don Shaulis

Solid Waste Operations

Attachment

I:\projects\Central County Solid Waste Disposal Complex\Landfill Gas\2002 reports\4th quarter 02 gas migration.doc

Monitoring	% LEL		
Location	(Methane in air)	Date	Observer
GP 1	0	11/21/02	T.F.
GP 2	0	11/21/02	T.F.
GP 3	0	11/21/02	T.F.
GP 4	0	11/21/02	T.F.
GP 5	0	11/21/02	T.F.
GP 6	0	11/21/02	T.F.
GM-1	0	11/21/02	T.F.
GM-2	0	11/21/02	T.F.
GM-3	0	11/21/02	T.F.
GM-4	0	11/21/02	T.F.
GM-5	0	11/21/02	T.F.
GM-6	0	11/21/02	T.F.
GM-7	0	11/21/02	T.F.

- 1. GP 1-6 = Landfill gas migration monitoring probes
- 2. GM-1 = Maintenance building, contractor operations
- 3. GM-2 = MRF office trailer
- 4. GM-3 = Maintenance building, County operations
- 5. GM-4 = Administration building
- 6. GM-5 = Scale house
- 7. GM-6 = Control booth
- 8. GM-7 = Electric panel at leachate tank





September 23, 2002

John Morris, P. G. Florida Department of Environmental Protection 3804 Coconut Palm Drive Tampa, Florida 33619-8318

Subject:

Central County Solid Waste Disposal Complex

Permit Number S058-299180

Third Quarter 2002 - Landfill Gas Migration Monitoring Report

Dear Mr. Morris:

Attached in accordance with Specific Condition Number 18 of the operating permit are the 3rd quarter landfill gas migration monitoring readings for the Central County Solid Waste Disposal Complex.

Please contact me if you have any questions.

Shaulis

Sincerely,

Don Shaulis

Solid Waste Operations

Attachment

Monitoring	% LEL		
Location	(Methane in air)	Date	Observer
GP 1	0	9/20/02	
GP 2	0	9/20/02	
GP 3	0	9/20/02	
GP 4	0	9/20/02	
GP 5	0	9/20/02	
GP 6	0	9/20/02	
GM-1	0	9/20/02	
GM-2	0	9/20/02	
GM-3	0	9/20/02	
GM-4	0	9/20/02	
GM-5	0	9/20/02	
GM-6	0	9/20/02	
GM-7	0	9/20/02	

- 1. GP 1-6 = Landfill gas migration monitoring probes
- 2. GM-1 = Maintenance building, contractor operations
- 3. GM-2 = MRF office trailer
- 4. GM-3 = Maintenance building, County operations
- 5. GM-4 = Administration building
- 6. GM-5 = Seale house
- 7. GM-6 = Control booth
- 8. GM-7 = Electric panel at leachate tank





May 14, 2002

John Morris, P. G. Florida Department of Environmental Protection 3804 Coconut Palm Drive Tampa, Florida 33619-8318

Subject:

Central County Solid Waste Disposal Complex

Permit Number S058-299180

Second Quarter 2002 - Landfill Gas Migration Monitoring Report

Dear Mr. Morris:

Attached in accordance with Specific Condition Number 18 of the operating permit are the 2nd quarter landfill gas migration monitoring readings for the Central County Solid Waste Disposal Complex.

Please contact me if you have any questions.

Don Shaulis


Sincerely,

Don Shaulis

Solid Waste Operations

Attachment

Monitoring	% LEL		
Location	(Methane in air)	Date	Observer
GP 1	0	5/9/02	T.F.
GP 2	0	5/9/02	T.F.
GP 3	0	5/9/02	T.F.
GP 4	0	5/9/02	T.F.
GP 5	0	5/9/02	T.F.
GP 6	0	5/9/02	T.F.
GM-1	0	5/9/02	T.F.
GM-2	0	5/9/02	T.F.
GM-3	0	5/9/02	T.F.
GM-4	0	5/9/02	T.F.
GM-5	0	5/9/02	T.F.
GM-6	0	5/9/02	T.F.
GM-7	0	5/9/02	T.F.



- 1. GP 1-6 = Landfill gas migration monitoring probes
- 2. GM-1 = Maintenance building, contractor operations
- 3. GM-2 = MRF office trailer
- 4. GM-3 = Maintenance building, County operations
- 5. GM-4 = Administration building
- 6. GM-5 = Scale house
- 7. GM-6 = Control booth
- 8. GM-7 = Electric panel at leachate tank



March 15, 2002

D.E.P.

MAR 2 0 2002

Southwest District Tampa

John Morris, P. G. Florida Department of Environmental Protection 3804 Coconut Palm Drive Tampa, Florida 33619-8318

Subject:

Central County Solid Waste Disposal Complex

Permit Number S058-299180

First Quarter 2002 - Landfill Gas Migration Monitoring Report

Dear Mr. Morris:

Attached in accordance with Specific Condition Number 18 of the operating permit are the 1st quarter landfill gas migration monitoring readings for the Central County Solid Waste Disposal Complex.

Please contact me if you have any questions.

Sincerely, Shaulis

Don Shaulis

Solid Waste Operations

DS

Attachment

C: Robert J. Butera, P.E., FDEP, Tampa w/o attachment

J:\USER\shared\projects\Central County Solid Waste Disposal Complex\Landfill Gas\2002 reports\1st quater 02 gas migration.doc

Monitoring	% LEL		
Location	(Methane in air)	Date	Observer
GP 1	0	3/07/01	J.S.
GP 2	0	3/07/01	J.S.
GP 3	0	3/07/01	J.S.
GP 4	0	3/07/01	J.S.
GP 5	0	3/07/01	J.S.
GP 6	0	3/07/01	J.S.
GM-1	0	3/07/01	J.S.
GM-2	0	3/07/01	J.S.
GM-3	0	3/07/01	J.S.
GM-4	0	3/07/01	J.S.
GM-5	0	3/07/01	J.S.
GM-6	0	3/07/01	J.S.
GM-7	0	3/07/01	J.S.

- 1. GP 1-6 = Landfill gas migration monitoring probes
- 2. GM-1 = Maintenance building, contractor operations
- 3. GM-2 = MRF office trailer
- 4. GM-3 = Maintenance building, County operations
- 5. GM-4 = Administration building
- 6. GM-5 = Scale house
- 7. GM-6 = Control booth
- 8. GM-7 = Electric panel at leachate tank



Southwest District Tempa

December 7, 2001

John Morris, P. G. Florida Department of Environmental Protection 3804 Coconut Palm Drive Tampa, Florida 33619-8318

Subject:

Central County Solid Waste Disposal Complex

Permit Number S058-299180

Fourth Quarter 2001 - Landfill Gas Migration Monitoring Report

Dear Mr. Morris:

Attached in accordance with Specific Condition Number 18 of the operating permit are the 4th quarter Landfill Gas Migration Monitoring Report for the Central County Solid Waste Disposal Complex.

Please contact me if you have any questions.

Sincerely,

Don Shaulis

Solid Waste Operations

Don Shaulis

DS

Attachment

C: Robert J. Butera, P.E., FDEP, Tampa w/o attachment

Kim Ford, P.E., FDEP, Tampa w/o attachment

	% LEL		
Monitoring	(Methane in		
Location	air)	Date	Observer
GP 1	0	12/7/01	JS
GP 2	0	12/7/01	JS
GP 3	0	12/7/01	JS
GP 4	0	12/7/01	JS
GP 5	0	12/7/01	JS
GP 6	0	12/7/01	JS
GM-1	0	12/7/01	JS
GM-2	0	12/7/01	JS
GM-3	0	12/7/01	JS
GM-4	0	12/7/01	JS
GM-5	0	12/7/01	JS
GM-6	0	12/7/01	JS
GM-7	0	12/7/01	JS
	0	12/7/01	JS

- 1. GP 1-6 = Landfill gas migration monitoring probes
- 2. GM-1 = Maintenance building, contractor operations
- 3. GM-2 = MRF office trailer
- 4. GM-3 = Maintenance building, County operations
- 5. GM-4 = Administration building
- 6. GM-5 = Scale house
- 7. GM-6 = Control booth
- 8. GM-7 = Electric panel at leachate tank





September 28, 2001

John Morris, P. G. Florida Department of Environmental Protection 3804 Coconut Palm Drive Tampa, Florida 33619-8318

Subject:

Central County Solid Waste Disposal Complex

Permit Number S058-299180

Third Quarter 2001 - Landfill Gas Migration Monitoring Report

Dear Mr. Morris:

Attached in accordance with Specific Condition Number 18 of the operating permit are the 3rd quarter landfill gas migration monitoring readings for the Central County Solid Waste Disposal Complex.

Please contact me if you have any questions.

Sincerely,

Don Shaulis

Solid Waste Operations

DonShaulis

DS

Attachment

C: Robert J. Butera, P.E., FDEP, Tampa w/o attachment

Kim Ford, P.E., FDEP, Tampa w/o attachment

	% LEL		
Monitoring	(Methane in		
Location	air)	Date	Observer
GP 1	0	9/26/01	TF
GP 2	0	9/26/01	TF
GP 3	0	9/26/01	TF
GP 4	0	9/26/01	TF
GP 5	0	9/26/01	TF
GP 6	0	9/26/01	TF
GM-1	0	9/26/01	TF
GM-2	0	9/26/01	TF
GM-3	0	9/26/01	TF
GM-4	0	9/26/01	TF
GM-5	0	9/26/01	TF
GM-6	0	9/26/01	TF
GM-7	0	9/26/01	TF

- 1. GP 1-6 = Landfill gas migration monitoring probes
- 2. GM-1 = Maintenance building, contractor operations
- 3. GM-2 = MRF office trailer
- 4. GM-3 = Maintenance building, County operations
- 5. GM-4 = Administration building
- 6. GM-5 = Scale house
- 7. GM-6 = Control booth
- 8. GM-7 = Electric panel at leachate tank



July 3, 2001



John Morris, P. G. Florida Department of Environmental Protection 3804 Coconut Palm Drive Tampa, Florida 33619-8318

Subject:

Central County Solid Waste Disposal Complex

Permit Number S058-299180

Second Quarter 2001 - Landfill Gas Migration Monitoring Report

Dear Mr. Morris:

Attached in accordance with Specific Condition Number 18 of the operating permit are the 2nd quarter landfill gas migration monitoring readings for the Central County Solid Waste Disposal Complex.

Please contact me if you have any questions.

Sincerely,

Don Shaulis Solid Waste Operations

DS

C:

Attachment

Robert J. Butera, P.E., FDEP, Tampa w/o attachment Kim Ford, P.E., FDEP, Tampa w/o attachment

J/USER/shared/projects/Central County Solid Waste Disposal Complex/Landfill Gas/2001 reports/2 nd quater gas migration.doc

Monitoring	% LEL	·	
Location	(Methane in air)	Date	Observer
GP 1	0	6/26/01	TF
GP 2	0	6/26/01	TF
GP 3	0	6/26/01	TF
GP 4	0	6/26/01	TF
GP 5	0	6/26/01	TF
GP 6	0	6/26/01	TF
GM-1	0	6/26/01	TF
GM-2	0	6/26/01	TF
GM-3	0	6/26/01	TF
GM-4	0	6/26/01	TF
GM-5	0	6/26/01	TF
GM-6	0	6/26/01	TF
GM-7	0	6/26/01	TF

- 1. GP 1-6 = Landfill gas migration monitoring probes
- 2. GM-1 = Maintenance building, contractor operations
- 3. GM-2 = MRF office trailer
- 4. GM-3 = Maintenance building, County operations
- 5. GM-4 = Administration building
- 6. GM-5 = Scale house
- 7. GM-6 = Control booth
- 8. GM-7 = Electric panel at leachate tank





March 23, 2001

John Morris, P. G. Florida Department of Environmental Protection 3804 Coconut Palm Drive Tampa, Florida 33619-8318

Subject:

Central County Solid Waste Disposal Complex

Permit Number S058-299180

First Quarter 2001 - Landfill Gas Migration Monitoring Report

Dear Mr. Morris:

Attached in accordance with Specific Condition Number 18 of the operating permit are the 1st quarter landfill gas migration monitoring readings for the Central County Solid Waste Disposal Complex.

Please contact me if you have any questions.

Sincerely, Shaulis

Don Shaulis

Solid Waste Operations

DS

C:

Attachment

Robert J. Butera, P.E., FDEP, Tampa w/o attachment

Kim Ford, P.E., FDEP, Tampa w/o attachment

Monitoring	% LEL	,	
Location	(Methane in air)	Date	Observer
GP 1	0	3/23/01	TF
GP 2	0	3/23/01	TF
GP 3	0	3/23/01	TF
GP 4	0	3/23/01	TF
GP 5	0	3/23/01	TF
GP 6	0	3/23/01	TF
GM-1	0	3/23/01	TF
GM-2	0	3/23/01	TF
GM-3	0	3/23/01	TF
GM-4	0	3/23/01	TF
GM-5	0	3/23/01	TF
GM-6	0	3/23/01	TF
GM-7	0	3/23/01	TF

- 1. GP 1-6 = Landfill gas migration monitoring probes
- 2. GM-1 = Maintenance building, contractor operations
- 3. GM-2 = MRF office trailer
- 4. GM-3 = Maintenance building, County operations
- 5. GM-4 = Administration building
- 6. GM-5 = Scale house
- 7. GM-6 = Control booth
- 8. GM-7 = Electric panel at leachate tank



D.E.R.

DEC 2 1 2000

Southwest District Tampa

December 19, 2000

John Morris, P. G. Florida Department of Environmental Protection 3804 Coconut Palm Drive Tampa, Florida 33619-8318

Subject:

Central County Solid Waste Disposal Complex

Permit Number S058-299180

Fourth Quarter 2000 - Landfill Gas Migration Monitoring Report

Dear Mr. Morris:

Attached in accordance with Specific Condition Number 18 of the operating permit are the landfill gas migration monitoring readings for the Central County Solid Waste Disposal Complex.

Please contact me if you have any questions.

Sincerely,

Don Shaulis

Solid Waste Operations

DS

Attachment

C Robert J. Butera, P.E., FDEP, Tampa w/o attachment

C Kim Ford, P.E., FDEP, Tampa w/o attachment

Monitoring	% LEL		
Location	(Methane in air)	Date	Observer
GP 1	0	12-19-00	TF
GP 2	0	12-19-00	TF
GP 3	0	12-19-00	TF
GP 4	0	12-19-00	TF
GP 5	0	12-19-00	TF
GP 6	0	12-19-00	TF
GM-1	0	12-19-00	TF
GM-2	0	12-19-00	TF
GM-3	0	12-19-00	TF
GM-4	0	12-19-00	TF
GM-5	0	12-19-00	TF
GM-6	0	12-19-00	TF
GM-7	0	12-19-00	TF

STATES.

- 1. GP 1-6 = Landfill gas migration monitoring probes
- 2. GM-1 = Maintenance building, contractor operations
- 3. GM-2 = MRF office trailer
- 4. GM-3 = Maintenance building, County operations
- 5. GM-4 = Administration building
- 6. GM-5 = Scale house
- 7. GM-6 = Control booth
- 8. GM-7 = Electric panel at leachate tank





D.E.R.
SEP 0 5 2000
Southwest District Tampa

August 30, 2000

John Morris, P. G. Florida Department of Environmental Protection 3804 Coconut Palm Drive Tampa, Florida 33619-8318

Subject:

Central County Solid Waste Disposal Complex

Permit Number S058-299180

Third Quarter 2000 - Landfill Gas Migration Monitoring Report

Dear Mr. Morris:

Attached in accordance with Specific Condition Number 18 of the operating permit are the landfill gas migration monitoring readings for the Central County Solid Waste Disposal Complex.

Please contact me if you have any questions.

Shaulis

Sincerely,

Don Shaulis

Solid Waste Operations

DS

Attachment

Robert J. Butera, P.E., FDEP, Tampa w/o attachment

Monitoring	% LEL		
Location	(Methane in air)	Date	Observer
GP 1	0	08-29-00	TF
GP 2	0	08-29-00	TF
GP 3	0	08-29-00	TF
GP 4	0	08-29-00	TF
GP 5	0	08-29-00	TF
GP 6	0	08-29-00	TF
GM-1	0	08-29-00	TF
GM-2	0	08-29-00	TF
GM-3	0	08-29-00	TF
GM-4	0	08-29-00	TF
GM-5	0	08-29-00	TF
GM-6	0	08-29-00	TF
GM-7	0	08-29-00	TF
GM-8	0	08-29-00	TF

- 1. GP 1-6 = Landfill gas migration monitoring probes
- 2. GM-1 = Maintenance building, contractor operations
- 3. GM-2 = MRF office trailer
- 4. GM-3 = Maintenance building, County operations
- 5. GM-4 = Administration building
- 6. GM-5 = Scale house
- 7. GM-6 = Control booth
- 8. GM-7 = Electric panel at leachate tank





May 3, 2000

John Morris, P. G. Florida Department of Environmental Protection 3804 Coconut Palm Drive Tampa, Florida 33619-8318

Subject:

Central County Solid Waste Disposal Complex

Permit Number S058-299180

Second Quarter 2000 - Landfill Gas Migration Monitoring Report

Dear Mr. Morris:

Attached in accordance with Specific Condition Number 18 of the operating permit are the landfill gas migration monitoring readings for the Central County Solid Waste Disposal Complex.

Please contact me if you have any questions.

Sincerely,

Don Shaulis

Solid Waste Operations

Don Shaulis

DS

C

Attachment

Robert J. Butera, P.E., FDEP, Tampa w/o attachment

Monitoring	% LEL		
Location	(Methane in air)	Date	Observer
GP 1	0	05-2-00	TF
GP 2	0	05-2-00	TF
GP 3	0	05-200	TF
GP 4	0	05-2-00	TF
GP 5	0	05-2-00	TF
GP 6	0	05-2-00	TF
GM-1	0	05-2-00	TF
GM-2	0	05-2-00	TF
GM-3	0	05-2-00	TF
GM-4	0	05-2-00	TF
GM-5	0	05-2-00	TF
GM-6	0	05-2-00	TF
GM-7	0	05-2-00	TF

- 1. GP 1-6 = Landfill gas migration monitoring probes
- 2. GM-1 = Maintenance building, contractor operations
- 3. GM-2 = MRF office trailer
- 4. GM-3 = Maintenance building, County operations
- 5. GM-4 = Administration building
- 6. GM-5 = Scale house
- 7. GM-6 = Control booth
- 8. GM-7 = Electric panel at leachate tank





January 14, 2000

Kim B. Ford, P. E.

Florida Department of Environmental Protection 3804 Coconut Palm Drive Tampa, Florida 33619-8318

Subject:

Central County Solid Waste Disposal Complex

Permit Number S058-299180

First Quarter 2000 - Landfill Gas Migration Monitoring Report

Dear Mr. Ford:

Attached in accordance with Specific Condition Number 18 of the operating permit are the landfill gas migration monitoring readings for the Central County Solid Waste Disposal Complex.

Please contact me if you have any questions.

Sincerely,

Don Shaulis

Solid Waste Operations Division

DonShaulis

DS

C

Attachment

Robert J. Butera, P.E., FDEP, Tampa

Monitoring	% LEL		
Location	(Methane in air)	Date	Observer
GP 1	0	01-14-00	ΤF
GP 2	0	01-14-00	TF
GP 3	0	01-14-00	TF
GP 4	0	01-14-00	TF
GP 5	0	01-14-00	TF
GP 6	0	01-14-00	TF
GM-1	0	01-14-00	TF
GM-2	0	01-14-00	TF
GM-3	0	01-14-00	TF
GM-4	0	01-14-00	TF
GM-5	0	01-14-00	TF
GM-6	0	01-14-00	TF
GM-7	0	01-14-00	TF

- 1. GP 1-6 = Landfill gas migration monitoring probes
- 2. GM-1 = Maintenance building, contractor operations
- 3. GM-2 = MRF office trailer
- 4. GM-3 = Maintenance building, County operations
- 5. GM-4 = Administration building
- 6. GM-5 = Scale house
- 7. GM-6 = Control booth
- 8. GM-7 = Electric panel at leachate tank

188444



NOV 17 1899

Department of Engineers of Profession

BY

SOUTHWEST DISTRICT

November 12, 1999

Kim B. Ford, P. E.

Florida Department of Environmental Protection 3804 Coconut Palm Drive Tampa, Florida 33619-8318

Subject:

Central County Solid Waste Disposal Complex

Permit Number S058-299180

Quarterly Landfill Gas Migration Monitoring Report

Dear Mr. Ford:

Attached in accordance with Specific Condition Number 18 of the operating permit are the fourth quarter landfill gas migration monitoring readings for the Central County Solid Waste Disposal Complex. Using the suggestion from John Morris that we purge the wells prior to reading, we came up with the following:

GP 1 went to zero after purging for 4 minutes, GP4 went to zero after 3 minutes of purging, GP 5 and GP 6 went to zero after 2 minutes of purging.

Also as requested the control panel will be included in the future gas migration reports.

Please contact me if you have any questions.

Sincerely,

Don Shaulis

Solid Waste Operations Division

Don Shaulis

DS

Attachment

Robert J. Butera, P.E., FDEP, Tampa

ichuser/shared/projects/central county solid waste disposal complex/landfill gas/1999 reports/3rd qtr 1999 lfg migration monitoring report.doc

Monitoring	% LEL		
Location	(Methane in air)	Date	Observer
GP 1	0	11-12-99	TF
GP 2	0	11-12-99	TF
GP 3	0	11-12-99	TF
GP 4	0	11-12-99	TF
GP 5	0	11-12-99	TF
GP 6	0	11-12-99	TF
GM-1	0	11-12-99	TF
GM-2	0	11-12-99	TF
GM-3	0	11-12-99	TF
GM-4	0	11-12-99	TF
GM-5	0	11-12-99	TF
GM-6	0	11-12-99	TF
GM-7	0	11-12-99	TF

- 1. GP 1-6 = Landfill gas migration monitoring probes
- 2. GM-1 = Maintenance building, contractor operations
- 3. GM-2 = MRF office trailer
- 4. GM-3 = Maintenance building, County operations
- 5. GM-4 = Administration building
- 6. GM-5 = Scale house
- 7. GM-6 = Control booth
- 8. GM-7 = Electric panel at leachate tank



O.E.P.

OCT 0 4 1999

Southwest District Tampa

September 29, 1999

Kim B. Ford, P. E.

Florida Department of Environmental Protection

3804 Coconut Palm Drive Tampa, Florida 33619-8318

Subject:

Central County Solid Waste Disposal Complex

Permit Number S058-299180

Quarterly Landfill Gas Migration Monitoring Report

Dear Mr. Ford:

Attached in accordance with Specific Condition Number 18 of the operating permit are the quarterly landfill gas migration monitoring readings for the Central County Solid Waste Disposal Complex.

There were concentrations of methane in excess of the action threshold of 50% LEL observed in GP-1 (240%), GP-3 (120%), GP-4 (80%) and GP-6 (760%). We believe these to be associated with the naturally decaying of organic matter as stated in the report dated October 8, 1998. We will continue to monitor on a quarterly basis.

Please contact me if you have any questions.

Sincerely,

Don Shaulis

Solid Waste Operations Division

Don Shaulis

DS

Attachment

C Robert J. Butera, P.E., FDEP, Tampa

i:\user\shared\projects\central county solid waste disposal complex\landfill gas\1999 reports\3rd qtr 1999 lfg migration monitoring report.doc

Monitoring	% LEL		
Location	(Methane in air)	Date	Observer
GP 1	240.0	28-Sep 99	TF
GP 2	0.0	28-Sep 99	ŤF
GP 3	120.0	28-Sep 99	TF
GP 4	80.0	28-Sep 99	TF
GP 5	0	28-Sep 99	TF
GP 6	760.0	28-Sep 99	TF
GM-1	0.0	28 Sep 99	TF
GM-2	0.0	28 Sep 99	TF
GM-3	0.0	28 Sep 99	TF
GM-4	0.0	28 Sep 99	TF
GM-5	0.0	28 Sep 99	TF
GM-6	0.0	28-Sep 99	TF

- 1. GP 1-6 = Landfill gas migration monitoring probes
- 2. GM-1 = Maintenance building, contractor operations
- 3. GM-2 = MRF office trailer
- 4. GM-3 = Maintenance building, County operations
- 5. GM-4 = Administration building
- 6. GM-5 = Scale house
- 7. GM-6 = Control booth





SARASOTA COUNTY GOVERNMENT SARASOTA, FLORIDA

ENVIRONMENTAL SERVICES Solid Waste Operations



4000 Knights Trail Road Nokomis, Florida 34275 Telephone (941) 486-2600 Facsimile (941) 486-2620

Jaly 13, 19

Kim B. Ford, P. E. Florida Department of Environmental Protection 3804 Coconut Palm Drive Tampa, Florida 33619-8318

Subject:

Central County Solid Waste Disposal Complex

Permit Number S058-299180

Quarterly Landfill Gas Migration Monitoring Report

Dear Mr. Ford:

Attached in accordance with Specific Condition Number 18 of the operating permit are the quarterly landfill gas migration monitoring readings for the Central County Solid Waste Disposal Complex.

There were concentrations of methane in excess of the action threshold of 50% LEL observed in GP-1 (100%), GP-5 (600%) and GP-6 (760%). We do not attribute these observations to indicate the presence of migrating landfill gas. We believe the methane observed to be associated with the naturally occurring anaerobic decay of organic matter contained in the soil layer in which the probes are screened as previously submitted to the Department in our initial compliance report for this facility (October 8, 1998). We do not feel it is appropriate to install any temporary monitoring points at this time or initiate a more frequent monitoring program. We will continue to perform routine quarterly monitoring.

Please contact me if you have any questions.

Sincerely,

Mark Triplett, P.E.

Solid Waste Operations Division

RMT

Attachment

Robert J. Butera, P.E., FDEP, Tampa

\user\shared\projects\central county solid waste disposal complex\landfill gas\1999 reports\1st qtr 1999 lfg migration monitoring report doc

Monitoring	% LEL		
Location	(Methane in air)	Date	Observer
GP 1	100.0	6 Jul 99	TF
GP 2	0.0	6 Jul 99	TF
GP 3	0.0	6 Jul 99	TF
GP 4	0.0	6 Jul 99	TF
GP 5	600.0	6 Jul 99	TF
GP 6	760.0	6 Jul 99	TF
GM-1	0.0	6 Jul 99	TF
GM-2	0.0	6 Jul 99	TF
GM-3	0.0	6 Jul 99	TF
GM-4	0.0	6 Jul 99	TF
GM-5	0.0	6 Jul 99	TF
GM-6	0.0	6 Jul 99	TF

- 1. GP 1-6 = Landfill gas migration monitoring probes
- 2. GM-1 = Maintenance building, contractor operations
- 3. GM-2 = MRF office trailer
- 4. GM-3 = Maintenance building, County operations
- 5. GM-4 = Administration building
- 6. GM-5 = Scale house
- 7. GM-6 = Control booth



SARASOTA COUNTY GOVERNMENT SARASOTA, FLORIDA

ENVIRONMENTAL SERVICES Solid Waste Operations

D.E.P.

ADD 1 6 1999

4000 Knights Trail Road Nokomis, Florida 34275 Telephone (941) 486-2600 Facsimile (941) 486-2620

Smallwasi diding rampa

April 13, 1999

Kim B. Ford, P. E. Florida Department of Environmental Protection 3804 Coconut Palm Drive Tampa, Florida 33619-8318

Subject:

Central County Solid Waste Disposal Complex

Permit Number S058-299180

Quarterly Landfill Gas Migration Monitoring Report

13T DIR 1999

Dear Mr. Ford:

Attached in accordance with Specific Condition Number 18 of the operating permit are the quarterly landfill gas migration monitoring readings for the Central County Solid Waste Disposal Complex.

There were concentrations of methane in excess of the action threshold of 50% LEL observed in GP-4 (200%) and GP-6 (400%). We do not attribute these observations to indicate the presence of migrating landfill gas. We believe the methane observed to be associated with the naturally occurring anaerobic decay of organic matter contained in the soil layer in which the probes are screened as previously submitted to the Department in our initial compliance report for this facility (October 8, 1998). We do not feel it is appropriate to install any temporary monitoring points at this time or initiate a more frequent monitoring program.

We will continue to perform routine quarterly monitoring. We will be proposing a meeting with the Department in the near future to evaluate alternative strategies for complying with the applicable regulations.

Please contact me if you have any questions.

Sincerely,

Mark Triplett, P.E.

Solid Waste Operations Division

RMT

Attachment

cc: Robert J. Butera, P.E., FDEP, Tampa

i/user/shared/projects/central county solid waste disposal complex/landfill gas/1999 reports/1st qtr 1999 lfg migration monitoring report/doc

Monitoring	% LEL			
Location	(Methane in air)	Date	Time	Observer
GP 1	0.0	16 Mar 99	0700	TF
GP 2	0.0	16 Mar 99	0705	TF
GP 3	0.0	16 Mar 99	0710	TF
GP 4	200.0	16 Mar 99	0715	TF
GP 5	0.0	16 Mar 99	0720	TF
GP 6	400.0	16 Mar 99	0725	TF
GM-1	0.0	16 Mar 99	0730	TF
GM-2	0.0	16 Mar 99	0735	TF
GM-3	0.0	16 Mar 99	0740	TF
GM-4	0.0	16 Mar 99	0745	TF
GM-5	0.0	16 Mar 99	0750	TF
GM-6	0.0	16 Mar 99	0755	TF

- 1. GP 1-6 = Landfill gas migration monitoring probes
- 2. GM-1 = Maintenance building, contract operations
- 3. GM-2 = MRF office trailer
- 4. GM-3 = Maintenance building, county operations
 5. GM-4 = Administration building
- 6. GM-5 = Scale house
- 7. GM-6 = Control booth



SARASOTA COUNTY GOVERNMENT SARASOTA, FLORIDA

ENIVORNMENTAL SERVICES

Utilities Department Solid Waste Operations Division

4000 Knights Trail Road Nokomis, Florida 34275 Telephone (941) 486-2600 FAX (941) 486-2620

Joth

December 14, 1998

Kim B. Ford, P. E. Florida Department of Environmental Protection 3804 Coconut Palm Drive Tampa, Florida 33619-8318

Subject:

Central County Solid Waste Disposal Complex

Permit Number S058-299180

Quarterly Landfill Gas Migration Monitoring Report

4th arz 1993

Dear Mr. Ford:

Attached in accordance with Specific Condition Number 18 of the operating permit are the quarterly landfill gas migration monitoring readings for the Central County Solid Waste Disposal Complex.

Methane was observed in excess of the action threshold of 50% LEL GP-6 (900%). We do not attribute this observation to indicate the presence of migrating landfill gas. This was discussed in the third quarter report and in our correspondence of December 4, 1998.

As discussed in that letter, samples were obtained from five locations. Theses samples were analyzed by GC/FID and GC/MS. The analytical results have been obtained and are summarized below for methane:

- Cell three whale $a = 370,000 \text{ mg/m}^3$
- Cell three whale $b = 250,000 \text{ mg/m}^3$
- Probe installed in the waste = 760 mg/m^3
- GP-6 = $370,000 \text{ mg/m}^3$
- Gp-4 = $390,000 \text{ mg/m}^3$

Kim B. Ford, P.E. December 14, 1998 Page 2

Methane and carbon disulfide were the only two analytes detected. The carbon disulfide concentrations were similar for all five samples ranging from 10 to 25 mg/m 3 . The methane concentrations appear to confirm the theory that the gas detected in the migration monitoring probes is related to the gas detected in the whales, but unrelated to the gas detected in the refuse.

Please note that the methane was detected only in monitoring probe GP-6 during this quarter. Therefore, prior to implementing any further action, we will continue quarterly monitoring in order to allow this probe to clear on its' own. An evaluation will be made of the results of the next quarterly monitoring to determine if any further action is warranted.

Please contact me if you have any questions.

Sincerely, Mach Liplett

Mark Triplett, P.E.

Solid Waste Operations Division

RMT Attachment

C Robert J. Butera, P.E., FDEP, Tampa

Monitoring	% LEL			
Location	(Methane in air)	Date	Time	Observer
GP 1	0.0	10 Dec 98	1300	TF
GP 2	0.0	10 Dec 98	1310	TF
GP 3	0.0	10 Dec 98	1315	TF
GP 4	0.0	10 Dec 98	1320	TF
GP 5	0.0	10 Dec 98	1325	TF
GP 6	900.0	10 Dec 98	1330	TF
GM-1	0.0	10 Dec 98	1340	TF
GM-2	0.0	10 Dec 98	1335	
GM-3	Not constructed			
GM-4	0.0	10 Dec 98	1350	TF
GM-5	0.0	10 Dec 98	1355	TF
GM-6	0.0	10 Dec 98	1400	TF

- 1. GP 1-6 = Landfill gas migration monitoring probes
- 2. GM-1 = Maintenance building, contract operations
- 3. GM-2 = MRF office trailer
- 4. GM-3 = Maintenance building, county operations
- 5. GM-4 = Administration building
- 6. GM-5 = Scale house
- 7. GM-6 = Control booth



SARASOTA COUNTY GOVERNMENT SARASOTA, FLORIDA

Utilities Department Solid Waste Operations Division

4000 Knights Trail Road Nokomis, Florida 34275 Telephone (941) 486-2600 FAX (941) 486-2620

DEC - 8 1998

December 4, 1998

Kim B. Ford, P.E.

Florida Department of Environmental Protection 3804 Coconut Palm Drive Tampa, Florida 33619

Re:

Central County Solid Waste Disposal Complex

Permit Number SO58-299180 Bubbles under the Cell 3 Liner

Dear Mr. Ford:

The purpose of this letter is to provide the Department with documentation of the actions taken to mitigate the bubbles (whales) that developed between the clay and synthetic liners in cell three. Whales had also developed in cells two and four, but of a much smaller nature. The whales in cells two and four have dissipated without any action taken.

In cell three, two two-inch diameter vents were installed to vent the accumulated gas. This gas was sampled and analyzed. The results will be presented with the fourth quarter landfill gas migration monitoring report as discussed. The vents will remain in place until just prior to the placement of waste in cell three. At that time, repairs will be made to the synthetic liner and will include quality assurance testing and documentation.

Please contact me if you have any questions.

Sincerely,

Mach Tiplett Mark Triplett, P.E.

Solid Waste Operations Division

RMT

C Robert J. Butera, P.E., FDEP - Tampa



SARASOTA COUNTY GOVERNMENT SARASOTA, FLORIDA

Utilities Department Solid Waste Operations Division

REC'D 10/2/98

4000 Knights Trail Road Nokomis, Florida 34275 Telephone (941) 486-2600 FAX (941) 486-2620

Dollar -

October 5, 1998

Kim B. Ford, P. E.

Florida Department of Environmental Protection 3804 Coconut Palm Drive Tampa, Florida 33619-8318

Subject:

Central County Solid Waste Disposal Complex

Permit Number S058-299180

Quarterly Landfill Gas Migration Monitoring Report

3º0 QTR 1998

Dear Mr. Ford:

Attached in accordance with Specific Condition Number 18 of the operating permit are the quarterly landfill gas migration monitoring readings for the Central County Solid Waste Disposal Complex.

There were concentrations of methane in excess of the action threshold of 50% LEL observed in GP-4 (400%) and GP-6 (360%). Methane was also observed in GP-1 (40%). All of these locations are located at various distances from the active cell (cell one).

We do not attribute these observations to indicate the presence of migrating landfill gas. We believe the methane observed to be associated with the naturally occurring anaerobic decay of organic matter contained in the soil layer in which the probes are screened. This organic layer was observed during installation of the probes and also during construction of the materials recovery facility.

A survey was conducted along the site boundary in ambient air to determine if any methane could be detected. There was none observed. Therefore, we do not feel it is appropriate to install any temporary monitoring points at this time or initiate a more frequent monitoring program.

Kim B. Ford, P.E. October 1, 1998 Page 2

Because the oldest refuse landfilled at this facility is only 90 days old, it is unreasonable to expect the formation of landfill gas in quantities great enough to be the source of these observations. This site is also underlain by a composite liner system which acts as a barrier to migrating landfill gas.

We will continue to perform routine quarterly monitoring. If the next quarterly observations again indicate the presence of methane, we will evaluate alternative strategies for complying with the applicable regulations.

Please contact me if you have any questions.

Sincerely,

Mark Triplett, P.E.

Solid Waste Operations Division

Mad Tiplet

RMT

Attachment

cc: Robert J. Butera, P.E., FDEP, Tampa

Permit Number SO58-299180 CENTRAL COUNTY SOLID WASTE DISPOSAL COMPLEX LANDFILL GAS MIGRATION MONITORING REPORT

ЯT	0760	15 Sep 98	0.0	9-MĐ
ЧT	\$160	15 Sep 98	0.0	CM-5
ЯT	0160	15 Sep 98	0.0	GM-4
			Not constructed	GM-3
			Not constructed	GM-2
HL	0060	15 Sep 98	0.0	GM-1
TF	\$\$80	86 dəS 51	0.03£	Э 4 Э
AT.	0\$80	15 Sep 98	2.0	GP 5
ТF	\$780	15 Sep 98	0.004	₽ 4
TF	0480	86 qə2 21	ε.0	GP 3
TF	5£80	15 Sep 98	1.0	GP 2
TF	0830	15 Sep 98	0.04	<u> </u>
Observer	əmiT	Date	(Methane in air)	Location
	,		%	Monitoring

5. GM-1 = Maintenance building, contract operations I. GP 1-6 = Landfill gas migration monitoring probes

4. GM-3 = Maintenance building, county operations

7. GM-6 = Control booth6. GM-5 = S cale house

3. GM-2 = MRF office trailer

5. GM-4 = Administration building