

FACILITY INFORMATION:

Facility Name: CITRUS CENTRAL SLF **On-Site Inspection Start Date:** 09/12/2012 09/12/2012 **On-Site Inspection End Date:** WACS No.: 39859 Facility Street Address: 3MI E LECANTO, SR44 City: LECANTO **County Name:** CITRUS Zip: 34461 **INSPECTION PARTICIPANTS:**

(Include ALL Landfill and Department Personnel with Corresponding Titles)Principal Inspector: Melissa Madden, InspectorOther Participants: Casey Stevens; Randy Messer

INSPECTION TYPE:

Routine Operation Inspection for Landfill - Class I facility Routine Long Term Care Inspection for Landfill - Class I Closed - Long Term Care facility Routine Operation Inspection for Other Facilities - Waste Tire Collection Center facility Routine Operation Inspection for Other Facilities - Landfill Gas Management System facility Routine Operation Inspection for Other Facilities - Source-Separated Organics (SOPF) facility

ATTACHMENTS TO THE INSPECTION CHECK LIST:

This Cover Page to the Inspection Checklist may include any or all of the following attachments as appropriate.

SECTION 1.0 - FILE REVIEW SECTION 2.0 - LANDFILL OPERATION AND MAINTENANCE SECTION 3.0 - LANDFILL - CLOSED SECTION 9.0 - WASTE TIRE FACILITIES SECTION 10.0 - REGISTERED SOURCE-SEPARATED ORGANICS PROCESSING FACILITIES

SECTION 1.0 - FILE REVIEW

Requirements:

Item No.	FILE REVIEW (Pre- or Post-Inspection, as appropriate.) Completed	Ok	Not Ok	Unk	N/A
1.1	For landfills and C&D disposal facilities, does the facility have a current plan for the method and sequence of filling wastes? 62-701.500(2)(f) for landfills; 62-701.730(7)(a) for C&D debris sites	~			
1.2	For landfills, are the following records being reported to the Department?(Check any that are Not OK) Waste reports (annually) 62-701.500(4) Annual estimate of remaining life 62-701.500(13)(c)	~			
1.3	Is leachate sampled, tested and disposed as required? 62-701.500(8)(a), 62-701.510(6)(c)	~			
1.4	Is gas monitoring being performed as required by the permit? 62-701.500(9), 62-701.530(2)	>			
1.5	Are the results of the gas sampling reported to the Department quarterly? 62-701.530(2)(c)	~			
1.6	Is water quality sampling and testing performed according to standard procedures and at the required frequencies? 62-701.510(2) for landfills; 62-701.730(4)(b) and (10) for C&D debris sites; 62-713.400(3) for stationary soil treatment facilities.	>			
1.7	Do the results of the water quality testing suggest there may be adverse impacts to water quality from the operation of the solid waste facility? 62-701.510(3) and (4); 62-701.730(4)(c) and (10) for C&D debris sites; 62-713.400(3) for stationary soil treatment facilities.			>	
1.8	For closed landfills and C&D disposal facilities with final elevations higher than 20 feet above grade, has a final survey report verifying the final elevations and contours of the facility been submitted to the Department? 62-701.600(6)(b), 62-701.730(9)(d)	~			
1.9	Is financial assurance adequate? 62-701.630 for landfills; 62-701.710(7)(a) and (10)(a) for waste processing facilities; 62-701.730(11)(a) for C&D debris facilities; 62-713.600(6)(a) for stationary soil treatment facilities; 62-711.500(3) for waste tire facilities. NOTE: The Solid Waste Financial Coordinator in Tallahassee can assist with this information.			<	
1.10	Are cost estimates current and adjusted every year? 62-701.630(4) for landfills; 62-701.710(7)(b) and (10)(a) for waste processing facilities; 62-701.730(11)(b) and (c) for C&D debris facilities; 62-713.600(6)(b) and (c) for stationary soil treatment facilities; 62-711.500(3) for waste tire facilities.			٨	
1.11	For C&D debris disposal and disposal with recycling facilities, is an Annual Report submitted to the Department for the disposal operation by April 1st of each year? 62-701.730(12)				~
1.12	For C&D recycling facilities with no disposal, is an Annual Report for the recycling facility submitted to the Department by April 1st of each year? 62-701.710(9)(b)				<
1.13	For compost facilities, has the compost product been sampled and analyzed every 20,000 tons or every 3 months (whichever is sooner)? 62-709.530(1)				<
1.14	For compost facilities, has the annual report been submitted by June 1st? 62-709.530(3)				>

SECTION 2.0 - LANDFILL OPERATION AND MAINTENANCE

Requirements:

ltem No.	SOLID WASTE PROHIBITIONS (unless "grandfathered" in, see 62- 701.300(18)) Completed	Ok	Not Ok	Unk	N/A
2.1.1	Unauthorized storage, processing, or disposal of solid waste except as authorized at a permitted solid waste management facility or other exempt facility. 62-701.300(1)(a)	~			
2.1.2	Unauthorized disposal or storage prohibited, except yard trash, within 500 feet of a potable water well? 62-701.300(2)(b)	~			
2.2	Unauthorized storage or disposal of yard trash prohibited within the minimum setbacks of (Check any that are Not OK) 62-701.300(12) 100 feet from potable water wells (except on-site)? 50 feet from water bodies?	~			
2.3	Unauthorized disposal or storage prohibited in any natural or artificial body of water including ground water and wetlands? (Does not apply to standing water after a storm event.) 62-701.300(2)(d)	>			
2.4	Unauthorized disposal or storage prohibited, except yard trash, within 200 feet of any natural or artificial body of water, including wetlands without permanent leachate controls, except impoundments or conveyances which are part of an on-site, permitted stormwater management system or on-site water bodies with no off-site discharge? 62-701.300(2)(e)	>			
2.5	Unauthorized open burning of solid waste prohibited except in accordance with Department requirements? 62-701.300(3)	~			
2.6	Are the following unauthorized wastes or special wastes properly controlled, managed and disposed? (Check any that are Not OK) Hazardous waste 62-701.300(4) Biomedical waste 62-701.300(6) Yard trash 62-701.300(8)(c) Whole waste tires 62-701.300(8)(e) Regulated asbestos waste 62-701.520(3), 62-701.730(19) Used oil and oily wastes, except as exempted 62-701.300(11) PCB wastes 62-701.300(5) Lead-acid batteries 62-701.300(8)(a) White goods 62-701.300(8)(d) Liquids 62-701.300(10) CCA treated wood 62-701.300(14)	¥			
2.7	Are only permitted waste types disposed at facility? 62-701.340(2), 62-701.500(6)(a), 62- 701.500(2)(c)	~			

ltem No.	LANDFILL OPERATION AND MAINTENANCE Completed	Ok	Not Ok	Unk	N/A
2.8	Is there a trained operator on-site at Class I and III landfills when receiving wastes? 62-701.500(1)	>			
2.9	Is there at least one trained spotter at each working face when receiving wastes at Class I and III landfills? 62-701.500(1)	>			
2.10	Are the following records or plans current and available on-site? (Check any that are Not OK) Training Plan 62-701.320(15)(a) Operating Plan 62-701.500(2) Waste weight records 62-701.500(4) Precipitation records 62-701.500(8)(g)	۲			

ltem No.	LANDFILL OPERATION AND MAINTENANCE Completed	Ok	Not Ok	Unk	N/A
2.10	Load-checking program records 62-701.500(6)(a)				
	Training records 62-701.320(15)(a)	93			
	Operation record 62-701.500(3)	~			
	Quantity of leachate 62-701.500(8)(f)				
2.11	Is the operation plan substantially followed? 62-701.500(2)	~			
2.12	Is incoming waste weighed? 62-701.500(4)(a) and (2)(d)	~			
2.13	Is the method and sequence of filling waste according to plans? 62-701.500(2)(f)	~			
2.14	Is access properly controlled to prevent unauthorized waste disposal? 62-701.500(5)	~			
2.15	Is waste compacted as required? 62-701.500(7)(a)	~			
2.16	Are the working face and side slopes above ground graded to a slope no greater than 3 feet horizontal to 1 foot vertical rise? 62-701.500(7)(c)	~			
2.17	Is a narrow working face practiced? 62-701.500(7)(d)	~			
2.18	Is the frequency, amount and quality of initial cover, as required? 62-701.500(7)(e)	 		~	
2.10	Is the frequency, amount and quality of intermediate cover, as required? 62-701.500(7)(f)			52	
2.19	Is litter controlled and are litter control devices maintained? 62-701.500(7)(i) and (11)(f)	81		~	
		~			
2.21	Is erosion control adequate? 62-701.500(7)(j)	~			
2.22	Is the leachate collection and removal system maintained and operated as required? 62-701.500(2)(j), 62-701.500(8)(b) and (h)	~			
2.23	Is leachate disposed of or treated as required? 62-701.500(8)(b), (c) and (d)	~			
2.24	If leachate recirculation is practiced at the facility, is it done in accordance with Department requirements and the Operation Plan? 62-701.400(5)	~			
2.25	Is gas controlled to not cause objectionable odors beyond the property boundary? 62-701.530(3)(b)	~			
2.26	Is gas controlled to not allow combustible gas concentrations to exceed specified limits? 62- 701.530(3)(a)	~			
2.27	Are gas vents intact and functioning properly? 62-701.500(9), 62-701.530(1)(a)3	~			
2.28	Is mixing of leachate and stormwater prevented or minimized? 62-701.500(10), 62-701.400(9)(c)	~			
2.29	Is stormwater management system maintained and operated as required? 62-701.500(10)	~			
2.30	Is there sufficient operating equipment? 62-701.500(11)(a)	~			
2.31	Is there sufficient reserve equipment (or other arrangements)? 62-701.500(11)(b)	~			
2.32	Are communication facilities adequate? 62-701.500(11)(c)	~			
2.33	Are approved dust control methods adequate? 62-701.500(11)(d)	~			
2.34	Are fire protection and fire fighting capabilities adequate and operational? 62-701.500(11)(e)	~			
2.35	Are there required signs for operational directions and public information? 62-701.500(11)(g)	~	L		L
2.36	Are all-weather access roads and inside perimeter roads properly maintained? 62-701.500(12)	~			L
2.37	Are ground water wells intact and properly maintained? 62-701.510(2)(b), 62-701.620(8)			~	
2.38	Are all additional specific conditions (not otherwise addressed above) in the permit, Department order, or certification, if any, being followed? 62-701.320(1), 403.161, F.S.	~			

SECTION 3.0 - LANDFILL - CLOSED

Requirements:

The requirements listed in this section provide an opportunity for the Department's inspector to indicate the conditions found at the time of the inspection. A "Not Ok" response to a requirement indicates either a potential violation of the corresponding rule or an area of concern that requires more attention. Both potential violations and areas of concern are discussed further at the end of this inspection report.

Type of Cover:

Closure/Final Cover Date:

Post-Closure Utilization:

Surrounding Land Use:

Date Long-Term Care Began:

ltem No.	LANDFILL - CLOSED Completed	Ok	Not Ok	Unk	N/A
3.1	Is site access controlled to prevent any unauthorized dumping? 62-701.600(3)(i)	~			
3.2	Are any unauthorized wastes stored or disposed at the site? 62-701.600(3)(i)	~			
3.3	Is stormwater management system maintained and operated as required? 62-701.600(3)(h)	~			
3.4	Is the final cover properly vegetated? 62-701.600(3)(f)2	~			
3.5	Are there any signs of erosion of the final cover? 62-701.620(1)	~			
3.6	Is there any evidence of damage to the barrier layer of the final cover? 62-701.620(1)	~			
3.7	Are areas of differential settlement being properly filled? 62-701.600(3)(f)4			~	
3.8	Are there any areas of ponding water on the final cover? 62-701.600(3)(f)3	~			
3.9	Is the leachate collection and removal system maintained and operated as required? 62- 701.500(2)(j), 62-701.500(8)(b) and (h)	~			
3.10	Is leachate disposed of or treated as required? 62-701.500(8)(b), (c) and (d)	~			
3.11	Are there any signs of leachate seeps at the closed landfill? 62-701.500(8)(b), 62-701.620(1)	~			
3.12	Condition of the ground water monitoring wells in accordance with the ground water monitoring plan. 62-701.620(1) (Check any that are Not OK) Access to monitoring wells Damage to monitoring wells Monitoring wells protected, secured and labeled.			Ŷ	
3.13	Are the wells for gas monitoring and detection intact and operable? 62-701.620(5)			~	
3.14	Is the gas collection system (active or passive) operating and maintained? 62-701.620(5) Signs of stressed vegetation Odors or foul smells	~			
3.15	Is gas monitoring being conducted as required? 62-701.620(5)	~			
3.16	Is there any evidence that gas pressure is interfering with or causing failure of the final cover? 62- 701.530(1)(a)4	~			
3.17	If required, are survey monuments properly installed? 62-701.600(6)	~			
3.18	Is there a potential hazard to public health and the environment resulting from the post-closure utilization of the solid waste disposal facilities or surrounding land-use changes? 62-701.610(1)	~			
3.19	If waste is being relocated, is this performed according to the Department's requirements? 62- 701.610(2)	~			
3.20	Are all additional specific conditions (not otherwise addressed above) in the closure or permit for long -term care, Department order, or certification, if any, being followed? 62-701.620(2), 403.161, F.S.	~			

Item No.	LANDFILL - CLOSED Completed	Ok	Not Ok	Unk	N/A
3.20		>			

SECTION 9.0 - WASTE TIRE FACILITIES

Requirements:

ltem No.	SOLID WASTE PROHIBITIONS (unless "grandfathered" in, see 62- 701.300(18)) Completed	Ok	Not Ok	Unk	N/A
9.1.1	Unauthorized storage, processing, or disposal of solid waste except as authorized at a permitted solid waste management facility or other exempt facility? 62-701.300(1)(a)	~			
9.1.2	Unauthorized disposal or storage prohibited, except yard trash, within 500 feet of a potable water well? 62-701.300(2)(b)	~			
9.2	Unauthorized storage or disposal of yard trash prohibited within the minimum setbacks of (Check any that are Not OK) 62-701.300(12) 100 feet from potable water wells (except on-site)? 50 feet from water bodies?	*			
9.3	Unauthorized disposal or storage prohibited in any natural or artificial body of water including ground water and wetlands? (Does not apply to standing water after a storm event.) 62-701.300(2)(d)	>			
9.4	Unauthorized disposal or storage prohibited, except yard trash, within 200 feet of any natural or artificial body of water, including wetlands without permanent leachate controls, except impoundments or conveyances which are part of an on-site, permitted stormwater management system or on-site water bodies with no off-site discharge? 62-701.300(2)(e)	>			
9.5	Unauthorized open burning of solid waste prohibited except in accordance with Department requirements? 62-701.300(3)	~			

ltem No.	WASTE TIRE FACILITY - GENERAL REQUIREMENTS FOR STORAGE Completed	Ok	Not Ok	Unk	N/A
9.6	If the facility accepts tires from the public, is a sign posted at the facility entrance stating operating hours, cost of disposal and site rules? 62-711.540(1)(a)	~			
9.7	Are operations involving the use of open flames conducted no closer than 25 feet of a waste tire pile? 62-711.540(1)(b)	~			
9.8	If the facility accepts tires from the public, is an attendant always present on site when the site is open for business? 62-711.540(1)(c)	~			
9.9	Are fire protection services assured through notification to local fire protection authorities? 62- 711.540(1)(d)	~			
9.10	Is an annual fire safety survey conducted? 62-711.540(1)(d)	~			
9.11	Is a copy of the annual fire safety report made part of the next quarterly report? 62-711.540(1)(d)				~
9.12	Does the facility have an Emergency Preparedness Manual (EPM) on-site? 62-711.540(1)(e)	~			
9.13	Does the EPM contain the following information? (Check all that are Not OK) Contact names and numbers 62-711.540(1)(e)1 List of emergency response equipment and locations on-site 62-711.540(1)(e)2 Procedures to be followed in the event of a fire 62-711.540(1)(e)3	>			
9.14	Is the operator at the facility maintaining records of the quantity of waste tires received at the site, stored at the site, and shipped from the site? 62-711.540(1)(g) and 62-711.400(5)	~			
9.15	If the operator of the site is not the owner of the property, has written authorization been obtained from the property owner to operate the facility? 62-711.540(1)(h)	>			
9.16	Is adequate communications equipment available at the site? 62-711.540(1)(i)	>			
9.17	Is the owner or operator providing for control of mosquitoes and rodents so as to protect the public health and welfare? $62-711.540(1)(j)$	>			

Item	WASTE TIRE FACILITY - STORAGE INDOORS Completed	Ok	Not	Unk	N/A
No.			Ok		

ltem No.	WASTE TIRE FACILITY - STORAGE INDOORS Completed	Ok	Not Ok	Unk	N/A
9.18	Are waste tire piles more than 50 feet in width? 62-711.540(2)(a)				~
9.19	Are waste tire piles along a wall more than 25 feet in width? 62-711.540(2)(a)				~
9.20	Are widths of main aisles between piles less than 8 feet? 62-711.540(2)(b)				~
9.21	Is there less than 3 feet of clearance between the top of storage to sprinkler detectors or roof structures? 62-711.540(2)(c)				>
9.22	Is there less than 3 feet of clearance between waste tire piles and unit heaters, etc.? 62- 711.540(2)(d)				>
9.23	If waste tires are stored up to15 feet in height, do walls have at least a 4- hour fire rating? 62- 711.540(2)(e)				>
9.24	If waste tires are stored more than 15 feet in height, do walls have a fire rating of not less than 6 hours and columns one hour FR? If more than 20 feet, do columns and its connections with other structural members have two hour FR? 62-711.540(2)(f)				>
9.25	Is the access controlled through the use of doors, fences, gates, natural barriers or other means? 62-711.540(2)(h)				>

ltem No.	WASTE TIRE FACILITY - STORAGE OUTDOORS Completed	Ok	Not Ok	Unk	N/A
9.26	Is the waste tire site operated within 200 feet from a body of water? 62-711.540(3)(a)	~			
9.27	Does the waste tire pile have a width less than 50 feet? 62-711.540(3)(b)	~			
9.28	Does the waste tire pile have an area less than 10,000 sq. ft? 62-711.540(3)(b)	~			
9.29	Does the waste tire pile have a height less than 15 feet? 62-711.540(3)(b)	~			
9.30	Is there a 50 feet wide fire lane around the perimeter of the waste tire pile? 62-711.540(3)(c)	~			
9.31	Is there unobstructed access to the fire lane? 62-711.540(3)(c)	~			
9.32	Is the access controlled through the use of doors, fences, gates, natural barriers or other means? 62- 711.540(3)(d)	~			
9.33	Is the site kept free of grass, underbrush, and other potentially flammable vegetation? 62- 711.540(3)(f)	~			
9.34	Is the site bermed or given other adequate protection to prevent liquid runoff from entering water bodies? 62-711.540(3)(e)	~			
9.35	Are residuals contained on-site and disposed of in a permitted solid waste management facility or properly recycled? 62-711.540(5)	~			
9.36	Does the waste tire site qualify for the exceptions to the technical and operational standards as allowed by rule? 62-711.540(6)	~			

ltem No.	WASTE TIRE FACILITY - COLLECTION CENTER Completed	Ok	Not Ok	Unk	N/A
9.37	Are no more than 1,500 tires at the collection center at any one time? 62-711.550(1)(a)	~			
9.38	Are all waste tires, which are not used tires, removed from site yearly for recycling, processing, or disposal? 62-711.550(1)(b)	>			

SECTION 10.0 - REGISTERED SOURCE-SEPARATED ORGANICS PROCESSING FACILITIES

Requirements:

FACILITY TYPE(S)	MATERIAL(S) PROCESSED	PRODUCES	METHOD OF COMPOSTING
Yard Trash Transfer Station	🗙 Yard Trash	🗙 Mulch	🗙 Windrow
X Yard Trash Recycling	Manure	Firewood	Passive aerated windrows
	Animal byproducts	Fuel	Aerated static piles
	Pre-consumer vegetative waste	Compost	In-vessel composting
	Vegetative waste	🗙 Soil Amendment	
		Soil	
		Other	
			Ok Not Unk N/A

No.	SOURCE-SEPARATED ORGANICS PROCESSING FACILITIES Completed	UK	Ok	UIIK	
10.1	Unauthorized storage, processing, or disposal of solid waste except as authorized at a permitted or registered solid waste management facility or other exempt facility? 62-701.300(1)(a)	~			
10.2	Have objectionable odors been caused or allowed in violation of Chapter 62-296, F.A.C.? 62-709.300(7)(a)	~			
10.3	Unauthorized storage or processing in a way or location that violates air quality or water quality standards? 62-709.300(7)(b), 62-701.300(1)(b)	~			
10.4	Do geological formations or subsurface features provide support for the facility? 62-709.300(7)(b), 62-701.300(2)(a)	~			
10.5	Unauthorized disposal or storage prohibited, except yard trash, within 200 feet of any natural or artificial body of water, including wetlands without permanent leachate controls, except impoundments or conveyances which are part of an on-site, permitted stormwater management system or on-site water bodies with no off-site discharge? 62-701.300(2)(e), 62-709.320(3)	~			
10.6	Unauthorized storage or processing in any natural or artificial water body (e.g. ground water and wetlands within DEP jurisdiction)? 62-709.300(7)(b), 62-701.300(2)(d)	>			
10.7	Unauthorized storage or processing on the right of way of any public highway, road, or alley? 62-709.300(7)(b), 62-701.300(2)(f)	>			
10.8	Unauthorized open burning of solid waste except in accordance with Department requirements? 62-709.300(7)(b), 62-701.300(3)	>			
10.9	Unauthorized incorporation of CCA treated wood into material that will be applied as a ground cover, soil or soil amendment? 62-709.300(7)(b), 62-701.300(14)	>			
10.10	Unauthorized unconfined emissions of particulate matter in violation of paragraph 62-296.320(4)(c), F.A.C.? 62-709.300(7)(b), 62-701.300(15)	>			
10.11	Does the facility have the necessary operational features and equipment - unless otherwise specified? Including: 62-709.320(2)(a)				
10.11.1	Effective barrier to prevent unauthorized entry and dumping? 62-709.320(2)(a)1	>			
10.11.2	Dust and litter control methods? 62-709.320(2)(a)2	>			
10.12	Does the facility have the necessary fire protection and control provisions to deal with accidental burning of solid waste? Including 62-709.320(2)(a)3				
10.12.1	20-foot all-weather access road all around the perimeter? 62-709.320(2)(a)3.a.	>			
10.12.2	No material mechanically compacted? 62-709.320(2)(a)3.b.	<			
10.12.3	No material more than 50 feet from access by motorized firefighting equipment? 62-709.320(2)(a)3.c.	~			
10.13	Is the facility operated in a manner to control vectors? 62-709.320(2)(b)	~			
10.14	Is the facility operated in a manner to control objectionable odors per with Rule 62-296.320(2), F.A.C.? 62-709.320(2)(c)	~			
10.15	Are any installed drains and leachate or condensate conveyances kept cleaned? 62-709.320(2)(d)				<
10.16	Is the received solid waste processed timely as follows? 62-709.320(2)(e)				

ltem No.	REQUIREMENTS AND PROHIBITIONS APPLICABLE TO ALL REGISTERED SOURCE-SEPARATED ORGANICS PROCESSING FACILITIES Completed	Ok	Not Ok	Unk	N/A
10.16					
10.16.1	Is yard trash size-reduced or removed within 6 months or time needed to receive 3,000 tons or 12,000 cubic yards, whichever is greater? (Separated logs with 6 inch diameter or greater can be stored for up to 12 months before being size-reduced or removed.) 62-709.320(2)(e)1	~			
10.16.2	Is putrescible waste (e.g. vegetative wastes, animal byproducts or manure) processed and incorporated into the composting material, or removed from the facility, within 48 hours? 62-709.320(2)(e)2	~			
10.17	Is any treated or untreated biomedical waste; hazardous waste; or any materials having (PCB) concentration of 50 ppm or greater containerized and removed immediately? 62-709.320(2)(f), 62-701.300(4), 62-701.300(5), 62-701.300(6)	~			
10.18	Have all residuals, solid waste and recyclable materials been removed and recycled or disposed and has any remaining processed material been properly used or disposed upon the facility ceasing operations? 62-709.320(2)(g)				~
10.19	If temperature is used to show disinfection or vector attraction achieved, are records kept for at least three years? 62-709.320(4)(b)				>
10.20	Is the registration for the facility current and on file with the Department? 62-709.320(3)(b)	~			
10.21	Are renewal applications for annual registration of the facility submitted to the Department by July 1st, if applicable? 62-709.320(3)(c)	>			
10.22	Are monthly records of incoming and outgoing material kept on-site or at another location as indicated on the registration form for at least three years? 62-709.320(4)(a)	~			
10.23	Are Annual Reports, based upon the preceding calendar year, summarizing monthly records, submitted to the Department as required? 62-709.320(4)(a)	~			
ltem No.	REQUIREMENTS AND PROHIBITIONS APPLICABLE TO YARD TRASH ONLY FACILITIES Completed	Ok	Not Ok	Unk	N/A

No.	ONLY FACILITIES Completed	ÜK	Ok	UIIK	N/A
10.24	Unauthorized storage or processing within 100 feet from off-site potable water well that existed before facility registered? 62-709.300(7)(b) and 62-701.300(12)(a)	~			
10.25	Unauthorized storage or processing within 50 feet from any body of water, including wetlands? (Does not include parts of permitted stormwater system, or water bodies totally within facility with no discharge to surface waters.) 62-709.300(7)(b), 62-701.300(12)(b)	~			
10.26	Is processed material removed from facility within 18 months, unless longer storage authorized by permit? 62-709.330(2)	>			
10.27	Is the facility accepting only yard trash, and bags used to collect yard trash and containerizing any other material? 62-709.330(3)	~			

ltem No.	REQUIREMENTS AND PROHIBITIONS APPLICABLE TO ONLY THOSE FACILITIES THAT BLEND MANURE OR COMPOST VEGETATIVE WASTES, ANIMAL BYPRODUCTS OR MANURE Completed	Ok	Not Ok	Unk	N/A
10.28	Unauthorized storage or processing within 500 feet off-site potable water well that existed before facility registered? 62-709.300(7)(b) and 62-701.300(2)(b)				<
10.29	Unauthorized storage or processing within 200 feet from any body of water, including wetlands? (Does not include parts of permitted stormwater system, or water bodies totally within facility with no discharge to surface waters.) 62-709.300(7)(b), 62-701.300(2)(e)				<
10.30	Unauthorized storage or processing within 10,000 feet of any licensed and operating airport runway used by turbine powered aircraft, or within 5,000 feet of any licensed and operating airport runway used only by piston engine aircraft, unless applicant demonstrates that the facility is designed and will be operated so that it does not pose a bird hazard to aircraft? 62-709.300(7)(b), 62-701.320(13)(b)				>
10.31	Is the carbon:nitrogen ratio of the blended feedstocks greater than 20? 62-709.350(2)				~
10.32	Do piles exceed 12 feet in height? 62-709.350(3)				<
10.33	Is all material removed within 18 months, unless longer storage authorized by permit? 62-709.350(5)				<
10.34	Is there documentation showing that disinfection has been achieved? Note that this is not required if they are composting only pre-consumer vegetative waste with or without yard trash. 62-709.350(6)				~
10.35	Is there vector attraction reduction controls that include one of the following? 62-709.350(7) Temperature monitoring records showing the waste was composted for at least 14 days, with temperature no lower than 40 degrees Celsius and average temperature of the material being composted higher than 45 degrees Celsius. or 62-709.350(7)(a) Results of testing showing the specific oxygen uptake rate (SOUR) for material being composted or blended equal to or less than 1.5 milligrams				>

ltem No.	REQUIREMENTS AND PROHIBITIONS APPLICABLE TO ONLY THOSE FACILITIES THAT BLEND MANURE OR COMPOST VEGETATIVE WASTES, ANIMAL BYPRODUCTS OR MANURE Completed	Ok	Not Ok	Unk	N/A
10.35	of oxygen per hour per gram of total solids (dry weight basis) at a temperature of 20 degrees Celsius. 62-709.350(7)(b)				~

COMMENTS:

09/13/2012

Item 1.7 - GW results not evaluated as part of this inspection.

Items 1.9, 1.10 - Annual FACE estimates pending review. Funding is evaluated post-district FACE review.

Item 2.13 - During the inspection, the WF was located within the first "third" of Phase 3. The facility has floored out approximately one half of Phase 3. Since latter sections of the cell were inundated with water after the recent storm events, the County is filling in portions of the cell which are reasonable dry while maintaining general compliance with the approved sequence of fill. Since the current design slopes stormwater back to the east, ponding was observed at the NE corner of the cell. According to the operator, this water will be managed as leachate due to the exposed waste and minimal cover. The County anticipates submitting a sequence modification to abandon the rain cell cover and floor the remaining portions of the cell. The County also plans to explore alternative methods of stormwater management as filling is expected to continue below grade for some time.

Items 2.17-2.19 - The County is currently filling dry, accessible portions of the active area. Since waste west of the working face was previously located below the "high water line", much of the in-place waste remains saturated. An all-weather access road was constructed to allow for vehicle and equipment access into and out of the cell. Outside of the roadway, waste was exposed through much of the cover, either due to erosion/rutting, use of ADC that has since rinsed away, or flotsam material in ponded areas. A majority of Phase 3 is "open" at this time. However, significant odors or vectors were not observed during the inspection. Floating trash was also observed in the western portion of the cell. Several stockpiles of soil had been placed adjacent to the roadway for use as cover once these areas have sufficient dried out for equipment access.

Item 2.22 - Several feet of standing water remain present in the western portion of Phase 3. According to County staff, the liquids have been pumped down at least twice, however, since significant rain has continued, some liquids have returned. All liquids generated within Phase 3 are currently being managed as leachate. Leachate is either pumped down via the leachate collection system pumps, a temporary pump direct to the tank or spray evaporated. At the time of the inspection, the primary lead and lag pumps for Phase 3 were set to manual to avoid overloading the system and pumps. The secondary for Phase 3 and all other pumps were set to automatic and appeared to be functioning as designed. The Phase 3 primary level indicator registered 128" during the inspection. It was not clear whether this provides an accurate head over liner quantity since the rain cell cover remains present. The County is currently treating leachate within the on -site treatment plant (~25-30k gals/day) and hauling an average of ~40k gals/day to the County WWTP.

During the inspection, pressure release valves at the main pump station and Phase 2 pump station were observed spraying liquid, presumably leachate mist, into the air when activated. The valves appear to be rusted and may be damaged. Please investigate and repair as necessary.

Item 2.28 - During the inspection, Department staff observed two areas of potential seepage on the W and S side of Phase I. Additional cover should be placed on these areas and monitored for future seepage.

Items 2.37, 3.12, 3.13 - All GW/Gas wells not observed during this inspection.

Inspection Date: 09/12/2012

Items 3.7, 3.8 - An area of ponded water was observed on the S portion of the closed Class I (located ~50' S of pyramid). Please provide documentation that these areas have been filled, re-graded, and vegetated.

ATTACHMENTS:

Phase 3



DRA 4



pressure release valve leaking?



WF & Ponding @ NE corner



DRA 5



Phase 3 sump level indicator



Ponding @NE corner, exposed waste



Seepage - Phase 1



WTPF



Ponding on closed, Class 1



Seepage - Phase 1



white goods



Inspection Date: 09/12/2012

Signed:

Melissa Madden PRINCIPAL INSPECTOR NAME	Inspector PRINCIPAL INSPECTOR TITLE	
MAN		9/14/2012
PRINCIPAL INSPECTOR SIGNATURE		DATE
Casey Stevens		
REPRESENTATIVE NAME		
NO SIGNATURE		
REPRESENTATIVE SIGNATURE		
Randy Messer		
REPRESENTATIVE NAME		
NO SIGNATURE		
REPRESENTATIVE SIGNATURE		

Supervisor: Stephanie Watson

NOTE: By signing this document, the Site Representative only acknowledges receipt of this Inspection Report and is not admitting to the accuracy of any of the items identified by the Department as "Not Ok" or areas of concern.