



**FLORIDA DEPARTMENT OF
ENVIRONMENTAL PROTECTION**

CENTRAL DISTRICT
3319 MAGUIRE BOULEVARD, SUITE 232
ORLANDO, FLORIDA 32803-3767

RICK SCOTT
GOVERNOR

JENNIFER CARROLL
LT. GOVERNOR

HERSCHEL T. VINYARD JR.
SECRETARY

January 11, 2013

ELECTRONIC MAIL

Amounir029@aol.com

Mr. Aziz Mounir
Rayan Used Wholesale Tires
750 Central Florida Parkway
Orlando, FL 32824

OCD-SW-13-008

Orange County – SW
Rayan Used Wholesale Tires- Waste Tires
FDEP WACS # 100855
Inspection Report Transmittal

Dear Mr. Mounir:

On January 03, 2012, a representative of the Florida Department of Environmental Protection conducted an inspection at the above referenced facility to determine the status of compliance with the Department's solid waste regulations. A copy of the inspection report is attached for your review.

Please contact me by telephone at (407) 897-4312 or by e-mail at Gloria.Depradine@dep.state.fl.us, or contact Carolin Heaviside at (407) 897-4327 or by e-mail at Carolin.Heaviside@dep.state.fl.us if you have any questions or need additional information.

Sincerely,

Gloria-Jean De Pradine
Compliance & Enforcement Supervisor
Solid Waste

GND/ch

Attachment: Inspection Report



Florida Department of
Environmental Protection
Inspection Checklist

FACILITY INFORMATION:

Facility Name: RAYAN USED TIRE WHOLESALE INC.

On-Site Inspection Start Date: 01/03/2013

On-Site Inspection End Date: 01/03/2013

WACS No.: 100855

Facility Street Address: 750 Central Florida Pkwy

City: Orlando

County Name: ORANGE

Zip: 32824

INSPECTION PARTICIPANTS:

(Include ALL Landfill and Department Personnel with Corresponding Titles)

Principal Inspector: Carolin Heaviside, Inspector

Other Participants: Gloria De Pradine, Inspector; Gary Allspach, Operator

INSPECTION TYPE:

Follow-up Operation Inspection for Other Facilities - Waste Tire Site facility

ATTACHMENTS TO THE INSPECTION CHECK LIST:

This Cover Page to the Inspection Checklist may include any or all of the following attachments as appropriate.

Inspection Date: 01/03/2013

Pre-existing Violations:

Rule: 62-711.550(1)(a)

Question Number: 9.37

Explanation: During the inspection, waste tires in excess of the 1500 waste limit were stored at the facility.

Corrective Action: A "Waste Tire Processing Facility" permit is required if storage will be greater than 1500 waste tires at any given time.

Rule: 62-701.300(1)(a)

Question Number: 9.1.1

Explanation: During the inspection, waste tires in excess of the 1500 waste limit were stored at the site.

Corrective Action: The operator/owner must apply for a "Waste Tire Processing Facility" permit if storage will be greater than 1500 waste tires at any given time.

COMMENTS:

01/03/2013

The Warehouse appears to be equipped with a sprinkler system in case of fire. A permit has not been issued for the site due to an incomplete permit application. The inspectors discussed with Gary Allspach particulars on how to achieve financial assurance in order to complete the permitting process.

At the time of the inspection the site was in good order.

ATTACHMENTS:

Tires Stacked Indoors



Tires Against the Warehouse Walls



Inspection Date: 01/03/2013

Access Around Tires was Evident



East Wall of the Warehouse



Inspection Date: 01/03/2013

Signed:

Carolyn Heaviside

PRINCIPAL INSPECTOR NAME**PRINCIPAL INSPECTOR SIGNATURE**

Inspector

PRINCIPAL INSPECTOR TITLE

1/7/2013

DATE

Gloria De Pradine

INSPECTOR NAME

Inspector

INSPECTOR TITLE

NO SIGNATURE

INSPECTOR SIGNATURE

FDEP

ORGANIZATION

Gary Allspach

REPRESENTATIVE NAME

Operator

REPRESENTATIVE TITLE

NO SIGNATURE

REPRESENTATIVE SIGNATURE**Supervisor:** Gloria DePradine

NOTE: By signing this document, the Site Representative only acknowledges receipt of this Inspection Report and is not admitting to the accuracy of any of the items identified by the Department as "Not Ok" or areas of concern.