

FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

HERSCHEL T. VINYARD JR.

RICK SCOTT

GOVERNOR

SECRETARY

CENTRAL DISTRICT 3319 MAGUIRE BOULEVARD, SUITE 232 ORLANDO, FLORIDA 32803-3767

May 20, 2013

E-MAIL

sgrant@wm.com

Ms. Sheree Grant Vista Landfill 242 W. Keene Road Apopka, FL 32703

OCD-SW-13-1431

Orange County – SW WACS # 87081 Vista Class III Landfill Inspection Report – LGCS Expansion

Dear Ms. Grant:

On April 26, 2013 a representative of the Florida Department of Environmental Protection conducted an inspection of the next phase of the landfill gas collection system (LGCS) at the above referenced facility to determine the status of compliance with the Department's solid waste regulations. At the time of this inspection, the construction activities were being conducted in compliance with applicable Rules and permits. A copy of the inspection report is attached for your review.

Please contact me by telephone at (407) 897-4314 or by e-mail at kim.rush@dep.state.fl.us if you have any questions or need additional information.

Sincerely,

Kimberly Rush, P.E. Solid Waste Permitting

Ginbery Ruch

Attachment: Inspection Report



Florida Department of Environmental Protection Inspection Checklist

FACILITY INFORMATION:

Facility Name: VISTA LANDFILL, LLC (BUTTREY/KEENE RD SOUTH)

On-Site Inspection Start Date: 04/26/2013
On-Site Inspection End Date: 04/26/2013

WACS No.: 87081

Facility Street Address: 230 WEST KEENE RD

City: APOPKA

County Name: ORANGE

Zip: 32703

INSPECTION PARTICIPANTS:

(Include ALL Landfill and Department Personnel with Corresponding Titles)

Principal Inspector: Kimberly M. Rush, Engineer

Other Participants: Allen Rainey, Inspector; Deborah Perez, Representative; Vince Coleman, Representative

INSPECTION TYPE:

Construction Completion Certification Inspection for Landfill - Class III facility

ATTACHMENTS TO THE INSPECTION CHECK LIST:

This Cover Page to the Inspection Checklist may include any or all of the following attachments as appropriate.

COMMENTS:

05/08/2013

On 4/26/13 a construction certification inspection was conducted for the installation of the next phase of the landfill gas collection system (LGCS). This phase consisted of the installation of 5 new gas wells, a condensate sump, and an expansion of the header pipe. The work was being done in cells 1 and 2. The 5 new gas wells installed were wells EW-5 through EW-9. At the time of this inspection, all installations were completed and the final survey was almost finished.

ATTACHMENTS:

Inspection Date: 04/26/2013

New Well Head



Inspection Date: 04/26/2013

Kimberly M. Rush	Engineer		
PRINCIPAL INSPECTOR NAME	PRINCIPAL INSPECTOR TITLE	PRINCIPAL INSPECTOR TITLE	
V			
SubelyRush	FDEP	5/8/2013	
PRINCIPAL INSPECTOR SIGNATURE	ORGANIZATION	DATE	
Allen Rainey	Inspector		
INSPECTOR NAME	INSPECTOR TITLE		
NO SIGNATURE	FDEP		
INSPECTOR SIGNATURE	ORGANIZATION		
Deborah Perez	Representative		
REPRESENTATIVE NAME	REPRESENTATIVE TITLE		
NO SIGNATURE	WM		
REPRESENTATIVE SIGNATURE	ORGANIZATION		
Vince Coleman	Representative		
REPRESENTATIVE NAME	REPRESENTATIVE TITLE		
NO SIGNATURE	CEC		
REPRESENTATIVE SIGNATURE	ORGANIZATION		

NOTE: By signing this document, the Site Representative only acknowledges receipt of this Inspection Report and is not admitting to the accuracy of any of the items identified by the Department as "Not Ok" or areas of concern.