

Department of Environmental Protection

Г	EP Form # 62-701.900(21)
	Waste Tire Processing Facility orm Title Quarterly Report
E	ffective Date 3/22/00
D	EP Application No.

Waste Tire Processing Facility Quarterly Report

Pursuant to Rule 62-711.530, Florida Administrative Code, the owner or operator of a waste tire

processing facility shall submit the following information to the Department quarterly.

Jarter	covered b	y this report	10/1/12 -	12/31/12	First quarter	begins on Jah	uary 1 of any	given year)
1. Fac	cility name	: _Globa	l Tire R	ecycline	of Sum	ter Cty	Inc	
. Fac	cility mailir	ng address: _	1201 Ind	ustrial	Drive_			
		dwood			Sumter		Zip: 34785	
. Fac	cility permi	it number:	136806-0	004-WT				
			(352) 3					
	•				ilev. VE	Plant (<u>Operation</u>	
		th facility:						
	•	*	rent from abo	ve): (<u> </u>			
	•	port in tons	. •	<u> </u>	 /			
		Beginning Inventory	Received	Processed	Consumed	Removed	Adjustments	Ending Inventory
Nse	d Tires	454,13	2271.70	(2344.70))			
Oth	er whole							
Ъ.	cessed tires	492.77		1819.62	(1691.58)	>	ı	
Was				525,08		(525.08)	· .	
Oth	er	j	·					
Tota	al							
List	t any perio				tory exceede	d the permitte	ed maximum fo	r that
		ss inventory a onal sheets, i		ne quarter, sta	te how and v	vhen this cond	dition will be re	lieved.
	tification: the best of	my knowledge	and belief, I ce	rtify the informa	ation provided	In this report is	true, accurate, a	nd complete
1	Mark	J. Bai	lou	.7.	Mark Bril	.	- 11	9/13
	Print Nam	e of Authorize	ed Agent	Sig	nature of Au	thorized Agen	t	Date

Mail complete form to the appropriate district office

160 Governmental Center Pensacola, FL 32501-5794

Northeast District 7825 Baymeadows Way, Ste. 200 8 Jacksonville, FL 32256-7590 904-448-4300

Central District 3319 Maguire Blvd., Ste, 232 Orlando, FL 32803-3767 407-894-7555

Southwest District 3804 Coconut Palm Dr. Tampa, FL 33619 813-744-6100

South District 2295 Victoria Ave., Ste. 364 Fort Myers, FL 33902-2549 941-332-6975

Southeast District 400 North Congress Ave West Palm Beach, Ft. 33401 561-681-6600



Sumter County Fire Rescue Fire & Life Safety Inspection

Date /2/20/2012 Time 3 Date of Last Inspection											
Address 1201 Industrial Bive William											
Name of Business Global The Addition											
Contact Person Mark	En	lor		Phone No. 330-	T 27						
Type of Construction	T	Na	N/A		T v	N ₂	TNIA				
1. General Bldg. Altered or renovated since last Insp.?	Yes	No	N/A	9. Protection of Vertical Openings Ceiling tiles missing or broken?	Yes	No	N/A				
Is building mixed occupancy?	<u>!</u>			Ducts and pipes properly sealed at ceiling?							
What other occupancies?				10. Interior Finish	····		1				
What other occupancies? Building construction acceptable? Wall and ceiling materials per code?						-	} 				
2. Occupant Load and Exits				Is interior finish per code?	المستومين المستومين						
Are exits per code?				Fixed Seating							
Number of exits? 1 2 3 4 or more				Are curtains and drapes per code?							
Is egress capacity adequate?				Floor finish per code?							
Fire rating of exit stair enclosure 1 hr 2 hr			مدمس	11. Operating Features	<u> </u>						
Fire rating of exit stair door 1 hr 1 ½ hr				Is there a written emergency plan?							
Doors self-closing?				Are fire drills conducted?	1		1				
Latching door hardware?				Number of fire drills conducted per year	J. 1						
Exit enclosures free of storage?				Are employees instructed in fire ext. use?							
Do 100% of exits discharge directly outside?				Has evacuation / relocation been established?							
Do 50% of exits discharge directly outside?	-			Is there daily inspection of exits?							
Is exit discharge level?			-	12. Alarm and Detection							
Is exit discharge sprinklered?				Is there a manual alarm system?							
Is stair entry per code?				Is there a fire detection system?							
3. Doors				Smoke detectors	مستعدد						
Are doors blocked?			_	Heat detectors	4. ***						
Are doors locked?				Audible alarm							
Is ≤15-lb force required to release latch?				Visual alarm	200						
Doors open in direction of travel?				Alarm system within certification?	1 30000						
Is there panic hardware per code?				Is alarm system monitored 24 hours a day?	. 100 - 100 - 10						
4. Egress Arrangement			`	Number and location of pull stations per code?	,						
Is egress clear and unobstructed?				13. Extinguishment							
Are dead-end corridors within limits?				Is the building sprinklered throughout?							
Is common path of travel within limits?				Partial sprinklers		* 11/m**********************************					
Is travel through intervening rooms okay?				Is there a water flow alarm?							
Is egress blocked?		سسمن		Are the valves supervised?							
Is aisle width adequate?			سسب	Is there a standpipe?		سر «سر»)					
Is travel distance per code?				Is the sprinkler system within certification?							
5. Emergency Lighting				Is there a fire pump?							
Is emergency lighting per code?	مسس			Date of last pump test							
Is it tested monthly?				Number of fire extinguishers within code?							
6. Exit Marking				Travel distance for fire extinguisher per code?							
Is exit marking per code?				Are fire extinguishers within certification?	200						
7. Corridors				Are fire extinguishers mounted properly?		.,					
Is 1 – hr rating required?			<i></i>	Are fire extinguishers accessible?	بمسمر						
Is rating 1-hr corridor walls w/ 20 min. doors?			مستمسية	14. Building HVAC & Utilities							
8. Protection of Hazards				Are Utilities in good working order?	10 20 000						
Hazards protected by fire rate enclosure?	سسسس			Emergency shut-offs/circuit breakers labeled?	"						
Hazards protected by ext. sys.?				Is there an emergency generator?							
Hazards protected by self-closing door?			م	Date last tested							
Is kitchen cooking protected?			Commander of the Comman	LP Gas Tanks, Location & Condition	المداد المسادر	35 P					
Kitchen hood and duct last cleaned LP Gas Meter & Shutoff											
9. Protection of Vertical Openings Electrical MDP per code?											
Are vertical openings enclosed?				Electrical wiring	1 June 1						
Are elevators enclosed?				Acceptable Use of Electrical Extension Cords			والمعادية				
Is atrium per code?			سسسري.	Acceptable Use of Power Strips							
Are ≤ 3 levels open per code?	}			Elevator recall (phase I)?							

14. Building HVAC & Utilities cont.	Yes	No	N/A
Fire Dept. elevator control (phase II)?			1
Are stages per code?			
Are platforms / risers per code?		,	1
HVAC system in good working order?			
Interior air intakes cond.?	17	, -	
Exterior air intakes cond.?			
Smoke removal system function			

Yes	No	N/A
	مسر س	
	_	
برسم برس		

Comments	
	·
	<u> </u>
	· · · · · · · · · · · · · · · · · · ·
:	
Caramarana and a caramaran	
211	
Inspection performed by: 5/1/ Richard	Insp. # 12769Z
Signature	Date: 12/20/20/2
	7
Inspection Passed on 12/20/2012 Inspector's In	isiala (A. (A.)
	mais 10000
Inspection Failed on Inspector's I	nitials
Re-Inspection scheduled for Time: _	
Re-Inspection Passed on Inspector's	s Initials
Re-Inspection Failed on Inspecto	r's Initials
mapooto	
I have received a copy of the results of this inspection. Lunderstand the nature of defici	onging noted during this

I have received a copy of the results of this inspection. I understand the nature of deficiencies noted during this inspection and that they need to be corrected in the specified time allowed.

Authorized Representative Date: 17/70/17