SOUTHEAST COUNTY WASTE TIRE PROCESSING FACILITY EMERGENCY PROCEDURES

IN CASE OF FIRE:

A. SMALL FIRES

- 1. Contact the Hillsborough County Solid Waste Management representatives immediately.
- 2. The gate valves on the two 8" HDPE pipes will be closed to prevent liquid runoff from entering the stormwater Basin D.
- 3. Notify the Fire Department in case the situation cannot be managed in-house.
- 4. Remove all vehicles from the immediate area.
- 5. Separate the unburned tires using a front end loader (or other on-site available equipment).
- 6. Utilize the on-site water wagon to extinguish the fire.
- 7. Place sand on the tires that are on fire to smother the fire. An active borrow area with equipment is located immediately to the east of the Waste Tire Processing Facility (WTPF). Sand also will be used to absorb water and oily residue.
- 8. Clean up and dispose of sandy and oily residue following the contingency plan as described in the operations plan. The contaminated sand will be disposed of in the on-site landfill.

B. LARGE FIRES

- Immediately contact the Hillsborough County Fire Department.
- 2. The gate valves on the two 8" HDPE pipes will be closed to prevent liquid runoff from entering the stormwater Basin D.
- 3. Remove all vehicles from the immediate area.
- Contact the Hillsborough County Solid Waste Management representatives immediately.
- 5. Begin containment measures to minimize spreading of the fire and containing residue from the burning tires by digging a swale around the area (this will be supplemented with a berm, but by excavating a swale, this will provide immediate containment capabilities with on-site equipment), separating the unburned tires using a front end loader to lessen the potential for additional tires to catch on fire, and placement of a berm around the area for containment.

- 6. Utilize the water wagon to contain the fire until the Fire Department arrives (only if worker safety is not at risk).
- 7. Place sand on the tires that are on fire to smother the fire. An active borrow area with equipment is located immediately to the east of the WTPF. Sand also will be used to absorb water and oily residue.
- 8. Clean up and dispose of sand and oily residue following the contingency plan as described in the operations plan. The contaminated sand will be disposed of in the on-site landfill.

In order to properly manage a fire emergency, the WTPF has been provided with the emergency procedures, as well as a cellular telephone for on and off-site communications. The WTPF is located at the Southeast County Class I Landfill, which is equipped with bulldozers, front-end loaders, scrapers and other such equipment, which is available for use in any emergency. Soil is available on site within 100 feet of the WTPF. If needed, the soil may be used for smothering a fire.

In accordance with Waste Tire Rule 62-711.540(1)(f), the operator of the site shall notify the Florida Department of Environmental Protection in the even of a fire or other emergency, which poses an unanticipated threat to the public health or environment. Within two weeks of any emergency, a written report detailing the emergency actions taken to resolve the emergency and a review of the situation will be sent to the following:

Florida Department of Environmental Protection Waste Management Division 13051 North Telecom Parkway Temple Terrace, Florida 33637

Hillsborough County Environmental Protection Commission 3629 Queen Palm Drive Tampa, Florida 33619

C. <u>EMERGENCY PHONE NUMBERS</u>

NAME	DURING OPERATING HOURS	AFTER OPERATING HOURS
EMERGENCY	911	911
Larry Ruiz Manager, Landfill Operations Hillsborough County Solid Waste	813-671-7707	813-449-3229
Ernest Ely District Manager Waste Management	813-637-9203	813-918-5804
FDEP Florida Department of Environmental Protection	813-632-7600	1-800-320-0519 (Emergency Response)
HCEPC Hillsborough County Environmental Protection Commission	813-627-2600	813-627-2600

D. NATURAL DISASTERS

In the event of a flood, hurricane or other natural disaster, the procedures in the Solid Waste Management Division's Comprehensive Emergency Plan (CEMP) will be immediately implemented. The CEMP is a general document that is applicable to all facilities operated by the SWMD and contains applicable and specific procedures that can be applied to the operations of the WTPF. The following sections from the CEMP are still the governing document for the facility.

- To the extent possible, SWMD sites will secure all equipment to protect it from flying debris or becoming flying debris.
- All gasoline powered equipment must be topped off with fuel.



2709 E. HANNA AVENUE TAMPA, FLORIDA 33610

PH: (813) 744-5541 FAX: (813) 744-5794

Survey: https://www.surveymonkey.com/s/FireInspectionSurvey

Reinsp 0 First - No Charge Assigned To GLORIOSO, Richard on 02/20/2015

Start Date:

HC SOUTH EAST LAND FILL

Finish Date:

Business Name: Address: City/State/Zip:

15960 C.R. 672 Unit No: LAETCH

LITHIA, FL 33547

Occupancy ID: 52465

Station No.: Station 03

Business Phone: (813)671-7707

Complex info	Main Flo	101	Stories		Estimated Values
Commercial Units: 1	Length:	0	Above Grade:	1	Property: \$0.00
Residential Units: 0	Width:	0	Below Grade:	0	Content \$0.00
Complex Type: 4	Area:	3,750	Upper Construction:	-	Nacional registration defined in registrative **Construction Action Acti
Complex:	Construction:	-			

Occupancy Use: 40-INDUSTRIAL - 40-Industrial Occupancia

Property Uses: 919 - Dump, sanitary landfill

Roof Type: -Roof Material: -

Building Style: -

Roof Access:

Building Status: 2 - In normal use

Inspection Fee: \$0.00

Construction Type: -Detector Type: -

Invoice Nbr. N/A

Power Supply: -Auto. Extinguisher: - Occupant Load: 37

Year of Construction: 0

Codes are referenced from the Florida Fire Prevention Code and Hillsborough County ordinance.

You have 10 business days to appeal this Notice of Violation, by sending a letter to the Fire Marshal's Office at 2709 E. Hanna Avenue, Tampa, Florida 33610. For information regarding the Administrative Appeals Process please contact the Fire Marshal's Office at (813)744-5541.

Violations

Date Found

Date Cleared

Standard/Reference

ELECTRICAL

Open slots in panel:

01/20/2015

02/20/2015

Unused openings shall be closed to afford protection substantially equivalent to the wall of the equipment in accordance with NFPA 70, Art. 110.12.

AS PER NATIONAL FIRE PROTECTION ASSOCIATION 70. IN PANEL BOX HP BY WATER COOLER PROVIDE BREAKER SPACER IN EACH OPEN SLOT.

EGRESS

Emergency lighting repair:

01/20/2015

02/20/2015

Repair or replace emergency lighting in accordance with NFPA 101, 4.6.13.

AS PER NATIONAL FIRE PROTECTION ASSOCIATION 101 CHAPTER 4.6.13. REPAIR OR REPLACE ALL EMERGENCY LIGHTS THAT DO NOT WORK.

1-A NO FINDING

No Findings/Violations:

02/20/2015

02/20/2015

No violations noted for this inspection.

Reinsp 0 First - No Charge Assigned To GLORIOSO, Richard on 02/20/2015

Start Date:

City/State/Zip:

Business Name:

HC SOUTH EAST LAND FILL

Address: 15960 C.R. 672 Unit No: LAETCH

LITHIA, FL 33547

Finish Date:

Occupancy ID: 52465

Station No.: Station 03

Business Phone: (813)671-7707

Recipient:

CINDY PELLEY

Inspector

Richard Glorioso

Re-Inspection Date:

ABOVE VIOLATIONS MAY CAUSE FIRE, CONTRIBUTE TO THE SPREAD OF FIRE, OR CAUSE UNDUE INJURY IN THE EVENT OF FIRE. VIOLATIONS MUST BE CORRECTED IMMEDIATELY.



HILLSBOROUGH COUNTY FIRE RESCUE 2709 E. HANNA AVENUE TAMPA, FLORIDA 33610

PH: (813) 744-5541 FAX: (813) 744-5794

Survey: https://www.surveymonkey.com/s/FireInspectionSurvey

Reinsp 0 First - No Charge Assigned To GLORIOSO, Richard on 02/20/2015

Start Date:

Finish Date:

Business Name:

HC SOUTH EAST LAND FILL

Occupancy ID: 52446

Address: City/State/Zip:

15960 C.R. 672 Unit No: MAIN OFFICE LITHIA, FL 33547

Station No.: Station 03

Business Phone: (813)671-7707

Complex Info	Main Flo	oor	Stories		Estimated Values
Commercial Units: 1	Length:	0	Above Grade:	1	Property: \$0.00
Residential Units: 0	Width:	0	Below Grade:	0	Content: \$0.00
Complex Type: 4	Area:	3,875	Upper Construction:	-	
Complex:	Construction:	-			

Occupancy Use: 39-BUS-EXIST - 39-Existing Business Occ

Roof Type: -

Property Uses: 599 - Business office

Building Style: -

Roof Material:

Building Status: 2 - In normal use

Roof Access:

Construction Type: -

Inspection Fee: \$0.00

Detector Type: -

Invoice Nbr. N/A Occupant Load:

Power Supply: -Auto. Extinguisher: -

Year of Construction: 0

Codes are referenced from the Florida Fire Prevention Code and Hillsborough County ordinance.

You have 10 business days to appeal this Notice of Violation, by sending a letter to the Fire Marshal's Office at 2709 E. Hanna Avenue, Tampa, Florida 33610. For information regarding the Administrative Appeals Process please contact the Fire Marshal's Office at (813)744-5541.

Violations

Date Found

Date Cleared

Standard/Reference

EGRESS

Emergency lighting repair:

01/20/2015

02/20/2015

Repair or replace emergency lighting in accordance with NFPA 101, 4.6.13.

AS PER NATIONAL FIRE PROTECTION ASSOCIATION 101 CHAPTER 4.6.13. REPAIR OR REPLACE EMERGENCY LIGHTS THAT DO NOT WORK THROUGHOUT THE FACILITY.

FYI: COME UP WITH A MAINTENANCE PLAN TO HAVE EMERGENCY AND EXIT SIGNS CHECKED ALONG WITH FIRE EXTINGUISHER ON A MONTHLY PLAN.

Exit sign not illuminated:

01/20/2015

02/20/2015

Exit signs shall be suitably illuminated by a reliable light source in both normal and emergency mode in accordance with NFPA 101, 7.10.5. Repair or replace exit sign.

AS PER NATIONAL FIRE PROTECTION ASSOCIATION 101 CHAPTER 7.10.5. REPAIR OR REPLACE ALL EXIT SIGNS THAT DO NOT WORK THROUGHOUT THE FACILITY.

1-A NO FINDING

No Findings/Violations:

02/20/2015

02/20/2015

No violations noted for this inspection.

Reinsp 0 First - No Charge Assigned To GLORIOSO, Richard on 02/20/2015

Start Date:

Business Name: HC SOUTH EAST LAND FILL

Address: 15960 C.R. 672 Unit No: MAIN OFFICE

City/State/Zip:

LITHIA, FL 33547

Finish Date:

Occupancy ID: 52446 Station No.: Station 03 Business Phone: (813)671-7707

Recipient:

hody A Pelley

CINDY PELLEY

Inspector

Richard Glorioso

Re-Inspection Date:

ABOVE VIOLATIONS MAY CAUSE FIRE, CONTRIBUTE TO THE SPREAD OF FIRE, OR CAUSE UNDUE INJURY IN THE EVENT OF FIRE. VIOLATIONS MUST BE CORRECTED IMMEDIATELY.



2709 E. HANNA AVENUE TAMPA, FLORIDA 33610

PH: (813) 744-5541 FAX: (813) 744-5794

Survey: https://www.surveymonkey.com/s/FireInspectionSurvey

Annual Insp 00-5k SF Assigned To GLORIOSO, Richard on 01/20/2015

Comple	ex Info	Main Floor	Stories
Address:	HC SOUTH EAST LAN 15960 C.R. 672 Uni LITHIA, FL 33547	DFILL	Finish Date: Occupancy ID: 51824 Station No.: Station 03 Business Phone: (813)671-7707

Complex Into Commercial Units: 1 Residential Units: 0 Complex Type: 4 Complex:	Length: Width:	0 0 320	Above Gi Below G Upper Construc	rade: 0	Property: \$0.00 Content: \$0.00
Property Use Building Sty	le: - us: 2 - In normal use ue: - ue: - ue: - ue: -	Business Occ	Roof Type: Roof Material: Roof Access: Inspection Fee: Invoice Nbr: Occupant Load:	- \$45.00 13-004517	

Codes are referenced from the Florida Fire Prevention Code and Hillsborough County ordinance.

You have 10 business days to appeal this Notice of Violation, by sending a letter to the Fire Marshal's Office at 2709 E. Hanna Avenue, Tampa, Florida 33610. For information regarding the Administrative Appeals Process please contact the Fire Marshal's Office at (813)744-5541.

Violations

Date Found

Date Cleared

Standard/Reference

1-A NO FINDING

No Findings/Violations:

01/20/2015

01/20/2015

Estimated Values

No violations noted for this inspection. FIRE INSPECTION FOR HC SOUTH EAST LAND FILL NO NOTED DEFICIENCIES.

	Inspector
Recipient:	1011
SIGNATURE ON MAIN OFFICE REPORT	Richard Glorioso
Re-Inspection Date:	
Page:1	

Start Date:

Finish Date:

Business Name: HC SOUTH EAST LANDFILL

Address: 15960 C.R. 672 Unit No: BATH RM

Occupancy ID: 51824 Station No.: Station 03

City/State/Zip: LITHIA, FL 33547

Business Phone: (813)671-7707

ABOVE VIOLATIONS MAY CAUSE FIRE, CONTRIBUTE TO THE SPREAD OF FIRE, OR CAUSE UNDUE INJURY IN THE EVENT OF FIRE. VIOLATIONS MUST BE CORRECTED IMMEDIATELY.



2709 E. HANNA AVENUE TAMPA, FLORIDA 33610

PH: (813) 744-5541 FAX: (813) 744-5794

BALM, FL 33598

Survey: https://www.surveymonkey.com/s/FireInspectionSurvey

Annual Insp 05-10k SF Assigned To GLORIOSO, Richard on 01/20/2015

04-4	-
Start	Date:

Finish Date:

Business Name: Address:

City/State/Zip:

HC SOUTH EAST LANDFILL

15960 C.R. 672 Unit No: GARAGE

NGL

Occupancy ID: 38741

Station No.: Station 03
Business Phone: (813)671-7707

Estimated Values Main Floor **Stories** Complex Info Property: \$0.00 Above Grade: 1 Length: 0 Commercial Units: 1 Content: \$0.00 Below Grade: 0 Width: 0 Residential Units: 0 Upper Construction: -Area: 8,125 Complex Type: 4 Construction: -Complex:

Occupancy Use: 40-INDUSTRIAL - 40-Industrial Occupancia

Property Uses: -

Building Style: -

Building Status: 2 - In normal use

Construction Type: Detector Type: -

Power Supply: Auto. Extinguisher: Year of Construction: 0

Roof Type: -

Roof Material: -Roof Access:

Inspection Fee: \$58.00

Invoice Nbr. 13-004517

Occupant Load: 81

Codes are referenced from the Florida Fire Prevention Code and Hillsborough County ordinance.

You have 10 business days to appeal this Notice of Violation, by sending a letter to the Fire Marshal's Office at 2709 E. Hanna Avenue, Tampa, Florida 33610. For information regarding the Administrative Appeals Process please contact the Fire Marshal's Office at (813)744-5541.

Violations

Date Found

Date Cleared

Standard/Reference

1-A NO FINDING

No Findings/Violations:

01/20/2015

01/20/2015

No violations noted for this inspection.

FIRE INSPECTION FOR HC SOUTH EAST LAND FILL NO NOTED DEFICIENCIES.

Recipient:	Inspector
SIGNATURE ON MAIN OFFICE REPORT	Richard Glorioso
Re-Inspection Date:	
Page:1	

Finish Date:

Start Date:

Business Name: HC SOUTH EAST LANDFILL
Address: 15960 C.R. 672 Unit No: GARAGE
City/State/Zip: BALM, FL 33598

Occupancy ID: 38741

Station No.: Station 03

Business Phone: (813)671-7707

ABOVE VIOLATIONS MAY CAUSE FIRE, CONTRIBUTE TO THE SPREAD OF FIRE, OR CAUSE UNDUE INJURY IN THE EVENT OF FIRE. VIOLATIONS MUST BE CORRECTED IMMEDIATELY.



2709 E. HANNA AVENUE TAMPA FLORIDA 33610

PH: (813) 744-5541 FAX: (813) 744-5794

LITHIA, FL 33547

Survey: https://www.surveymonkey.com/s/FireInspectionSurvey

Annual Insp 00-5k SF Assigned To GLORIOSO, Richard on 01/20/2015

Start Date:

City/State/Zip:

Finish Date:

Business Name: Address: HC SOUTH EAST LAND FILL

15960 C.R. 672 Unit No: LFG FLARE

Occupancy ID: 52467 Station No.: Station 03

Business Phone: (813)671-7707

Estimated Values Complex Info Main Floor **Stories** Property: \$0.00 Commercial Units: 1 Length: 40 Above Grade: 1 Content: \$0.00 Residential Units: 0 Width: 30 Below Grade: 0 Area: 1,200 Upper Construction: -Complex Type: 4 Construction: -Complex:

Occupancy Use: 40-INDUSTRIAL - 40-Industrial Occupancia

Property Uses: 614 - Steam or heat generating plant

Building Style: -

Building Status: 5 - Vacant and secured

Construction Type: -

Detector Type: -

Power Supply:

Auto. Extinguisher: -Year of Construction: 0 Roof Type: -

Roof Material: -

Roof Access:

Inspection Fee: \$45.00 Invoice Nbr. 13-004517

Occupant Load: 12

Codes are referenced from the Florida Fire Prevention Code and Hillsborough County ordinance.

You have 10 business days to appeal this Notice of Violation, by sending a letter to the Fire Marshal's Office at 2709 E. Hanna Avenue, Tampa, Florida 33610. For information regarding the Administrative Appeals Process please contact the Fire Marshal's Office at (813)744-5541.

Violations

Date Found

Date Cleared

Standard/Reference

1-A NO FINDING

No Findings/Violations:

01/20/2015

01/20/2015

No violations noted for this inspection.

FIRE INSPECTION FOR HC SOUTH EAST LAND FILL NO NOTED DEFICIENCIES.

Recipient:	Inspector
	1
SIGNATURE ON MAIN OFFICE REPORT	Richard Glorioso
Re-Inspection Date:	
Page:1	

Start Date:

Finish Date:

Business Name: HC SOUTH EAST LAND FILL

Address: 15960 C.R. 672 Unit No: LFG FLARE

City/State/Zip: LITHIA, FL 33547

Occupancy ID: 52467 Station No.: Station 03 Business Phone: (813)671-7707

ABOVE VIOLATIONS MAY CAUSE FIRE, CONTRIBUTE TO THE SPREAD OF FIRE, OR CAUSE UNDUE INJURY IN THE EVENT OF FIRE. VIOLATIONS MUST BE CORRECTED IMMEDIATELY.



2709 E. HANNA AVENUE TAMPA, FLORIDA 33610

PH: (813) 744-5541 FAX: (813) 744-5794

Survey: https://www.surveymonkey.com/s/FireInspectionSurvey

Annual Insp 00-5k SF Assigned To GLORIOSO, Richard on 01/20/2015

Start	Date:
-------	-------

City/State/Zip:

Finish Date:

Business Name:

HC SOUTH EAST LAND FILL

LITHIA, FL 33547

Address: 15960 C.R. 672 Unit No: BATH BY TRLR

Occupancy ID: 52453

Station No.: Station 03

Business Phone: (813)671-7707

Complex Info	Main Flo	100	Stories		Estimated Values
Commercial Units: 1 Residential Units: 0 Complex Type: 4 Complex:	Length: Width: Area: Construction:	28 280	Above Grade: Below Grade: Upper Construction:	0	Property:\$0.00 Content:\$0.00

Occupancy Use: 39-BUS-EXIST - 39-Existing Business Occ

Property Uses: 599 - Business office

Building Style: -

Building Status: 2 - In normal use

Construction Type: -

Detector Type: -Power Supply: -

Auto, Extinguisher: -Year of Construction: 0

Roof Type: -

Roof Material: -

Roof Access:

Inspection Fee: \$45.00

Invoice Nbr: 13-004517

Occupant Load: 3

Codes are referenced from the Florida Fire Prevention Code and Hillsborough County ordinance.

You have 10 business days to appeal this Notice of Violation, by sending a letter to the Fire Marshal's Office at 2709 E. Hanna Avenue, Tampa, Florida 33610. For information regarding the Administrative Appeals Process please contact the Fire Marshal's Office at (813)744-5541.

Violations

Page:1

Date Found

Date Cleared

Standard/Reference

1-A NO FINDING

No Findings/Violations:

01/20/2015

01/20/2015

No violations noted for this inspection.

FIRE INSPECTION FOR HC SOUTH EAST LAND FILL NO NOTED DEFICIENCIES.

Recipient:	Inspector	
SIGNATURE ON MAIN OFFICE REPORT	Richard Glorioso	•
Re-Inspection Date:		

Start Date:

Finish Date:

Business Name: HC SOUTH EAST LAND FILL

Address: 15960 C.R. 672 Unit No: BATH BY TRLR

City/State/Zip: LITHIA, FL 33547

Occupancy ID: 52453

Station No.: Station 03 Business Phone: (813)671-7707

ABOVE VIOLATIONS MAY CAUSE FIRE, CONTRIBUTE TO THE SPREAD OF FIRE, OR CAUSE UNDUE INJURY IN THE EVENT OF FIRE. VIOLATIONS MUST BE CORRECTED IMMEDIATELY.



2709 E. HANNA AVENUE TAMPA, FLORIDA 33610

PH: (813) 744-5541 FAX: (813) 744-5794

Survey: https://www.surveymonkey.com/s/FireInspectionSurvey

Annual Insp 00-5k SF Assigned To GLORIOSO, Richard on 01/20/2015

	Allitual hisp ou on or nee	.9				
Address: 1596	OUTH EAST LAND FILL D. C.R. 672 Unit No: TIRE OFFI IA, FL 33547	CE	ate: Occupancy ID: Station No.: siness Phone:	Station 03	707	
Complex Info	Main Floo	r	Sto	ries	<u> </u>	stimated Values
	Length:		Above Gr	rade: 1	Pro	operty: \$0.00
Commercial Units: 1 Residential Units: 0	Width:		Below G		C	ontent: \$0.00
Complex Type: 4	Area:		Upper Construc	ction: -		
Complex:	Construction: -		St 50			
Composed line	: 39-BUS-EXIST - 39-Existing Bu	isiness Occ	Roof Type:			
Property Uses	5: 599 - Business office		Roof Material:			
Building Style			Roof Access:			
	s: 2 - In normal use	i	nspection Fee:	\$45.00		
Construction Type			Invoice Nbr.	13-004517		
Detector Type	9: -	Oc	cupant Load:	6		
Power Supply						
Auto. Extinguishe Year of Construction						
Teal of Construction	1. 0					
Fir th	You have 10 business days to a e Marshal's Office at 2709 E. Han he Administrative Appeals Proces	na Avenue, Tam s please contac	pa, Florida 336 t the Fire Mars	10. For info	rmation regard	н.
<u>Violations</u>		Date Found	Date Cle	eared S	tandardriveren	
1-A NO FINDING						
No Findings/V	Tiolations:	01/20/201	5 01/20/2	2015		
No violat	tions noted for this inspection.	TIAND FILL NO	NOTED DEEK	NENCIES		
FIRE IN	SPECTION FOR HC SOUTH EAS	I LAND FILL NO	NOTED DETTO	JILITOILO.		
Recipient:			Inspector			
SIGNATURE ON MA	IN OFFICE REPORT		Richard Glo	orioso		

Start Date:

Finish Date: Occupancy ID: 52449

Business Name: HC SOUTH EAST LAND FILL
Address: 15960 C.R. 672 Unit No: TIRE OFFICE
LITHIA, FL 33547

Station No.: Station 03

Business Phone: (813)671-7707

ABOVE VIOLATIONS MAY CAUSE FIRE, CONTRIBUTE TO THE SPREAD OF FIRE, OR CAUSE UNDUE INJURY IN THE EVENT OF FIRE. VIOLATIONS MUST BE CORRECTED IMMEDIATELY.



2709 E. HANNA AVENUE TAMPA, FLORIDA 33610

PH: (813) 744-5541 FAX: (813) 744-5794

Survey: https://www.surveymonkey.com/s/FireInspectionSurvey

Annual Insp 05-10k SF Assigned To GLORIOSO, Richard on 01/20/2015

Start Date:

Finish Date:

Business Name:

HC SOUTH EAST LAND FILL

15960 C.R. 672 Unit No: SHREDDER

Occupancy ID: 52463 Station No.: Station 03

Address: City/State/Zip:

LITHIA, FL 33547

Business Phone: (813)671-7707

Estimated Values Stories Main Floor Complex Info Property: \$0.00 Above Grade: 1 Length: 0 Commercial Units: 1 Content: \$0.00 Below Grade: 0 Width: 0 Residential Units: 0 Upper Construction: -Area: 8,000 Complex Type: 4 Construction: -Complex:

Occupancy Use: 40-INDUSTRIAL - 40-Industrial Occupancio

Roof Type: -

Property Uses: 808 - Outbuilding or shed

Roof Material:

Building Style: -

Roof Access: Inspection Fee: \$58.00

Building Status: 2 - In normal use Construction Type: -

Invoice Nbr: 13-004517

Detector Type: -

Power Supply: -

Auto. Extinguisher: -Year of Construction: 0

Occupant Load:

Codes are referenced from the Florida Fire Prevention Code and Hillsborough County ordinance.

You have 10 business days to appeal this Notice of Violation, by sending a letter to the Fire Marshal's Office at 2709 E. Hanna Avenue, Tampa, Florida 33610. For information regarding the Administrative Appeals Process please contact the Fire Marshal's Office at (813)744-5541.

Violations

Date Found

Date Cleared

Standard/Reference

1-A NO FINDING

No Findings/Violations:

01/20/2015

01/20/2015

No violations noted for this inspection.

FIRE INSPECTION FOR HC SOUTH EAST LAND FILL NO NOTED DEFICIENCIES.

Recipient

MMR. DAVID CASWELL

Richard Glorioso

Inspector

Re-Inspection Date:

Start Date:

Business Name: HC SOUTH EAST LAND FILL

Address: 15960 C.R. 672 Unit No: SHREDDER

City/State/Zip: LITHIA, FL 33547

Finish Date:

Occupancy ID: 52463
Station No.: Station 03

Business Phone: (813)671-7707

ABOVE VIOLATIONS MAY CAUSE FIRE, CONTRIBUTE TO THE SPREAD OF FIRE, OR CAUSE UNDUE INJURY IN THE EVENT OF FIRE. VIOLATIONS MUST BE CORRECTED IMMEDIATELY.



2709 E. HANNA AVENUE TAMPA, FLORIDA 33610

PH: (813) 744-5541 FAX: (813) 744-5794

Survey: https://www.surveymonkey.com/s/FireInspectionSurvey

Annual Insp 00-5k SF Assigned To GLORIOSO, Richard on 01/20/2015

Start Date:

City/State/Zip:

Finish Date:

Business Name: Address: HC SOUTH EAST LAND FILL

LITHIA, FL 33547

15960 C.R. 672 Unit No: LFG STRG

Occupancy ID: 52451

Station No.: Station 03

Business Phone: (813)671-7707

Complex Info Main Floor **Stories Estimated Values** Commercial Units: 1 Length: 40 Above Grade: 1 Property: \$0.00 Residential Units: 0 Width: 30 Below Grade: 0 Content: \$0.00 Complex Type: 4 Area: 1,200 Upper Construction: -Complex: Construction: -

Occupancy Use: 42-STORAGE - 42-Storage Occupancies

Property Uses: 808 - Outbuilding or shed

Building Style: -

Building Status: 2 - In normal use

Construction Type: -Detector Type: -

Power Supply: -

Auto. Extinguisher: -Year of Construction: 0

Roof Type: -

Roof Material: -

Roof Access:

Inspection Fee: \$45.00 Invoice Nbr: 13-004517

Occupant Load:

Codes are referenced from the Florida Fire Prevention Code and Hillsborough County ordinance.

You have 10 business days to appeal this Notice of Violation, by sending a letter to the Fire Marshal's Office at 2709 E. Hanna Avenue, Tampa, Florida 33610. For information regarding the Administrative Appeals Process please contact the Fire Marshal's Office at (813)744-5541.

Violations

Date Found

Date Cleared

Standard/Reference

1-A NO FINDING

No Findings/Violations:

01/20/2015

01/20/2015

No violations noted for this inspection.

FIRE INSPECTION FOR HC SOUTH EAST LAND FILL NO NOTED DEFICIENCIES.

Recipient:

MR. DAVID CASWELL

Inspector

Richard Glorioso

Re-Inspection Date:

Start Date:

Finish Date:

Business Name: HC SOUTH EAST LAND FILL

Address: 15960 C.R. 672 Unit No: LFG STRG City/State/Zip: LITHIA, FL 33547

Occupancy ID: 52451 Station No.: Station 03

Business Phone: (813)671-7707

ABOVE VIOLATIONS MAY CAUSE FIRE, CONTRIBUTE TO THE SPREAD OF FIRE, OR CAUSE UNDUE INJURY IN THE EVENT OF FIRE. VIOLATIONS MUST BE CORRECTED IMMEDIATELY.



2709 E. HANNA AVENUE TAMPA, FLORIDA 33610

PH: (813) 744-5541 FAX: (813) 744-5794

Survey: https://www.surveymonkey.com/s/FireInspectionSurvey

Annual Insp 00-5k SF Assigned To GLORIOSO, Richard on 01/20/2015

Start Date:

Finish Date:

Business Name:

HC SOUTH EAST LAND FILL 15960 C.R. 672 Unit No: DERIMMER

Occupancy ID: 52460 Station No.: Station 03

Address: City/State/Zip:

LITHIA, FL 33547

Business Phone: (813)671-7707

Estimated Values Stories Main Floor Complex Info Property: \$0.00 Above Grade: 1 Length: 0 Commercial Units: 1 Content \$0.00 Below Grade: 0 Width: 0 Residential Units: 0 Upper Construction: -Area: 2,000 Complex Type: 4 Construction: -

Occupancy Use: 40-INDUSTRIAL - 40-Industrial Occupancia

Property Uses: 808 - Outbuilding or shed

Building Style: -

Building Status: 2 - in normal use

Construction Type: -

Complex:

Power Supply: -

Detector Type: -

Auto. Extinguisher: -Year of Construction: 0 Roof Type: -

Roof Material: Roof Access:

Inspection Fee: \$45.00 Invoice Nbr. 13-004517

Occupant Load: 20

You have 10 business days to appeal this Notice of Violation, by sending a letter to the Fire Marshal's Office at 2709 E. Hanna Avenue, Tampa, Florida 33610. For information regarding the Administrative Appeals Process please contact the Fire Marshal's Office at (813)744-5541.

Codes are referenced from the Florida Fire Prevention Code and Hillsborough County ordinance.

Violations

Date Found

Date Cleared

Standard/Reference

1-A NO FINDING

No Findings/Violations:

01/20/2015

01/20/2015

No violations noted for this inspection.

FIRE INSPECTION FOR HC SOUTH EAST LAND FILL NO NOTED DEFICIENCIES.

Recipient:

MR. DAVID CASWELL

Inspector

Richard Glorioso

Re-Inspection Date:

Start Date:

Business Name: HC SOUTH EAST LAND FILL

Address: 15960 C.R. 672 Unit No: DERIMMER

City/State/Zip: LITHIA, FL 33547

Finish Date:

Occupancy ID: 52460

Station No.: Station 03

Business Phone: (813)671-7707

ABOVE VIOLATIONS MAY CAUSE FIRE, CONTRIBUTE TO THE SPREAD OF FIRE, OR CAUSE UNDUE INJURY IN THE EVENT OF FIRE. VIOLATIONS MUST BE CORRECTED IMMEDIATELY.



2709 E. HANNA AVENUE TAMPA, FLORIDA 33610

PH: (813) 744-5541 FAX: (813) 744-5794

Survey: https://www.surveymonkey.com/s/FireInspectionSurvey

Annual Insp 00-5k SF Assigned To GLORIOSO, Richard on 01/20/2015

Start Date:

Finish Date:

Business Name:

HC SOUTH EAST LAND FILL

Address: 15960 C.R. 672 Unit No: CHML STRG

City/State/Zip: LITHIA, FL 33547

Occupancy ID: 52464

Station No.: Station 03 Business Phone: (813)671-7707

Complex Info	Main Flo	oor	<u>Stories</u>		Estimated Values
Commercial Units: 0	Length:	0	Above Grade:	1	Property: \$0.00
Residential Units: 0	Width:	0	Below Grade:	0	Content \$0.00
Complex Type: 4	Area:	2,500	Upper Construction:	-	
Complex:	Construction:	-			

Occupancy Use: 42-STORAGE - 42-Storage Occupancies

Property Uses: 807 - Outside material storage area

Building Style: -

Building Status: 2 - In normal use

Construction Type: -

Detector Type: -Power Supply: -

Auto. Extinguisher: -Year of Construction: 0

Roof Type: -

Roof Material: -Roof Access:

Inspection Fee: \$45.00 Invoice Nbr. 13-004517

Occupant Load:

You have 10 business days to appeal this Notice of Violation, by sending a letter to the Fire Marshal's Office at 2709 E. Hanna Avenue, Tampa, Florida 33610. For information regarding the Administrative Appeals Process please contact the Fire Marshal's Office at (813)744-5541.

Codes are referenced from the Florida Fire Prevention Code and Hillsborough County ordinance.

Violations

Date Found

Date Cleared

Standard/Reference

1-A NO FINDING

No Findings/Violations:

01/20/2015

01/20/2015

No violations noted for this inspection.

FIRE INSPECTION FOR HC SOUTH EAST LAND FILL NO NOTED DEFICIENCIES.

Recipient:

MR. DAVID CASWELL

Inspector

Richard Glorioso

Re-Inspection Date:

Start Date:

Business Name: HC SOUTH EAST LAND FILL

Address: 15960 C.R. 672 Unit No: CHML STRG

City/State/Zip: LITHIA, FL 33547

Finish Date:

Occupancy ID: 52464
Station No.: Station 03

Business Phone: (813)671-7707

ABOVE VIOLATIONS MAY CAUSE FIRE, CONTRIBUTE TO THE SPREAD OF FIRE, OR CAUSE UNDUE INJURY IN THE EVENT OF FIRE. VIOLATIONS MUST BE CORRECTED IMMEDIATELY.