

Florida Department of Environmental Protection

Inspection Checklist

FACILITY INFORMATION:

Facility Name: PASCO COUNTY RESOURCE RECOVERY

On-Site Inspection Start Date: 01/23/2015
On-Site Inspection End Date: 01/23/2015

WACS No.: 45799

Facility Street Address: 14230 HAYS ROAD

City: SPRING HILL

County Name: PASCO

Zip: 34610

INSPECTION PARTICIPANTS:

(Include ALL Landfill and Department Personnel with Corresponding Titles)

Principal Inspector: Amaury Betancourt, Inspector

Other Participants: Steven Tafuni, Inspector; Nick Roff, Inspector; John Power, Director of Solid Waste; Viet

Ta, Facility Environmental Engineer; Michael Frestick, Solid Waste Operator

INSPECTION TYPE:

Routine Operation Inspection for WPF - Waste To Energy Facility

Routine Operation Inspection for Landfill - Class I facility

Routine Operation Inspection for Landfill - Class III facility

Routine Operation Inspection for WPF - Waste Tire Processing Facility

Routine Operation Inspection for WPF - Source-Separated Organics Proc Fac (SOPF) facility

Routine Operation Inspection for Other (user defined) facility

ATTACHMENTS TO THE INSPECTION CHECK LIST:

This Cover Page to the Inspection Checklist may include any or all of the following attachments as appropriate.

SECTION 1.0 - FILE REVIEW

SECTION 2.0 - LANDFILL OPERATION AND MAINTENANCE

SECTION 9.0 - WASTE TIRE FACILITIES

SECTION 10.0 - REGISTERED SOURCE-SEPARATED ORGANICS PROCESSING FACILITIES

SECTION 12.0 - WTE FACILITIES

SECTION 1.0 - FILE REVIEW

Requirements:

Item No.	FILE REVIEW (Pre- or Post-Inspection, as appropriate.) Completed	Ok	Not Ok	Unk	N/A
1.1	For landfills and C&D disposal facilities, does the facility have a current plan for the method and sequence of filling wastes? 62-701.500(2)(f) for landfills; 62-701.730(7)(a) for C&D debris sites	~			
1.2	For landfills, are the following records being reported to the Department?(Check any that are Not OK) Waste reports (annually) 62-701.500(4) Annual estimate of remaining life 62-701.500(13)(c)	>			
1.3	Is gas monitoring being performed as required by the permit? 62-701.500(9), 62-701.530(2)	~			
1.4	Are the results of the gas sampling reported to the Department quarterly? 62-701.530(2)(c)	>			
1.5	Is water quality sampling and testing performed according to standard procedures and at the required frequencies? 62-701.510(2) for landfills; 62-701.730(4)(b) and (10) for C&D debris sites; 62-713.400(3) for stationary soil treatment facilities.	>			
1.6	Do the results of the water quality testing suggest there may be adverse impacts to water quality from the operation of the solid waste facility? 62-701.510(3) and (4); 62-701.730(4)(c) and (10) for C&D debris sites; 62-713.400(3) for stationary soil treatment facilities.			<	
1.7	For closed landfills and C&D disposal facilities with final elevations higher than 20 feet above grade, has a final survey report verifying the final elevations and contours of the facility been submitted to the Department? 62-701.600(6)(b), 62-701.730(9)(d)	~			
1.8	Is financial assurance adequate? 62-701.630 for landfills; 62-701.710(7)(a) and (10)(a) for waste processing facilities; 62-701.730(11)(a) for C&D debris facilities; 62-713.600(6)(a) for stationary soil treatment facilities; 62-711.500(3) for waste tire facilities. NOTE: The Solid Waste Financial Coordinator in Tallahassee can assist with this information.	>			
1.9	Are cost estimates current and adjusted every year? 62-701.630(4) for landfills; 62-701.710(7)(b) and (10)(a) for waste processing facilities; 62-701.730(11)(b) and (c) for C&D debris facilities; 62-713.600(6)(b) and (c) for stationary soil treatment facilities; 62-711.500(3) for waste tire facilities.	>			
1.10	For C&D debris disposal and disposal with recycling facilities, is an Annual Report submitted to the Department for the disposal operation by February 1st of each year? 62-701.730(12)				~
1.11	For C&D recycling facilities with no disposal, is an Annual Report for the recycling facility submitted to the Department by February 1st of each year? 62-701.710(8)(b)				~
1.12	For compost facilities, has the compost product been sampled and analyzed every 20,000 tons or every 3 months (whichever is sooner)? 62-709.530(1)				~
1.13	For compost facilities, has the annual report been submitted by June 1st? 62-709.530(3)				~

SECTION 2.0 - LANDFILL OPERATION AND MAINTENANCE

Requirements:

Item No.	SOLID WASTE PROHIBITIONS (unless "grandfathered" in, see 62-701.300(18)) Completed	Ok	Not Ok	Unk	N/A
2.1.1	Unauthorized storage, processing, or disposal of solid waste except as authorized at a permitted solid waste management facility or other exempt facility. 62-701.300(1)(a)	>			
2.1.2	Unauthorized disposal or storage prohibited, except yard trash, within 500 feet of a potable water well? 62-701.300(2)(b)	>			
2.2	Unauthorized storage or disposal of yard trash prohibited within the minimum setbacks of (Check any that are Not OK) 62-701.300(12) 100 feet from potable water wells (except on-site)? 50 feet from water bodies?	>			
2.3	Unauthorized disposal or storage prohibited in any natural or artificial body of water including ground water and wetlands? (Does not apply to standing water after a storm event.) 62-701.300(2)(d)	>			
2.4	Unauthorized disposal or storage prohibited, except yard trash, within 200 feet of any natural or artificial body of water, including wetlands without permanent leachate controls, except impoundments or conveyances which are part of an on-site, permitted stormwater management system or on-site water bodies with no off-site discharge? 62-701.300(2)(e)	>			
2.5	Unauthorized open burning of solid waste prohibited except in accordance with Department requirements? 62-701.300(3)	٧			
2.6	Are the following unauthorized wastes or special wastes properly controlled, managed and disposed? (Check any that are Not OK) Hazardous waste 62-701.300(4) Biomedical waste 62-701.300(6) Yard trash 62-701.300(8)(c) Whole waste tires 62-701.300(8)(e) Regulated asbestos waste 62-701.520(3), 62-701.730(19) Used oil and oily wastes, except as exempted 62-701.300(11) PCB wastes 62-701.300(5) Lead-acid batteries 62-701.300(8)(a) White goods 62-701.300(8)(d) Liquids 62-701.300(10) CCA treated wood 62-701.300(14)	>			
2.7	Are only permitted waste types disposed at facility? 62-701.340(2), 62-701.500(6)(a), 62-701.500(2)(c)	~			

Item No.	LANDFILL OPERATION AND MAINTENANCE Completed	Ok	Not Ok	Unk	N/A
2.8	Is there a trained operator on-site at Class I and III landfills when receiving wastes? 62-701.500(1)	~			
2.9	Is there at least one trained spotter at each working face when receiving wastes at Class I and III landfills? 62-701.500(1)	~			
2.10	Are the following records or plans current and available on-site? (Check any that are Not OK) Training Plan 62-701.320(15)(a) Operating Plan 62-701.500(2) Waste weight records 62-701.500(4) Precipitation records 62-701.500(8)(g)	~			

Item No.	LANDFILL OPERATION AND MAINTENANCE Completed	Ok	Not Ok	Unk	N/A
2.10	Load-checking program records 62-701.500(6)(a)				
	Training records 62-701.320(15)(a)	93			
	Operation record 62-701.500(3)	~			
	Quantity of leachate 62-701.500(8)(f)				
2.11	Is the operation plan substantially followed? 62-701.500(2)	~			
2.12	Is incoming waste weighed? 62-701.500(4)(a) and (2)(d)	~			
2.13	Is the method and sequence of filling waste according to plans? 62-701.500(2)(f)	~			
2.14	Is access properly controlled to prevent unauthorized waste disposal? 62-701.500(5)	~			
2.15	Is waste compacted as required? 62-701.500(7)(a)	~			
2.16	Are the working face and side slopes above ground graded to a slope no greater than 3 feet horizontal to 1 foot vertical rise? 62-701.500(7)(c)	~			
2.17	Is a narrow working face practiced? 62-701.500(7)(d)	~			
2.18	Is the frequency, amount and quality of initial cover, as required? 62-701.500(7)(e)	~			
2.19	Is the frequency, amount and quality of intermediate cover, as required? 62-701.500(7)(f)	~			
2.20	Is litter controlled and are litter control devices maintained? 62-701.500(7)(i) and (11)(f)	~			
2.21	Is erosion control adequate? 62-701.500(7)(j)	~			
2.22	Is the leachate collection and removal system maintained and operated as required? 62-701.500(2)(j), 62-701.500(8)(b) and (h)	~			
2.23	Is leachate disposed of or treated as required? 62-701.500(8)(b), (c) and (d)	~			
2.24	If leachate recirculation is practiced at the facility, is it done in accordance with Department requirements and the Operation Plan? 62-701.400(5)				~
2.25	Is gas controlled to not cause objectionable odors beyond the property boundary? 62-701.530(3)(b)	~			
2.26	Is gas controlled to not allow combustible gas concentrations to exceed specified limits? 62-701.530(3)(a)	~			
2.27	Are gas vents intact and functioning properly? 62-701.500(9), 62-701.530(1)(a)3	~			
2.28	Is mixing of leachate and stormwater prevented or minimized? 62-701.500(10), 62-701.400(9)(b)	~			
2.29	Is stormwater management system maintained and operated as required? 62-701.500(10)	~			
2.30	Is there sufficient operating equipment? 62-701.500(11)(a)	~			
2.31	Is there sufficient reserve equipment (or other arrangements)? 62-701.500(11)(b)	~			
2.32	Are communication facilities adequate? 62-701.500(11)(c)	~			
2.33	Are approved dust control methods adequate? 62-701.500(11)(d)	~			
2.34	Are fire protection and fire fighting capabilities adequate and operational? 62-701.500(11)(e)	~			
2.35	Are there required signs for operational directions and public information? 62-701.500(11)(g)	~			
2.36	Are all-weather access roads and inside perimeter roads properly maintained? 62-701.500(12)	~			
2.37	Are ground water wells intact and properly maintained? 62-701.510(2)(b), 62-701.620(8)	~			
2.38	Are all additional specific conditions (not otherwise addressed above) in the permit, Department order, or certification, if any, being followed? 62-701.320(1), 403.161, F.S.	~			

SECTION 9.0 - WASTE TIRE FACILITIES

Requirements:

Item No.	SOLID WASTE PROHIBITIONS (unless "grandfathered" in, see 62-701.300(18)) Completed	Ok	Not Ok	Unk	N/A
9.1.1	Unauthorized storage, processing, or disposal of solid waste except as authorized at a permitted solid waste management facility or other exempt facility? 62-701.300(1)(a)	~			
9.1.2	Unauthorized disposal or storage prohibited, except yard trash, within 500 feet of a potable water well? 62-701.300(2)(b)	>			
9.2	Unauthorized storage or disposal of yard trash prohibited within the minimum setbacks of (Check any that are Not OK) 62-701.300(12) 100 feet from potable water wells (except on-site)? 50 feet from water bodies?	>			
9.3	Unauthorized disposal or storage prohibited in any natural or artificial body of water including ground water and wetlands? (Does not apply to standing water after a storm event) 62-701.300(2)(d)	>			
9.4	Unauthorized disposal or storage prohibited, except yard trash, within 200 feet of any natural or artificial body of water, including wetlands without permanent leachate controls, except impoundments or conveyances which are part of an on-site, permitted stormwater management system or on-site water bodies with no off-site discharge? 62-701.300(2)(e)	>			
9.5	Unauthorized open burning of solid waste prohibited except in accordance with Department requirements? 62-701.300(3)	>			

Item No.	WASTE TIRE FACILITY - GENERAL REQUIREMENTS FOR STORAGE Completed	Ok	Not Ok	Unk	N/A
9.6	If the facility accepts tires from the public, is a sign posted at the facility entrance stating operating hours, cost of disposal and site rules? 62-711.540(1)(a)	>			
9.7	Are operations involving the use of open flames conducted no closer than 25 feet of a waste tire pile? 62-711.540(1)(b)				٧
9.8	If the facility accepts tires from the public, is an attendant always present on site when the site is open for business? 62-711.540(1)(c)	~			
9.9	Are fire protection services assured through notification to local fire protection authorities? 62-711.540(1)(d)	>			
9.10	Is an annual fire safety survey conducted? 62-711.540(1)(d)	~			
9.11	Is a copy of the annual fire safety report made part of the next quarterly report? 62-711.540(1)(d)	>			
9.12	Does the facility have an Emergency Preparedness Manual (EPM) on-site? 62-711.540(1)(e)	>			
9.13	Does the EPM contain the following information? (Check all that are Not OK) Contact names and numbers 62-711.540(1)(e)1 List of emergency response equipment and locations on-site 62-711.540(1)(e)2 Procedures to be followed in the event of a fire 62-711.540(1)(e)3	>			
9.14	Is the operator at the facility maintaining records of the quantity of waste tires received at the site, stored at the site, and shipped from the site? 62-711.540(1)(g) and 62-711.400(5)	٧			
9.15	If the operator of the site is not the owner of the property, has written authorization been obtained from the property owner to operate the facility? 62-711.540(1)(h)				~
9.16	Is adequate communications equipment available at the site? 62-711.540(1)(i)	~			
9.17	Is the owner or operator providing for control of mosquitoes and rodents so as to protect the public health and welfare? 62-711.540(1)(j)	٧			

Item No.	WASTE TIRE FACILITY - STORAGE INDOORS Completed	Ok	Not Ok	Unk	N/A

Item No.	WASTE TIRE FACILITY - STORAGE INDOORS Completed	Ok	Not Ok	Unk	N/A
9.18	Are waste tire piles more than 50 feet in width? 62-711.540(2)(a)				~
9.19	Are waste tire piles along a wall more than 25 feet in width? 62-711.540(2)(a)				~
9.20	Are widths of main aisles between piles less than 8 feet? 62-711.540(2)(b)				~
9.21	Is there less than 3 feet of clearance between the top of storage to sprinkler detectors or roof structures? 62-711.540(2)(c)				~
9.22	Is there less than 3 feet of clearance between waste tire piles and unit heaters, etc.? 62-711.540(2)(d)				~
9.23	If waste tires are stored up to 15 feet high, do walls between adjacent warehouse areas and between manufacturing and warehouse areas have at least a four-hour fire rating? 62-711.540(2)(e)				~
9.24	If waste tires are stored over 15 feet high, do walls between manufacturing and warehouse areas have a fire rating of not less than six hours and do steel columns have one-hour fireproofing? If the top of storage exceeds 20 feet in height, do columns and their connections with other structural members have two-hour fireproofing? 62-711.540(2)(f)				v
9.25	Is the access controlled through the use of doors, fences, gates, natural barriers or other means? 62-711.540(2)(h)				~

Item No.	WASTE TIRE FACILITY - STORAGE OUTDOORS Completed	Ok	Not Ok	Unk	N/A
9.26	Is the waste tire site operated within 200 feet from a body of water? 62-711.540(3)(a)	~			1
9.27	Does the waste tire pile have a width less than 50 feet? 62-711.540(3)(b)	~			
9.28	Does the waste tire pile have an area less than 10,000 sq. ft? 62-711.540(3)(b)	~			
9.29	Does the waste tire pile have a height less than 15 feet? 62-711.540(3)(b)	~			
9.30	Is there a 50 feet wide fire lane around the perimeter of the waste tire pile? 62-711.540(3)(c)	~			
9.31	Is there unobstructed access to the fire lane? 62-711.540(3)(c)	~			
9.32	Is the access controlled through the use of doors, fences, gates, natural barriers or other means? 62-711.540(3)(d)	~			
9.33	Is the site kept free of grass, underbrush, and other potentially flammable vegetation? 62-711.540(3)(f)	~			
9.34	Is the site bermed or given other adequate protection to prevent liquid runoff from entering water bodies? 62-711.540(3)(e)	~			
9.35	Are residuals contained on-site and disposed of in a permitted solid waste management facility or properly recycled? 62-711.540(5)	>	_		
9.36	Does the waste tire site qualify for the exceptions to the technical and operational standards as allowed by rule? 62-711.540(6)				٧

Item No.	WASTE TIRE FACILITY - COLLECTION CENTER Completed	Ok	Not Ok	Unk	N/A
9.37	Are no more than 1,500 tires at the collection center at any one time? 62-711.550(1)(a)				>
9.38	Are all waste tires, which are not used tires, removed from site yearly for recycling, processing, or disposal? 62-711.550(1)(b)	>			

SECTION 10.0 - REGISTERED SOURCE-SEPARATED ORGANICS PROCESSING FACILITIES

Requirements:

FACILITY T	YPE(S)	MATERIAL(S) PROCESSED	PRODUCES	METHO	DD OF C	ОМРО	STING
☐ Yard Trash Transfer Station ☐ Yard Trash ☐ Mulch ☐ Yard Trash Recycling ☐ Manure ☐ Firewood		☐ Wir	ndrow				
X Yard Tra	ash Recycling	Manure	Firewood	Pas	ssive aeı	rated wi	ndrows
		Animal byproducts	☐ Fuel	Aeı	rated sta	tic piles	
		Pre-consumer vegetative waste	Compost	☐ In-\	essel co	ompostii	ng
		▼ Vegetative waste	Soil Amendment				
			Soil				
			Other				
Item No.	· ·	S AND PROHIBITIONS APPLICAB		Ok	Not Ok	Unk	N/A
10.1	Upauthorized storage	e, processing, or disposal of solid waste excep	at as authorized at a permitted or				
10.1		e, processing, or disposal of solid waste except e management facility or other exempt facility		~			
10.2	709.300(7)(a)	odors been caused or allowed in violation of C	•	~			
10.3	standards? 62-709.3	e or processing in a way or location that violat 00(7)(b), 62-701.300(1)(b)		~			
10.4	701.300(2)(a)	ions or subsurface features provide support fo				~	
10.5	artificial body of wate impoundments or co	al or storage prohibited, except yard trash, wit er, including wetlands without permanent leach nveyances which are part of an on-site, permi ter bodies with no off-site discharge? 62-701.	nate controls, except tted stormwater management	~			
10.6		e or processing in any natural or artificial wate jurisdiction)? 62-709.300(7)(b), 62-701.300(2		~			
10.7	Unauthorized storage 709.300(7)(b), 62-70	e or processing on the right of way of any pub 1.300(2)(f)	lic highway, road, or alley? 62-	~			
10.8	709.300(7)(b), 62-70			~			
10.9	soil or soil amendme	oration of CCA treated wood into material that nt? 62-709.300(7)(b), 62-701.300(14)		~			
10.10		ined emissions of particulate matter in violation (b), 62-701.300(15)	n of paragraph 62-296.320(4)(c),	~			
10.11	specified? Including:	, , , ,					
10.11.1	Effective barrier to pr	revent unauthorized entry and dumping? 62-7	09.320(2)(a)1	~			
10.11.2	Dust and litter contro	l methods? 62-709.320(2)(a)2		~			
10.12		e the necessary fire protection and control pro e? Including 62-709.320(2)(a)3	visions to deal with accidental				
10.12.1	20-foot all-weather a	ccess road all around the perimeter? 62-709.3	320(2)(a)3.a.	~			
10.12.2	No material mechani	cally compacted? 62-709.320(2)(a)3.b.		~			
10.12.3	No material more that	nn 50 feet from access by motorized firefightin	g equipment? 62-709.320(2)(a)3.c.	~			
10.13	Is the facility operate	d in a manner to control vectors? 62-709.320	(2)(b)	~			
10.14	Is the facility operate F.A.C.? 62-709.320(d in a manner to control objectionable odors p2)(c)	per with Rule 62-296.320(2),	~			
10.15	Are any installed dra	ins and leachate or condensate conveyances	kept cleaned? 62-709.320(2)(d)	~			
10.16	Is the received solid	waste processed timely as follows? 62-700 33	20(2)(a)				

Item No.	REQUIREMENTS AND PROHIBITIONS APPLICABLE TO ALL REGISTERED SOURCE-SEPARATED ORGANICS PROCESSING FACILITIES Completed	Ok	Not Ok	Unk	N/A
10.16					
10.16.1	Is yard trash size-reduced or removed within 6 months or time needed to receive 3,000 tons or 12,000 cubic yards, whichever is greater? (Separated logs with 6 inch diameter or greater can be stored for up to 12 months before being size-reduced or removed.) 62-709.320(2)(e)1	~			
10.16.2	Is putrescible waste (e.g. vegetative wastes, animal byproducts or manure) processed and incorporated into the composting material, or removed from the facility, within 48 hours? 62-709.320(2)(e)2	~			
10.17	Is any treated or untreated biomedical waste; hazardous waste; or any materials having (PCB) concentration of 50 ppm or greater containerized and removed immediately? 62-709.320(2)(f), 62-701.300(4), 62-701.300(5), 62-701.300(6)	~			
10.18	Have all residuals, solid waste and recyclable materials been removed and recycled or disposed and has any remaining processed material been properly used or disposed upon the facility ceasing operations? 62-709.320(2)(g)	~			
10.19	If temperature is used to show disinfection or vector attraction achieved, are records kept for at least three years? 62-709.320(4)(b)				>
10.20	Is the registration for the facility current and on file with the Department? 62-709.320(3)(b)	~			
10.21	Are renewal applications for annual registration of the facility submitted to the Department by July 1st, if applicable? 62-709.320(3)(c)	~			
10.22	Are monthly records of incoming and outgoing material kept on-site or at another location as indicated on the registration form for at least three years? 62-709.320(4)(a)	~			
10.23	Are Annual Reports, based upon the preceding calendar year, summarizing monthly records, submitted to the Department as required? 62-709.320(4)(a)	~			

Item No.	REQUIREMENTS AND PROHIBITIONS APPLICABLE TO YARD TRASH ONLY FACILITIES Completed	Ok	Not Ok	Unk	N/A
10.24	Unauthorized storage or processing within 100 feet from off-site potable water well that existed before facility registered? 62-709.300(7)(b) and 62-701.300(12)(a)	>			
10.25	Unauthorized storage or processing within 50 feet from any body of water, including wetlands? (Does not include parts of permitted stormwater system, or water bodies totally within facility with no discharge to surface waters.) 62-709.300(7)(b), 62-701.300(12)(b)	>			
10.26	Is processed material removed from facility within 18 months, unless longer storage authorized by permit? 62-709.330(2)	>			
10.27	Is the facility accepting only yard trash, and bags used to collect yard trash and containerizing any other material? 62-709.330(3)	~			

Item No.	REQUIREMENTS AND PROHIBITIONS APPLICABLE TO ONLY THOSE FACILITIES THAT BLEND MANURE OR COMPOST VEGETATIVE WASTES, ANIMAL BYPRODUCTS OR MANURE Completed	Ok	Not Ok	Unk	N/A
10.28	Unauthorized storage or processing within 500 feet off-site potable water well that existed before facility registered? 62-709.300(7)(b) and 62-701.300(2)(b)				~
10.29	Unauthorized storage or processing within 200 feet from any body of water, including wetlands? (Does not include parts of permitted stormwater system, or water bodies totally within facility with no discharge to surface waters.) 62-709.300(7)(b), 62-701.300(2)(e)				>
10.30	Unauthorized storage or processing within 10,000 feet of any licensed and operating airport runway used by turbine powered aircraft, or within 5,000 feet of any licensed and operating airport runway used only by piston engine aircraft, unless applicant demonstrates that the facility is designed and will be operated so that it does not pose a bird hazard to aircraft? 62-709.300(7)(b), 62-701.320(13)(b)				٨
10.31	Is the carbon:nitrogen ratio of the blended feedstocks greater than 20? 62-709.350(2)				>
10.32	Do piles exceed 12 feet in height? 62-709.350(3)				٧
10.33	Is all material removed within 18 months, unless longer storage authorized by permit? 62-709.350(5)				~
10.34	Is there documentation showing that disinfection has been achieved? Note that this is not required if they are composting only pre-consumer vegetative waste with or without yard trash. 62-709.350(6)				>
10.35	Is there vector attraction reduction controls that include one of the following? 62-709.350(7) Temperature monitoring records showing the waste was composted for at least 14 days, with temperature no lower than 40 degrees Celsius and average temperature of the material being composted higher than 45 degrees Celsius. or 62-709.350(7)(a) Results of testing showing the specific oxygen uptake rate (SOUR) for material being composted or blended equal to or less than 1.5 milligrams				>

	REQUIREMENTS AND PROHIBITIONS APPLICABLE TO ONLY THOSE FACILITIES THAT BLEND MANURE OR COMPOST VEGETATIVE WASTES, ANIMAL BYPRODUCTS OR MANURE Completed	Ok	Not Ok	Unk	N/A
10.35	of oxygen per hour per gram of total solids (dry weight basis) at a temperature of 20 degrees Celsius. 62-709.350(7)(b)				~

SECTION 12.0 - WTE FACILITIES

Requirements:

The requirements listed in this section provide an opportunity for the Department's inspector to indicate the conditions found at the time of the inspection. A "Not Ok" response to a requirement indicates either a potential violation of the corresponding rule or an area of concern that requires more attention. Both potential violations and areas of concern are discussed further at the end of this inspection report.

Item No.	SOLID WASTE PROHIBITIONS (unless "grandfathered" in, see 62-701.300(18)) Completed	Ok	Not Ok	Unk	N/A
12.1.1	Unauthorized storage, processing, or disposal of solid waste except as authorized at a permitted solid waste management facility or other exempt facility? 62-701.300(1)(a)	~			
12.1.2	Unauthorized disposal or storage prohibited, except yard trash, within 500 feet of a potable water well? 62-701.300(2)(b)	>			
12.2	Unauthorized storage or disposal of yard trash prohibited within the minimum setbacks of (Check any that are Not OK) 62-701.300(12) 100 feet from potable water wells (except on-site)? 50 feet from water bodies?	>			
12.3	Unauthorized disposal or storage prohibited in any natural or artificial body of water including ground water and wetlands? (Does not apply to standing water after a storm event.) 62-701.300(2)(d)	>			
12.4	Unauthorized disposal or storage prohibited, except yard trash, within 200 feet of any natural or artificial body of water, including wetlands without permanent leachate controls, except impoundments or conveyances which are part of an on-site, permitted stormwater management system or on-site water bodies with no off-site discharge? 62-701.300(2)(e)	>			
12.5	Unauthorized open burning of solid waste prohibited except in accordance with Department requirements? 62-701.300(3)	~			
12.6	Are the following unauthorized wastes or special wastes properly managed? (Check any that are Not OK) Lead-acid batteries, mercury-containing switches and lamps in WTEs 62-701.300(9) CCA treated wood 62-701.300(14)	>			
Item	WTE FACILITY OPERATION AND MAINTENANCE Completed	Ok	Not	Unk	N/A

Item No.	WTE FACILITY OPERATION AND MAINTENANCE Completed	Ok	Not Ok	Unk	N/A
12.7	WTE facility in compliance with all permit conditions, site certification conditions, Department order, or certification, if any, and applicable requirements? 62-701.320(1), 403.161, F.S.	~			

COMMENTS:

05/13/2015

COMMENTS SECTION 2 OF 2:

9.12, 9.13 - Emergency Preparedness Plan appears to be part of Contingency Plan, included in this facility's Operations Plans for the Class I and III areas. Contact names, procedures, and locations of fire extinguishers and fire hydrants are listed. Specific telephone numbers, other than 9-1-1, are not listed, but Operations Plan indicates that operators carry two-way radios. Locations of other equipment may or may not be listed in Operations Plan specifically, but types of equipment are listed and procedures indicate that field staff are to use landfill equipment and soil from an on-site pile to control fire in the event of a controllable fire. Scale House attendant will contact Landfill Supervisor and 9-1-1 to request Fire Department assistance if an uncontrollable fire occurs, and Landfill Supervisor will direct additional manpower and equipment to the scene as necessary.

9.34 - Tire storage area was relatively small and appeared to be maintained properly.

- 9.35 Tires not being processed at time of inspection.
- 10.4 The Geotechnical/Hydrogeologic Investigations by Jammal & Associates, Inc., dated April 17, 1987 and May 26, 1987, do not appear to have included the present area where the source-separated organics processing facility (SOPF) is located, so it is currently unknown if geological formations or subsurface features provide support for the SOPF facility.
- 10.22 Annual records reviewed as part of SOPF annual registration, but individual monthly records were not reviewed as part of this inspection.
- 10.26 Waste in pile appeared to be processed in a timely manner.
- 12.7 Ash handling runoff drain depth sensor appeared to be caught and not working properly. Facility notified Department on 02/09/2015 via e-mail that issue had been addressed and drain float was fixed. Also see associated air pollution walkthrough inspection report conducted on the same day.

ADDITIONAL COMMENTS: Ash and Solid Waste Class I areas were inspected together and reported together for this inspection report (the "Other" category in this inspection report is for the Ash Class I Landfill Areas and is reported in the same sections as the requirements for the Solid Waste Class I Landfill Areas). In addition, Facility e-mail from 02/25/2015 states that it has been the County's policy not to receive asbestos materials at the West Pasco Landfill from the opening date back in 1991.

05/08/2015

COMMENTS SECTION 1 OF 2:

- 1.5 1st and 2nd semiannual 2014 groundwater reports reviewed for this inspection.
- 1.6 Groundwater trending analysis not conducted during for this inspection.
- 1.8 Financial assurance for Class III and Class I areas will be submitted together by September 1st.
- 2.10 The following records were reviewed at the FDEP SWD office from the facility's submittals: leachate generation (4th quarter 2013 and 1st, 2nd, 3rd, and 4th quarters 2014), groundwater monitoring (1st and 2nd Halves 2014), gas monitoring (1st, 2nd, 3rd, and 4th Quarters 2014 and 1st Quarter 2015), waste quantity reports (1st, 2nd, 3rd, and 4th Quarters 2014), and estimates of remaining life (2013 reporting year for Class III, received April 2014, and 2013 reporting year for Class I SW-2 and Class I A-4 Cells, received April 2014). Records that were not reviewed during this inspection were training records, waste weight records (other than waste quantity reports), precipitation records (other than average rainfalls included in leachate generation reports), load-checking program records, and the training plan. The facility is operations plans are available online through the Department's online archive, OCULUS.
- 2.27 Groundwater wells 2MW-4 and 4MW-4 are also gas monitoring wells and were observed during this walkthrough inspection. These two wells appeared to be adequately maintained. All other gas monitoring wells were not observed during this walkthrough inspection.
- 2.28 Runoff from Cells SW-1 and SW-2 into central dividing lined ditch is treated as leachate. Vegetation blocking lined central ditch was cleared as noted in 02/23/2015 e-mail from facility to FDEP.
- 2.29 Leachate collection systems for Cells SW-2 and A-3 were observed during this walkthrough inspection. Leachate was observed to be flowing through collection sumps for these cells. Some flows appeared to have values that did not match visual observations. Facility Authorized Representative indicated that facility has redundancies that still allow for back-calculation of flows, but that flow meters would be checked, with possible system overhaul, to ensure that flows are

being accurately reported.

2.34 - Facility e-mailed FDEP on 05/13/2015 indicating that facility has called Fire Marshal to schedule an inspection of the tire storage area and will follow up and submit the Fire Marshal's inspection report once the inspection report is completed and submitted to the facility. This report will then be reviewed by FDEP as a separate activity. The facility's most recent fire safety inspection report was not reviewed as a part of this inspection. Facility's 05/13/2015 e-mail also indicates the types of equipment available, also listed in the Operations Plan, in the event of a fire, which includes: 3,000 gallon water truck with cannon sprayers, 6" non-potable water line with camlock connection at 75 psi, 6,000 gallon tanker truck to fill Emergency Responding equipment, and more. Also, facility stated that tires are stored on lime rock and appropriate setbacks are observed as required by facility's Fire Department.

2.37 - Groundwater wells observed during this inspection included the furthest downgradient wells 2MW-4 and 4MW-4, which appeared to be adequately maintained. FDEP also observed groundwater wells 2MW-24S, 2MW-24D, 2MW-25S, and 2MW-25D, which needed minor maintenance including lock and cap replacements and lock installations. The facility addressed this concern on 02/10/2015. All other groundwater monitoring wells were not observed during this walkthrough inspection.

9.8 - Tire storage area appeared to be well-maintained.

9.9, 9.10, 9.11 - See comments above for Section 2.34 of this inspection report.

COMMENTS CONTINUED IN NEXT FIELD.

ATTACHMENTS:

GW Compliance/Gas Well 2MW-4



Class I Cell SW-1 Exposed Waste



Class I Cell SW-1 cover added



Vegetation in Stormwater SW ditch



Stormwater ditch veg removed 2



Class I Cell SW-1 cover added 2



Stormwater ditch veg removed



Class I Cell SW-2 Working Face



Class I Cell SW-2 Leachate sump



Class I Cell A-4 Working Face



Waste tire storage area



Class I Cell A-3 Leachate sump



Ballast (removed) from Class III



SOPF area



Tipping floor, WTE Facilityi



Ash handling runoff drain (fixed)



Signed:

Inspector	
PRINCIPAL INSPECTOR TITLE	
FDFD	E/40/004E
_	<u>5/13/2015</u>
URGANIZATION	DATE
INSPECTOR TITLE	
FDEP	
_	
Inspector	
INSPECTOR TITLE	
FDEP	
ORGANIZATION	
Director of Solid Waste	
KEI KEGENTATTE TITE	
Pasco County	
ORGANIZATION	
Facility Environmental Engineer	
REPRESENTATIVE TITLE	_
Covente	
ORGANIZATION	
Solid Waste Operator	
REPRESENTATIVE TITLE	
D 0 1	
·	
ORGANIZATION	
	Inspector INSPECTOR TITLE FDEP ORGANIZATION Inspector INSPECTOR TITLE FDEP ORGANIZATION Director of Solid Waste REPRESENTATIVE TITLE Pasco County ORGANIZATION Facility Environmental Engineer REPRESENTATIVE TITLE Covanta ORGANIZATION Solid Waste Operator REPRESENTATIVE TITLE Pasco County ORGANIZATION Solid Waste Operator REPRESENTATIVE TITLE

NOTE: By signing this document, the Site Representative only acknowledges receipt of this Inspection Report and is not admitting to the accuracy of any of the items identified by the Department as "Not Ok" or areas of concern.