

Florida Department of

Environmental Protection

Inspection Checklist

FACILITY INFORMATION:

Facility Name: CITRUS CENTRAL SLF

On-Site Inspection Start Date: 07/27/2015
On-Site Inspection End Date: 07/27/2015

WACS No.: 39859

Facility Street Address: 3MI E LECANTO, SR44

City: LECANTO

County Name: CITRUS

Zip: 34461

INSPECTION PARTICIPANTS:

(Include ALL Landfill and Department Personnel with Corresponding Titles)

Principal Inspector: Nick Roff, Inspector

Other Participants: John Morris, Inspector; Larry Brock, Assistant Public Works Director; Dan Sherlock,

Hazardous Waste Coordinator

INSPECTION TYPE:

Routine Operation Inspection for Landfill - Class I facility

Routine Long Term Care Inspection for Landfill - Class I Closed - Long Term Care facility

Routine Operation Inspection for WPF - Waste Tire Processing Facility

Routine Operation Inspection for Other - Landfill Gas Management System facility

Routine Operation Inspection for WPF - Source-Separated Organics Proc Fac (SOPF) facility

ATTACHMENTS TO THE INSPECTION CHECK LIST:

This Cover Page to the Inspection Checklist may include any or all of the following attachments as appropriate.

SECTION 1.0 - FILE REVIEW

SECTION 2.0 - LANDFILL OPERATION AND MAINTENANCE

SECTION 3.0 - LANDFILL - CLOSED

SECTION 9.0 - WASTE TIRE FACILITIES

SECTION 10.0 - REGISTERED SOURCE-SEPARATED ORGANICS PROCESSING FACILITIES

SECTION 1.0 - FILE REVIEW

Requirements:

Item No.	FILE REVIEW (Pre- or Post-Inspection, as appropriate.) Completed	Ok	Not Ok	Unk	N/A
1.1	For landfills and C&D disposal facilities, does the facility have a current plan for the method and sequence of filling wastes? 62-701.500(2)(f) for landfills; 62-701.730(7)(a) for C&D debris sites	~			
1.2	For landfills, are the following records being reported to the Department?(Check any that are Not OK) Waste reports (annually) 62-701.500(4) Annual estimate of remaining life 62-701.500(13)(c)	>			
1.3	Is gas monitoring being performed as required by the permit? 62-701.500(9), 62-701.530(2)	~			
1.4	Are the results of the gas sampling reported to the Department quarterly? 62-701.530(2)(c)	>			
1.5	Is water quality sampling and testing performed according to standard procedures and at the required frequencies? 62-701.510(2) for landfills; 62-701.730(4)(b) and (10) for C&D debris sites; 62-713.400(3) for stationary soil treatment facilities.	>			
1.6	Do the results of the water quality testing suggest there may be adverse impacts to water quality from the operation of the solid waste facility? 62-701.510(3) and (4); 62-701.730(4)(c) and (10) for C&D debris sites; 62-713.400(3) for stationary soil treatment facilities.		~		
1.7	For closed landfills and C&D disposal facilities with final elevations higher than 20 feet above grade, has a final survey report verifying the final elevations and contours of the facility been submitted to the Department? 62-701.600(6)(b), 62-701.730(9)(d)	>			
1.8	Is financial assurance adequate? 62-701.630 for landfills; 62-701.710(7)(a) and (10)(a) for waste processing facilities; 62-701.730(11)(a) for C&D debris facilities; 62-713.600(6)(a) for stationary soil treatment facilities; 62-711.500(3) for waste tire facilities. NOTE: The Solid Waste Financial Coordinator in Tallahassee can assist with this information.	\			
1.9	Are cost estimates current and adjusted every year? 62-701.630(4) for landfills; 62-701.710(7)(b) and (10)(a) for waste processing facilities; 62-701.730(11)(b) and (c) for C&D debris facilities; 62-713.600(6)(b) and (c) for stationary soil treatment facilities; 62-711.500(3) for waste tire facilities.	>			
1.10	For C&D debris disposal and disposal with recycling facilities, is an Annual Report submitted to the Department for the disposal operation by February 1st of each year? 62-701.730(12)				~
1.11	For C&D recycling facilities with no disposal, is an Annual Report for the recycling facility submitted to the Department by February 1st of each year? 62-701.710(8)(b)				~
1.12	For compost facilities, has the compost product been sampled and analyzed every 20,000 tons or every 3 months (whichever is sooner)? 62-709.530(1)			_	~
1.13	For compost facilities, has the annual report been submitted by June 1st? 62-709.530(3)				~

CITRUS CENTRAL SLF Page 3 of 15

Inspection Date: 07/27/2015

SECTION 2.0 - LANDFILL OPERATION AND MAINTENANCE

Requirements:

Item No.	SOLID WASTE PROHIBITIONS (unless "grandfathered" in, see 62-701.300(18)) Completed	Ok	Not Ok	Unk	N/A
2.1.1	Unauthorized storage, processing, or disposal of solid waste except as authorized at a permitted solid waste management facility or other exempt facility. 62-701.300(1)(a)	>			
2.1.2	Unauthorized disposal or storage prohibited, except yard trash, within 500 feet of a potable water well? 62-701.300(2)(b)	>			
2.2	Unauthorized storage or disposal of yard trash prohibited within the minimum setbacks of (Check any that are Not OK) 62-701.300(12) 100 feet from potable water wells (except on-site)? 50 feet from water bodies?	>			
2.3	Unauthorized disposal or storage prohibited in any natural or artificial body of water including ground water and wetlands? (Does not apply to standing water after a storm event.) 62-701.300(2)(d)	>			
2.4	Unauthorized disposal or storage prohibited, except yard trash, within 200 feet of any natural or artificial body of water, including wetlands without permanent leachate controls, except impoundments or conveyances which are part of an on-site, permitted stormwater management system or on-site water bodies with no off-site discharge? 62-701.300(2)(e)	>			
2.5	Unauthorized open burning of solid waste prohibited except in accordance with Department requirements? 62-701.300(3)	>			
2.6	Are the following unauthorized wastes or special wastes properly controlled, managed and disposed? (Check any that are Not OK) Hazardous waste 62-701.300(4) Biomedical waste 62-701.300(6) Yard trash 62-701.300(8)(c) Whole waste tires 62-701.300(8)(e) Regulated asbestos waste 62-701.520(3), 62-701.730(19) Used oil and oily wastes, except as exempted 62-701.300(11) PCB wastes 62-701.300(5) Lead-acid batteries 62-701.300(8)(a) White goods 62-701.300(8)(d) Liquids 62-701.300(10) CCA treated wood 62-701.300(14)	Ş			
2.7	Are only permitted waste types disposed at facility? 62-701.340(2), 62-701.500(6)(a), 62-701.500(2)(c)	>			

Item No.	LANDFILL OPERATION AND MAINTENANCE Completed	Ok	Not Ok	Unk	N/A
2.8	Is there a trained operator on-site at Class I and III landfills when receiving wastes? 62-701.500(1)	~			
2.9	Is there at least one trained spotter at each working face when receiving wastes at Class I and III landfills? 62-701.500(1)	~			
2.10	Are the following records or plans current and available on-site? (Check any that are Not OK) Training Plan 62-701.320(15)(a) Operating Plan 62-701.500(2) Waste weight records 62-701.500(4) Precipitation records 62-701.500(8)(g)	~			

Item No.	LANDFILL OPERATION AND MAINTENANCE Completed	Ok	Not Ok	Unk	N/A
2.10	Load-checking program records 62-701.500(6)(a)				
	Training records 62-701.320(15)(a)	95			
	Operation record 62-701.500(3)	~			
	Quantity of leachate 62-701.500(8)(f)				
2.11	Is the operation plan substantially followed? 62-701.500(2)	~			
2.12	Is incoming waste weighed? 62-701.500(4)(a) and (2)(d)	~			
2.13	Is the method and sequence of filling waste according to plans? 62-701.500(2)(f)	~			
2.14	Is access properly controlled to prevent unauthorized waste disposal? 62-701.500(5)	~			
2.15	Is waste compacted as required? 62-701.500(7)(a)	~			
2.16	Are the working face and side slopes above ground graded to a slope no greater than 3 feet horizontal to 1 foot vertical rise? 62-701.500(7)(c)	~			
2.17	Is a narrow working face practiced? 62-701.500(7)(d)	~			
2.18	Is the frequency, amount and quality of initial cover, as required? 62-701.500(7)(e)		~		
2.19	Is the frequency, amount and quality of intermediate cover, as required? 62-701.500(7)(f)		~		
2.20	Is litter controlled and are litter control devices maintained? 62-701.500(7)(i) and (11)(f)	~			
2.21	Is erosion control adequate? 62-701.500(7)(j)	~			
2.22	Is the leachate collection and removal system maintained and operated as required? 62-701.500(2)(j), 62-701.500(8)(b) and (h)		~		
2.23	Is leachate disposed of or treated as required? 62-701.500(8)(b), (c) and (d)	~			
2.24	If leachate recirculation is practiced at the facility, is it done in accordance with Department requirements and the Operation Plan? 62-701.400(5)				>
2.25	Is gas controlled to not cause objectionable odors beyond the property boundary? 62-701.530(3)(b)	^			
2.26	Is gas controlled to not allow combustible gas concentrations to exceed specified limits? 62-701.530(3)(a)	~			
2.27	Are gas vents intact and functioning properly? 62-701.500(9), 62-701.530(1)(a)3	~			
2.28	Is mixing of leachate and stormwater prevented or minimized? 62-701.500(10), 62-701.400(9)(b)		~		
2.29	Is stormwater management system maintained and operated as required? 62-701.500(10)	~			
2.30	Is there sufficient operating equipment? 62-701.500(11)(a)	~			
2.31	Is there sufficient reserve equipment (or other arrangements)? 62-701.500(11)(b)	~			
2.32	Are communication facilities adequate? 62-701.500(11)(c)	~			
2.33	Are approved dust control methods adequate? 62-701.500(11)(d)	~			
2.34	Are fire protection and fire fighting capabilities adequate and operational? 62-701.500(11)(e)	~			
2.35	Are there required signs for operational directions and public information? 62-701.500(11)(g)	~			
2.36	Are all-weather access roads and inside perimeter roads properly maintained? 62-701.500(12)	~			
2.37	Are ground water wells intact and properly maintained? 62-701.510(2)(b), 62-701.620(8)	~			
2.38	Are all additional specific conditions (not otherwise addressed above) in the permit, Department order, or certification, if any, being followed? 62-701.320(1), 403.161, F.S.	~			

CITRUS CENTRAL SLF Page 5 of 15

Inspection Date: 07/27/2015

SECTION 3.0 - LANDFILL - CLOSED

Requirements:

The requirements listed in this section provide an opportunity for the Department's inspector to indicate the conditions found at the time of the inspection. A "Not Ok" response to a requirement indicates either a potential violation of the corresponding rule or an area of concern that requires more attention. Both potential violations and areas of concern are discussed further at the end of this inspection report.

Type of Cover: 7-acre re-closure 12" soil, 40-mil LLDPE, 24" soil & veg.

Closure/Final Cover Date:

Post-Closure Utilization: Sheriff Training Facility

Surrounding Land Use: Recreation (State Forest), commercial and residential

Date Long-Term Care Began:

Item No.	LANDFILL - CLOSED Completed	Ok	Not Ok	Unk	N/A
3.1	Is site access controlled to prevent any unauthorized dumping? 62-701.600(3)(i)	~			
3.2	Are any unauthorized wastes stored or disposed at the site? 62-701.600(3)(i)	~			
3.3	Is stormwater management system maintained and operated as required? 62-701.600(3)(h)	~			
3.4	Is the final cover properly vegetated? 62-701.600(3)(f)2	~			
3.5	Are there any signs of erosion of the final cover? 62-701.620(1)	~			
3.6	Is there any evidence of damage to the barrier layer of the final cover? 62-701.620(1)		~		
3.7	Are areas of differential settlement being properly filled? 62-701.600(3)(f)4		~		
3.8	Are there any areas of ponding water on the final cover? 62-701.600(3)(f)3		~		
3.9	Is the leachate collection and removal system maintained and operated as required? 62-701.500(2)(j), 62-701.500(8)(b) and (h)	~			
3.10	Is leachate disposed of or treated as required? 62-701.500(8)(b), (c) and (d)	~			
3.11	Are there any signs of leachate seeps at the closed landfill? 62-701.500(8)(b), 62-701.620(1)	~			
3.12	Condition of the ground water monitoring wells in accordance with the ground water monitoring plan. 62-701.620(1) (Check any that are Not OK) Access to monitoring wells Damage to monitoring wells Monitoring wells protected, secured and labeled.	v			
3.13	Are the wells for gas monitoring and detection intact and operable? 62-701.620(5)	~			
3.14	Is the gas collection system (active or passive) operating and maintained? 62-701.620(5) Signs of stressed vegetation Odors or foul smells	~			
3.15	Is gas monitoring being conducted as required? 62-701.620(5)	~			
3.16	Is there any evidence that gas pressure is interfering with or causing failure of the final cover? 62-701.530(1)(a)4	~			
3.17	If required, are survey monuments properly installed? 62-701.600(6)	~			
3.18	Is there a potential hazard to public health and the environment resulting from the post-closure utilization of the solid waste disposal facilities or surrounding land-use changes? 62-701.610(1)	~			
3.19	If waste is being relocated, is this performed according to the Department's requirements? 62-701.610(2)				~
3.20	Are all additional specific conditions (not otherwise addressed above) in the closure or permit for long -term care, Department order, or certification, if any, being followed? 62-701.620(2), 403.161, F.S.	~			

CITRUS CENTRAL SLF

Page 6 of 15

Item No.	LANDFILL - CLOSED Completed	Ok	Not Ok	Unk	N/A
3.20		<			

CITRUS CENTRAL SLF Page 7 of 15

Inspection Date: 07/27/2015

SECTION 9.0 - WASTE TIRE FACILITIES

Requirements:

Item No.	SOLID WASTE PROHIBITIONS (unless "grandfathered" in, see 62-701.300(18)) Completed	Ok	Not Ok	Unk	N/A
9.1.1	Unauthorized storage, processing, or disposal of solid waste except as authorized at a permitted solid waste management facility or other exempt facility? 62-701.300(1)(a)	٧			
9.1.2	Unauthorized disposal or storage prohibited, except yard trash, within 500 feet of a potable water well? 62-701.300(2)(b)	>			
9.2	Unauthorized storage or disposal of yard trash prohibited within the minimum setbacks of (Check any that are Not OK) 62-701.300(12) 100 feet from potable water wells (except on-site)? 50 feet from water bodies?	>			
9.3	Unauthorized disposal or storage prohibited in any natural or artificial body of water including ground water and wetlands? (Does not apply to standing water after a storm event) 62-701.300(2)(d)	>			
9.4	Unauthorized disposal or storage prohibited, except yard trash, within 200 feet of any natural or artificial body of water, including wetlands without permanent leachate controls, except impoundments or conveyances which are part of an on-site, permitted stormwater management system or on-site water bodies with no off-site discharge? 62-701.300(2)(e)	>			
9.5	Unauthorized open burning of solid waste prohibited except in accordance with Department requirements? 62-701.300(3)	>			

Item No.	WASTE TIRE FACILITY - GENERAL REQUIREMENTS FOR STORAGE Completed	Ok	Not Ok	Unk	N/A
9.6	If the facility accepts tires from the public, is a sign posted at the facility entrance stating operating hours, cost of disposal and site rules? 62-711.540(1)(a)	~			
9.7	Are operations involving the use of open flames conducted no closer than 25 feet of a waste tire pile? 62-711.540(1)(b)	>			
9.8	If the facility accepts tires from the public, is an attendant always present on site when the site is open for business? 62-711.540(1)(c)	~			
9.9	Are fire protection services assured through notification to local fire protection authorities? 62-711.540(1)(d)	~			
9.10	Is an annual fire safety survey conducted? 62-711.540(1)(d)	~			
9.11	Is a copy of the annual fire safety report made part of the next quarterly report? 62-711.540(1)(d)	>			
9.12	Does the facility have an Emergency Preparedness Manual (EPM) on-site? 62-711.540(1)(e)	>			
9.13	Does the EPM contain the following information? (Check all that are Not OK) Contact names and numbers 62-711.540(1)(e)1 List of emergency response equipment and locations on-site 62-711.540(1)(e)2 Procedures to be followed in the event of a fire 62-711.540(1)(e)3	>			
9.14	Is the operator at the facility maintaining records of the quantity of waste tires received at the site, stored at the site, and shipped from the site? 62-711.540(1)(g) and 62-711.400(5)	~			
9.15	If the operator of the site is not the owner of the property, has written authorization been obtained from the property owner to operate the facility? 62-711.540(1)(h)	>			
9.16	Is adequate communications equipment available at the site? 62-711.540(1)(i)	~			
9.17	Is the owner or operator providing for control of mosquitoes and rodents so as to protect the public health and welfare? 62-711.540(1)(j)	٧			

Item No.	WASTE TIRE FACILITY - STORAGE INDOORS Completed	Ok	Not Ok	Unk	N/A

CITRUS CENTRAL SLF Page 8 of 15

Item No.	WASTE TIRE FACILITY - STORAGE INDOORS Completed	Ok	Not Ok	Unk	N/A
9.18	Are waste tire piles more than 50 feet in width? 62-711.540(2)(a)				~
9.19	Are waste tire piles along a wall more than 25 feet in width? 62-711.540(2)(a)				~
9.20	Are widths of main aisles between piles less than 8 feet? 62-711.540(2)(b)				~
9.21	Is there less than 3 feet of clearance between the top of storage to sprinkler detectors or roof structures? 62-711.540(2)(c)				~
9.22	Is there less than 3 feet of clearance between waste tire piles and unit heaters, etc.? 62-711.540(2)(d)				~
9.23	If waste tires are stored up to 15 feet high, do walls between adjacent warehouse areas and between manufacturing and warehouse areas have at least a four-hour fire rating? 62-711.540(2)(e)				~
9.24	If waste tires are stored over 15 feet high, do walls between manufacturing and warehouse areas have a fire rating of not less than six hours and do steel columns have one-hour fireproofing? If the top of storage exceeds 20 feet in height, do columns and their connections with other structural members have two-hour fireproofing? 62-711.540(2)(f)				v
9.25	Is the access controlled through the use of doors, fences, gates, natural barriers or other means? 62-711.540(2)(h)				~

Item No.	WASTE TIRE FACILITY - STORAGE OUTDOORS Completed	Ok	Not Ok	Unk	N/A
9.26	Is the waste tire site operated within 200 feet from a body of water? 62-711.540(3)(a)	~			
9.27	Does the waste tire pile have a width less than 50 feet? 62-711.540(3)(b)	>			
9.28	Does the waste tire pile have an area less than 10,000 sq. ft? 62-711.540(3)(b)	٧			
9.29	Does the waste tire pile have a height less than 15 feet? 62-711.540(3)(b)	>			
9.30	Is there a 50 feet wide fire lane around the perimeter of the waste tire pile? 62-711.540(3)(c)	~			
9.31	Is there unobstructed access to the fire lane? 62-711.540(3)(c)	>			
9.32	Is the access controlled through the use of doors, fences, gates, natural barriers or other means? 62-711.540(3)(d)	>			
9.33	Is the site kept free of grass, underbrush, and other potentially flammable vegetation? 62-711.540(3)(f)	٧			
9.34	Is the site bermed or given other adequate protection to prevent liquid runoff from entering water bodies? 62-711.540(3)(e)	~			
9.35	Are residuals contained on-site and disposed of in a permitted solid waste management facility or properly recycled? 62-711.540(5)	٧			
9.36	Does the waste tire site qualify for the exceptions to the technical and operational standards as allowed by rule? 62-711.540(6)	>			

Item No.	WASTE TIRE FACILITY - COLLECTION CENTER Completed	Ok	Not Ok	Unk	N/A
9.37	Are no more than 1,500 tires at the collection center at any one time? 62-711.550(1)(a)				>
9.38	Are all waste tires, which are not used tires, removed from site yearly for recycling, processing, or disposal? 62-711.550(1)(b)				>

CITRUS CENTRAL SLF Page 9 of 15

Inspection Date: 07/27/2015

SECTION 10.0 - REGISTERED SOURCE-SEPARATED ORGANICS PROCESSING FACILITIES

Requirements:

FACILITY T	YPE(S)	MATERIAL(S) PROCESSED	PRODUCES	METH	OD OF C	COMPO	STING
Yard Tra	ash Transfer Station		Mulch	☐ Wii	ndrow		
X Yard Tra	ash Recycling	Manure	Firewood	☐ Pa	ssive ae	rated wi	ndrows
		Animal byproducts	Fuel	Ae	rated sta	atic piles	;
		Pre-consumer vegetative waste	Compost	☐ In-	vessel co	omposti	ng
		Vegetative waste	Soil Amendment				
			Soil				
			Other				
Item		S AND PROHIBITIONS APPLICAB		Ok	Not	Unk	N/A
No.	SOURCE-SEPA	RATED ORGANICS PROCESSING	FACILITIES Completed		Ok		
10.1		e, processing, or disposal of solid waste excep		84			
		e management facility or other exempt facility		~			
10.2	Have objectionable of 709.300(7)(a)	odors been caused or allowed in violation of C	hapter 62-296, F.A.C.? 62-	~			
10.3		e or processing in a way or location that violat 00(7)(b), 62-701.300(1)(b)	es air quality or water quality	~			
10.4		ions or subsurface features provide support fo	or the facility? 62-709.300(7)(b), 62-	~			
10.5	Unauthorized dispos	al or storage prohibited, except yard trash, wit					
		er, including wetlands without permanent leach nveyances which are part of an on-site, permi		~			
		ter bodies with no off-site discharge? 62-701.					
10.6		e or processing in any natural or artificial wate jurisdiction)? 62-709.300(7)(b), 62-701.300(2		~			
10.7	Unauthorized storage	e or processing on the right of way of any pub		~			
10.8	709.300(7)(b), 62-70	1.300(2)(f) purning of solid waste except in accordance wi	ith Department requirements? 62-	6.7		-	
	709.300(7)(b), 62-70	1.300(3)		~			
10.9		oration of CCA treated wood into material that nt? 62-709.300(7)(b), 62-701.300(14)	will be applied as a ground cover,	~			
10.10		fined emissions of particulate matter in violation 7)(b), 62-701.300(15)	on of paragraph 62-296.320(4)(c),	~			
10.11	Does the facility have specified? Including:	e the necessary operational features and equi 62-709.320(2)(a)	pment - unless otherwise				
10.11.1		revent unauthorized entry and dumping? 62-7	09.320(2)(a)1	~			
10.11.2	Dust and litter contro	l methods? 62-709.320(2)(a)2		~			
10.12		e the necessary fire protection and control pro e? Including 62-709.320(2)(a)3	visions to deal with accidental				
10.12.1	20-foot all-weather a	ccess road all around the perimeter? 62-709.3	320(2)(a)3.a.	~			
10.12.2	No material mechani	cally compacted? 62-709.320(2)(a)3.b.		~			
10.12.3	No material more that	an 50 feet from access by motorized firefightin	g equipment? 62-709.320(2)(a)3.c.	~			
10.13	Is the facility operate	d in a manner to control vectors? 62-709.320	(2)(b)	~			
10.14	Is the facility operate F.A.C.? 62-709.320(d in a manner to control objectionable odors p 2)(c)	per with Rule 62-296.320(2),	~			
10.15		ins and leachate or condensate conveyances	kept cleaned? 62-709.320(2)(d)				~
10.16	Is the received solid	waste processed timely as follows? 62-709.32	20(2)(e)	<u> </u>	1		

Item No.	REQUIREMENTS AND PROHIBITIONS APPLICABLE TO ALL REGISTERED SOURCE-SEPARATED ORGANICS PROCESSING FACILITIES Completed	Ok	Not Ok	Unk	N/A
10.16					
10.16.1	Is yard trash size-reduced or removed within 6 months or time needed to receive 3,000 tons or 12,000 cubic yards, whichever is greater? (Separated logs with 6 inch diameter or greater can be stored for up to 12 months before being size-reduced or removed.) 62-709.320(2)(e)1	~			
10.16.2	Is putrescible waste (e.g. vegetative wastes, animal byproducts or manure) processed and incorporated into the composting material, or removed from the facility, within 48 hours? 62-709.320(2)(e)2	~			
10.17	Is any treated or untreated biomedical waste; hazardous waste; or any materials having (PCB) concentration of 50 ppm or greater containerized and removed immediately? 62-709.320(2)(f), 62-701.300(4), 62-701.300(5), 62-701.300(6)	~			
10.18	Have all residuals, solid waste and recyclable materials been removed and recycled or disposed and has any remaining processed material been properly used or disposed upon the facility ceasing operations? 62-709.320(2)(g)	~			
10.19	If temperature is used to show disinfection or vector attraction achieved, are records kept for at least three years? 62-709.320(4)(b)				>
10.20	Is the registration for the facility current and on file with the Department? 62-709.320(3)(b)	~			
10.21	Are renewal applications for annual registration of the facility submitted to the Department by July 1st, if applicable? 62-709.320(3)(c)	~			
10.22	Are monthly records of incoming and outgoing material kept on-site or at another location as indicated on the registration form for at least three years? 62-709.320(4)(a)	~			
10.23	Are Annual Reports, based upon the preceding calendar year, summarizing monthly records, submitted to the Department as required? 62-709.320(4)(a)	~			

Item No.	REQUIREMENTS AND PROHIBITIONS APPLICABLE TO YARD TRASH ONLY FACILITIES Completed	Ok	Not Ok	Unk	N/A
10.24	Unauthorized storage or processing within 100 feet from off-site potable water well that existed before facility registered? 62-709.300(7)(b) and 62-701.300(12)(a)	>			
10.25	Unauthorized storage or processing within 50 feet from any body of water, including wetlands? (Does not include parts of permitted stormwater system, or water bodies totally within facility with no discharge to surface waters.) 62-709.300(7)(b), 62-701.300(12)(b)	>			
10.26	Is processed material removed from facility within 18 months, unless longer storage authorized by permit? 62-709.330(2)	>			
10.27	Is the facility accepting only yard trash, and bags used to collect yard trash and containerizing any other material? 62-709.330(3)	>			

Item No.	REQUIREMENTS AND PROHIBITIONS APPLICABLE TO ONLY THOSE FACILITIES THAT BLEND MANURE OR COMPOST VEGETATIVE WASTES, ANIMAL BYPRODUCTS OR MANURE Completed	Ok	Not Ok	Unk	N/A
10.28	Unauthorized storage or processing within 500 feet off-site potable water well that existed before facility registered? 62-709.300(7)(b) and 62-701.300(2)(b)				>
10.29	Unauthorized storage or processing within 200 feet from any body of water, including wetlands? (Does not include parts of permitted stormwater system, or water bodies totally within facility with no discharge to surface waters.) 62-709.300(7)(b), 62-701.300(2)(e)				>
10.30	Unauthorized storage or processing within 10,000 feet of any licensed and operating airport runway used by turbine powered aircraft, or within 5,000 feet of any licensed and operating airport runway used only by piston engine aircraft, unless applicant demonstrates that the facility is designed and will be operated so that it does not pose a bird hazard to aircraft? 62-709.300(7)(b), 62-701.320(13)(b)				>
10.31	Is the carbon:nitrogen ratio of the blended feedstocks greater than 20? 62-709.350(2)				~
10.32	Do piles exceed 12 feet in height? 62-709.350(3)				~
10.33	Is all material removed within 18 months, unless longer storage authorized by permit? 62-709.350(5)				~
10.34	Is there documentation showing that disinfection has been achieved? Note that this is not required if they are composting only pre-consumer vegetative waste with or without yard trash. 62-709.350(6)				>
10.35	Is there vector attraction reduction controls that include one of the following? 62-709.350(7) Temperature monitoring records showing the waste was composted for at least 14 days, with temperature no lower than 40 degrees Celsius and average temperature of the material being composted higher than 45 degrees Celsius. or 62-709.350(7)(a) Results of testing showing the specific oxygen uptake rate (SOUR) for material being composted or blended equal to or less than 1.5 milligrams				>

	REQUIREMENTS AND PROHIBITIONS APPLICABLE TO ONLY THOSE FACILITIES THAT BLEND MANURE OR COMPOST VEGETATIVE WASTES, ANIMAL BYPRODUCTS OR MANURE Completed	Ok	Not Ok	Unk	N/A
10.35	of oxygen per hour per gram of total solids (dry weight basis) at a temperature of 20 degrees Celsius. 62-709.350(7)(b)				~

Current Areas Of Concern:

Rule: 62-701.510(3), 62-701.730(4)(c), 62-701.510(4), 62-713.400(3), 62-701.730(10)

Question Number: 1.6

Explanation: Well MW-10 exceeded the ground water standard for benzene and vinyl chloride since

the Jan. 2013 sampling event. Well MW-19 exceeded the ground water standard for benzene, vinyl chloride and methylene chloride for samples collected during Jan. 2015.

Background well MW-7 exceeded the ground water standard for benzene since the Jan.

2014 sampling event.

Corrective Action: Impacts to ground water quality shall be included in the monitoring plan evaluation

report required by Spec. Cond. #E.11.a., of permit #21375-018-SO/01, due Oct. 15,

2015, as part of the operating permit renewal application.

Rule: 62-701.500(7)(e)

Question Number: 2.18

Explanation: Inadequate alternate daily cover (ADC) was observed in the central portion of Phase III

footprint.

The absence of daily cover was observed in the eastern portion of the Phase III

footprint at the working face.

Corrective Action: E-mail received on July 31, 2015 from Dan Sherlock/Citrus County provided a schedule

for the application of adequate intermediate cover in Phase III within 30 days (by August

31, 2015).

E-mail received Aug. 14, 2015 from Larry Brock/Citrus County provided documentation

that additional intermediate cover was placed in Phase III.

Attachments:

Phase III Insufficent cover



CITRUS CENTRAL SLF Page 12 of 15

Inspection Date: 07/27/2015

Rule: 62-701.500(7)(f)

Question Number: 2.19

Explanation: See Section 2.18.

Corrective Action: See Section 2.18.

Rule: 62-701.500(10), 62-701.400(9)(b)

Question Number: 2.28

Explanation: Standing water/leachate was observed in the western portion of Phase III footprint in an

area with intermediate cover. Standing water/leachate was observed in the eastern

portion of Phase III footprint adjacent to the working face.

Corrective Action: E-mail received on July 31, 2015 from Dan Sherlock/Citrus County provided a schedule

for removal of standing water/leachate within Phase III within 30 days (by August 31, 2015). E-mail received Aug. 14, 2015 from Larry Brock/Citrus County provided documentation that standing water/leachate had been pumped to the leachate storage tanks. Please ensure that standing water/leachate within the Phase III footprint is pumped to the leachate collection system/leachate tanks for proper treatment/disposal.

Attachments:

Ponding Stromwater Phase III



Rule: 62-701.620(1)

Question Number: 3.6

Explanation: Two north-south oriented low areas were observed at the 7-acre cell. Standing water

was observed along the south portion of the 7-acre cell in these low areas. Additionally, visible damage to the final cover soil/vegetation was observed due to vehicular traffic.

Corrective Action: The need to perform repairs to the final cover system of the 7-acre cell to prevent

ponding within the disposal areas in accordance with Spec. Cond. #G.3.b., of permit

#21375-018-SO/01, as part of the operating permit renewal application.

Rule: 62-701.600(3)(f)4.

Question Number: 3.7

Explanation: See Section 3.6.

Corrective Action: See Section 3.6.

Rule: 62-701.600(3)(f)3.

Question Number: 3.8

Explanation: See Section 3.6.

Corrective Action: See Section 3.6.

Rule: 62-701.500(8)(h), 62-701.500(2)(j), 62-701.500(8)(b)

Question Number: 2.22

Explanation: Periodic notifications that the leakage action rate has been exceeded for the current

disposal area have been provided by Citrus County. The most recent notification received via e-mail dated August 12, 2015 indicated periods of time when the leakage

action rate was exceeded for both Phase II and Phase III during July 2015.

Corrective Action: The need for corrective actions to the leachate collection system shall be evaluated as

part of the operating permit renewal application.

COMMENTS:

08/14/2015

Item 1.9 -- The annual inflation-adjusted financial assurance cost estimate due by Sept. 1, 2015 (see Spec. Cond. #D.4.a., of permit #21375-018-SO/01) does not need to be submitted provided that the revised financial assurance cost estimates required to be included with the permit renewal application is submitted by Oct. 15, 2015.

Item 2.22 -- E-mail received Aug. 14, 2015 indicated the Phase III riser pipe relief valve had been repaired.

Item 10.16.1 -- It was indicated that Citrus County was working through the procurement process to hire a third party contractor to grind the accumulated yard waste.

Items 10.20 and 10.21 -- The current SOPF registration was valid until Aug. 1, 2015. Please ensure this registration has been renewed in a timely manner.

ATTACHMENTS:

7-Acre



Phase III Overview



SOPF



DRA 4



Phase III Overview



Supervisor: Steve Tafuni

Nick Roff	Inspector				
PRINCIPAL INSPECTOR NAME	PRINCIPAL INSPECTOR TITLE				
1hRoll	FDEP	8/28/2015			
PRINCIPAL INSPECTOR SIGNATURE	ORGANIZATION	DATE			
John Morris	Inspector				
INSPECTOR NAME	INSPECTOR TITLE				
NO SIGNATURE	FDEP				
INSPECTOR SIGNATURE	ORGANIZATION				
Larry Brock	Assistant Public Works Director				
REPRESENTATIVE NAME	REPRESENTATIVE TITLE				
NO SIGNATURE	Citrus County				
REPRESENTATIVE SIGNATURE	ORGANIZATION	 .			
Dan Sherlock	Hazardous Waste Coordinator				
REPRESENTATIVE NAME	REPRESENTATIVE TITLE				
NO SIGNATURE	Citrus County				
REPRESENTATIVE SIGNATURE	ORGANIZATION				

NOTE: By signing this document, the Site Representative only acknowledges receipt of this Inspection Report and is not admitting to the accuracy of any of the items identified by the Department as "Not Ok" or areas of concern.