

# Florida Department of Environmental Protection

Southwest District Office 13051 North Telecom Parkway Temple Terrace, FL 33637-0926 Rick Scott Governor

Carlos Lopez-Cantera Lt. Governor

Jonathan P. Steverson Secretary

July 20, 2016

Mr. Henry Norris, Jr., Director Division of Solid Waste Management Citrus County PO Box 340 Lecanto, FL 34460 <u>Henry.Norris@citrusbocc.com</u>

Re: Inspection Report and "1<sup>st</sup> Semiannual Compliance Monitoring Report" Consent Order #05-1078 Citrus County Central Class I Landfill and Closed Class I Landfill S.R. 44, Lecanto Citrus County

Dear Mr. Norris:

On June 27, 2016, the Department conducted an inspection of the referenced facility. During this inspection, possible violations of Chapter 403, F.S., and Chapter 62-701, Florida Administrative Code, were observed. Also, the Department received the "1<sup>st</sup> Semiannual Compliance Monitoring Report" dated June 13, 2016. Based on the inspection and review of the referenced report, the Department would like to discuss concerns regarding potential non-compliance issues, which include impacts to groundwater, the management of land-fill gas, and stormwater management.

We look forward to resolving these concerns with you. Please contact John Morris at 813-470-5751 or via email at: John.R.Morris@dep.state.fl.us within 7-days of receipt of this letter to schedule a meeting regarding these concerns.

Sincerely,

Kelley M. Bootwagth

Kelley M. Boatwright Assistant Director Southwest District Florida Department of Environmental Protection

KMB/

Cc: Steven Tafuni, FDEP, <u>Steven.tafuni@dep.state.fl.us</u> John Morris, FDEP, <u>John.R.Morris@dep.state.fl.us</u>

Enclosure: Inspection Report

www.dep.state.fl.us



# **FACILITY INFORMATION:**

**Facility Name:** CITRUS CENTRAL SLF **On-Site Inspection Start Date:** 06/27/2016 **On-Site Inspection End Date:** 06/27/2016 WACS No.: 39859 Facility Street Address: 3MI E LECANTO, SR44 City: LECANTO **County Name:** CITRUS Zip: 34461 **INSPECTION PARTICIPANTS:** (Include ALL Landfill and Department Personnel with Corresponding Titles) Principal Inspector: Nick Roff, Inspector Other Participants: Melissa Madden, Inspector; Henry Norris Jr., Director

# **INSPECTION TYPE:**

Routine Operation Inspection for Landfill - Class I facility Routine Operation Inspection for WPF - Waste Tire Processing Facility Routine Operation Inspection for WPF - Source-Separated Organics Proc Fac (SOPF) facility

# ATTACHMENTS TO THE INSPECTION CHECK LIST:

This Cover Page to the Inspection Checklist may include any or all of the following attachments as appropriate.

SECTION 1.0 - FILE REVIEW SECTION 2.0 - LANDFILL OPERATION AND MAINTENANCE SECTION 3.0 - LANDFILL - CLOSED SECTION 9.0 - WASTE TIRE FACILITIES SECTION 10.0 - REGISTERED SOURCE-SEPARATED ORGANICS PROCESSING FACILITIES

#### **SECTION 1.0 - FILE REVIEW**

#### Requirements:

ltem No.	FILE REVIEW (Pre- or Post-Inspection, as appropriate.) Completed	Ok	Not Ok	Unk	N/A
1.1	For landfills and C&D disposal facilities, does the facility have a current plan for the method and sequence of filling wastes? 62-701.500(2)(f) for landfills; 62-701.730(7)(a) for C&D debris sites	~			
1.2	For landfills, are the following records being reported to the Department?(Check any that are Not OK)           Waste reports (annually) 62-701.500(4)           Annual estimate of remaining life 62-701.500(13)(c)	>			
1.3	Is gas monitoring being performed as required by the permit? 62-701.500(9), 62-701.530(2)	~			
1.4	Are the results of the gas sampling reported to the Department quarterly? 62-701.530(2)(c)	~			
1.5	Is water quality sampling and testing performed according to standard procedures and at the required frequencies? 62-701.510(2) for landfills; 62-701.730(8) and 62-701.730(10) for C&D debris sites; 62-713.400(3) for stationary soil treatment facilities.	>			
1.6	Do the results of the water quality testing suggest there may be adverse impacts to water quality from the operation of the solid waste facility? 62-701.510(3) and (4); 62-701.730(4)(c) and (10) for C&D debris sites; 62-713.400(3) for stationary soil treatment facilities.		~		
1.7	For closed landfills and C&D disposal facilities with final elevations higher than 20 feet above grade, has a final survey report verifying the final elevations and contours of the facility been submitted to the Department? 62-701.600(6)(b), 62-701.730(9)(e)	~			
1.8	Is financial assurance adequate? 62-701.630 for landfills; 62-701.710(7)(a) and 62-701.710(1)(d)1. for waste processing facilities; 62-701.730(11)(a) for C&D debris facilities; 62-713.600(6)(a) for stationary soil treatment facilities; 62-711.500(3) for waste tire facilities. NOTE: The Solid Waste Financial Coordinator in Tallahassee can assist with this information.	~			
1.9	Are cost estimates current and adjusted every year? 62-701.630(4) for landfills; 62-701.710(7)(a) and 62-701.710(1)(d)1. for waste processing facilities; 62-701.730(11)(a) for C&D debris facilities; 62-713.600(6)(b) and 62-713.600(6)(c) for stationary soil treatment facilities; 62-711.500(3) for waste tire facilities.	~			
1.10	For C&D debris disposal and disposal with recycling facilities, is an Annual Report submitted to the Department for the disposal operation by February 1st of each year? 62-701.730(12)				>
1.11	For C&D recycling facilities with no disposal, is an Annual Report for the recycling facility submitted to the Department by February 1st of each year? 62-701.710(8)(b)				~
1.12	For compost facilities, has the compost product been sampled and analyzed every 20,000 tons or every 3 months (whichever is sooner)? 62-709.530(1)				~
1.13	For compost facilities, has the annual report been submitted by June 1st? 62-709.530(3)				~

# SECTION 2.0 - LANDFILL OPERATION AND MAINTENANCE

#### **Requirements:**

Item No.	SOLID WASTE PROHIBITIONS (unless "grandfathered" in, see 62- 701.300(18)) Completed	Ok	Not Ok	Unk	N/A
211	Unauthorized storage, processing, or disposal of solid waste except as authorized at a permitted solid				
2.1.1	waste management facility or other exempt facility. 62-701.300(1)(a)	~			
2.1.2	Unauthorized disposal or storage prohibited, except yard trash, within 500 feet of a potable water well? 62-701.300(2)(b)	>			
2.2	Unauthorized storage or disposal of yard trash prohibited within the minimum setbacks of (Check any that are Not OK) 62-701.300(12) 100 feet from potable water wells (except on-site)? 50 feet from water bodies?	*			
2.3	Unauthorized disposal or storage prohibited in any natural or artificial body of water including ground water and wetlands? (Does not apply to standing water after a storm event.) 62-701.300(2)(d)	~			
2.4	Unauthorized disposal or storage prohibited, except yard trash, within 200 feet of any natural or artificial body of water, including wetlands without permanent leachate controls, except impoundments or conveyances which are part of an on-site, permitted stormwater management system or on-site water bodies with no off-site discharge? 62-701.300(2)(e)	>			
2.5	Unauthorized open burning of solid waste prohibited except in accordance with Department requirements? 62-701.300(3)	>			
2.6	Are the following unauthorized wastes or special wastes properly controlled, managed and disposed? (Check any that are Not OK)				
	Hazardous waste 62-701.300(4)				
	Biomedical waste 62-701.300(6)				
	Yard trash 62-701.300(8)(c)				
	Whole waste tires 62-701.300(8)(e)				
	Regulated asbestos waste 62-701.520(3), 62-701.730(19)	2			
	Used oil and oily wastes, except as exempted 62-701.300(11)	×			
	PCB wastes 62-701.300(5)				
	Lead-acid batteries 62-701.300(8)(a)				
	White goods 62-701.300(8)(d)				
	Liquids 62-701.300(10)				
	CCA treated wood 62-701.300(14)				
2.7	Are only permitted waste types disposed at facility? 62-701.340(2), 62-701.500(6)(a), 62-701.500(2)(c)	~			

ltem No.	LANDFILL OPERATION AND MAINTENANCE Completed	Ok	Not Ok	Unk	N/A
2.8	Is there a trained operator on-site at Class I and III landfills when receiving wastes? 62-701.500(1)	>			
2.9	Is there at least one trained spotter at each working face when receiving wastes at Class I and III landfills? 62-701.500(1)	>			
2.10	Are the following records or plans current and available on-site? (Check any that are Not OK)  Training Plan 62-701.320(15)(a)  Operating Plan 62-701.500(2)  Waste weight records 62-701.500(4)  Precipitation records 62-701.500(8)(g)	>			

ltem No.	LANDFILL OPERATION AND MAINTENANCE Completed	Ok	Not Ok	Unk	N/A
2.10	Load-checking program records 62-701.500(6)(a)				
	Training records 62-701.320(15)(a)	93			
	Operation record 62-701.500(3)	~			
	Quantity of leachate 62-701.500(8)(f)				
2.11	Is the operation plan substantially followed? 62-701.500(2)	~			
2.12	Is incoming waste weighed? 62-701.500(4)(a) and 62-701.500(2)(d)	~			
2.13	Is the method and sequence of filling waste according to plans? 62-701.500(2)(f)	~			
2.14	Is access properly controlled to prevent unauthorized waste disposal? 62-701.500(5)	~			
2.15	Is waste compacted as required? 62-701.500(7)(a)	~			
2.16	Are the working face and side slopes above ground graded to a slope no greater than 3 feet horizontal to 1 foot vertical rise? 62-701.500(7)(c)	~			
2.17	Is a narrow working face practiced? 62-701.500(7)(d)	<			
2.18	Is the frequency, amount and quality of initial cover, as required? 62-701.500(7)(e)	~			
2.19	Is the frequency, amount and quality of intermediate cover, as required? 62-701.500(7)(f)	~			
2.20	Is litter controlled and are litter control devices maintained? 62-701.500(7)(i) and 62-701.500(11)(f)	~			
2.21	Is erosion control adequate? 62-701.500(7)(j)	<			
2.22	Is the leachate collection and removal system maintained and operated as required? 62-701.500(2)(j), 62-701.500(8)(b) and 62-701.500(8)(h)	~			
2.23	Is leachate disposed of or treated as required? 62-701.500(8)(b), 62-701.500(8)(c) and 62- 701.500(8)(d)	~			
2.24	If leachate recirculation is practiced at the facility, is it done in accordance with Department requirements and the Operation Plan? 62-701.400(5)				~
2.25	Is gas controlled to not cause objectionable odors beyond the property boundary? 62-701.530(3)(b)	~			
2.26	Is gas controlled to not allow combustible gas concentrations to exceed specified limits? 62- 701.530(3)(a)	~			
2.27	Are gas vents intact and functioning properly? 62-701.500(9), 62-701.530(1)(a)3		~		
2.28	Is mixing of leachate and stormwater prevented or minimized? 62-701.500(10), 62-701.400(9)(b)		~		
2.29	Is stormwater management system maintained and operated as required? 62-701.500(10)	~			
2.30	Is there sufficient operating equipment? 62-701.500(11)(a)	~			
2.31	Is there sufficient reserve equipment (or other arrangements)? 62-701.500(11)(b)	~			
2.32	Are communication facilities adequate? 62-701.500(11)(c)	~			
2.33	Are approved dust control methods adequate? 62-701.500(11)(d)	~			
2.34	Are fire protection and fire fighting capabilities adequate and operational? 62-701.500(11)(e)	~			
2.35	Are there required signs for operational directions and public information? 62-701.500(11)(g)	~			
2.36	Are all-weather access roads and inside perimeter roads properly maintained? 62-701.500(12)	~			
2.37	Are groundwater wells intact and properly maintained? 62-701.510(2)(b), 62-701.620(8)	~			
2.38	Are all additional specific conditions (not otherwise addressed above) in the permit, Department order, or certification, if any, being followed? 62-701.320(1), 403.161, F.S.	~			

# **SECTION 3.0 - LANDFILL - CLOSED**

#### Requirements:

Type of Cover:	7-acre re-closure 12" soil, 40-mil LLDPE, 24" soil & veg
Closure/Final Cover Date:	
Post-Closure Utilization:	Sheriff Training Facility
Surrounding Land Use:	Recreation (State Forest), Commercial and Residential
Date Long-Term Care Began:	

ltem No.	LANDFILL - CLOSED Completed	Ok	Not Ok	Unk	N/A
3.1	Is site access controlled to prevent any unauthorized dumping? 62-701.600(3)(i)	~			
3.2	Are any unauthorized wastes stored or disposed at the site? 62-701.600(3)(i)	~			
3.3	Is stormwater management system maintained and operated as required? 62-701.600(3)(h)	~			
3.4	Is the final cover properly vegetated? 62-701.600(3)(f)2	~			
3.5	Are there any signs of erosion of the final cover? 62-701.620(1)	~			
3.6	Is there any evidence of damage to the barrier layer of the final cover? 62-701.620(1)	~			
3.7	Are areas of differential settlement being properly filled? 62-701.600(3)(f)4	~			
3.8	Are there any areas of ponding water on the final cover? 62-701.600(3)(f)3	~			
3.9	Is the leachate collection and removal system maintained and operated as required? 62- 701.500(2)(j), 62-701.500(8)(b) and 62-701.500(8)(h)	~			
3.10	Is leachate disposed of or treated as required? 62-701.500(8)(b), 62-701.500(8)(c) and 62- 701.500(8)(d)	~			
3.11	Are there any signs of leachate seeps at the closed landfill? 62-701.500(8)(b), 62-701.620(1)	~			
3.12	Condition of the ground water monitoring wells in accordance with the ground water monitoring plan. 62-701.620(1) (Check any that are Not OK) Access to monitoring wells Damage to monitoring wells Monitoring wells protected, secured and labeled.	~			
3.13	Are the wells for gas monitoring and detection intact and operable? 62-701.620(5)	~			
3.14	Is the gas collection system (active or passive) operating and maintained? 62-701.620(5)          Signs of stressed vegetation         Odors or foul smells	~			
3.15	Is gas monitoring being conducted as required? 62-701.620(5)	~			
3.16	Is there any evidence that gas pressure is interfering with or causing failure of the final cover? 62- 701.530(1)(a)4	~			
3.17	If required, are survey monuments properly installed? 62-701.600(6)	~			
3.18	Is there a potential hazard to public health and the environment resulting from the post-closure utilization of the solid waste disposal facilities or surrounding land-use changes? 62-701.610(1)	~			
3.19	If waste is being relocated, is this performed according to the Department's requirements? 62- 701.610(2)				~
3.20	Are all additional specific conditions (not otherwise addressed above) in the closure or permit for long -term care, Department order, or certification, if any, being followed? 62-701.620(2), 403.161, F.S.	~			

Item No.	LANDFILL - CLOSED Completed	Ok	Not Ok	Unk	N/A
3.20		>			

# **SECTION 9.0 - WASTE TIRE FACILITIES**

#### Requirements:

ltem No.	SOLID WASTE PROHIBITIONS (unless "grandfathered" in, see 62- 701.300(18)) Completed	Ok	Not Ok	Unk	N/A
9.1.1	Unauthorized storage, processing, or disposal of solid waste except as authorized at a permitted solid waste management facility or other exempt facility? 62-701.300(1)(a)	~			
9.1.2	Unauthorized disposal or storage prohibited, except yard trash, within 500 feet of a potable water well? 62-701.300(2)(b)	~			
9.2	Unauthorized storage or disposal of yard trash prohibited within the minimum setbacks of (Check any that are Not OK) 62-701.300(12) 100 feet from potable water wells (except on-site)? 50 feet from water bodies?	*			
9.3	Unauthorized disposal or storage prohibited in any natural or artificial body of water including ground water and wetlands? (Does not apply to standing water after a storm event) 62-701.300(2)(d)	>			
9.4	Unauthorized disposal or storage prohibited, except yard trash, within 200 feet of any natural or artificial body of water, including wetlands without permanent leachate controls, except impoundments or conveyances which are part of an on-site, permitted stormwater management system or on-site water bodies with no off-site discharge? 62-701.300(2)(e)	>			
9.5	Unauthorized open burning of solid waste prohibited except in accordance with Department requirements? 62-701.300(3)	~			

ltem No.	WASTE TIRE FACILITY - GENERAL REQUIREMENTS FOR STORAGE Completed	Ok	Not Ok	Unk	N/A
9.6	If the facility accepts tires from the public, is a sign posted at the facility entrance stating operating hours, cost of disposal and site rules? 62-711.540(1)(a)	~			
9.7	Are operations involving the use of open flames conducted no closer than 25 feet of a waste tire pile? 62-711.540(1)(b)				~
9.8	If the facility accepts tires from the public, is an attendant always present on site when the site is open for business? 62-711.540(1)(c)	>			
9.9	Are fire protection services assured through notification to local fire protection authorities? 62- 711.540(1)(d)	~			
9.10	Is an annual fire safety survey conducted? 62-711.540(1)(d)	~			
9.11	Is a copy of the annual fire safety report made part of the next quarterly report? 62-711.540(1)(d)	>			
9.12	Does the facility have an Emergency Preparedness Manual (EPM) on-site? 62-711.540(1)(e)	~			
9.13	Does the EPM contain the following information? (Check all that are Not OK)         Contact names and numbers 62-711.540(1)(e)1         List of emergency response equipment and locations on-site 62-711.540(1)(e)2         Procedures to be followed in the event of a fire 62-711.540(1)(e)3	>			
9.14	Is the operator at the facility maintaining records of the quantity of waste tires received at the site, stored at the site, and shipped from the site? 62-711.540(1)(g) and 62-711.400(5)	>			
9.15	If the operator of the site is not the owner of the property, has written authorization been obtained from the property owner to operate the facility? 62-711.540(1)(h)				~
9.16	Is adequate communications equipment available at the site? 62-711.540(1)(i)	>			
9.17	Is the owner or operator providing for control of mosquitoes and rodents so as to protect the public health and welfare? $62-711.540(1)(j)$	>			
•			Net		

ltem No.	WASTE TIRE FACILITY - STORAGE INDOORS Completed	Ok	Not Ok	Unk	N/A	
NO.			UK			

ltem No.	WASTE TIRE FACILITY - STORAGE INDOORS Completed	Ok	Not Ok	Unk	N/A
9.18	Are waste tire piles more than 50 feet in width? 62-711.540(2)(a)				~
9.19	Are waste tire piles along a wall more than 25 feet in width? 62-711.540(2)(a)				~
9.20	Are widths of main aisles between piles less than 8 feet? 62-711.540(2)(b)				~
9.21	Is there less than 3 feet of clearance between the top of storage to sprinkler detectors or roof structures? 62-711.540(2)(c)				~
9.22	Is there less than 3 feet of clearance between waste tire piles and unit heaters, etc.? 62- 711.540(2)(d)				>
9.23	If waste tires are stored up to 15 feet high, do walls between adjacent warehouse areas and between manufacturing and warehouse areas have at least a four-hour fire rating? 62-711.540(2)(e)				>
9.24	If waste tires are stored over 15 feet high, do walls between manufacturing and warehouse areas have a fire rating of not less than six hours and do steel columns have one-hour fireproofing? If the top of storage exceeds 20 feet in height, do columns and their connections with other structural members have two-hour fireproofing? 62-711.540(2)(f)				>
9.25	Is the access controlled through the use of doors, fences, gates, natural barriers or other means? 62-711.540(2)(h)				>

Item No.	WASTE TIRE FACILITY - STORAGE OUTDOORS Completed	Ok	Not Ok	Unk	N/A
9.26	Is the waste tire site operated within 200 feet from a body of water? 62-711.540(3)(a)	~			
9.27	Does the waste tire pile have a width less than 50 feet? 62-711.540(3)(b)	~			
9.28	Does the waste tire pile have an area less than 10,000 sq. ft? 62-711.540(3)(b)	~			
9.29	Does the waste tire pile have a height less than 15 feet? 62-711.540(3)(b)	~			
9.30	Is there a 50 feet wide fire lane around the perimeter of the waste tire pile? 62-711.540(3)(c)	~			
9.31	Is there unobstructed access to the fire lane? 62-711.540(3)(c)	~			
9.32	Is the access controlled through the use of doors, fences, gates, natural barriers or other means? 62- 711.540(3)(d)	~			
9.33	Is the site kept free of grass, underbrush, and other potentially flammable vegetation? 62- 711.540(3)(f)	~			
9.34	Is the site bermed or given other adequate protection to prevent liquid runoff from entering water bodies? 62-711.540(3)(e)	~			
9.35	Are residuals contained on-site and disposed of in a permitted solid waste management facility or properly recycled? 62-711.540(5)	~			
9.36	Does the waste tire site qualify for the exceptions to the technical and operational standards as allowed by rule? 62-711.540(6)	~			

ltem No.	WASTE TIRE FACILITY - COLLECTION CENTER Completed	Ok	Not Ok	Unk	N/A
9.37	Are no more than 1,500 tires at the collection center at any one time? 62-711.550(1)(a)				~
9.38	Are all waste tires, which are not used tires, removed from site yearly for recycling, processing, or disposal? 62-711.550(1)(b)				~

#### SECTION 10.0 - REGISTERED SOURCE-SEPARATED ORGANICS PROCESSING FACILITIES

#### **Requirements:**

FACILITY TYPE(S)	MATERIAL(S) PROCESSED	PRODUCES	METHOD OF COMPOSTING
Yard Trash Transfer Station	🔀 Yard Trash	🗙 Mulch	Windrow
X Yard Trash Recycling	Manure	Firewood	Passive aerated windrows
	Animal byproducts	Fuel	Aerated static piles
	Pre-consumer vegetative waste	Compost	In-vessel composting
	Vegetative waste	X Soil Amendment	
		Soil	
		Other	
Item REQUIREMENT	S AND PROHIBITIONS APPLICAE	RIE TO ALL REGISTERED	)   Ok   Not   Unk   N/A

No.	SOURCE-SEPARATED ORGANICS PROCESSING FACILITIES Completed	OK	Ok	onix	
10.1	Unauthorized storage, processing, or disposal of solid waste except as authorized at a permitted or registered solid waste management facility or other exempt facility? 62-701.300(1)(a)	~			
10.2	Have objectionable odors been caused or allowed in violation of Chapter 62-296, F.A.C.? 62-709.300(7)(a)	>			
10.3	Unauthorized storage or processing in a way or location that violates air quality or water quality standards? 62-709.300(7)(b), 62-701.300(1)(b)	~			
10.4	Do geological formations or subsurface features provide support for the facility? 62-709.300(7)(b), 62-701.300(2)(a)	>			
10.5	Unauthorized disposal or storage prohibited, except yard trash, within 200 feet of any natural or artificial body of water, including wetlands without permanent leachate controls, except impoundments or conveyances which are part of an on-site, permitted stormwater management system or on-site water bodies with no off-site discharge? 62-701.300(2)(e), 62-709.320(3)	>			
10.6	Unauthorized storage or processing in any natural or artificial water body (e.g. ground water and wetlands within DEP jurisdiction)? 62-709.300(7)(b), 62-701.300(2)(d)	>			
10.7	Unauthorized storage or processing on the right of way of any public highway, road, or alley? 62-709.300(7)(b), 62-701.300(2)(f)	>			
10.8	Unauthorized open burning of solid waste except in accordance with Department requirements? 62-709.300(7)(b), 62-701.300(3)	>			
10.9	Unauthorized incorporation of CCA treated wood into material that will be applied as a ground cover, soil or soil amendment? 62-709.300(7)(b), 62-701.300(14)	>			
10.10	Unauthorized unconfined emissions of particulate matter in violation of paragraph 62-296.320(4)(c), F.A.C.? 62-709.300(7)(b), 62-701.300(15)	>			
10.11	Does the facility have the necessary operational features and equipment - unless otherwise specified? Including: 62-709.320(2)(a)				
10.11.1	Effective barrier to prevent unauthorized entry and dumping? 62-709.320(2)(a)1	>			
10.11.2	Dust and litter control methods? 62-709.320(2)(a)2	~			
10.12	Does the facility have the necessary fire protection and control provisions to deal with accidental burning of solid waste? Including 62-709.320(2)(a)3				
10.12.1	20-foot all-weather access road all around the perimeter? 62-709.320(2)(a)3.a.		>		
10.12.2	No material mechanically compacted? 62-709.320(2)(a)3.b.	>			
10.12.3	No material more than 50 feet from access by motorized firefighting equipment? 62-709.320(2)(a)3.c.	>			
10.13	Is the facility operated in a manner to control vectors? 62-709.320(2)(b)	>			
10.14	Is the facility operated in a manner to control objectionable odors per with Rule 62-296.320(2), F.A.C.? 62-709.320(2)(c)	~			
10.15	Are any installed drains and leachate or condensate conveyances kept cleaned? 62-709.320(2)(d)				<
10.16	Is the received solid waste processed timely as follows? 62-709.320(2)(e)				

ltem No.	REQUIREMENTS AND PROHIBITIONS APPLICABLE TO ALL REGISTERED SOURCE-SEPARATED ORGANICS PROCESSING FACILITIES Completed	Ok	Not Ok	Unk	N/A
10.16					
10.16.1	Is yard trash size-reduced or removed within 6 months or time needed to receive 3,000 tons or 12,000 cubic yards, whichever is greater? (Separated logs with 6 inch diameter or greater can be stored for up to 12 months before being size-reduced or removed.) 62-709.320(2)(e)1	~			
10.16.2	Is putrescible waste (e.g. vegetative wastes, animal byproducts or manure) processed and incorporated into the composting material, or removed from the facility, within 48 hours? 62-709.320(2)(e)2	~			
10.17	Is any treated or untreated biomedical waste; hazardous waste; or any materials having (PCB) concentration of 50 ppm or greater containerized and removed immediately? 62-709.320(2)(f), 62-701.300(4), 62-701.300(5), 62-701.300(6)	~			
10.18	Have all residuals, solid waste and recyclable materials been removed and recycled or disposed and has any remaining processed material been properly used or disposed upon the facility ceasing operations? 62-709.320(2)(g)	~			
10.19	If temperature is used to show disinfection or vector attraction achieved, are records kept for at least three years? 62-709.320(4)(b)				~
10.20	Is the registration for the facility current and on file with the Department? 62-709.320(3)(b)	~			
10.21	Are renewal applications for annual registration of the facility submitted to the Department by July 1st, if applicable? 62-709.320(3)(c)	~			
10.22	Are monthly records of incoming and outgoing material kept on-site or at another location as indicated on the registration form for at least three years? 62-709.320(4)(a)	>			
10.23	Are Annual Reports, based upon the preceding calendar year, summarizing monthly records, submitted to the Department as required? 62-709.320(4)(a)	~			
Item	REQUIREMENTS AND PROHIBITIONS APPLICABLE TO YARD TRASH	Ok	Not	Unk	N/A

No.	ONLY FACILITIES Completed	UK	Ok	UNK	N/A
10.24	Unauthorized storage or processing within 100 feet from off-site potable water well that existed before facility registered? 62-709.300(7)(b) and 62-701.300(12)(a)	>			
10.25	Unauthorized storage or processing within 50 feet from any body of water, including wetlands? (Does not include parts of permitted stormwater system, or water bodies totally within facility with no discharge to surface waters.) 62-709.300(7)(b), 62-701.300(12)(b)	>			
10.26	Is processed material removed from facility within 18 months, unless longer storage authorized by permit? 62-709.330(2)	>			
10.27	Is the facility accepting only yard trash, and bags used to collect yard trash and containerizing any other material? 62-709.330(3)	<			

ltem No.	REQUIREMENTS AND PROHIBITIONS APPLICABLE TO ONLY THOSE FACILITIES THAT BLEND MANURE OR COMPOST VEGETATIVE WASTES, ANIMAL BYPRODUCTS OR MANURE Completed	Ok	Not Ok	Unk	N/A
10.28	Unauthorized storage or processing within 500 feet off-site potable water well that existed before facility registered? 62-709.300(7)(b) and 62-701.300(2)(b)				<
10.29	Unauthorized storage or processing within 200 feet from any body of water, including wetlands? (Does not include parts of permitted stormwater system, or water bodies totally within facility with no discharge to surface waters.) 62-709.300(7)(b), 62-701.300(2)(e)				<
10.30	Unauthorized storage or processing within 10,000 feet of any licensed and operating airport runway used by turbine powered aircraft, or within 5,000 feet of any licensed and operating airport runway used only by piston engine aircraft, unless applicant demonstrates that the facility is designed and will be operated so that it does not pose a bird hazard to aircraft? 62-709.300(7)(b), 62-701.320(13)(b)				<
10.31	Is the carbon:nitrogen ratio of the blended feedstocks greater than 20? 62-709.350(2)				<
10.32	Do piles exceed 12 feet in height? 62-709.350(3)				<
10.33	Is all material removed within 18 months, unless longer storage authorized by permit? 62-709.350(5)				<
10.34	Is there documentation showing that disinfection has been achieved? Note that this is not required if they are composting only pre-consumer vegetative waste with or without yard trash. 62-709.350(6)				~
10.35	Is there vector attraction reduction controls that include one of the following? 62-709.350(7)  Temperature monitoring records showing the waste was composted for at least 14 days, with temperature no lower than 40 degrees Celsius and average temperature of the material being composted higher than 45 degrees Celsius. or 62-709.350(7)(a)  Results of testing showing the specific oxygen uptake rate (SOUR) for material being composted or blended equal to or less than 1.5 milligrams				>

	REQUIREMENTS AND PROHIBITIONS APPLICABLE TO ONLY THOSE FACILITIES THAT BLEND MANURE OR COMPOST VEGETATIVE WASTES, ANIMAL BYPRODUCTS OR MANURE Completed	Ok	Not Ok	Unk	N/A
10.35	of oxygen per hour per gram of total solids (dry weight basis) at a temperature of 20 degrees Celsius. 62-709.350(7)(b)				~

# **Current Violations:**

Rule:	62-701.510(4), 62-701.510(3), 62-701.730(10), 62-713.400(3), 62-701.730(8)(f)
Question Number:	1.6
Explanation:	In the "1st SA 2016 Groundwater Monitoring Report" (GWMR) indicated that the most likely source of VOC's in Ground water is attributed to the presence of landfill gas specifically in MW-7 (BG), MW-19 (AS), and MW-21 (CO). The report also indicated that the groundwater quality in the vicinity of MW-7 was not attributed to a discharge of leachate from the lined disposal area (Phase I/IA/II/III). Additionally this report indicated impacts to groundwater quality in MW-7 were not from an offsite source.
Corrective Action:	Supplemental assessment activities need to be completed/ implemented adjacent to MW-19 to define the vertical extent of groundwater impacts, in accordance with Consent Order (CO) #05-1078. The occurrence of groundwater impacts at locations not addressed by the CO # 05-1078 (MW-7 & MW-21) also need to be evaluated.

# **Current Areas Of Concern:**

Rule:	62-701.500(10), 62-701.400(9)(b)
Question Number:	2.28
Explanation:	During the most inspection, a sump area was observed that collected water from cell-3. A pump was observed that is being used to move water out of sump area into a Stormwater conveyance which in turn flows to DRA-4 (it shall be noted that this Stormwater conveyance runs within close proximity of MW-7 (BG). Observed a small amount of miscellaneous litter located in the sump.
Corrective Action:	The facility should take care to ensure that only non-contact water is being discharged to the Stormwater management system.
Rule:	62-709.320(2)(a)3.a.
Question Number:	10.12.1
Explanation:	Access roads through the yard waste piles and around the yard waste piles appeared to be holding water. These access roads may be difficult for fire fighting equipment to effectively gain access.
Corrective Action:	Please ensure that all access roads through and around the SOPF area are able to be traveled on by emergency equipment.
Rule:	62-701.530(1)(a)3., 62-701.500(9)
Question Number:	2.27
Explanation:	The most recent gas monitoring event conducted at the perimeter gas probes (April 2016), reported a Zero percent LEL. However the "1st SA 2016 Groundwater Monitoring Report" (GWMR) indicated that a combustible gas concentration of 32% by volume was measured at well MW-7 (BG). The report also indicated that landfill gas collecting in MW-7 is most likely from migrating landfill gas.
Corrective Action:	The adequacy of the gas venting system in lined and unlined portions of the facility needs to be evaluated.

#### **Pre-existing Areas Of Concern:**

Rule:	62-701.510(4), 62-701.510(3), 62-701.730(10), 62-713.400(3), 62-701.730(8)(f)
Question Number:	1.6
Explanation:	Well MW-10 exceeded the ground water standard for benzene and vinyl chloride since the Jan. 2013 sampling event. Well MW-19 exceeded the ground water standard for benzene, vinyl chloride and methylene chloride for samples collected during Jan. 2015.
	Background well MW-7 exceeded the ground water standard for benzene since the Jan. 2014 sampling event.
Corrective Action:	Impacts to ground water quality shall be included in the monitoring plan evaluation report required by Spec. Cond. #E.11.a., of permit #21375-018-SO/01, due Oct. 15, 2015, as part of the operating permit renewal application.

#### **COMMENTS:**

#### 07/14/2016

Item 3.6: Please continue to monitor and maintain the portions of the landfill that have been closed, this includes but is not limited to preventing ponding water, damage to the barrier layer, repairing any differential settlement.

Item 9.17: Please continue to maintain the waste tire collection area and provide adequate treatment to prevent the presence of mosquito breeding.

#### ATTACHMENTS:

Cell-3 Overview



Cell-3 Stormwater Sump Area



Inspection Date: 06/27/2016

# MW-7 (BG)



DRA-4



GP-16



Inspection Date: 06/27/2016

# Signed:

Nick Roff	Inspector				
PRINCIPAL INSPECTOR NAME	PRINCIPAL INSPECTOR TITLE				
And Red B	FDEP	7/11/2016			
PRINCIPAL INSPECTOR SIGNATURE	ORGANIZATION	DATE			
Melissa Madden	Inspector				
INSPECTOR NAME	INSPECTOR TITLE				
NO SIGNATURE	FDEP				
INSPECTOR SIGNATURE	ORGANIZATION	-			
Henry Norris Jr.	Director				
REPRESENTATIVE NAME	REPRESENTATIVE TITLE				
NO SIGNATURE	Citrus county Division of Solid Waste				
REPRESENTATIVE SIGNATURE	Management ORGANIZATION	-			

# Supervisor: <u>Steve Tafuni</u>

NOTE: By signing this document, the Site Representative only acknowledges receipt of this Inspection Report and is not admitting to the accuracy of any of the items identified by the Department as "Not Ok" or areas of concern.