

## Hunter, Wendy

---

**From:** Kim Montis <kmontis@daytonandrews.com>  
**Sent:** Monday, April 3, 2023 1:00 PM  
**To:** Hunter, Wendy  
**Subject:** [X-TRN] RE: Non-Compliance ICECAP Letter DRC - Dayton Andrews - FAC ID #528630965  
**Attachments:** FDEP-Facility Id # 528630965-Repair Pictures.pdf

**Please see attached repairs done.**

Thank you,

Kim Montis  
Controller  
Dodge City Inc  
Dayton Andrews DCJR  
2301 34th Street North  
St Petersburg FL 33713  
727-321-0500 ext 3346  
727-432-3188 cell  
[kmontis@daytonandrews.com](mailto:kmontis@daytonandrews.com)

---

**From:** Hunter, Wendy <WHunter@NorthStar.com>  
**Sent:** Monday, March 27, 2023 10:18 AM  
**To:** Kim Montis <kmontis@daytonandrews.com>  
**Cc:** Busen, Kenneth <Kenneth.Busen@dep.state.fl.us>; philip.wilkerson@floridadep.gov; Porto, Janice <Janice.Porto@FloridaDEP.gov>  
**Subject:** Non-Compliance ICECAP Letter DRC - Dayton Andrews - FAC ID #528630965

Dear Ms. Montis,

Attached is a letter of non-compliance that includes the results of the March 21, 2023, inspection at the subject facility. Please contact me if you have questions.

Sincerely,

**Wendy Hunter**

Site Manager

FDEP Petroleum Restoration Program, Team 5

**NorthStar Contracting Group, Inc.**

2760 S. Falkenburg Road

Riverview, Florida 33578

**813.684.4400, Ext 4829**

24 Hour Emergency Response: 800.283.2933


[www.NorthStar.com](http://www.NorthStar.com) | [whunter@NorthStar.com](mailto:whunter@NorthStar.com)

The World's Most Comprehensive Infrastructure & Environmental Solutions Company - **We Bring Answers.**

Confidentiality Note: This e-mail, and any attachment to it, contains privileged and confidential information intended only for the use of the individual(s) or entity named on the e-mail. If the reader of this e-mail is not the intended recipient, or the employee or agent responsible for delivering it to the intended recipient, you are hereby notified that reading it is strictly prohibited. If you have received this e-mail in error, please immediately return it to the sender and delete it from your system. Thank you.



Description of Photograph #3: A view of the two (2) breaches located.




Description of Photograph #4: A view of the two (2) breaches located.

SITE PHOTOGRAPHS PAGE 2 OF 4

FAC ID No: 528630965  
FDEP INSPECTOR: Rick Gonzalez  
FDEP MANAGER: Wendy Hunter-PRP-Team 5

DATE: 03/21/2023





Sent from my iPhone

