Smith, George

From: Gray, Walter < GrayW@HillsboroughCounty.ORG>

Sent: Thursday, October 13, 2016 2:05 PM **To:** SWD_Waste (Shared Mailbox)

Cc: Morgan, Steve; Cope, Ronald; Clark, Bruce

Subject: WACS ID SWD/29/41193-Southeast County Landfill- Gas Monitoring Report

Attachments: sclf gas monitoring rpt sept2016.pdf

Attached is the Landfill Gas Monitoring Report for the Southeast County Landfill. All recipients will receive this electronic copy only. Should you have any questions concerning the information provided, please call me. Thanks.

Walter J. Gray General Manager II

Public Works Department, Solid Waste Management Division

P: (813) 209 3059 M: (813) 731 5741

E: GrayW@HillsboroughCounty.org

W: HillsboroughCounty.org

Hillsborough County

332 N. Falkenburg Road, Tampa, FL 33619

Facebook | Twitter | YouTube | LinkedIn

Please note: All correspondence to or from this office is subject to Florida's Public Records law.



Public Works

October 11, 2016

Board of County Commissioners

Kevin Beckner
Victor D. Crist
Ken Hagan
Al Higginbotham
Lesley "Les" Miller, Jr.
Sandra L. Murman
Stacy R. White

County Administrator

Michael S. Merrill

County Administrator Executive Team

Lucia E. Garsys Carl S. Harness Gregory S. Horwedel Ramin Kouzehkanani Liana Lopez Bonnie M. Wise

Internal Auditor Peggy Caskey

County Attorney
Chip Fletcher

Public Works PO Box 1110 Tampa, FL 33601-1110 Phone: (813) 272-5912 Fax: (813) 272-5811 Mr. Steve Morgan
Solid Waste Permitting
Florida Department of Environmental Protection
Southwest District
13051 N. Telecom Pkwy
Temple Terrace, Florida 33637-0926

RE: Southeast County Landfill - Gas Monitoring Report

Dear Mr. Morgan:

In accordance with Specific Conditions E 4 of Permit No. 35435-022-SO/01, the Public Works Department, Solid Waste Management Division (SWMD) is submitting the quarterly landfill gas monitoring report for the Southeast County Landfill for the quarter ending October 15, 2016.

The monitoring was performed on September 14, 2016. The information includes the structure and the subsurface monitoring point gas sampling and results. No methane was detected at any of the sampling locations.

Please advise should you have any questions concerning the attached submittal.

Sincerely,

Landfill Operations Manager

Solid Waste Management Division

Attachment

xc: Kimberly Byer, PW
Walter Gray, PW
Dan Cooper, SCS Engineers
Ron Cope, EPC

HILLSBOROUGH COUNTY SOLID WASTE MANAGEMENT DEPARTMENT SOUTHEAST COUNTY LANDFILL - LFG READINGS

ADMINISTRATION BUILDING

	Methane Gas	LEL	Carbon Dioxide	Oxygen	Balance Gas
SP-1	0	0	0	20	80
SP-2	0	0	0	20	80
SP-3	0	0	0	20	80
SP-4	0	0	0	20	80
SP-5	0	0	0	20	80
SP-6	0	0	0	20	80
SP-7	0	0	0	20	80
SP-8	0	0	0	20	80

MAINTENANCE BUILDING

Methane Gas	LEL	Carbon Dioxide	Oxygen	Balance Gas
0	0	0	19.8	80.2
0	0	- 0	19.8	80.2
0	0	0	19.8	80.2
0	0	0	19.8	80.2
				Gas LEL Dioxide Oxygen 0 0 0 19.8 0 0 0 19.8 0 0 0 19.8 0 0 19.8

LEACHATE TREATMENT PLANT

	Methane Gas	LEL	Carbon Dioxide	Oxygen	Balance Gas
SP-13	0	0	0	19.7	20.3
SP-14	0	0	0	19.7	20.3
SP-15	0	0	0	19.7	20.3

LANDFILL GAS PERIMETER MONITOTING PONT

	Methane Gas	LEL	Carbon Dioxide	Oxygen	Balance Gas	Objectional Ambient Odor (Y/N)
LFG-1	0	0	0.1	19.6	80.3	N
LFG-2	0	0	3.9	16.7	79.4	N
LFG-3	0	0	4.2	17.6	78.8	N
LFG-4	0	0	1.8	18	80.2	N

TECHNICIAN SIGNATURE:	my Cull	
SUPERVISOR SIGNATURE:	vy E. fri	
DATE: 9/14/16		
COMMENTS:	W	
		_

Legend: SP = Ambient Sample Point