#### Smith, George

From:	Brent C Steele <brentc.steele@cemex.com></brentc.steele@cemex.com>
Sent:	Thursday, July 20, 2017 3:54 PM
То:	SWD_Waste
Subject:	CEMEX Quarterly Waste Tire Reports
Attachments:	BrS 2nd Quarter 2017 Waste Tire Report Submittal.pdf; BrN 2nd Quarter 2017 Waste Tire Report
	Submittal.pdf

Hi Javier,

Please find attached the quarterly waste tire reports for the second quarter of 2017 for both the CEMEX Brooksville South and Brooksville North cement plants. Please let me know if you need anything else.

Thanks, Brent



Environmental Manager - Brooksville South - United States of America Office: (352) 799-7881 ext.109 Fax: (352) 799-6088 Mobile: (352) 514-3683 Address: 10311 Cement Plant Road, Brooksville, FL 34601 e-Mail: brentc.steele@cemex.com www.cemexusa.com



This email message and any attachments are for the sole use of the intended recipient(s) and contain confidential and/or privileged information. Any unauthorized review, use, disclosure or distribution is prohibited. If you are not the intended recipient, please contact the sender by reply email and destroy all copies of the original message and any attachments. Thank you. CONFIDENTIALITY: The information contained in this transmission may contain privileged and confidential information. It is intended only for the use of the person(s) named above. If you are not the intended recipient, you are hereby notified that any review, dissemination, distribution or duplication of this communication, and the information contained in it, is strictly prohibited. If you are not the intended recipient, please contact the sender and immediately destroy all copies of the original message.



July 20, 2017

Electronic Submittal

Mr. Javier Ramirez Solid Waste Section Florida Department of Environmental Protection Southwest District 13051 N. Telecom Parkway Temple Terrace, FL 33637-0926

Re: CEMEX Construction Materials Florida, LLC, Brooksville North Cement Plant Waste Tire Processing Facility Quarterly Report, Permit No. 71066-006-WT/02, Facility ID No. SWD-27-40777

Dear Mr. Ramirez:

Please find enclosed the completed Waste Tire Processing Facility Quarterly Report prepared for the aforementioned facility, for the **2nd Quarter of 2017**. The Brooksville North Cement Plant was temporarily shut down on December 12, 2008 and remains closed, as of this report.

If there are any questions and/or comments concerning this submittal or you require additional information, please contact me at (352) 799-7881, ext 109 or brentc.steele@cemex.com.

Respectfully

Bran Sal

Brent Steele Environmental Manager

pc: Alberto Calleros, Plant Manager



# Department of Environmental Protection

DEP Form # <u>62-701.900(21)</u> Waste Tire Processing Facility Form Title <u>Quarterly Report</u> Effective Date <u>3/22/00</u>

## Waste Tire Processing Facility Quarterly Report

Pursuant to Rule 62-711.530, Florida Administrative Code, the owner or operator of a waste tire processing facility shall submit the following information to the Department quarterly.

Quarter covered by this report 4/1/17 - 6/30/17 (First quarter begins on January 1 of any given year)

1. Facility name: CEMEX Brooksville North Cement Plant

2. Facility mailing address: 13601 Ponce De Leon Blvd.

ville	County:	Hernando	Zip:	34614	
	line	County:	County: Tiernando	County: Lip: Zip:	County: Hemando Zip: 34014

3. Facility permit number: 71066-006-WT/02

4. Facility telephone number (352) 799-7881

5. Authorized person preparing report:

- 6. Affiliation with facility:
- 7. Telephone number (if different from above): (
- 8. Activity: Report in tons

	Beginning Inventory	Received	Processed	Consumed	Removed	Adjustments	Ending Inventory
Used Tires	0	0		0			0
Other whole Tires							
Processed tires							
Processing Waste							
Other							
Total			4				

a. Explain all inventory adjustments.

b. List any period in which one or more category of inventory exceeded the permitted maximum for that category. How was that condition relieved?

For any excess inventory at the end of the quarter, state how and when this condition will be relieved. Attach Additional sheets, if necessary.

9. Certification:

To the best of my knowledge and belief, I certify the information provided in this report is true, accurate, and complete.

**Brent Steele** 

Signature of Authorized Agent

07/20/17 Date

Mail complete form to the appropriate district office

Northwest District 160 Governmental Center Pensacola, FL 32501-5794 850-595-8360 Northeast District 7825 Baymeadows Way, Ste. 200 B Jacksonville, FL 32256-7590 904-448-4300

Print Name of Authorized Agent

Central District 3319 Maguire Blvd., Ste. 232 Orlando, FL 32803-3767 407-894-7555 Southwest District 3804 Coconut Palm Dr. Tampa, FL 33619 813-744-6100 South District 2295 Victoria Ave., Ste. 364 Fort Myers, FL 33902-2549 941-332-6975 Southeast District 400 North Congress Ave. West Palm Beach, FL 33401 561-681-6600



July 20, 2017

Electronic Submittal

Mr. Javier Ramirez Solid Waste Section Florida Department of Environmental Protection Southwest District 13051 N. Telecom Parkway Temple Terrace, FL 33637-0926

Re: CEMEX Construction Materials Florida, LLC, Brooksville South Cement Plant Waste Tire Processing Facility Quarterly Report Permit No. 22787-003-WT/02 Site Certification No. PA82-17Q

Dear Mr. Ramirez:

Please find enclosed the completed Waste Tire Processing Facility Quarterly Report prepared for the aforementioned facility, for the **2nd Quarter of 2017**.

If there are any questions and/or comments concerning this submittal or you require additional information, please contact me at (352) 799-7881, ext 109 or brentc.steele@cemex.com.

Respectfully

Ball

Brent Steele Environmental Manager

pc: Alberto Calleros, Plant Manager



# Department of Environmental Protection

DEP Form # <u>62-701.900(21)</u> Waste Tire Processing Facility Form Title <u>Quarterly Report</u>

Effective Date 3/22/00

DEP Application No. \_

(Filled in by DEP)

### Waste Tire Processing Facility Quarterly Report

Pursuant to Rule 62-711.530, Florida Administrative Code, the owner or operator of a waste tire processing facility shall submit the following information to the Department quarterly.

Quarter covered by this report 4/1/17 - 6/30/17 (First quarter begins on January 1 of any given year)

-1	E Illin	CEM
1.	Facility name:	OLIVI

EX Construction Materials Florida, LLC

2. Facility mailing address: 10311 Cement Plant Road

	City:	Brooksville	County:	Hernando	Zip:	34601	
3.	Facility p	ermit number:	22787-003-WT, PA82-1	17Q			

4. Facility telephone number (352) 799-7881

5. Authorized person preparing report:

- 6. Affiliation with facility:
- 7. Telephone number (if different from above):
- 8. Activity: Report in tons

	Beginning Inventory	Received	Processed	Consumed	Removed	Adjustments	Ending Inventory
Used Tires	37.25	1073.00		954.11	and any order and the set of the set of the	0.0	156.14
Other whole Tires							
Processed tires							
Processing Waste							
Other							
Total							

- a. Explain all inventory adjustments. 0.0 physical inventory
- b. List any period in which one or more category of inventory exceeded the permitted maximum for that category. How was that condition relieved?

For any excess inventory at the end of the quarter, state how and when this condition will be relieved. Attach Additional sheets, if necessary.

9. Certification:

To the best of my knowledge and belief, I certify the information provided in this report is true, accurate, and complete.

**Brent Steele** 

Signature of Authorized Agent

07/20/17 Date

Print Name of Authorized Agent

Mail complete form to the appropriate district office

Northwest District 160 Governmental Center Pensacola, FL 32501-5794 850-595-8360 Northeast District 7825 Baymeadows Way, Ste. 200 B Jacksonville, FL 32256-7590 904-448-4300 Central District 3319 Maguire Blvd., Ste. 232 Orlando, FL 32803-3767 407-894-7555 Southwest District 3804 Coconut Palm Dr. Tampa, FL 33619 813-744-6100 South District 2295 Victoria Ave., Ste. 364 Fort Myers, FL 33902-2549 941-332-6975 Southeast District 400 North Congress Ave. West Palm Beach, FL 33401 561-681-6600