

Florida Department of Environmental Protection

Central District 3319 Maguire Boulevard, Suite 232 Orlando, Florida 32803-3767 Rick Scott Governor

Carlos Lopez-Cantera Lt. Governor

> Noah Valenstein Secretary

January 12, 2018

Timothy Hawkins Waste Management Inc. of Florida 2700 Wiles Road Pompano Beach, Florida 33073 <u>thawkins@wm.com</u>

Re: Vista Landfill, LLC (Buttrey/Keene Rd South) SW Facility ID #87081 Orange County

Dear Mr. Hawkins:

Department personnel conducted an inspection of the above-referenced facility on December 7, 2017. Based on the information provided during and following the inspection, the facility was determined to be in compliance with the Department's rules and regulations. A copy of the inspection report is attached for your records, and any non-compliance items which may have been identified at the time of the inspection have been corrected.

The Department appreciates your efforts to maintain this facility in compliance with state and federal rules. Should you have any questions or comments, please contact Michael Eckoff at 407-897-4308 or via e-mail at michael.eckoff@dep.state.fl.us.

Sincerely,

Reggie Phillips, Manager Central District Florida Department of Environmental Protection

Enclosure: Inspection Report



Florida Department of Environmental Protection Inspection Checklist

FACILITY INFORMATION:

Facility Name: VISTA LANDFILL, LLC (BUTTREY/KEENE RD SOUTH)

On-Site Inspection Start Date: 12/07/2017

 On-Site Inspection End Date:
 12/07/2017

 WACS No.:
 87081

Facility Street Address: 242 WEST KEENE RD

City: APOPKA

County Name: ORANGE

Zip: 32703

INSPECTION PARTICIPANTS:

(Include ALL Landfill and Department Personnel with Corresponding Titles)

Principal Inspector: Michael Eckoff, Inspector

Other Participants: Gloria-Jean DePradine, Environmental Consultant; Daniel Galarza, Lead Operator; Deborah Perez, District Manager

INSPECTION TYPE:

Routine Operation Inspection for Landfill - Class III

Routine Operation Inspection for WPF - Waste Tire Processing Facility

ATTACHMENTS TO THE INSPECTION CHECK LIST:

This Cover Page to the Inspection Checklist may include any or all of the following attachments as appropriate.

Note: Checklist items with shaded boxes are for informational purposes only.

- 1.0 SECTION 1.0 FILE REVIEW
- 2.0 SECTION 2.0 LANDFILL OPERATION AND MAINTENANCE
- 9.0 SECTION 9.0 WASTE TIRE FACILITIES

Inspection Date: 12/07/2017

1.0 - SECTION 1.0 - FILE REVIEW

Requirements:

The requirements listed in this section provide an opportunity for the Department's inspector to indicate the conditions found at the time of the inspection. A "Not Ok" response to a requirement indicates either a potential violation of the corresponding rule or an area of concern that requires more attention. Both potential violations and areas of concern are discussed further at the end of this inspection report.

Item No.	FILE REVIEW (Pre- or Post-Inspection, as appropriate.)	Ok	Not Ok	Unk	N/A
1.1	For landfills and C&D disposal facilities, does the facility have a current plan for the method and sequence of filling wastes? 62-701.500(2)(f) for landfills; 62-701.730(7)(a) for C&D debris sites	>			
1.2	For landfills, are the following records being reported to the Department?(Check any that are Not OK) Waste reports (annually) 62-701.500(4) Annual estimate of remaining life 62-701.500(13)(c)	>			
1.3	Is gas monitoring being performed as required by the permit? 62-701.500(9), 62-701.530(2)	>			
1.4	Are the results of the gas sampling reported to the Department quarterly? 62-701.530(2)(c)	>			
1.5	Is water quality sampling and testing performed according to standard procedures and at the required frequencies? 62-701.510(2) for landfills; 62-701.730(8) and 62-701.730(10) for C&D debris sites; 62-713.400(3) for stationary soil treatment facilities.	>			
1.6	Do the results of the water quality testing suggest there may be adverse impacts to water quality from the operation of the solid waste facility? 62-701.510(3) and (4); 62-701.730(4)(c) and (10) for C&D debris sites; 62-713.400(3) for stationary soil treatment facilities.			>	
1.7	For closed landfills and C&D disposal facilities with final elevations higher than 20 feet above grade, has a final survey report verifying the final elevations and contours of the facility been submitted to the Department? 62-701.600(6)(b), 62-701.730(9)(e)				>
1.8	Is financial assurance adequate? 62-701.630 for landfills; 62-701.710(7)(a) and 62-701.710(1)(d)1. for waste processing facilities; 62-701.730(11)(a) for C&D debris facilities; 62-713.600(6)(a) for stationary soil treatment facilities; 62-711.500(3) for waste tire facilities. NOTE: The Solid Waste Financial Coordinator in Tallahassee can assist with this information.	>			
1.9	Are cost estimates current and adjusted every year? 62-701.630(4) for landfills; 62-701.710(7)(a) and 62-701.710(1)(d)1. for waste processing facilities; 62-701.730(11)(a) for C&D debris facilities; 62-713.600(6)(b) and 62-713.600(6)(c) for stationary soil treatment facilities; 62-711.500(3) for waste tire facilities.	>			
1.10	For C&D debris disposal and disposal with recycling facilities, is an Annual Report submitted to the Department for the disposal operation by February 1st of each year? 62-701.730(12)				>
1.11	For C&D recycling facilities with no disposal, is an Annual Report for the recycling facility submitted to the Department by February 1st of each year? 62-701.710(8)(b)				~
1.12	For compost facilities, has the compost product been sampled and analyzed every 20,000 tons or every 3 months (whichever is sooner)? 62-709.530(1)			~	
1.13	For compost facilities, has the annual report been submitted by June 1st? 62-709.530(3)			~	

Inspection Date: 12/07/2017

2.0 - SECTION 2.0 - LANDFILL OPERATION AND MAINTENANCE

Requirements:

The requirements listed in this section provide an opportunity for the Department's inspector to indicate the conditions found at the time of the inspection. A "Not Ok" response to a requirement indicates either a potential violation of the corresponding rule or an area of concern that requires more attention. Both potential violations and areas of concern are discussed further at the end of this inspection report.

Item No.	SOLID WASTE PROHIBITIONS (unless "grandfathered" in, see 62-701.300(18))	Ok	Not Ok	Unk	N/A
2.1.1	Unauthorized storage, processing, or disposal of solid waste except as authorized at a permitted solid waste management facility or other exempt facility. 62-701.300(1)(a)	~			
2.1.2	Unauthorized disposal or storage prohibited, except yard trash, within 500 feet of a potable water well? 62-701.300(2)(b)	~			
2.2	Unauthorized storage or disposal of yard trash prohibited within the minimum setbacks of (Check any that are Not OK) 62-701.300(12) 100 feet from potable water wells (except on-site)? 50 feet from water bodies?	>			
2.3	Unauthorized disposal or storage prohibited in any natural or artificial body of water including ground water and wetlands? (Does not apply to standing water after a storm event.) 62-701.300(2)(d)	>			
2.4	Unauthorized disposal or storage prohibited, except yard trash, within 200 feet of any natural or artificial body of water, including wetlands without permanent leachate controls, except impoundments or conveyances which are part of an on-site, permitted stormwater management system or on-site water bodies with no off-site discharge? 62-701.300(2)(e)	~			
2.5	Unauthorized open burning of solid waste prohibited except in accordance with Department requirements? 62-701.300(3)	~			
2.6	Are the following unauthorized wastes or special wastes properly controlled, managed and disposed? (Check any that are Not OK)				
	Hazardous waste 62-701.300(4)				
	Biomedical waste 62-701.300(6)				
	Yard trash 62-701.300(8)(c)				
	Whole waste tires 62-701.300(8)(e)				
	Regulated asbestos waste 62-701.520(3), 62-701.730(19)	2			
	Used oil and oily wastes, except as exempted 62-701.300(11)				
	PCB wastes 62-701.300(5)				
	Lead-acid batteries 62-701.300(8)(a)				
	White goods 62-701.300(8)(d)				
	Liquids 62-701.300(10)				
	CCA treated wood 62-701.300(14)				
2.7	Are only permitted waste types disposed at facility? 62-701.340(2), 62-701.500(6)(a), 62-701.500(2)(c)	~			
Item No.	LANDFILL OPERATION AND MAINTENANCE	Ok	Not Ok	Unk	N/A
2.8	Is there a trained operator on-site at Class I and III landfills when receiving wastes? 62-701.500(1)	~			
2.9	Is there at least one trained spotter at each working face when receiving wastes at Class I and III landfills? 62-701.500(1)	~			

Inspection Date: 12/07/2017

Item	LANDFILL OPERATION AND MAINTENANCE	Ok	Not	Unk	N/A
No.			Ok		
2.10	Are the following records or plans current and available on-site? (Check any that are Not OK)				
	Training Plan 62-701.320(15)(a)				
	Operating Plan 62-701.500(2)				
	Waste weight records 62-701.500(4)	92.			
	Precipitation records 62-701.500(8)(g)	~			
	Load-checking program records 62-701.500(6)(a)				
	Training records 62-701.320(15)(a)				
	Operation record 62-701.500(3)				
	Quantity of leachate 62-701.500(8)(f)				
2.11	Is the operation plan substantially followed? 62-701.500(2)	~			
2.12	Is incoming waste weighed? 62-701.500(4)(a) and 62-701.500(2)(d)	~			
2.13	Is the method and sequence of filling waste according to plans? 62-701.500(2)(f)	~			
0.11		~			
2.14	Is access properly controlled to prevent unauthorized waste disposal? 62-701.500(5)	~			
2.15	Is waste compacted as required? 62-701.500(7)(a)	~			
2.16	Are the working face and side slopes above ground graded to a slope no greater than 3 feet horizontal to 1 foot vertical rise? 62-701.500(7)(c)	~			
2.17	Is a narrow working face practiced? 62-701.500(7)(d)	<			
2.18	Is the frequency, amount and quality of initial cover, as required? 62-701.500(7)(e)	~			
2.19	Is the frequency, amount and quality of intermediate cover, as required? 62-701.500(7)(f)	~			
2.20	Is litter controlled and are litter control devices maintained? 62-701.500(7)(i) and 62-701.500(11)(f)	~			
2.21	Is erosion control adequate? 62-701.500(7)(j)	~			
2.22	Is the leachate collection and removal system maintained and operated as required? 62-701.500(2)(j), 62-701.500(8)(b) and 62-701.500(8)(h)	~			
2.23	Is leachate disposed of or treated as required? 62-701.500(8)(b), 62-701.500(8)(c) and 62-701.500(8)(d)	~			
2.24	If leachate recirculation is practiced at the facility, is it done in accordance with Department requirements and the Operation Plan? 62-701.400(5)				~
2.25	Is gas controlled to not cause objectionable odors beyond the property boundary? 62-701.530(3)(b)	~			
2.26	Is gas controlled to not allow combustible gas concentrations to exceed specified limits? 62-701.530(3)(a)			~	
2.27	Are gas vents intact and functioning properly? 62-701.500(9), 62-701.530(1)(a)3	~			
2.28	Is mixing of leachate and stormwater prevented or minimized? 62-701.500(10), 62-701.400(9)(b)	~			
2.29	Is stormwater management system maintained and operated as required? 62-701.500(10)	~			
2.30	Is there sufficient operating equipment? 62-701.500(11)(a)	~			
2.31	Is there sufficient reserve equipment (or other arrangements)? 62-701.500(11)(b)	~			
2.32	Are communication facilities adequate? 62-701.500(11)(c)	~			
2.33	Are approved dust control methods adequate? 62-701.500(11)(d)	~			

Inspection Date: 12/07/2017

Item No.	LANDFILL OPERATION AND MAINTENANCE	Ok	Not Ok	Unk	N/A
		~			
2.34	Are fire protection and fire fighting capabilities adequate and operational? 62-701.500(11)(e)	~			
2.35	Are there required signs for operational directions and public information? 62-701.500(11)(g)	~			
2.36	Are all-weather access roads and inside perimeter roads properly maintained? 62-701.500(12)	~			
2.37	Are groundwater wells intact and properly maintained? 62-701.510(2)(b), 62-701.620(8)	~			
2.38	Are all additional specific conditions (not otherwise addressed above) in the permit, Department order, or certification, if any, being followed? 62-701.320(1), 403.161, F.S.	~			

Inspection Date: 12/07/2017

9.0 - SECTION 9.0 - WASTE TIRE FACILITIES

Requirements:

The requirements listed in this section provide an opportunity for the Department's inspector to indicate the conditions found at the time of the inspection. A "Not Ok" response to a requirement indicates either a potential violation of the corresponding rule or an area of concern that requires more attention. Both potential violations and areas of concern are discussed further at the end of this inspection report.

ltem No.	SOLID WASTE PROHIBITIONS (unless "grandfathered" in, see 62-701.300(18))	Ok	Not Ok	Unk	N/A
9.1.1	Unauthorized storage, processing, or disposal of solid waste except as authorized at a permitted solid waste management facility or other exempt facility? 62-701.300(1)(a)	>			
9.1.2	Unauthorized disposal or storage prohibited, except yard trash, within 500 feet of a potable water well? 62-701.300(2)(b)	>			
9.2	Unauthorized storage or disposal of yard trash prohibited within the minimum setbacks of (Check any that are Not OK) 62-701.300(12) 100 feet from potable water wells (except on-site)? 50 feet from water bodies?	>			
9.3	Unauthorized disposal or storage prohibited in any natural or artificial body of water including ground water and wetlands? (Does not apply to standing water after a storm event) 62-701.300(2)(d)	~			
9.4	Unauthorized disposal or storage prohibited, except yard trash, within 200 feet of any natural or artificial body of water, including wetlands without permanent leachate controls, except impoundments or conveyances which are part of an on-site, permitted stormwater management system or on-site water bodies with no off-site discharge? 62-701.300(2)(e)	>			
9.5	Unauthorized open burning of solid waste prohibited except in accordance with Department requirements? 62-701.300(3)	>			
ltem No.	WASTE TIRE FACILITY - GENERAL REQUIREMENTS FOR STORAGE	Ok	Not Ok	Unk	N/A
9.6	If the facility accepts tires from the public, is a sign posted at the facility entrance stating operating hours, cost of disposal and site rules? 62-711.540(1)(a)	~			
9.7	Are operations involving the use of open flames conducted no closer than 25 feet of a waste tire pile? 62-711.540(1)(b)	~			
9.8	If the facility accepts tires from the public, is an attendant always present on site when the site is open for business? 62-711.540(1)(c)	~			
9.9	Are fire protection services assured through notification to local fire protection authorities? 62-711.540(1)(d)	~			
9.10	Is an annual fire safety survey conducted? 62-711.540(1)(d)				~
9.11	Is a copy of the annual fire safety report made part of the next quarterly report? 62-711.540(1)(d)				<
9.12	Does the facility have an Emergency Preparedness Manual (EPM) on-site? 62-711.540(1)(e)	>			
9.13	Does the EPM contain the following information? (Check all that are Not OK) Contact names and numbers 62-711.540(1)(e)1 List of emergency response equipment and locations on-site 62-711.540(1)(e)2 Procedures to be followed in the event of a fire 62-711.540(1)(e)3	~			
9.14	Is the operator at the facility maintaining records of the quantity of waste tires received at the site, stored at the site, and shipped from the site? 62-711.540(1)(g) and 62-711.400(5)	~			
9.15	If the operator of the site is not the owner of the property, has written authorization been obtained from the property owner to operate the facility? 62-711.540(1)(h)	>			
9.16	Is adequate communications equipment available at the site? 62-711.540(1)(i)	>			

Inspection Date: 12/07/2017

ltem No.	WASTE TIRE FACILITY - GENERAL REQUIREMENTS FOR STORAGE	Ok	Not Ok	Unk	N//
9.17	Is the owner or operator providing for control of mosquitoes and rodents so as to protect the public health and welfare? 62-711.540(1)(j)	~			
ltem No.	WASTE TIRE FACILITY - STORAGE INDOORS	Ok	Not Ok	Unk	N//
9.18	Are waste tire piles more than 50 feet in width? 62-711.540(2)(a)				~
9.19	Are waste tire piles along a wall more than 25 feet in width? 62-711.540(2)(a)				~
9.20	Are widths of main aisles between piles less than 8 feet? 62-711.540(2)(b)				>
9.21	Is there less than 3 feet of clearance between the top of storage to sprinkler detectors or roof structures? 62-711.540(2)(c)				>
9.22	Is there less than 3 feet of clearance between waste tire piles and unit heaters, etc.? 62-711.540(2)(d)				>
9.23	If waste tires are stored up to 15 feet high, do walls between adjacent warehouse areas and between manufacturing and warehouse areas have at least a four-hour fire rating? 62-711.540(2)(e)				~
9.24	If waste tires are stored over 15 feet high, do walls between manufacturing and warehouse areas have a fire rating of not less than six hours and do steel columns have one-hour fireproofing? If the top of storage exceeds 20 feet in height, do columns and their connections with other structural members have two-hour fireproofing? 62-711.540(2)(f)				~
9.25	Is the access controlled through the use of doors, fences, gates, natural barriers or other means? 62-711.540(2)(h)				>
ltem No.	WASTE TIRE FACILITY - STORAGE OUTDOORS	Ok	Not Ok	Unk	N/
9.26	Is the waste tire site operated within 200 feet from a body of water? 62-711.540(3)(a)	~			
9.27	Does the waste tire pile have a width less than 50 feet? 62-711.540(3)(b)	~			
9.28	Does the waste tire pile have an area less than 10,000 sq. ft? 62-711.540(3)(b)	~			
9.29	Does the waste tire pile have a height less than 15 feet? 62-711.540(3)(b)	~			
9.30	Is there a 50 feet wide fire lane around the perimeter of the waste tire pile? 62-711.540(3)(c)	~			
9.31	Is there unobstructed access to the fire lane? 62-711.540(3)(c)	~			
9.32	Is the access controlled through the use of doors, fences, gates, natural barriers or other means? 62-711.540(3)(d)	>			
9.33	Is the site kept free of grass, underbrush, and other potentially flammable vegetation? 62-711.540(3)(f)	~			
9.34	Is the site bermed or given other adequate protection to prevent liquid runoff from entering water bodies? 62-711.540(3)(e)	~			
9.35	Are residuals contained on-site and disposed of in a permitted solid waste management facility or properly recycled? 62-711.540(5)	~			
9.36	Does the waste tire site qualify for the exceptions to the technical and operational standards as allowed by rule? 62-711.540(6)				~
ltem No.	WASTE TIRE FACILITY - COLLECTION CENTER	Ok	Not Ok	Unk	N
9.37	Are no more than 1,500 tires at the collection center at any one time? 62-711.550(1)(a)	~			
9.38	Are all waste tires, which are not used tires, removed from site yearly for recycling, processing, or disposal? 62-711.550(1)(b)	~			

Inspection Date: 12/07/2017

COMMENTS:

Class III landfill permit 0165969-030-SO was issued 11/2/2017 and expires 6/1/2036. Waste tire processing facility permit 0165969-023-WT-06 was issued 8/12/2014 and expires 9/16/2019.

Section 1.0-File Review

Item 1.2 - 2016 annual waste report was received 1/24/2017. 2017 annual estimate of remaining life was received 6/2/2017.

Item 1.4 - 1st quarter (Q) 2017 gas report was received 1/18/2017. 2nd Q 2017 gas report was received 4/11/2017. 3rd Q 2017 gas report was received 8/18/2017. 4th Q 2017 gas report was received 11/21/2017. Item 1.5 - 2nd semi-annual (SA) 2016 water report was received 2/28/2017. 1st SA 2017 water report was received 8/31/2017.

Item 1.6 - Ground water reports are reviewed as a separate function and not part of this inspection. Item 1.8 - In an email dated 12/4/2017 from the Department's Financial Coordinator, financials were determined to be adequate.

Item 1.9 - Current cost estimates were determined to be adequate on 3/9/2017, with a subsequent approval of revised cost estimates dated 10/6/2017.

Items 1.10 and 1.11 - Permit condition Section 2-C.14.d. requires submission of an annual construction and demolition debris (C&D) report for landfills that knowingly accept dedicated loads of C&D. Ms. Perez stated the facility does not accept dedicated loads of C&D.

Items 1.12 and 1.13 - The yard trash and organic processing and recycling facility was not part of this inspection.

Section 2.0-Landfill Operation and Maintenance

Items 2.8 and 2.9 - Leslie Holmes, Jr.-Class I, III Landfill Operator (current until 10/17/2018), C&D Landfill Operator (current until 10/17/2018), and Spotter/Waste Screener (current until 2/27/2021). Daniel Galarza-Class I, III Landfill Operator (current until 3/19/2020) and C&D Landfill Operator (current until 3/19/2020). Item 2.10 - Operation plan-hard copy reviewed during the inspection was dated 7/7/2016, Ms. Perez stated the most current version dated 11/2/2017 is available electronically. Load-checking program records-at least three load inspections are conducted weekly.

Item 2.13 - Currently placing waste in Cells 1, 2, 3, and 4. Waste is also being added to slopes in these cells. Item 2.16 - The slope angles were not measured in order to verify they are no greater than three feet horizontal to one foot vertical, only a visual assessment was conducted.

Items 2.18 and 2.19 - Cover material is obtained from the future Cell 6 area. Ms. Perez stated initial cover is applied every Friday.

Item 2.23 - Leachate is disposed at the City of Apopka wastewater treatment facility. Leachate is currently being applied on the active portion of the landfill. A log is kept documenting the dates of application and the amount applied.

Item 2.26 - Gas monitoring reports are reviewed as a separate function and not part of this inspection.

Section 9.0-Waste Tire Facilities

Items 9.6 and 9.8 - The facility does not accept dedicated loads of waste tires from the public. If a customer does not take its waste tires back they are charged a fee that is posted on a sign at the scale house. The attendant that accepts the waste tires is either the operator or spotter that discovered the waste tires in a load.

Items 9.10 and 9.11 - Permit condition C.12. requires a fire safety survey annually only when a mobile shredder is on-site. Ms. Perez stated a mobile shredder is not used on-site.

Item 9.12 - The EPM is incorporated as part of the landfill operation plan.

Item 9.14 - Most current waste tire shipment to Wheelabrator was on 8/16/2017. 4th Q 2016 waste tire report was received 1/19/2017. 1st Q 2017 waste tire report was received 4/12/2017. 2nd Q 2017 waste tire report was received 7/14/2017. 3rd Q 2017 waste tire report was received 10/25/2017.

Items 9.27, 9.28, and 9.29 - Waste tires were stored in four 30-yard containers at the time of the inspection. Ms. Perez stated approximately 100 yards of waste tires are accumulated prior to shipping off-site.

Inspection Date: 12/07/2017

Signed:

Michael Eckoff	Inspector	
PRINCIPAL INSPECTOR NAME	PRINCIPAL INSPECTOR TIT	ĨLE
Michael Edut	DEP	12/07/2017
PRINCIPAL INSPECTOR SIGNATURE	ORGANIZATION	DATE
Gloria-Jean DePradine	Environmental Consultant	
INSPECTOR NAME	INSPECTOR TITLE	
NO SIGNATURE REQUIRED	FDEP - Central District	
INSPECTOR SIGNATURE	ORGANIZATION	
Daniel Galarza	Lead Operator	
REPRESENTATIVE NAME	REPRESENTATIVE TITLE	
NO SIGNATURE REQUIRED	Waste Management Inc of Flo	orida
REPRESENTATIVE SIGNATURE	ORGANIZATION	
NOTE: By signing this document, the Site Re Report and is not admitting to the accuracy of areas of concern.		
Deborah Perez	District Manager	
REPRESENTATIVE NAME	REPRESENTATIVE TITLE	

REPRESENTATIVE SIGNATURE

Waste Management Inc of Florida
ORGANIZATION

NOTE: By signing this document, the Site Representative only acknowledges receipt of this Inspection Report and is not admitting to the accuracy of any of the items identified by the Department as "Not Ok" or areas of concern.

Report Approvers:

Approver: Reginald F. Phillips Inspection Approval Date: 01/12/2018
