

## Smith, George

---

**From:** John Arnold <[john.phillip.arnold@gmail.com](mailto:john.phillip.arnold@gmail.com)>  
**Sent:** Wednesday, March 21, 2018 4:29 PM  
**To:** SWD\_Waste; Black, Alexis  
**Subject:** Re: WACS 87895 Inspection Response  
**Attachments:** Erosion Maintenance Cells 3 and 4.jpg; Erosion Maintenance Cell 5.jpg

Additional photos documenting intermediate cover maintenance on Cells 3, 4, and 5.

On Mon, Mar 19, 2018 at 2:20 PM, John Arnold <[john.phillip.arnold@gmail.com](mailto:john.phillip.arnold@gmail.com)> wrote:

I've attached a response addressing the items listed in the latest inspection report. Please let me know if you need anything else or if you have any questions. I'll let you know when we receive an inspection date from the fire marshal.

Thanks,

--

John Arnold, P.E.  
Ph. [\(813\) 477-1719](tel:8134771719)

--

John Arnold, P.E.  
Ph. (813) 477-1719







