# Johnson, Sabrina O

**From:** Gray, Walter < GrayW@HillsboroughCounty.ORG>

**Sent:** Thursday, April 12, 2018 2:26 PM

**To:** SWD\_Waste

Cc: Morgan, Steve; Cope, Ronald; Clark, Bruce; Byer, Kimberly; Ruiz, Larry

**Subject:** WACS ID SWD/29/41193-Southeast County Landfill- Gas Monitoring Report

**Attachments:** sclf gas monitoring rpt april 2018.pdf

Attached is the Landfill Gas Monitoring Report for the Southeast County Landfill. All recipients will receive this electronic copy only. Should you have any questions concerning the information provided, please call me. Thanks.

### Walter J. Gray General Manager II

Public Works Department, Solid Waste Management Division

P: (813) 209 3059 M: (813) 455 2183 E: GrayW@HCFLGov.net

W: HCFLGov.net

### **Hillsborough County**

332 N. Falkenburg Road, Tampa, FL 33619

Facebook | Twitter | YouTube | LinkedIn

Please note: All correspondence to or from this office is subject to Florida's Public Records law.



### **PUBLIC WORKS**

PO Box 1110 Tampa, FL 33601-1110 (813) 272-5912 | Fax: (813) 272-5811

April 10, 2018

Mr. Steve Morgan
Solid Waste Permitting
Florida Department of Environmental Protection
Southwest District
13051 N. Telecom Pkwy
Temple Terrace, Florida 33637-0926

RE: Southeast County Landfill - Gas Monitoring Report

BOARD OF COUNTY COMMISSIONERS

Victor D. Crist
Ken Hagan
Al Higginbotham
Pat Kemp
Lesley "Les" Miller, Jr.
Sandra L. Murman
Stacy R. White
COUNTY ADMINISTRATOR
Michael S. Merrill
COUNTY ATTORNEY
Chip Fletcher
INTERNAL AUDITOR

CHIEF DEVELOPMENT & INFRASTRUCTURE SERVICES ADMINISTRATOR

Lucia E. Garsys

Peggy Caskey

### Dear Mr. Morgan:

In accordance with Specific Conditions E 4 of Permit No. 35435-022-SO/01, the Public Works Department, Solid Waste Management Division (SWMD) is submitting the quarterly landfill gas monitoring report for the Southeast County Landfill for the quarter ending April 15, 2018.

The monitoring was performed on March 28, 2018. The information includes the structure and the subsurface monitoring point gas sampling and results. No methane was detected at any of the sampling locations.

Please advise should you have any questions concerning the attached submittal.

Sincerely,

Landfill Operations Manager

Solid Waste Management Division

### Attachment

xc: Kimberly Byer, PWD/SWMD Walter Gray, PWD/SWMD Dan Cooper, SCS Engineers Ron Cope, EPC

# HILLSBOROUGH COUNTY SOLID WASTE MANAGEMENT DEPARTMENT SOUTHEAST COUNTY LANDFILL - LFG READINGS

### **ADMINISTRATION BUILDING**

	.Methane Gas		Carbon Dioxide	Oxygen .	Balance Gas
SP-1	0	0	0	21.5	78.5
	0	0	0	21.5	78.5
SP-2 SP-3	0	0	0	21.5	78.5
SP-4	0	0	0	21.5	78.5
SP-5	0	0	0	21.5	78.5
SP-6	0	0	0	21.5	78.5
SP-7	0	0	0	21.5	78.5
SP-8	0	0	0	21.5	78.5

### MAINTENANCE BUILDING

	Methane Gas	LEL	Carbon Dloxide	Oxygen	Balance Gas
SP-9	0	0	0	20.4	79.6
SP-9 SP-10	0	0	0	20.4	79.6
SP-11	0	0	0	20.4	79.6
SP-12	0	0	0	20.4	79.6

## LEACHATE TREATMENT PLANT

	Methane Gas	e de LEL	(Odyse) (Spikold)	Oxygen	Balance Gás já
SP-13	0	0	0	20	80
SP-14	0	0	0	20	80
SP-14 SP-15	0	0	0	20	80

# LANDFILL GAS PERIMETER MONITOTING PONT

	Migthane Gas	ueu.	Carbon Dioxide	Oxygen	Balance Gasi	Objectional Ambient Odor (Y/N)
LFG-1	0	0	2.8	16.1	81.1	N
LFG-2	0	0	1.9	18.5	79.6	N
LFG-3	0	0	0.6	20	79.4	N
LFG-4	0	0	1	20.5	78.5	N
LFG-4	0	0	1	20.5	78.5	N N

TECHNICIAN SIGNATURE: SUPERVISOR SIGNATURE:	Jarry R	<u>Cus</u>	
DATE: 3/28/18	<u> </u>		
COMMENTS:			

Legend: SP = Ambient Sample Point