

Johnson, Sabrina O

From: John Arnold <john.phillip.arnold@gmail.com>
Sent: Wednesday, April 25, 2018 9:14 AM
To: Black, Alexis
Cc: SWD_Waste
Subject: Re: WACS 87895 Inspection Response
Attachments: CCF04252018.pdf

The follow up fire inspection report for the waste tire processing area is attached. The facility is listed as "approved" by Pasco County Fire Rescue.

John

On Fri, Apr 20, 2018 at 12:14 PM, John Arnold <john.phillip.arnold@gmail.com> wrote:
Alexis,

The inspection of the Waste Tire Processing Facility by Pasco County Fire Rescue is attached. All of the items listed in the inspection report are in the process of being addressed . I will ask for the Fire Inspector to re-inspect the facility prior to their 5/21/18 deadline. We will forward that re-inspection to you.

We have placed additional initial cover over all area of the landfill such that there is no exposed wood ash. I've attached pictures of the additional soil/mulch cover. We have address all areas of erosion, initial cover maintenance, and wood ash exposure listed in the inspection.

Please let me know if you have any questions, or if you need anything else to fully address the issues raised by the Department.

Thanks
John

On Thu, Mar 22, 2018 at 6:42 AM, Black, Alexis <Alexis.Black@dep.state.fl.us> wrote:

Good morning, John:

Thank you for these photos. Please keep me updated on your progress to resolve the items granted a time extension until April 21st.

Thank you, and have a great day.

Alexis Black

Environmental Specialist I

Compliance Assurance Program

Florida Department of Environmental Protection

Southwest District

PLEASE NOTE: Florida has a very broad public records law. Electronic communications regarding state business are public records available upon request. Your e-mail communications may therefore be subject to public disclosure.

From: John Arnold [mailto:john.phillip.arnold@gmail.com]

Sent: Wednesday, March 21, 2018 4:29 PM

To: SWD_Waste <SWD_Waste@dep.state.fl.us>; Black, Alexis <Alexis.Black@dep.state.fl.us>

Subject: Re: WACS 87895 Inspection Response

Additional photos documenting intermediate cover maintenance on Cells 3, 4, and 5.

On Mon, Mar 19, 2018 at 2:20 PM, John Arnold <john.phillip.arnold@gmail.com> wrote:

I've attached a response addressing the items listed in the latest inspection report. Please let me know if you need anything else or if you have any questions. I'll let you know when we receive an inspection date from the fire marshal.

Thanks,

--

John Arnold, P.E.

Ph. [\(813\) 477-1719](tel:(813)477-1719)

--

John Arnold, P.E.

Ph. (813) 477-1719



--

John Arnold, P.E.

Ph. (813) 477-1719

--

John Arnold, P.E.

Ph. (813) 477-1719

Business Name: Angelo's Recycled Materials Phone #: 352-521-3607
Business Address: 4111 Enterprise Rd Hazard Class: 1 2 3 4 N/A
City: Dade City State: FL ZIP: 33525
Occupancy: Storage Stories: N/A Const. Type: N/A
Sprinklers: Y / N Standpipes: Y / N Alarm System: Y / N Max Occupant Load: _____
Access Box: Y / N Location: — Sq. Feet: N/A

Date: 4 / 25 / 18 Time: 09:00 Type of Inspection: Re-Inspection

[illegible]

You have the right to appeal to the Pasco County Fire Marshal at: 4111 Land O'Lakes Boulevard, Land O'Lakes, Florida, telephone (813) 929-2737 or (727) 847-2411, Extension 2737, within 24 hours of service of this Order to Comply.

Fire Safety Inspector's Signature _____

Print Name Here \ Bunker #

Fire Safety Inspector's Signature _____

Print Name Here \ Bunker #