

# MIAMI-DADE FIRE RESCUE DEPARTMENT - INSPECTION REPORT



FIRE PREVENTION DIVISION  
9300 NW 41 STREET, DORAL, FLORIDA 33178  
PHONE 786.331.4800 FAX 786.331.4801



**PERMIT #** 00128-00614

**Business Address:** (District 19)  
MMD TIRES CORP  
9965-9995 NW 88 AVE  
MEDLEY, FL 33178

**Billing Address:**  
MMD TIRES CORP  
9975 NW 88TH AVE  
MEDLEY, FL 33178

**RESULT: Inspected / Approved**

**Resulted Date:** 1/11/18

**Permit Type:** Storage / Storage Occupancies. **Inspection**

**Month:** February

**Inspector:**  
JEFFREY FULMORE  
(786) 367-6736  
fulmore@miamidade.gov

Please Note: A Life Safety Permit required by Section 14-39, Code of Miami-Dade County, to operate the above named occupancy will be issued upon correction of all outstanding violations and payment of fees assessed. Failure to obtain the required Life Safety Permit will result in enforcement actions including fines, citations, liens and/or orders to cease and desist operation.

No violations noted at this time

CUSTOMER SIGNATURE

Title: Secretary  
Name: CANDICE GARCIA

Please Note: A life safety permit will be issued upon compliance of outstanding violations and payment of fees assessed. One (1) re-inspection will be performed at no additional cost. All subsequent re-inspections will be billed at one-half the original permit fee amount.



We would like feedback on your experience with your Life Safety Inspection .  
Please take a minute to complete our survey at:  
[http://bit.ly/mdfr\\_2tcSXHm](http://bit.ly/mdfr_2tcSXHm)