



TRAIL RIDGE LANDFILL, INC.

5110 U.S. Highway 301 South
Baldwin, Florida 32234-3608
(904) 289-9100
(904) 289-9013 Fax

EDIP 2018 AUG 23 AM 11:22

August 22, 2018

Mr. Brian Durden
Department of Environmental Protection
Northeast District
8800 Baymeadows Way West, Suite 100
Jacksonville, FL 32256-7598

RE: Permit No. 0013493-025-SO-01
Waste Tire Processing Facility Annual Facility Fire Inspection

Mr. Durden:
Attached please find a copy of the 2018 Trail Ridge Landfill Fire Safety Inspection Report, which includes the Waste Tire Area.

If you have any questions concerning the report, please call me at (904) 748-6012.

Sincerely,

Greg Mathes
Senior District Manager

Enclosures

cc Eric Parker – WMIF
Allen Rhodes – Trail Ridge Landfill Inc.



JACKSONVILLE FIRE AND RESCUE DEPARTMENT
FIRE PREVENTION DIVISION
FIRE SAFETY BILLING FORM
CITY OF JACKSONVILLE ORDINANCE 2004 - 1003



Business Name: TRAIL RIDGE LANDFILL INC
Inspection Type: ROUTINE Date: 08/17/18
Inspection Address: 5110 US 301 S Occupant Use: EHS
City, State: JACKSONVILLE FLORIDA Square Footage: ON FILE
Email Address: _____ Zip Code: 32234
Billing Information: Business Telephone: 904-289-9100
Billing Address: _____ (FEIN/SSN) #: ON FILE
City, State: _____ Zip code: _____

YOUR ATTENTION IS CALLED TO THE FOLLOWING VIOLATIONS
NO VIOLATIONS OBSERVED

* _____
* _____
* _____
THIS FACILITY HAS A USED TIRE STORAGE AREA WITH A 1500 TIRE MAXIMUM
LOCATED JUST WEST OF THE SCALE AREA.
* _____
* _____

FAILURE TO CORRECT ANY OBSERVED VIOLATIONS MAY RESULT IN CIVIL AND/OR PENALTIES AS REQUIRED BY LAW

Warning number(s): _____ Return Date: _____

Inspection Notes: 8-17

Fire Extinguisher: _____ Alarm: 2-18 Sprinkler/Riser: X Fire Pump/Back Flow: X

Hood Cleaning: X Hood: X Occupant Load: X Other: _____

This occupancy meets minimum fire safety requirements at this time. Yes X No _____

DEE DEE HALL 08/17/18
I acknowledge receipt of this inspection form. Print Date

Inspector Name: CAPT JACKSON Inspector Contact Number: 904-630-0445