## Smith, George

**From:** Gray, Walter < GrayW@HillsboroughCounty.ORG>

Sent: Tuesday, October 15, 2019 2:09 PM

**To:** SWD\_Waste

**Cc:** Morgan, Steve; Cope, Ronald; Spradlin, Kollan

**Subject:** WACS ID SWD/29/41193-Southeast County Landfill- Gas Monitoring Report

**Attachments:** Ifg Probes monitoring report Oct 2019.pdf

Attached is the Landfill Gas Monitoring Report for the Southeast County Landfill. All recipients will receive this electronic copy only. Should you have any questions concerning the information provided, please call me. Thanks.

### Walter J. Gray

### Manager

Solid Waste Management Division Transportation & Utilities Services

P: (813) 209 3059 M: (813) 455 2183

E: GrayW@HCFLGov.net

W: HCFLGov.net

### **Hillsborough County**

332 N. Falkenburg Road, Tampa, FL 33619

Facebook | Twitter | YouTube | LinkedIn

Please note: All correspondence to or from this office is subject to Florida's Public Records law.



#### **PUBLIC UTILITIES**

PO Box 1110 Tampa, FL 33601-1110

October 14, 2019

Mr. Steve Morgan Solid Waste Permitting Florida Department of Environmental Protection **Southwest District** 13051 N. Telecom Pkwy Temple Terrace, Florida 33637-0926

RE: Southeast County Landfill - Gas Monitoring Report

Dear Mr. Morgan:

In accordance with Specific Conditions E.4 of Permit No. 35435-022-SO/01, the Solid Waste Management Division (SWMD) is submitting the quarterly landfill gas monitoring report for the Southeast County Landfill for the quarter ending October 15, 2019.

The monitoring was performed on September 23, 2019. The information includes the structure and the subsurface monitoring point gas sampling and results. Methane was not detected at any of the sampling locations.

Please advise should you have any questions concerning the attached submittal.

Sincerely,

Landfill Operations Manager

Attachment

Kimberly Byer, PWD/SWMD xc: Walter Gray, PWD/SWMD Dan Cooper, SCS Engineers

Ron Cope, EPC

**BOARD OF COUNTY COMMISSIONERS** 

Ken Hagan Pat Kemp Lesley "Les" Miller, Jr. Sandra L. Murman Kimberly Overman Mariella Smith Stacy R. White **COUNTY ADMINISTRATOR** 

Michael S. Merrill **COUNTY ATTORNEY** 

Christine M. Beck

**INTERNAL AUDITOR** Peggy Caskey

**DEPUTY CNTY ADMINISTRATOR DEVELOP & INFRASTRUCTURE** 

Lucia E. Garsys

# HILLSBOROUGH COUNTY SOLID WASTE MANAGEMENT DEPARTMENT SOUTHEAST COUNTY LANDFILL - LFG READINGS

## **ADMINISTRATION BUILDING**

	Methane Gas	Time ye	Garbon Garbon	Oxygen	Balance Gas
SP-1	0	0	0.1	20.4	79.5
SP-2	0	0	0.1	20.4	79.5
SP-3	0	0	0.1	20.4	79.5
SP-4	0	0	0.1	20.4	79.5
SP-5	0	0	0.1	20.4	79.5
SP-6	0	0	0.1	20.4	79.5
SP-7	0	0	0.1	20.4	79.5
SP-8	0	0	0.1	20.4	79.5

## **MAINTENANCE BUILDING**

	Methane Gas	LEU	Gallan s Ploxide s	#Oxygen	Balance Gas
SP-9	0	0	0	20.2	79.8
SP-10	0	0	0	20.2	79.8
SP-11	0	0	0	20.2	79.8
SP-9 SP-10 SP-11 SP-12	0	0	0	20.2	79.8

## LEACHATE TREATMENT PLANT

	Methane Gas	SUBL .	Carbon : Dioxide	Oxygen	Balance Gas
SP-13	0	0	0	20.5	79.5
	0	0	0	20.5	79.5
SP-14 SP-15	0	0	0	20.5	79.5

## LANDFILL GAS PERIMETER MONITOTING PONT

	Methane Gas	THE LET	Carban Dibride	Oxygen	Balance Gas	Objectional Ambient Odor (Y/N)
LFG-1	0	0	0.2	19.9	79.9	No
LFG-2	0	0	3.2	17.7	79.1	No
LFG-3	0	0	3.3	18.5	78.2	No
LFG-4	0	0	2.3	18.7	79	No

TECHNICIAN SIGNATURE:	Thus of	Citt	
SUPERVISOR SIGNATURE:	Farne		
DATE: 9/23/19	77		
COMMENTS:			 
	*****	1	

Legend: SP = Ambient Sample Point