



## Florida Department of Environmental Protection Bureau of Mining & Minerals Regulation P.O. Box 306 Jay, Florida 32565

Office: (850)675-6558 Fax: (850)675-3440

## ANNUAL WELL SITE INSPECTION REPORT

County	Santa Ros	a	API#	09-11	3-20031	I	Permit#_	50	8			
Operator	Quantum Re	sources	Well#	& Nam	ie	7-4 F	Kelly					
Field	Jay		Well Ty	уре	I	BCS/I	BCNP _		No			
Surface Lo	ocation(SHL)	778' FNI	<u> </u>	6' FWL	,	_Sec _	7 T	5N	_R	29W		
Spud	8/16/71	KB	(subsea	corr) _	173'	_TD	15,687	7'				
_												
Well Statu	s: <u>Temporar</u>	ilv shut in	due to f	acility t	urn arou	nd for	repairs.					
	<u> </u>						<u>*</u>					
Site is clean and well maintained. No evidence of leaks or excessive corrosion on well												
head. H2S detection system in place.												
	•	-										
I certify that I inspected the above well and premise on the <u>24<sup>th</sup></u> day of <u>April, 2013</u> and found no violation of Rules 62C-25 through 30, FAC.												
		S	Signed		Op	ln o	L.L	, ecc	es	2		
				(	OIL ANI	O GAS	COORI	DINA	ATO!	R		

Note: If a violation exists, designate the rule violated and describe the infraction. Specify to the operator what must be done and time frame. A copy of rule 62C-25.0075 as well as a copy of the rule violated will be mailed upon request.

cc: [X] FDEP (Oil & Gas Section): Tallahassee

[ X ] FDEP (Oil & Gas Section): Jay

[ X ] Quantum Resources, Jay Field Office