

FLORIDA DEPARTMENT OF Environmental Protection

Southwest District Office 13051 North Telecom Parkway #101 Temple Terrace, Florida 33637-0926 Ron DeSantis Governor

Jeanette Nuñez Lt. Governor

Noah Valenstein Secretary

March 16, 2020

Ali Belfakir US 27 Tires, LLC 29612 US Highway 27 Lake Hamilton, FL 33838 Us27tires@gmail.com

Re: Compliance Assistance Offer

US 27 Tires, LLC WACS ID 101295 Polk County

Dear Mr. Belfakir:

An inspection was conducted at your facility on February 20, 2020. During this inspection, potential non-compliance was noted. The purpose of this letter is to offer compliance assistance as a means of resolving these matters.

Specifically, potential non-compliance with the requirements of chapter 403, Florida Statutes, chapter 62-701, Florida Administrative Code were observed. Please see the attached inspection report for a full account of Department observations and recommendations.

We request you review the items of concern noted and respond via email within **15 days** of receipt of this Compliance Assistance Offer. Your written response should include one of the following:

- 1. Describe what has been done to resolve the non-compliance issue or provide a schedule describing how/when the issue will be addressed.
- 2. Provide the requested information, or information that mitigates the concerns or demonstrates them to be invalid, or
- 3. Arrange for the case manager to visit your facility to discuss the items of concern.

It is the Department's desire that you are able adequately address the aforementioned issues so that this matter can be closed. Your failure to respond promptly may result in the initiation of formal enforcement proceedings.

US 27 Tires, LLC: WACS ID No.: 101295

Compliance Assistance Offer

Page 2 of 2

Please address your response and any questions to Kaitlyn Newsome of the Southwest District Office at (813) 470-5877 or via e-mail at kaitlyn.newsome@floridadep.gov. We look forward to your cooperation with this matter.

Sincerely,

Steven Tafuni

Government Operations Consultant

Compliance Assurance Program

Southwest District

Florida Department of Environmental Protection

Enclosures: Inspection Report

ec: Kaitlyn Newsome, DEP – Southwest District, <u>kaitlyn.newsome@floridadep.gov</u>

Steven Tafuni, DEP – Southwest District, steven.tafuni@floridadep.gov Steve Morgan, DEP – Southwest District, steven.tafuni@floridadep.gov



Florida Department of Environmental Protection Inspection Checklist

FACILITY INFORMATION:

Facility Name: US 27 TIRES, LLC

On-site Inspection Start Date: 02/20/2020 On-site Inspection End Date: 02/20/2020

WACS No.: 101295

Facility Street Address: 29612 HWY 27

City: DUNDEE
County Name: POLK
Zip: 33838

INSPECTION PARTICIPANTS:

(Include ALL Landfill and Department Personnel with Corresponding Titles)

Principal Inspector: Kaitlyn Newsome, Environmental Specialist II

Other Participants: Ali Belfakir, Owner;

INSPECTION TYPE:

Routine Operation Inspection for WPF - Waste Tire Processing Facility

ATTACHMENTS TO THE INSPECTION CHECKLIST:

This Cover Page to the Inspection Checklist may include any or all of the following attachments as appropriate.

Note: Checklist items with shaded boxes are for informational purposes only.

1.0 - SECTION 1.0 - FILE REVIEW

9.0 - SECTION 9.0 - WASTE TIRE FACILITIES

1.0 - SECTION 1.0 - FILE REVIEW

Requirements:

The requirements listed in this section provide an opportunity for the Department's inspector to indicate the conditions found at the time of the inspection. A "Not Ok" response to a requirement indicates either a potential violation of the corresponding rule or an area of concern that requires more attention. Both potential violations and areas of concern are discussed further at the end of this inspection report.

Item No.	FILE REVIEW (Pre- or Post-Inspection, as appropriate.)	Ok	Not Ok	Unk	N/A
1.1	For landfills and C&D disposal facilities, does the facility have a current plan for the method and sequence of filling wastes? 62-701.500(2)(f) for landfills; 62-701.730(7)(a) for C&D debris sites				1
1.2	For landfills, are the following records being reported to the Department?(Check any that are Not OK) Waste reports (annually) 62-701.500(4) Annual estimate of remaining life 62-701.500(13)(c)				1
1.3	Is gas monitoring being performed as required by the permit? 62-701.500(9), 62-701.530(2)				1
1.4	Are the results of the gas sampling reported to the Department quarterly? 62-701.530(2)(c)				1
1.5	Is water quality sampling and testing performed according to standard procedures and at the required frequencies? 62-701.510(2) for landfills; 62-701.730(8) and 62-701.730(10) for C&D debris sites; 62-713.400(3) for stationary soil treatment facilities.				1
1.6	Do the results of the water quality testing suggest there may be adverse impacts to water quality from the operation of the solid waste facility? 62-701.510(3) and (4); 62-701.730(4)(c) and (10) for C&D debris sites; 62-713.400(3) for stationary soil treatment facilities.				1
1.7	For closed landfills and C&D disposal facilities with final elevations higher than 20 feet above grade, has a final survey report verifying the final elevations and contours of the facility been submitted to the Department? 62-701.600(6)(b), 62-701.730(9)(e)				1
1.8	Is financial assurance adequate? 62-701.630 for landfills; 62-701.710(7)(a) and 62-701.710(1)(d)1. for waste processing facilities; 62-701.730(11)(a) for C&D debris facilities; 62-713.600(6)(a) for stationary soil treatment facilities; 62-711.500(3) for waste tire facilities. NOTE: The Solid Waste Financial Coordinator in Tallahassee can assist with this information.	1			
1.9	Are cost estimates current and adjusted every year? 62-701.630(4) for landfills; 62-701.710(7)(a) and 62-701.710(1)(d)1. for waste processing facilities; 62-701.730(11)(a) for C&D debris facilities; 62-713.600(6)(b) and 62-713.600(6)(c) for stationary soil treatment facilities; 62-711.500(3) for waste tire facilities.	1			
1.10	For C&D debris disposal and disposal with recycling facilities, is an Annual Report submitted to the Department for the disposal operation by February 1st of each year? 62-701.730(12)				1
1.11	For C&D recycling facilities with no disposal, is an Annual Report for the recycling facility submitted to the Department by February 1st of each year? 62-701.710(8)(b)				1
1.12	For compost facilities, has the compost product been sampled and analyzed every 20,000 tons or every 3 months (whichever is sooner)? 62-709.530(1)				1
1.13	For compost facilities, has the annual report been submitted by June 1st? 62-709.530(3)				1

9.0 - SECTION 9.0 - WASTE TIRE FACILITIES

Requirements:

The requirements listed in this section provide an opportunity for the Department's inspector to indicate the conditions found at the time of the inspection. A "Not Ok" response to a requirement indicates either a potential violation of the corresponding rule or an area of concern that requires more attention. Both potential violations and areas of concern are discussed further at the end of this inspection report.

Item No.	SOLID WASTE PROHIBITIONS (unless "grandfathered" in, see 62-701.300(18))	Ok	Not Ok	Unk	N/A
9.1.1	Unauthorized storage, processing, or disposal of solid waste except as authorized at a permitted solid waste management facility or other exempt facility? 62-701.300(1)(a)		1		
9.1.2	Unauthorized disposal or storage prohibited, except yard trash, within 500 feet of a potable water well? 62-701.300(2)(b)	1			
9.2	Unauthorized storage or disposal of yard trash prohibited within the minimum setbacks of (Check any that are Not OK) 62-701.300(12) 100 feet from potable water wells (except on-site)? 50 feet from water bodies?	1			
9.3	Unauthorized disposal or storage prohibited in any natural or artificial body of water including ground water and wetlands? (Does not apply to standing water after a storm event) 62-701.300(2)(d)	1			
9.4	Unauthorized disposal or storage prohibited, except yard trash, within 200 feet of any natural or artificial body of water, including wetlands without permanent leachate controls, except impoundments or conveyances which are part of an on-site, permitted stormwater management system or on-site water bodies with no off-site discharge? 62-701.300(2)(e)	1			
9.5	Unauthorized open burning of solid waste prohibited except in accordance with Department requirements? 62-701.300(3)	1			
Item No.	WASTE TIRE FACILITY - GENERAL REQUIREMENTS FOR STORAGE	Ok	Not Ok	Unk	N/A
9.6	If the facility accepts tires from the public, is a sign posted at the facility entrance stating operating hours, cost of disposal and site rules? 62-711.540(1)(a)	1			
9.7	Are operations involving the use of open flames conducted no closer than 25 feet of a waste tire pile? 62-711.540(1)(b)	1			
9.8	If the facility accepts tires from the public, is an attendant always present on site when the site is open for business? 62-711.540(1)(c)	1			
9.9	Are fire protection services assured through notification to local fire protection authorities? 62-711.540(1)(d)	1			
9.10	Is an annual fire safety survey conducted? 62-711.540(1)(d)	1			
9.11	Is a copy of the annual fire safety report made part of the next quarterly report? 62-711.540(1)(d)	1			
9.12	Does the facility have an Emergency Preparedness Manual (EPM) on-site? 62-711.540(1)(e)	1			
9.13	Does the EPM contain the following information? (Check all that are Not OK) Contact names and numbers 62-711.540(1)(e)1 List of emergency response equipment and locations on-site 62-711.540(1)(e)2 Procedures to be followed in the event of a fire 62-711.540(1)(e)3	1			
9.14	Is the operator at the facility maintaining records of the quantity of waste tires received at the site, stored at the site, and shipped from the site? 62-711.540(1)(g) and 62-711.400(5)	1			
9.15	If the operator of the site is not the owner of the property, has written authorization been obtained from the property owner to operate the facility? 62-711.540(1)(h)	1			
9.16	Is adequate communications equipment available at the site? 62-711.540(1)(i)	1			
9.17	Is the owner or operator providing for control of mosquitoes and rodents so as to protect the public health and welfare? 62-711.540(1)(j)	1			
			1	1	<u> </u>

Item No.	WASTE TIRE FACILITY - STORAGE INDOORS	Ok	N O	ot k	Unk	N/A
9.18	Are waste tire piles more than 50 feet in width? 62-711.540(2)(a)	1				
9.19	Are waste tire piles along a wall more than 25 feet in width? 62-711.540(2)(a)	1				
9.20	Are widths of main aisles between piles less than 8 feet? 62-711.540(2)(b)	1				
9.21	Is there less than 3 feet of clearance between the top of storage to sprinkler detectors or roof structures? 62-711.540(2)(c)	1				
9.22	Is there less than 3 feet of clearance between waste tire piles and unit heaters, etc.? 62-711.540(2)(d)	1				
9.23	If waste tires are stored up to 15 feet high, do walls between adjacent warehouse areas and between manufacturing and warehouse areas have at least a four-hour fire rating? 62-711.540(2)(e)	1				
9.24	If waste tires are stored over 15 feet high, do walls between manufacturing and warehouse areas have a fire rating of not less than six hours and do steel columns have one-hour fireproofing? If the top of storage exceeds 20 feet in height, do columns and their connections with other structural members have two-hour fireproofing? 62-711.540(2)(f)					1
9.25	Is the access controlled through the use of doors, fences, gates, natural barriers or other means? 62-711.540(2)(h)	1				
Item No.	WASTE TIRE FACILITY - STORAGE OUTDOORS		Ok	Not Ok	Unk	N/A
9.26	Is the waste tire site operated within 200 feet from a body of water? 62-711.540(3)(a)					1
9.27	Does the waste tire pile have a width less than 50 feet? 62-711.540(3)(b)					1
9.28	Does the waste tire pile have an area less than 10,000 sq. ft? 62-711.540(3)(b)					1
9.29	Does the waste tire pile have a height less than 15 feet? 62-711.540(3)(b)					1
9.30	Is there a 50 feet wide fire lane around the perimeter of the waste tire pile? 62-711.540(3)(c)				1
9.31	Is there unobstructed access to the fire lane? 62-711.540(3)(c)					1
9.32	Is the access controlled through the use of doors, fences, gates, natural barriers or other means? 62-711.540(3)(d)					1
9.33	Is the site kept free of grass, underbrush, and other potentially flammable vegetation? 62 711.540(3)(f)	-				1
9.34	Is the site bermed or given other adequate protection to prevent liquid runoff from enterin water bodies? 62-711.540(3)(e)	g				1
9.35	Are residuals contained on-site and disposed of in a permitted solid waste management facility or properly recycled? 62-711.540(5)					1
9.36	Does the waste tire site qualify for the exceptions to the technical and operational standa as allowed by rule? 62-711.540(6)	rds				1
Item No.	WASTE TIRE FACILITY - COLLECTION CENTER		Ok	Not Ok	Unk	N/A
9.37	Are no more than 1,500 tires at the collection center at any one time? 62-711.550(1)(a)					1
9.38	Are all waste tires, which are not used tires, removed from site yearly for recycling, processing, or disposal? 62-711.550(1)(b)					1

US 27 TIRES, LLC

Inspection Date: 02/20/2020

Current Violations:

Rule: 62-701.300(1)(a)

Question Number: 9.1.1

Explanation: During the inspection, waste tires were observed to not be stored in accordance

with the facility's approved application documents including the Figure #2 Building Detail Plan and Facility Operations Plan received by the Department on October 8, 2018. Mr. Belfakir indicated that the facility has recently installed additional tire storage racks along the North Western exterior wall in order to increase storage

capacity at the facility.

On March 9, 2020, Mr. Steve Morgan (Solid Waste Permitting) conducted a follow up site visit of the facility. During the site visit, Mr. Belfakir indicated that he would provide additional information regarding the current configuration of the

new tire racks and how this impacts storage capacity on site.

Corrective Action: Please provide the information as noted above. Additionally, please note that a

permit modification will be required following receipt and review of this

information.

Attachments:

Racks Along North Western Wall



COMMENTS:

Item 9.10: The most recent fire safety survey was completed by Polk County Fire Rescue on August 21, 2019 indicating no violations at the time of inspection.

Item 9.14: Incoming/outgoing documentation was reviewed from February - December 2019. The ending balance of tires stored at the facility in December 2019 was 2631 tires indicating compliance with the permitted waste tire storage capacity limit (5300 tires).

ATTACHMENTS:







Aug. 2019 Fire Inspection Report



EPM Located On Site



US 27 TIRES, LLC

Inspection Date: 02/20/2020

Signed:							
Kaitlyn Newsome	Environmental Specialist II						
PRINCIPAL INSPECTOR NAME	PRINCIPAL INSPECTOR TITLE						
King Van	DEP	03/10/2020					
PRINCIPAL INSPECTOR SIGNATURE	ORGANIZATION	DATE					
Ali Belfakir	Owner						
REPRESENTATIVE NAME	REPRESENTATIVE TITLE						
NO SIGNATURE REQUIRED	US 27 Tires	_					
REPRESENTATIVE SIGNATURE	ORGANIZATION						
NOTE: By signing this document, the Site Rep Report and is not admitting to the accuracy of or areas of concern.							
Report Approvers:							
Annrover: Steve Tafuni	Inspection Approval Date	• 03/16/2020					