## **KERRY BARNETT** FIRE SAFETY CONSULTING

43951 CR 54E, KATHLEEN, FL 33849 813-778-4981 kbarnett@firesafetycons.com

Business Informati Name: Central F	<sub>ion</sub> Iorida Tire Terminal	l Pe	mit Number: n/a		
Address: 301 S Fea	agan Ave		Inspection: Annual  Re-inspection: Yes No Number: 0		
Avon Park					
Contact:		Sc	neduled Date: 4/10/19	Time: 925 am	
Tel No: 863-452-	5788		-inspection Date:	The state of	
Occupancy: Mixed	t	Ins	Inspector: Kerry Barnett		
Inspection Results	Pass	Fail	Condition		
This inspection was co	onducted utilizing the Florid	da Fire Prevention	Code and any other ap	plicable standard or code.	
- Every entrance into a buil - Tire height may not excee - Width of piles may not ex - Separation distance betw - Tire storage shall be reme - Emergency tools shall be - Repair/Reinstall security - Tire storage shall be loca - Tire shavings shall be reme Interior Storage (1 year) - Tire storage may not be in - Tire storage requires mini	ceed 50 feet reen tire piles and buildings to reved from unloading area and kept in at least two different al guards on top of perimeter fen- ted a minimum of 10 ft from penoved from all surface areas a m a row (single row) stacked or imum 18 in from ceiling rows (side to side/end to end/sic	tires shall be a minim out from under roof s reas (list of tools not cing (barbed wire are erimeter fencing, exc and properly disposed or on tread in rack, no	num of 20 feet storage at the unloading a ed in code provided) ea) ept where covered storag	area.	
Inspector Signature:			Date: 4/10/19 Total Time: 1 h 20 r	Time: 1045 am11	