Johnson, Sabrina O

From: Robin G Simons <robing.simons@cemex.com>

Sent: Thursday, July 9, 2020 12:17 PM

To: SWD_Waste Cc: David T Singer

Subject: CEMEX - Q2 Waste Tire Reports

Attachments: Brooksville North_CEMEX_71066066WT_Wast Tire Quarterly Report.pdf; Brooksville South_CEMEX_

2278707WT_2nd QTR Report.pdf

Please find the attached waste tire reports for CEMEX's Brooksville North and Brooksville South cement plants. Contact me if you have any questions.

Thank you,

Robin Simons



Robin Simons

Environmental Manager - Brooksville - United States of America Office: (352) 799-7881 ext. 104 Fax: (352) 799-6088 Mobile: (863)-602-8024

Address: 10311 Cement Plant Road, Brooksville, FL 34601

e-Mail: robing.simons@cemex.com

www.cemexusa.com

CONFIDENTIAL AND ATTORNEY PRIVILEGED: The information contained in this transmission may contain privileged and confidential information. It is intended only for the use of the person(s) named above. If you are not the intended recipient, you are hereby notified that any review, dissemination, distribution or duplication of this communication, and the information contained in it, is strictly prohibited. If you are not the intended recipient, please contact the sender and immediately destroy all copies of the original message.

CONFIDENTIALITY: The information contained in this transmission may contain privileged and confidential information. It is intended only for the use of the person(s) named above. If you are not the intended recipient, you are hereby notified that any review, dissemination, distribution or duplication of this communication, and the information contained in it, is strictly prohibited. If you are not the intended recipient, please contact the sender and immediately destroy all copies of the original message.



July 10th, 2020

Electronic Submittal

Ms. Kaitlyn Newsome Solid Waste Section Florida Department of Environmental Protection Southwest District 13051 N. Telecom Parkway Temple Terrace, FL 33637-0926

Re: CEMEX Construction Materials Florida, LLC, Brooksville North Cement Plant Waste

Tire Processing Facility Quarterly Report, Permit No. 71066-006-WT/02, Facility ID No.

SWD-27-40777

Dear Ms. Newsome:

Please find enclosed the completed Waste Tire Processing Facility Quarterly Report prepared for the aforementioned facility, for the 2nd Quarter of 2020. The Brooksville North Cement Plant was temporarily shut down on December 12, 2008 and remains closed, as of this report.

If there are any questions and/or comments concerning this submittal or you require additional information, please contact me at (352) 799-7881, ext. 104 or robing.simons@cemex.com.

Respectfully,

Robin Simons

Environmental Manager

Kolin Sinces

pc: Zahid Iran Rangel Paz, Plant Manager



Department of Environmental Protection

DEP Form # 62-701.900(21)
Waste Tire Processing Facility
Form Title Quarterly Report
Effective Date 3/22/00
DEP Application No.
(Filled in by DED)

Waste Tire Processing Facility Quarterly Report

Pursuant to Rule 62-711.530, Florida Administrative Code, the owner or operator of a waste tire processing facility shall submit the following information to the Department quarterly.

Quarter covered	by this report	4/1/2020 - 6/30/2020 (First quarter begins on January 1 of any given year)								
1. Facility name	e: CE	MEX Brooksville North Cement Plant								
2. Facility maili	ng address: _	13601 Ponce De Leon Blvd.								
City:	Brooksville		County:	Hernando		Zip: 34614				
3. Facility perm	nit number:	71066-006-WT/02								
4. Facility telep	hone number	(352) 79	9-7881							
5. Authorized person preparing report: Robin Simons										
6. Affiliation w	6. Affiliation with facility: Environmental Manager									
7. Telephone n	umber (if diffe	erent from abo	ve): ()						
8. Activity: R	eport in tons									
	Beginning Inventory	Received	Processed	Consumed	Removed	Adjustments	Ending Inventory			
Used Tires	0	0		0			0			
Other whole Tires										
Processed tires										
Processing Waste										
Other										
Total										
c Euplain all in	u contonu odiuo	tmonto		<u> </u>						
a. Explain all in	iventory adjus	iments.								
	b. List any period in which one or more category of inventory exceeded the permitted maximum for that category. How was that condition relieved?									
	ess inventory a tional sheets,		he quarter, st	ate how and v	when this con	dition will be r	elieved.			
9. Certification										
To the best	of my knowledg	e and belief, I c	ertify the inforr			true, accurate,	and complete.			
	n Simons			Thin Sem		07/10/2020				
Print Nar	me of Authoriz	zed Agent	S	ignature of Au	nt	Date				

Mail complete form to the appropriate district office



July 10th, 2020

Electronic Submittal

Ms. Kaitlyn Newsome Solid Waste Section Florida Department of Environmental Protection Southwest District 13051 N. Telecom Parkway Temple Terrace, FL 33637-0926

Re: CEMEX Construction Materials Florida, LLC, Brooksville South Cement Plant Waste

Tire Processing Facility Quarterly Report Permit No. 22787-007-WT/MM Site

Certification No. PA82-17T

Dear Ms. Newsome:

Please find enclosed the completed Waste Tire Processing Facility Quarterly Report prepared for the aforementioned facility, for the 2nd Quarter of 2020.

No tires were consumed in the 2nd quarter of 2020. Nine tire trailers were shipped off site. The remaining tires and trailers will be removed form the site prior to the end of the year.

If there are any questions and/or comments concerning this submittal or you require additional information, please contact me at (352) 799-7881, ext. 104 or robing.simons@cemex.com.

Respectfully

Robin Simons

Rolin Simone

Environmental Manager

pc: Zahid Iran Rangel Paz, Plant Manager



Department of Environmental Protection

DEP Form # 62-701.900(21)				
Waste Tire Processing Facility				
Form Title Quarterly Report				
Effective Date 3/22/00				
DEP Application No.				
(Filled in by DEP)				

Waste Tire Processing Facility Quarterly Report

Pursuant to Rule 62-711.530, Florida Administrative Code, the owner or operator of a waste tire processing facility shall submit the following information to the Department quarterly.

Qua	rter covered b	y this report	4/1/20 - 6/3	0/2020	(First quarter	begins on Jai	nuary 1	of any	given year)	
1.	Facility name	:CE	MEX Constru	uction Materia	als Florida, Ll	LC				-
2.	Facility mailin	ng address: _	10311 C	ement Plant F	Road					_
	City:	Brooksville		County:	Hernando		Zip:	346	01	_
3.	Facility permi	t number:	22787-007	-WT/MM, PA	82-17T					_
4.	Facility teleph	none number	(352)799-	7881 ext. 10	4					_
5.	Authorized pe	erson preparii	ng report: F	Robin Simons	;					_
6.	Affiliation wit	th facility:	Environmen	tal Manager						•
7.	Telephone nu	ımber (if diffe	erent from abo	ve): ()					•
	Activity: Re				,					,
		Beginning Inventory	Received	Processed	Consumed	Removed	Adjust	tments	Ending Inventory	
	Used Tires	199.5	0.0		0.0	139.5	No tire	es were	e 66e0d during	the quarter. 9
	Other whole Tires									
	Processed tires									
	Processing Waste									
	Other									
	Total									
a.	Explain all inv	entory adjus	tments. No	tires were us	sed during the	e quarter. 9 t	railers w	ere sh	nipped off site	•
b.			ne or more cat condition reliev		ntory exceede	ed the permitt	ed maxi	mum fo	or that	-
	For any exces Attach Additi		at the end of t if necessary.	he quarter, st	ate how and v	when this cor	ndition w	vill be re	elieved.	
9.	Certification: To the best of	f my knowledg	ge and belief, I c	ertify the inforn	11 2 . 1	(4)	s true, ac	curate,	and complete.	•
	Robin Simo				John Se			07/10	/2020	
	Print Nam	e of Authoriz	zed Agent	Si	ignature of Au	ithorized Age	nt		Date	

Mail complete form to the appropriate district office