

Florida Department of Environmental Protection Oil & Gas Program

MONTHLY O&G INSPECTION CHECKLIST

		WELL#& NAME		WELL TYPE		(OG/PA NUMBER		DATE INSPECTED		
	23-4 WATSON					525	309880	2/17/2022			
	OPERATOR WATSON		FIELD			COUNTY API NUMBER					
Е	BREITBURN OPERATING, L.P.				JAY		SANTA ROSA		09-113-20042		
	·							1			
					WELL STATUS					LAST MIT	P F
					PRODUCING					4/17/2019	√
WELL SITE INSPECTION CHECKPOINTS				YES	NO			NO	OTES		
LEGIBLE WELL SIGN POSTED					~						
PAD HOUSEKEEPING SUFFICIENT					>						
PERIM	ETER BE	ERM/DIKE SUF	FICIENT		~						
FLOWL	INE/PIP	ELINE ACCESI	BLE/CLEAN		~						
EVIDENCE OF LEAKS/SPILLS ON PAD/LOCATION					>						
		WELLHEA	DS		YES	NO	NOTES				
PRESSURE GAUGES IN WORKING CONDITION				·	.,,				3.20		
TUBING ANNULAR SURFACE											
	25	0	0		_				PPO	DUCING	
			•		_				FRO	DOCING	
HIGH/LOW FLOWLINE SHUT IN SENSORS											
HIGH: 800 LOW: 0											
CELLAR CONDITION SATISFACTORY				_							
WELLHEAD LEAKING				·	_						
WELLHEAD LEARING											
	HYDRO	OGEN SULFIE	DE DETECTION	N SY	STEM		NO			OTES	
<u>IF YES, FILL OUT</u>				YES	NO						
DETECTION SYSTEM REQUIRED					~						
ENTRY ALARMS IN WORKING CONDITION					~						
SENSORS IN WORKING CONDITION					~						
CHEMICAL ADDITIVE SYSTEM				YES	NO			NO	OTES		
SYSTEM PRESENT					~						
SYSTEM LEAKING						~					
SECONDARY CONTAINMENT PROVIDED					~						
CHEMICALS ON LOCATION				1.)							
					2.)						
1					3 /						



Florida Department of Environmental Protection Oil & Gas Program

MONTHLY O&G INSPECTION CHECKLIST

H'S DETECTION SYSTEM IN PLACE.

SITE IS CLEAN & WELL MAINTAINED. NO EVIDENCE OF LEAKS OR EXCESSIVE CORROSION ON WELLHEAD.

Permit Number	525		
Oculus ID	OG_525	Current Status	PROD
API Number	0911320042	Historical Status	PRODUCER
PA Number	309880	TVD	15,995
Well Name	SAM WATSON ETUX #23-4	MD	15,995
Operator	BREITBURN OPERATING LP	Conductor Casing	16"@ 80'
Field	JAY	Surface Casing	10-3/4" @ 3701
County	SANTA ROSA	Intermediate Casing	NA
Sec/Twp/Range	4S23 5N 29W	Production Casing	7" @ 15995
SHL	1680'FSL&1980'FEL	Tubing	3-1/2"@ 15425'
BHL	SAME	Perforations	15583-15714
Latitude	30.92881049	Plugs	
Longitude	-87.14549034	Issue Date	9/21/1971
		Spud Date	10/19/1971
		Completion Date	11/6/1972
		Plug Date	



WELL SIGN

WELL & PAD

I inspected the above well & premise on February 17, 2022

Signed

OIL AND GAS COORDINATOR

cc: [X]FDEP (Oil & Gas Section): Tallahassee

Form IH-1