

# Florida Department of Environmental Protection Inspection Checklist

# **FACILITY INFORMATION:**

Facility Name: CITRUS CENTRAL SLF

On-Site Inspection Start Date: 12/16/2008
On-Site Inspection End Date: 12/16/2008

**WACS No.:** 39859

Facility Street Address: 3MI E LECANTO, SR44

City: LECANTO

County Name: CITRUS

**Zip:** 34452

#### **INSPECTION PARTICIPANTS:**

(Include ALL Landfill and Department Personnel with Corresponding Titles)

Principal Inspector: Nancy D Gaskin, Inspector
Other Participants: Billy Gilmore; Carmen Bruno

#### **INSPECTION TYPE:**

Routine Operation Inspection for Landfill - Class I facility

Routine Operation Inspection for Other Facilities - Waste Tire Collection Center facility

### ATTACHMENTS TO THE INSPECTION CHECK LIST:

This Cover Page to the Inspection Checklist may include any or all of the following attachments as appropriate.

**SECTION 1.0 - FILE REVIEW** 

SECTION 2.0 - LANDFILL OPERATION AND MAINTENANCE

SECTION 3.0 - LANDFILL LONG-TERM CARE

**SECTION 9.0 - WASTE TIRE FACILITIES** 

# **SECTION 1.0 - FILE REVIEW**

# Requirements:

The requirements listed in this section provide an opportunity for the Department's inspector to indicate the conditions found at the time of the inspection. A "Not Ok" response to a requirement indicates either a potential violation of the corresponding rule or an area of concern that requires more attention. Both potential violations and areas of concern are discussed further at the end of this inspection report.

Item No.	FILE REVIEW (Pre- or Post-Inspection, as appropriate.) Completed	Ok	Not Ok	Unk	N/A
1.1	For landfills, is the method and sequence of filling wastes according to plans? 62-701.500(2)(f)			>	
1.2	For landfills, are the following records being reported to the Department?(Check any that are Not OK.)  Waste reports (quarterly) 62-701.500(4)  Annual estimate of remaining life 62-701.500(13)(c)	<b>&gt;</b>			
1.3	Is leachate sampled, tested and disposed as required? 62-701.500(8)(a) & 62-701.510(6)(c)	٧			
1.4	Is gas monitoring being performed as required by the permit? 62-701.500(9) & 62-701.530(2)	~			
1.5	Are the results of the gas sampling reported to the Department quarterly? 62-701.530(2)	~			
1.6	Is water quality sampling and testing performed according to standard procedures and at the required frequencies? See 62-701.510(2) for landfills; 62-701.730(4)(b) & (10) for C&D debris sites; 62-713.400(3) for stationary soil treatment facilities.	>			
1.7	Do the results of the water quality testing suggest there may be adverse impacts to water quality from the operation of the solid waste facility? 62-701.510(3) & (4)		~		
1.8	For closed landfills and C&D disposal facilities with final elevations higher than 20 feet above grade, has a final survey report verifying the final elevations and contours of the facility been submitted to the Department? 62-701.610(3) & 62-701.730(9)(c)			>	
1.9	Is financial assurance adequate? See 62-701.630 for landfills; 62-710(7)(a) & (10)(a) for WPFs; 62-701.730(11)(a) for C&D debris facilities; 62-713.600(6)(a) for stationary soil treatment facilities; 62-711.500(3) for waste tire facilities. NOTE: The Solid Waste Financial Coordinator in Tallahassee can assist with this information.			>	
1.10	Are cost estimates current and adjusted every year? See 62-701.630(4) for landfills; 62-701.710(7)(b) & (10)(a) for WPFs; 62-701.730(11)(b) for C&D debris facilities; 62-713.600(6)(b) & (c) for stationary soil treatment facilities; 62-711.500(3) for waste tire facilities.	~			
1.11	For C&D debris disposal and disposal with recycling facilities, is an Annual Report submitted to the Department for the disposal operation by April 1st of each year? 62-701.730(12)				~
1.12	For C&D recycling facilities with no disposal, is an Annual Report for the recycling operation submitted to the Department by April 1st of each year? 62-701.710(9)(b)				~
1.13	For compost facilities, has the compost product been sampled and analyzed every 20,000 tons or every 3 months (whichever is sooner)? 62-709.530(1)				~
1.14	For compost facilities, has the annual report been submitted by June 1st? 62-709.530(3)				~

# **SECTION 2.0 - LANDFILL OPERATION AND MAINTENANCE**

# Requirements:

The requirements listed in this section provide an opportunity for the Department's inspector to indicate the conditions found at the time of the inspection. A "Not Ok" response to a requirement indicates either a potential violation of the corresponding rule or an area of concern that requires more attention. Both potential violations and areas of concern are discussed further at the end of this inspection report.

Item No.	SOLID WASTE PROHIBITIONS (unless "grandfathered" in, see 62-701.300(16)) Completed	Ok	Not Ok	Unk	N/A
2.1	Unauthorized disposal/storage prohibited, except yard trash, within 500' of a potable water well? 62-701.300(2)(b)	٧			
2.2	Unauthorized disposal/storage prohibited, except yard trash, within 1000' of a potable water well serving a community water system? 62-701.300(2)(h)	>			
2.3	Unauthorized storage/disposal of yard trash prohibited within the minimum setbacks of (Check any that are Not OK) 62-701.300(12)  100 feet for potable water wells (except on-site)?  50 feet for water bodies?  200 feet for community water supply wells?	>			
2.4	Unauthorized disposal/storage prohibited in an area subject to frequent and periodic flooding unless flood protection measures in place? 62-701.300(2)(d)	>			
2.5	Unauthorized disposal/storage prohibited in any natural or artificial body of water including ground water? 62-701.300(2)(e)	~			
2.6	Unauthorized disposal/storage prohibited, except yard trash, within 200' of any natural or artificial body of water, including wetlands without permanent leachate controls, except impoundments or conveyances which are part of an on-site, permitted stormwater management system or on-site water bodies with no off-site discharge? 62-701.300(2)(f)	>			
2.7	Unauthorized open burning of solid waste prohibited except in accordance with Department requirements? 62-701.300(3)	~			
2.8	Are the following prohibited wastes or special wastes properly controlled, managed and disposed? (Check any that are Not OK)  Hazardous waste 62-701.300(4)  Biomedical waste 62-701.300(6)  Yard trash 62-701.300(8)(c)  Whole waste tires 62-701.300(8)(e)  Used oil, except as exempted 62-701.300(11)  Lead-acid batteries, mercury-containing switches and lamps in WTEs 62-  PCB wastes 62-701.300(5)  Lead-acid batteries 62-701.300(8)(a)  White goods 62-701.300(8)(d)  Liquids 62-701.300(10)	>			
2.9	Are only permitted waste types disposed at facility? 62-701.340(3), 62-701.500(6)(a)&(2)(c)	~			

Item No.	LANDFILL OPERATION AND MAINTENANCE Completed	Ok	Not Ok	Unk	N/A
2.10	Is there a trained operator on-site at Class I and III landfills when receiving wastes? 62-701.500(1)	~			
2.11	Is there at least one spotter at each working face when receiving wastes at Class I and III landfills? 62 -701.500(1)	~			
2.12	Are the following records or plans current and available on-site? (Check any that are Not OK.)  Training Plan 62-701.320(15)(a)  Operating Plan 62-701.500(2)  Waste weight records 62-701.500(4)  Precipitation records 62-701.500(8)(g)  Load-checking program records 62-701.500(6)(a)  Training records 62-701.320(15)(a)	<b>&gt;</b>			

Item No.	LANDFILL OPERATION AND MAINTENANCE Completed	Ok	Not Ok	Unk	N/A
2.12	Operation record 62-701.500(3)	93			
	Quantity of leachate 62-701.500(8)(f)	~			
2.13	Is the operation plan substantially followed? 62-701.500(2)		~		
2.14	Is incoming waste weighed? 62-701.500(4)(a)&(2)(d)	~			
2.15	Is the method and sequence of filling wastes according to plans? 62-701.500(2)(f)	~			
2.16	Is access properly controlled to prevent unauthorized waste disposal? 62-701.500(5)	~			
2.17	Is waste compacted as required? 62-701.500(7)(a)	~			
2.18	Are the working face and side slopes above ground graded to a slope no greater than 3 ft. horizontal to 1 ft. vertical rise? 62-701.500(7)(c)	~			
2.19	Is a narrow working face practiced? 62-701.500(7)(d)	~			
2.20	Is the frequency, amount and quality of initial cover, as required? 62-701.500(7)(e)		~		
2.21	Is the frequency, amount and quality of intermediate cover, as required? 62-701.500(7)(f)		~		
2.22	Is litter controlled and are litter control devices maintained? 62-701.500(7)(i) and (11)(f)	~			
2.23	Is erosion control adequate? 62-701.500(7)(j)	~			
2.24	Is the leachate collection and removal system maintained and operated as required? 62-701.500(2)(j), 62-701.500(8)(b) & (h)	~			
2.25	Is leachate disposed of or treated as required? 62-701.500(8)(b), (c) and (d)	~			
2.26	If leachate recirculation is practiced at the facility, is it done in accordance with Department requirements and the Operation Plan? 62-701.400(5)				~
2.27	Is gas controlled to not cause objectionable odors beyond the property boundary? 62-701.530(3)(b)	^			
2.28	Is gas controlled to not allow combustible gas concentrations to exceed specified limits? 62-701.530(3)(a)	~			
2.29	Are gas vents intact and functioning properly? 62-701.500(9) & 62-701.530(1)(a)3.				٧
2.30	Is mixing of leachate and stormwater prevented or minimized? 62-701.500(10) & 62-701.400(9)(c)	~			
2.31	Is stormwater management system maintained and operated as required? 62-701.500(10)	~			
2.32	Is there sufficient operating equipment? 62-701.500(11)(a)	~			
2.33	Is there sufficient reserve equipment (or other arrangements)? 62-701.500(11)(b)	~			
2.34	Are communication facilities adequate? 62-701.500(11)(c)	~			
2.35	Are approved dust control methods adequate? 62-701.500(11)(d)	~			
2.36	Are fire protection and fire fighting capabilities adequate and operational? 62-701.500(11)(e)	~			
2.37	Are there required signs for operational directions and public information? 62-701.500(11)(g)	~			
2.38	Are all-weather access roads and inside perimeter roads properly maintained? 62-701.500(12)	~			
2.39	Are ground water wells intact and properly maintained? 62-701.510(2)(b), 62-701.620(9)			~	
2.40	Are all specific conditions in the permit being followed? 62-701.320(1)		~		

# **SECTION 3.0 - LANDFILL LONG-TERM CARE**

#### Requirements:

The requirements listed in this section provide an opportunity for the Department's inspector to indicate the conditions found at the time of the inspection. A "Not Ok" response to a requirement indicates either a potential violation of the corresponding rule or an area of concern that requires more attention. Both potential violations and areas of concern are discussed further at the end of this inspection report.

Type Of Cover: PVC/Soil Closure/Final Cover Date:01/01/1990

Post-Closure Firearms training facility
Surrounding Land Use: Withlacochee state forrest

Item No.	LANDFILL LONG-TERM CARE Completed	Ok	Not Ok	Unk	N/A
3.1	Is site access controlled to prevent any unauthorized dumping? 62-701.600(5)(i)	~			
3.2	Are any unauthorized wastes stored or disposed at the site? 62-701.600(5)(i)	~			
3.3	Is stormwater management system maintained and operated as required? 62-701.600(5)(h)	~			
3.4	Is the final cover properly vegetated? 62-701.600(5)(f)2.	~			
3.5	Are there any signs of erosion of the final cover? 62-701.600(5)(f)2.	~			
3.6	Is there any evidence of damage to the barrier layer of the final cover? 62-701.620(1)	~			
3.7	Are areas of differential settlement being properly filled? 62-701.600(5)(f)4.	~			
3.8	Are there any areas of ponding water on the final cover? 62-701.600(5)(f)3.	~			
3.9	Is the leachate collection and removal system maintained and operated as required? 62-701.500(2)(j), 62-701.500(8)(b) & (h)				~
3.10	Is leachate disposed of or treated as required? 62-701.500(8)(b), (c) and (d)				~
3.11	Are there any signs of leachate seeps at the closed landfill? 62-701.500(8)(b) and 62-701.620(1)	~			
3.12	Condition of the ground water monitoring wells. 62-701.620(1) (Check any that are Not OK.)				
	Access to monitoring wells			. 84	
	Damage to monitoring wells			~	
	Monitoring wells protected, secured and labeled.				
3.13	Are the wells for gas monitoring and detection intact and operable? 62-701.620(5)			~	
3.14	Is the gas collection system (active or passive) operating and maintained? 62-701.620(5)	~			
3.15	Is gas monitoring being conducted as required? 62-701.620(5)	~			
3.16	Are there any signs of stressed vegetation of the final cover? 62-701.620(5)	~			
3.17	Is there any evidence that gas pressure is interfering with or causing failure of the final cover? 62-701.530(1)(a)4.	~			
3.18	If required, are survey monuments properly installed? 62-701.610(2)			~	
3.19	Is there a potential hazard to public health and the environment resulting from the post-closure utilization of the landfill? 62-701.610(7)	~			
3.20	Is there a potential hazard to public health resulting from land-use changes surrounding the closed landfill?	~			
3.21	If waste is being relocated, is this performed according to the Department's requirements? 62-701.620(8)	~			
3.22	Are all specific conditions in the closure or long-term care permit being followed? 62-701.620(2)	~			

# **SECTION 9.0 - WASTE TIRE FACILITIES**

# Requirements:

The requirements listed in this section provide an opportunity for the Department's inspector to indicate the conditions found at the time of the inspection. A "Not Ok" response to a requirement indicates either a potential violation of the corresponding rule or an area of concern that requires more attention. Both potential violations and areas of concern are discussed further at the end of this inspection report.

Item	SOLID WASTE PROHIBITIONS (unless "grandfathered" in, see 62-	Ok	Not	Unk	N/A
No.	701.300(16)) Completed		Ok		
9.1	Unauthorized disposal/storage prohibited, except yard trash, within 500' of a potable water well? 62-701.300(2)(b)	>			
9.2	Unauthorized disposal/storage prohibited, except yard trash, within 1000' of a potable water well serving a community water system? 62-701.300(2)(h)	>			
9.3	Unauthorized storage/disposal of yard trash prohibited within the minimum setbacks of (Check any that are Not OK) 62-701.300(12)				
	100 feet for potable water wells (except on-site)?	~			
	50 feet for water bodies?				
	200 feet for community water supply wells?				
9.4	Unauthorized disposal/storage prohibited in an area subject to frequent and periodic flooding unless flood protection measures in place? 62-701.300(2)(d)	>			
9.5	Unauthorized disposal/storage prohibited in any natural or artificial body of water including ground water? 62-701.300(2)(e)	>			
9.6	Unauthorized disposal/storage prohibited, except yard trash, within 200' of any natural or artificial body of water, including wetlands without permanent leachate controls, except impoundments or conveyances which are part of an on-site, permitted stormwater management system or on-site water bodies with no off-site discharge? 62-701.300(2)(f)				
9.7	Unauthorized open burning of solid waste prohibited except in accordance with Department requirements? 62-701.300(3)	~			
9.8	Are the following prohibited wastes or special wastes properly managed? (Check any that are Not OK)				
	Hazardous waste 62-701.300(4)				i
	Biomedical waste 62-701.300(6)				
	Yard trash 62-701.300(8)(c)				
	Whole waste tires 62-701.300(8)(e)				
	Used oil, except as exempted 62-701.300(11)	~			
	Lead-acid batteries, mercury-containing switches and lamps in WTEs 62-				
	PCB wastes 62-701.300(5)				
	Lead-acid batteries 62-701.300(8)(a)				
	White goods 62-701.300(8)(d)				
	Liquids 62-701.300(10)				

Item No.	WASTE TIRE FACILITY - GENERAL REQUIREMENTS FOR STORAGE Completed	Ok	Not Ok	Unk	N/A
9.9	If the facility accepts tires from the public, is a sign posted at the facility entrance stating operating hours, cost of disposal and site rules? 62-711.540(1)(a)	>			
9.10	Are operations involving the use of open flames conducted no closer than 25 feet of a waste tire pile? 62-711.540(1)(b)	>			
9.11	If the facility accepts tires from the public, is an attendant always present on site when the site is open for business? 62-711.540(1)(c)	>			
9.12	Are fire protection services assured through notification to local fire protection authorities? 62-711.540(1)(d)	~			
9.13	Is an annual fire safety survey conducted? 62-711.540(1)(d)	~			
9.14	Is a copy of the annual fire safety report made part of the next quarterly report? 62-711.540(1)(d)			٧	
9.15	Does the facility have an Emergency Preparedness Manual (EPM) on-site? 62-711.540(1)(e)	>			
9.16	Does the EPM contain the following information? (Check all that are Not OK.)  Contact names and numbers 62-711.540(1)(e)1.	>			

CITRUS CENTRAL SLF Page 7 of 10

Inspection Date: 12/16/2008

Item No.	WASTE TIRE FACILITY - GENERAL REQUIREMENTS FOR STORAGE Completed	Ok	Not Ok	Unk	N/A
9.16	List of emergency response equipment and locations on-site 62-711.540  Procedures to be followed in the event of a fire 62-711.540(1)(e)3.	~			
9.17	Is the operator at the facility maintaining records of the quantity of WT received at the site, stored at the site, and shipped from the site? 62-711.540(1)(g) and 62-711.400(5)	~			
9.18	If the operator of the site is not the owner of the property, has written authorization been obtained from the property owner to operate the facility? 62-711.540(1)(h)	>			
9.19	Is adequate communications equipment available at the site? 62-711.540(1)(i)	~			
9.20	Is the owner or operator providing for control of mosquitoes and rodents so as to protect the public health and welfare? 62-711.540(1)(j)	>			

Item No.	WASTE TIRE FACILITY - STORAGE INDOORS Completed	Ok	Not Ok	Unk	N/A
9.21	Are WT piles more than 50 feet in width? 62-711.540(2)(a)				>
9.22	Are WT piles along a wall more than 25 feet in width? 62-711.540(2)(a)				~
9.23	Are widths of main aisles between piles less than 8 feet? 62-711.540(2)(b)				~
9.24	Is there less than 3 feet of clearance between the top of storage to sprinkler detectors or roof structures? 62-711.540(2)(c)				~
9.25	Is there less than 3 feet of clearance between waste tire piles and unit heaters, etc.? 62-711.540(2)(c)				~
9.26	If waste tires are stored up to15 feet in height, do walls have at least a 4-hour fire rating? 62-711.540(2)(e)				<b>Y</b>
9.27	If waste tires are stored >15 feet in height, do walls have a fire rating of not less than 6 hours and columns one hour FR? If > 20 feet, do columns and its connections with other structural members have two hour FR? 62-711.540(2)(f)				~
9.28	Is the access controlled through the use of doors, fences, gates, natural barriers or other means? 62-711.540(2)(h)				~

Item No.	WASTE TIRE FACILITY - STORAGE OUTDOORS Completed	Ok	Not Ok	Unk	N/A
9.29	Is the waste tire site operated >200 feet from a body of water? 62-711.540(3)(a)	~			
9.30	Does the waste tire pile have a width < 50 feet? 62-711.540(3)(b)	~			
9.31	Does the waste tire pile have an area < 10,000 sq. ft? 62-711.540(3)(b)	~			
9.32	Does the waste tire pile have a height < 15 ft.? 62-711.540(3)(b)	~			
9.33	Is there a 50 ft. wide fire lane around the perimeter of the waste tire pile? 62-711.540(3)(c)	~			
9.34	Is there unobstructed access to the fire lane? 62-711.540(3)(c)	~			
9.35	Is the access controlled through the use of doors, fences, gates, natural barriers or other means? 62-711.540(3)(d)	~			
9.36	Is the site kept free of grass, underbrush, and other potentially flammable vegetation? 62-711.540(3)(f)	~			
9.37	Is the site bermed or given other adequate protection to prevent liquid runoff from entering water bodies? 62-711.540(3)(e)	~			
9.38	Are residuals contained on-site and disposed of in a permitted SW management facility? 62-711.540(5)				~
9.39	Does the waste tire site qualify for the exceptions to the technical and operational standards as allowed by rule? 62-711.540(6)			~	

Item No.	WASTE TIRE FACILITY - COLLECTION CENTER Completed	Ok	Not Ok	Unk	N/A
9.40	Are no more than 1500 tires at the CC at any one time? 62-711.550(1)(a)				~
9.41	Are all waste tires, which are not used tires, removed from site yearly for recycling, processing, or disposal? 62-711.550(1)(b)				~

# **Pre-existing Potential Violations:**

Area: Phase II Landfill Rule: 62-701.500(7)(f)

Question Number: 2.21

Explanation: Minor flagging and small spots of exposed waste were observed in an area to the west

of the working face Spots of exposed waste were primarily isolated and along the northern half of the current lift. Some areas of exposed waste were on the access road used for equipment coming into the western end of the cell. Minor flagging was

observed on the southern side of this access road.

Corrective Action: Please spot repair the cover in these areas and reinforce the access rd with additional

cover to avoid this issue as the road continues to be used.

#### **Attachments:**

# Flagging on roadway



# Small spot of exposed waste



Rule: 62-701.510(3), 62-701.510(4)

Question Number: 1.7

Explanation: The results of the January 2008 sampling event continue to show impacts to ground

water quality at compliance well MW-10.

Corrective Action: The Department's letter dated September 4 2008 requires the County to submit a Site

Assessment Report Addendum that provides alternate conclusions and recommendations regarding future assessment or remedial activities.

### **Pre-existing Area Of Concern:**

Area: Phase II Landfill

Rule: 62-701.500(7)(e)

Question Number: 2.20

Explanation: During the inspection, the working face was in the east half of the current lift. Minor

flagging and small spots of exposed waste were observed in an area immediately adjaccent to the working face. Some of this was the in the traffic path of the compactor

and dump trucks some was not.

Corrective Action: Monitor this area and repair flagging outside of working face and traffic patterns

# **Attachments:**

# Flagging adjacent to the WF



Rule: 62-701.500(2)

Question Number: 2.13

Explanation: See items 2.20 & 2.21

Rule: 62-701.320(1)

Question Number: 2.40

Explanation: See items 2.20 & 2.21.

Signed:		
Nancy D Gaskin	Inspector	
PRINCIPAL INSPECTOR NAME	PRINCIPAL INSPECTOR TITLE	
Cancy I Gushin		12/30/2008
PRINCIPAL INSPECTOR SIGNATURE		DATE
Billy Gilmore	<u> </u>	
REPRESENTATIVE NAME		
NO SIGNATURE	Citrus Co	
REPRESENTATIVE SIGNATURE	ORGANIZATION	
Carmen Bruno		
REPRESENTATIVE NAME	<u> </u>	
NO SIGNATURE	Citrus	
REPRESENTATIVE SIGNATURE	ORGANIZATION	

NOTE: By signing this document, the Site Representative only acknowledges receipt of this Inspection Report and is not admitting to the accuracy of any of the items identified by the Department as "Not Ok" or areas of concern.