



Florida Department of Environmental Protection Oil & Gas Program

Permit # **525**

MONTHLY O&G INSPECTION CHECKLIST

WELL # & NAME	WELL TYPE	OG/PA NUMBER	DATE INSPECTED
23-4 WATSON	PRODUCER	OG_525/309880	1/2/2019
OPERATOR	FIELD	COUNTY	API NUMBER
BREITBURN OPERATING, L.P.	JAY	SANTA ROSA	09-113-20042

WELL STATUS	LAST MIT	P	F
SHUT IN (NEED REPAIRS)	6/17/2014	✓	

WELL SITE INSPECTION CHECKPOINTS	YES	NO	NOTES
LEGIBLE WELL SIGN POSTED	✓		
PAD HOUSEKEEPING SUFFICIENT	✓		
PERIMETER BERM/DIKE SUFFICIENT	✓		
FLOWLINE/PIPELINE ACESIBLE/CLEAN	✓		
EVIDENCE OF LEAKS/SPILLS ON PAD/LOCATION		✓	

WELLHEADS	YES	NO	NOTES
PRESSURE GAUGES IN WORKING CONDITION	✓		
TUBING			
ANNULAR			
SURFACE			
200 240 0	✓		SI 12.3.18
HIGH/LOW FLOWLINE SHUT IN SENSORS LOCATED NEAR WELLHEAD	✓		
HIGH: 800 LOW: 0			
CELLAR CONDITION SATISFACTORY	✓		
WELLHEAD LEAKING		✓	

HYDROGEN SULFIDE DETECTION SYSTEM	YES	NO	NOTES
IF YES, FILL OUT			
DETECTION SYSTEM REQUIRED	✓		
ENTRY ALARMS IN WORKING CONDITION	✓		
SENSORS IN WORKING CONDITION	✓		

CHEMICAL ADDITIVE SYSTEM	YES	NO	NOTES
SYSTEM PRESENT	✓		
SYSTEM LEAKING		✓	
SECONDARY CONTAINMENT PROVIDED	✓		
CHEMICALS ON LOCATION	1.)		CORROSION/SCALE INHIBITOR
	2.)		
	3.)		



Florida Department of Environmental Protection Oil & Gas Program

Permit # **525**

MONTHLY O&G INSPECTION CHECKLIST

525 IS AN INACTIVE PRODUCER; WAS SHUT IN ON 12.3.18.

WELL WILL REMAIN SHUT IN UNTIL REPAIRS ARE MADE & AN MIT IS PASSED BEFORE BEING RETURNED TO SERVICE.

H'S DETECTION SYSTEM IN PLACE.

SITE IS CLEAN & WELL MAINTAINED. NO EVIDENCE OF LEAKS OR EXCESSIVE CORROSION ON WELLHEAD.

Permit Number	525	Current Status	PROD
Oculus ID	OG_525	Historical Status	PRODUCER
API Number	0911320042	TVD	15,995
PA Number	309880	MD	15,995
Well Name	SAM WATSON ETUX #23-4	Conductor Casing	16" @ 80'
Operator	BREITBURN OPERATING LP	Surface Casing	10-3/4" @ 3701
Field	JAY	Intermediate Casing	NA
County	SANTA ROSA	Production Casing	7" @ 15995
Sec/Twp/Range	4S23 5N 29W	Tubing	3-1/2" @ 15425'
SHL	1680'FSL&1980'FEL	Perforations	15583-15714
BHL	SAME	Plugs	
Latitude	30.92881049	Issue Date	9/21/1971
Longitude	-87.14549034	Spud Date	10/19/1971
		Completion Date	11/6/1972
		Plug Date	



WELL SIGN



WELL & PAD

I inspected the above well & premise on January 2, 2019

Signed

John L. Leccese
OIL AND GAS COORDINATOR

cc: [X] FDEP (Oil & Gas Section): Tallahassee

Form IH-1