Compliance file

FLORIDA TIRE & RECYCLING

DEC 15, 1993 — Surface water samples.

St. Lucie Co.



Sample site at North end of culvert, entrance to Dairy Feed Inc



2nd Sample at North end of culvert South of FTR Property





Third sample North end of culvert at the entrance of FTR.

South of FTR property



Plug closing the canal discharge

