



Department of Environmental Protection

Lawton Chiles
Governor

Southeast District
P.O. Box 15425
West Palm Beach, Florida 33416

Virginia B. Wetherell
Secretary

Certified Mail
Return Receipt Requested

March 4, 1998

Mr. David Quarterson
Florida Tire Recycling, Inc.
9675 Range Line Road
Port St. Lucie, FL 34987

St. Lucie County
SW - FTRI
Permit Files

Dear Mr. Quarterson:

On August 10, 1994, you were notified that your application for a solid waste management permit, DEP file number 41202-SO-001 (formerly WT 56-252068), was incomplete. The required information necessary to complete your application is itemized (copy attached).

It has been 1248 days since we notified you of the deficiencies in your application. Please submit the itemized information within thirty (30) days of receipt of this letter.

Sincerely,

Joseph Lurix

Joseph Lurix, Engineer
Solid Waste Section

enclosure(s)

attachment

cc: Inger Hansen, MSSW/WPB
Joseph T. Friscia, P.E.
Al Ford, OGC/TLH
Chris McGuire, OGC/TLH
Frances Keith, SW/TLH

Please advise us if:

- ☐ You wish to withdraw your application.
- ☒ You need additional time to obtain the required information and we will receive the information in approximately 30 days.
- ☐ You have questions about our request and you wish to discuss your application with us.

You may check more than one of these items. Please sign and return this cover letter to us within 15 days of the day you receive it.

DEP File No. 41202-SC-001 Signature

David Quarterson
March 10, 1998

"Protect, Conserve and Manage Florida's Environment and Natural Resources"

Printed on recycled paper.

Florida Tire Recycling, Inc.
Page 2 of 2

41202-SO-001 (formerly WT 56-252068)

In order to complete review of your application pursuant to Sections 403.087(4), and 403.707, Florida Statutes (F.S.) and Rules 62-711.530 and 62-711.540 Florida Administrative Code (F.A.C.), please provide the following information below.

1. Please clarify the depth of the existing well in the northeast portion of the property as shown on the revised plot plan. The plot plan shows depth of the well to be 40 feet and the written response states 60 feet.
2. Please provide a copy of a recent fire survey conducted by a fire protection authority in accordance with Rule 62-711.540(1)(d), Florida Administrative Code to support the renewal of this application.
3. Please provide a list of the processing equipment that is used at this site, along with the projected daily and annual processing rates of the equipment for waste tires.

Is your RETURN ADDRESS completed on the reverse side?

SENDER:

- Complete items 1 and/or 2 for additional services.
- Complete items 3, 4a, and 4b.
- Print your name and address on the reverse of this form so that we can return this card to you.
- Attach this form to the front of the mailpiece, or on the back if space does not permit.
- Write "Return Receipt Requested" on the mailpiece below the article number.
- The Return Receipt will show to whom the article was delivered and the date delivered.

I also wish to receive the following services (for an extra fee):

1. ☐ Addressee's Address
2. ☐ Restricted Delivery

Consult postmaster for fee.

3. Article Addressed to:

David Guenterson
Florida Tire Recycling
9675 Range Line Road
Port St. Lucie, FL 34989

REF-41202-50-001

5. Received By: (Print Name)

D. Guenterson

6. Signature: (Addressee or Agent)

X

4a. Article Number

7109457588

4b. Service Type

- | | |
|---|---|
| <input type="checkbox"/> Registered | <input checked="" type="checkbox"/> Certified |
| <input type="checkbox"/> Express Mail | <input type="checkbox"/> Insured |
| <input type="checkbox"/> Return Receipt for Merchandise | <input type="checkbox"/> COD |

7. Date of Delivery

3-5-98

8. Addressee's Address (Only if requested and fee is paid)

PS Form 3811, December 1994

Domestic Return Receipt

Thank you for using Return Receipt Service.