



Florida Department of Environmental Protection
Twin Towers Office Bldg. 2600 Blair Stone Road, Tallahassee, Florida, 32399-2400
Division of Waste Management
Petroleum Storage Systems
Storage Tank Facility Routine Compliance Site Inspection Report

Facility Information:

Facility ID: 9046767 County: CHARLOTTE Inspection Date: 09/05/2018
Facility Type: A - Retail Station
Facility Name: MOBIL-PUNTA GORDA #758 # of Inspected ASTs: 0
3949 TAMIAMI TRL USTs: 2
PUNTA GORDA, FL 33950-7904 Mineral Acid Tanks: 0
Latitude: 26° 53' 28.1562"
Longitude: 82° 1' 28.2448"
LL Method: DPHO

Inspection Result:

Result: In Compliance

Signatures:

TKLENR - LEE COUNTY DIVISION OF NATURAL RESOURCES (239) 533-8129

Storage Tank Program Office and Phone Number

Mark Allen Sautter

Mike Bateman

Inspector Name

Representative Name

Inspector Signature
Principal Inspector
LEE COUNTY DIVISION OF NATURAL
RESOURCES

Representative Signature
APEC

Owners of UST facilities are reminded that the Federal Energy Policy Act of 2005 and 40 CFR 280 Subpart J, requires Operator Training at all facilities by October 13, 2018. For further information please visit:
<https://floridadep.gov/waste/permitting-compliance-assistance/content/underground-storage-tank-operator-training>

Financial Responsibility:

Financial Responsibility: FULLY FUNDED TRUST

Insurance Carrier:

Effective Date: 05/31/2018 Expiration Date: 05/31/2019

Findings:

Class B Maintenance Training Certificates are present.

Completed System Tests

Type	Date Completed	Results	Reviewed	Next Due Date	Comment
Annual Operability Test	04/25/2018	Passed	09/26/2018	04/25/2019	Testing conducted by Hy-Tech Petroleum
Annual Inline Leak Detector Test	04/25/2018	Passed	09/26/2018	04/25/2019	Testing conducted by Hy-Tech Petroleum

Reviewed Records

Record Category	Record Type	From Date	To Date	Reviewed Record Comment
Two Years	Monthly Maint. Visual Examinations and Results	09/09/2016	08/11/2018	Records associated with monthly visuals
Two Years	Certificate of Financial Responsibility	12/31/2015	12/31/2017	

Inspection Comments

09/05/2018

Checked required documentation (Visuals, insurance, maintenance records, etc..) along with required storage tank components (Tanks, lines, spill buckets, hoses, etc...)

Updated registration info as needed.

Alarm/Maintenance History:
Nothing significant to note.