



Florida Department of Environmental Protection

Central District
3319 Maguire Boulevard, Suite 232
Orlando, Florida 32803-3767

Charlie Crist
Governor

Jeff Kottkamp
Lt. Governor

Michael W. Sole
Secretary

CERTIFIED MAIL

7006 0810 0000 0865 7970

Mr. Bart D. Phillips
419 Metal and Auto Recycling Center, Inc.
600 Old Sanford Oviedo Road
Winter Springs, FL 32708-2646

OCD-HW-C/E-07-185

Seminole County - HW
419 Metal and Auto Recycling Center, Inc.
FLR000026625
OGC 05-0188
Review of "Interim Source Removal Report"

Dear Mr. Phillips:

We have reviewed the above referenced document from your consultant, W. Z. Baumgartner & Associates, dated August 6, 2007 and received August 10, 2007. Following are our comments:

1. Ground water sampling was to be done for lead and arsenic. Lead results were not submitted.
2. Arsenic results were submitted, but the turbidity was >500 NTUs. Field measured turbidity for a properly designed, constructed, and developed well should not exceed 20 Nephelometric Turbidity Units (NTUs) during ground water sampling. If turbidity values are high the monitoring well may have to be abandoned and a new properly designed well will need to be installed.
3. Because of the issues cited in Paragraphs 1 & 2, another water sample is required to be taken and sampled for lead and arsenic. The results of that sampling will determine the need for further action.
4. Sampling reports must include the attached Ground Water Sampling Log.

The resampling report must be submitted to the Department with 45 days of receipt of this letter.

The Department must have at least 10 days notice before the water sampling is conducted.

Please contact me by e-mail at marjorie.heidorn@dep.state.fl.us or phone at (407) 893-3320 with questions.

Sincerely,

Marjorie Heidorn, P.G.
SW/HW Technical Support

Date: October 17, 2007

Enclosure: Ground Water Sampling Log

cc: Michael Tant, P.E., W. Z. Baumgartner & Associates, metant1@comcast.net

