



FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

HAZARDOUS WASTE INSPECTION REPORT

Facility Information:

Facility Name: Cliff Berry Inc

On-Site Inspection Start Date: 08/25/2008

On-Site Inspection End Date: 08/25/2008

ME ID#: 13562

EPA ID#: FLR000013888

Facility Street Address: 5218 Saint Paul St, Tampa, Florida 33619-6118

Mailing Address: PO Box 13079, Fort Lauderdale, FL 33316-0100

County Name: Hillsborough

Phone: (954) 763-3390

NOTIFIED AS:

Transporter

TSD Facility Unit Type(s)

Used Oil

CURRENT STATUS:

Transporter

Transfer Facility

Used Oil

FACILITY TYPE:

Transporter

Transfer Facility

Used Oil

INSPECTION TYPE:

Routine

Routine

Routine

Inspection Participants:

Principal Inspector: Tara A Swanson

Other Participants: Bob Soich, Dan Stone

LATITUDE / LONGITUDE: Lat 27° 55' 12.3033" / Long 82° 23' 43.3281"

SIC CODE: 5093 - Wholesale trade - scrap and waste materials

TYPE OF OWNERSHIP:

Private



FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

HAZARDOUS WASTE INSPECTION REPORT

Introduction:

Cliff Berry, Inc. (CBI - Tampa) was inspected on August 25, 2008 to determine the facility's compliance with its Used Oil Processing Permit and Federal and State Hazardous waste transporter and used oil regulations. Dan Stone, Facility Manager, accompanied the inspectors throughout the inspection. The facility is generating less than 100 kg of hazardous waste a month. The facility has seven drivers and five facility personnel.

Process Description:

CBI transports and temporarily stores used oil, oily water, used oil filters, solids contaminated with oil and used antifreeze. CBI has a tank farm with ten tanks for the storage of used oil/oily water and one tank for the storage of used antifreeze. All tanks were labeled. There is an office, small maintenance area and two storage buildings on site. The storage buildings on site are for the storage of spill response equipment and empty drums.

The final destination facility for all used oil, oily water, used oil filters, used antifreeze and contaminated solids is the Cliff Berry, Miami facility.

CBI - Tampa drivers transport hazardous waste under the Ft Lauderdale ID number (FLR 000 083 071) to Freehold Cartage, EQ of Florida or Clean Harbors of Florida. The hazardous waste is not brought to the CBI - Tampa facility.

CBI - Tampa conducts routine preventative maintenance on their vehicles. There is a small parts washer in the maintenance building that uses a soap/water mixture. The waste sludge from the parts washer is transported under CBI - Tampa's ID number as a non-hazardous waste to CBI - Miami.

Violations Summary

Violations

No Violations

Areas of Concern

No Areas of Concern

Conclusion:

At the time of the inspection CBI - Tampa was operating in compliance with its permit and Federal and State hazardous waste transporter and used oil regulations.

History:

Activity Closed Date: 09/23/2008

Activity Result: In Compliance

Signed:



**FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION
HAZARDOUS WASTE INSPECTION REPORT**

FDEP SWD Division of Waste Management
ORGANIZATION

Environmental Specialist II
INSPECTOR TITLE

Bob Soich
INSPECTOR NAME

NO SIGNATURE REQUIRED
INSPECTOR SIGNATURE

FDEP SWD Division of Waste Management
ORGANIZATION

Environmental Specialist II
PRINCIPAL INSPECTOR TITLE

Tara A Swanson
PRINCIPAL INSPECTOR NAME

PRINCIPAL INSPECTOR SIGNATURE

8/29/2008
DATE

CBI - Tampa
ORGANIZATION

Facility Manager
REPRESENTATIVE TITLE

Dan Stone
REPRESENTATIVE NAME

NO SIGNATURE REQUIRED
REPRESENTATIVE SIGNATURE

NOTE: By signing this document, the Site Representative only acknowledges receipt of this Inspection Report and is not admitting to the accuracy of any of the items identified by the Department as "Not Ok" or areas of concern.