



Florida Department of
Environmental Protection
Hazardous Waste Inspection Report

FACILITY INFORMATION:

Facility Name: McKenzie Tank Lines Inc

On-Site Inspection Start Date: 01/22/2009

On-Site Inspection End Date: 01/22/2009

ME ID#: 7388

EPA ID#: FL0000347815

Facility Street Address: 535 Port Leon Drive, Saint Marks, Florida 32355

Contact Mailing Address: PO Box 155, Saint Marks, Florida 32355-0155

County Name: Wakulla

Contact Phone: (850) 925-6309

NOTIFIED AS:

SQG (100-1000 kg/month)

Transporter

INSPECTION TYPE:

Routine Inspection for Used Oil facility

Routine Inspection for CESQG (<100 kg/month) facility

INSPECTION PARTICIPANTS:

Principal Inspector: Nicole McDonald, Inspector

Other Participants: John Johnson, Inspector; Mark Arnold, Terminal Manager

LATITUDE / LONGITUDE: Lat 30° 10' 8.1445" / Long 84° 12' 25.994"

SIC CODE: 4231 - Trans. & utilities - trucking terminal facilities

TYPE OF OWNERSHIP: Private

Introduction:

McKenzie Tank Lines (MTL) is located at 535 Port Leon Drive, St. Marks, Florida, Wakulla County. MTL was last inspected on February 28, 2007, as a Conditionally Exempt Small Quantity Generator with violations cited for used oil and used oil filter management. This terminal is managed by Mr. Leonard Arnold. Mr. Arnold answered questions and facilitated the inspection.

Process Description:

This facility consists of four work bays, one washing facility and a large parking/storage area. Located behind this facility were two 12,000 gallon diesel tanks that are utilized for MTL's refueling purposes. These tanks are located in secondary containment.

MTL performs routine preventative maintenance on its fleet of trucks. This four bay repair facility is surrounded by asphalt parking lot and washing facility. Located throughout the facility were several containers that were not labeled with the words "Used Oil" or "Used Oil Filters". Before leaving we provided the facility with stencils and labels. One Black Beauty heater/furnace is hard piped to a 250 gallon labeled used oil tank that burns the used oil generated at the facility.

The wash rack is used to wash McKenzie trucks/trailers before maintenance work is performed. The drains are designed to flow to a collection sump and oil water separator. According to Mr. Arnold the sump/oil water separator is serviced by skimming the oil off the top of the water, then the water is collected in an onsite treatment tank, the pH is adjusted and sent to the Tallahassee Treatment Facility. According to Mr. Arnold the PCW and sludge's are collected and sent for disposal. Also located in this area were several 55-gallon drums of unlabeled used oil and used oil filters.

Inspection Date: 01/22/2009

On February 23, 2009 John Johnson reinspected the facility and all containers of used oil and used oil filters were labeled properly.

Summary of Potential Violations and Areas of Concern:

Potential Violations

No Violations

Areas of Concern

No Areas of Concern

Conclusion:


MTL needs to ensure that all used oil and used oil filter containers are managed and stored in accordance with state and federal regulations.


Inspection Date: 01/22/2009

Signed:

A hazardous waste compliance inspection was conducted on this date, to determine your facility's compliance with applicable portions of Chapters 403 & 376, F.S., and Chapters 62-710, 62-730, 62-737, & 62-740 Florida Administrative Code (F.A.C.). Portions of the United States Environmental Protection Agency's Title 40 Code of Federal Regulations (C.F.R.) 260 - 279 have been adopted by reference in the state rules under Chapters 62-730 and 62-710, F.A.C. The above noted potential items of non-compliance were identified by the inspector(s).

This is not a formal enforcement action and may not be a complete listing of all items of non-compliance discovered during the inspection.

Nicole McDonald	Inspector	
PRINCIPAL INSPECTOR NAME	PRINCIPAL INSPECTOR TITLE	
	FDEP	3/3/2009
PRINCIPAL INSPECTOR SIGNATURE	ORGANIZATION	DATE

John Johnson	Inspector	
INSPECTOR NAME	INSPECTOR TITLE	
	FDEP	3/3/2009
INSPECTOR SIGNATURE	ORGANIZATION	DATE

Mark Arnold	Terminal Manager	
REPRESENTATIVE NAME	REPRESENTATIVE TITLE	
NO SIGNATURE	McKenzie Tank Lines, Inc.	
REPRESENTATIVE SIGNATURE	ORGANIZATION	

NOTE: By signing this document, the Site Representative only acknowledges receipt of this Inspection Report and is not admitting to the accuracy of any of the items identified by the Department as "Potential Violations" or areas of concern.