



APR 16 2010

10000084377526

March 30, 2010

Certified Mail #70060810000084377526

Mr. Bheem Kothur
Florida Department of Environmental Protection
Hazardous Waste Management Section
2600 Blair Stone Rd., MS 4560
Tallahassee, FL 32399-2400

RE: Used Oil Spill Report, Safety-Kleen Systems, Inc., 359 Cypress Rd., Ocala, FL 34472. Permit Number: 161967-HO-004. EPA ID Number FLR000060301.

Dear Mr. Kothur:

The Safety-Kleen Systems, Inc. facility referenced above is submitting this report per Part I – General and Standard Condition #43 of its permit:

- **Name, address, and telephone number of facility and person reporting:** Safety-Kleen Systems, Inc., 359 Cypress Rd., Ocala, FL 34472 (352) 687-0688. Jeff Curtis, 5610 Alpha Drive, Boynton Beach, FL 33426
- **Location of used oil spill:** The used oil spill took place on the north end of the facility at the rail spur area.
- **Date and time of discharge:** The used oil spill occurred at approximately 5:30 a.m. on March 16, 2010.
- **Type of material released:** Used oil was the material involved in this release.
- **Estimated Quantity of total discharge:** The total discharge of used oil was approximately 3,400 gallons. Of this total 3,200 gallons were captured within the secondary containment structure and 200 gallons were discharged to the ground area between the rail spur and rail line
- **Source of discharge:** While transferring used oil from the tank farm to a rail car the rail car was overfilled.
- **Description of affected media:** The affected media consists of gravel and soil along the north side of the rail spur. The total area affected was approximately 160 ft. long and 4 ft. wide at the widest point. Soil was affected at a depth of 8 to 12 inches.
- **Cause of discharge:** While transferring used oil from the tank farm to the rail car the Safety-Kleen employee involved left the area. When he returned the rail car was already overflowing.
- **Injuries caused by the discharge:** No injuries resulted from the discharge.

**RECEIVED
RCRA**

APR 16 2010

Hazardous Waste Regulation

Safety-Kleen Systems, Inc.

359 Cypress Rd Ocala, FL 34472 PHONE 352.687.0688 FAX 352.687.8511



SK Ocala Used Oil Spill Report

- **Action used to stop, remove and mitigate the effects of the discharge:** The transfer pump was immediately turned off and absorbent material used to contain the used oil. In addition a vacuum truck on site was used to pump free liquid from several holes & dikes that were constructed at the spill site.
- **Discharge status:** Presently all free liquid has been removed from the area. A small amount of contaminated soil was removed and is being stored at the facility until final clean up activities are completed. The entire area is covered with heavy plastic at this time. On Thursday April 1, 2010 a crew from American Compliance Technologies, Inc. will be on site to begin remediation activities.

Thank you for the Departments time in this matter. If you should have any questions or require additional information please do not hesitate to contact me at (561) 523-4719.

Best regards,



Jeff Curtis
EHS Manager, Florida
Safety-Kleen Systems, Inc.
5610 Alpha Drive
Boynton Beach, FL 33426
jeff.curtis@safety-kleen.com

cc: FDEP Central District