



Jeb Bush  
Governor

# Department of Environmental Protection

Twin Towers Office Building  
2600 Blair Stone Road  
Tallahassee, Florida 32399-2400

Colleen M. Castille  
Secretary

*Reading*

*July 13, 2005*  
~~March 16, 2004~~

### CERTIFIED - RETURN RECEIPT

~~7000 0520 0021 3399 7734~~

*Garry Allen, Facility Manager*  
~~Mr. John R. Feagle, Vice President~~

~~Atlantic Industrial Services, Inc.~~ *US Filter Recovery Service (Mid-Atlantic), Inc.*  
~~359 Cypress Road~~ *105 South Alexander Street*  
~~Ocala, Florida 34472~~ *Plant City, Florida 33563*

SUBJECT: *US Filter Recovery Service (Mid-Atlantic), Inc.*  
~~Atlantic Industrial Services, Inc. - Ocala Facility~~

EPA I.D. Number ~~FLR 000 060 301~~

Used Oil and Material Processing Facility

Permit Number ~~161967-HO S6-002~~

~~Marion County Hillsborough County~~  
First Notice of Deficiencies

*Plant City*  
*PLD 065 680 613*

*0030676-HO-003*

*Allen*  
Dear Mr. Feagle:

Your application for a major modification of the operating permit for this facility dated ~~January 23, 2004~~ *June 13, 2005* and received by the Department on ~~February 16, 2004~~ *June 17, 2005* has been reviewed and found to be incomplete. The required information and amendments necessary to complete your application are itemized in this Notice of Deficiencies.

When a permit application is incomplete, all processing of the application is suspended. You are hereby advised to provide us with the requested additional information pursuant to Rules 62-701 and 62-710, Florida Administrative Code (F.A.C.), and Chapter 403.769, Florida Statutes (F.S.). Please submit ~~three~~ *two* copies of your written response within 30 days of receipt of this notice.

You are encouraged to contact this office to discuss the deficiencies noted by the application review. This exchange of ideas will assist you in developing a complete and adequate response.

If you cannot submit this information within thirty (30) days, you must formally request an extension and provide a detailed schedule with dates indicating when this information will be submitted.

RMC      QA'ed  
Initials \_\_\_\_\_ Date \_\_\_\_\_

"More Protection, Less Process"

Garry Allen  
Mr. John R. Feagle  
March 16, 2004  
Page two

July 15, 2005

Rabin Prusty

Should you like to arrange a meeting or if you have any questions, please contact ~~Bill Parker~~  
at 850-245-8766.  
80

Sincerely,

Douglas G. Outlaw  
Douglas G. Outlaw, Professional Engineer III  
Hazardous Waste Regulation

DGO/bpp

Attachment

- cc: ~~Al Gephart~~ ~~Lu Burson, DEP/Orlando~~ ~~Raoul Clarke, DEP/Tallahassee~~ ~~Lee Martin, DEP/Tallahassee~~ ~~Tim Rudolph, Environceering Inc./Ponte Vedra Beach~~ ~~Carol Kessler, USfilter/Plant City~~ ~~Catherine pothouse, USfilter/Plant City~~
- Recovery Services
- Recovery Services

July 15, 2005  
ATTACHMENT

~~March 15, 2004~~

Atlantic Industrial Services, Inc. Ocala

EPA I.D. No. FLR 000 060 301

First Notice of Deficiency

USPiller Recovery Services  
(Mid-Atlantic), Inc.  
Plant City

FLD 065680 613

GENERAL COMMENTS:

1. The Atlantic Industrial Services, Inc. letter of January 23, 2004 referenced a letter dated October 14, 2003 which has not been received at this office. Please provide a copy of this letter.
2. Neither the current submittal nor any previous submittal fulfills the requirement of Part III, Item 16 of the permit. Please submit certified "as built" drawings of the solid waste building for the Department's review.
3. Page numbering in the submittal is not consistent. Please select a system and use it consistently throughout the application.
4. Please provide a certification by a Professional Engineer for the application as modified by the response to this NOD.

SPECIFIC COMMENTS:

1. An original signature is required for the Operator Certification, the Owner Certification and the Land Owner Certification. The documents submitted were unsigned.
2. Figure 8 and Page 6 of 23. The State Warning Point numbers are (850) 413-9911 and (800) 320-0519. The State Emergency Response Commission number, (800) 635-7179, is a business hours only number.
3. Page 66 of 81, page 67 of 81, page 69 of 81, page (C8) 9-1 of 22, page (C8) 9-2 of 22 and page (C8) 9-4 of 22. Please modify the sketches to show the inside dimensions and use the correct inside dimensions in the calculations.
4. Page (C8) 9-3 of 23 uses dimensions that do not agree with Figure 12 as revised on 12/31/03. Please review and revise as appropriate.
5. Page (C8) 3 of 22 refers to tanks RN 1- RN 3. Page (C9) 58 refers to tanks RN 1- RN 4. Please review and revise as appropriate.
6. On pages 1 of 23 and 6 of 23 in the Spill Contingency Plan, please revise "Florida Department of Environmental Regulation" to "Florida Department of Environmental Protection."
7. USGS Map and Warehouse Building Detail are both labeled Figure 1. Site Plan and Evacuation Plan are both labeled Figure 2. Please provide a unique number for each figure.

8. Figure 5 shows used oil tanks that are not included elsewhere in the application. Some of the numbers identifying these tanks duplicate the numbers of other tanks at the facility. Please review and revise as appropriate.
9. Figures 6 and 13 show a North arrow that is not consistent with the North arrow on Figures 2, 3, 4 etcetera. Please review and revise the North arrow orientation on all layout figures as appropriate.
10. Figure 6 does not appear to match the other figures as to the number, location and capacity of the tanks. None of the figures match the permit. Please review the figures and revise as appropriate.
11. Please modify an existing figure or provide an additional figure that shows all the names and numbers that are used to designate each tank and each secondary containment area.