

3/10/97

Hi-

I visited the facility yesterday @ 4:45. I inspected the transfer trailer where HW is stored while en-route to disposal facilities out of state. All waste containers were labeled, dated and in good condition. I noted no evidence of leakage or spillage either in the trailer or on paved surfaces underneath, and surrounding the trailer.

Facility personnel knew of no spills or leaks, either from the transfer trailer or trucks delivering waste to the trailer. Neither did they recall having either been approached from the complainant or refusing to allow pictures to be taken.

In addition to AETC, now AETS, who occupy suite L at 4317 Fortune PL in Melbourne, a sister company, MTI (mercury light/device recycling facility) (952-1516) occupies suite J next door in the building. Frank Soldano, with MTI, confirmed per telecon today, that they receive no liquid wastes for mercury reclamation at the facility. He knew of no leaking trucks making deliveries but would confirm with his night maintenance person.

I did not meet with the third facility in the building, Nilson Van and Storage (Mayflower Transit), who occupy suite A. I did note any leaks or spills on their portion of the pad, however.

I would recommend getting the name and telephone of the complainant, or having them contact me directly, so we can obtain more information, if necessary. The AETS and MTI facilities are concerned and want to cooperate to resolve any complaints of substance.

FAX to Bill Kapler ✓

DEP - MELBOURNE OFFICE
COMPLAINT REFERRAL/RECEIPT FORM

NUMBER:

PROGRAM:

WATER MANAGEMENT

WATER FACILITIES

WASTE MANAGEMENT ✓

AIR

HW 97-017

Date: 3/10/97 Time: _____ County: Brevard

COMPLAINANT: Representative Futch's Office via VGarfen

Street Address: _____

City: _____ Zip: _____ Phone: _____

NATURE OF COMPLAINT: Possible Hazardous Waste Disposal Problem

How long has problem existed: _____

Contact person: Advanced Environmental Technology

Address or directions to site: 4317 Fortune Place W. Melbourne
192 to John Rodas Blvd north then east onto Fortune Pl.

REMARKS: The complainant (thru Reps office) said that trucks with
out of state tags arrive at night with liquids leaking. They
objected to complainant taking photographs.

OUTCOME: DV advises to FAX to Bill Kapler.

Bill - Pls coordinate w/ Debby - Thanks

Person receiving complaint: sm DW

Person/Agency designated to investigate: _____

see from Melbourne

CITIZEN COMPLAINT

Complaint No. 97-058 Section Referred To: _____

Call Received By: Susan Moore (Melbourne)

Date: 3/10/97 Time: _____ County: Brevard

Facility Name: Advanced Environmental Technology

Address: 4317 Fortune Place w. Melbourne

Phone #: _____

Owner's Name (Responsible Official): _____

Type of Business: _____

Description of Complaint: see attached

Chemical(s) Involved: _____

Is The Material Involved Product or Waste: _____

How Long Has Problem Occurred: _____

How Often Does Problem Occur: _____

When Does Problem Occur (morning, afternoon, etc.) _____

Amount Of Chemicals Involved: _____

Complainant (May Remain Anonymous): _____

How Does Complainant Know About Problem: _____

Address: _____

Phone: _____

May We Contact You Again If Necessary: _____

Have You Contacted Anyone Else (County, news media, etc.) _____

If Yes, Who: _____

Outcome: _____
