

**From:** Charles E Walz [charles.walz@cemex.com]  
**Sent:** Wednesday, February 22, 2012 2:04 PM  
**To:** Carman, Roger  
**Cc:** Kantor, Karen E.  
**Subject:** Re: FW: Additional information request  
**Attachments:** FDEP Haz Waste Inspection Dec 2011 response.  
doc; Recirculating line leakPhotos 001.jpg; Miami Plant Kiln oil tank spill  
Photos 002.jpg; oil pail relabeled Photos 003.jpg

Hi Roger

Attached is our response to your email

I am attaching photos of the tank clean up, the oil line leak and oil pail label replacement.

Charlie



Charles E Walz  
Environmental Manager - Miami Cement Plant - Environmental - United States of America  
Office : +1305(229)2955 , Fax: +1305(229)8015 , Mobile: +1305(586)8379  
Address: 1200 NW 137th Ave Miami, Florida 33182  
e-Mail: [Charles.Walz@CEMEX.com](mailto:Charles.Walz@CEMEX.com)  
[www.cemexusa.com](http://www.cemexusa.com)

From: "Carman, Roger" <[Roger.Carman@dep.state.fl.us](mailto:Roger.Carman@dep.state.fl.us)>  
To: Charles E Walz/US/Cemex@CEMEX  
Cc: "Kantor, Karen E." <[Karen.E.Kantor@dep.state.fl.us](mailto:Karen.E.Kantor@dep.state.fl.us)>  
Date: 02/15/2012 02:23 PM  
Subject: FW: Additional information request

---

Dear Mr. Walz,

I'm sending the message below again asking for the additional information. This information is necessary to accurately complete the inspection report for our inspection conducted on 12/19/2011. Please provide the information as soon as possible, but no later than February 23, 2012.

Thank you.

Roger E. Carman  
Environmental Specialist II, Hazardous Waste Section  
Florida Department of Environmental Protection  
Southeast District Office  
400 N. Congress Avenue , Suite 200  
West Palm Beach, FL 33304  
PH: 561.681.6720 FAX: 561.681.6770  
Email: [Roger.Carman@dep.state.fl.us](mailto:Roger.Carman@dep.state.fl.us)

*Please take a few minutes to share your comments on the service you received from the department by clicking on this link [DEP Customer Survey](#).*

**From:** Carman, Roger  
**Sent:** Tuesday, January 10, 2012 7:40 AM  
**To:** 'Charles.walz@cemex.com'  
**Cc:** Kantor, Karen E.; Winston, Kathy  
**Subject:** Additional information request

RE: Facility: Cemex –Miami Cement Plant  
Inspection date: 12/19/11  
EPA ID#: FLD 981 758 485

Dear Mr. Walz,

Please provide the following information:

1. We observed two parts washers during the inspection. A Safety-Kleen unit near the kiln day tank and a System One unit in the small engine repair shop. Please provide us a description of the waste and any analytical results Cemex used to determine whether or not the waste from these units was hazardous. Please provide an generation rate of this waste.
2. Please provide a description of the glycerol waste from the cement lab and any waste determination information. Please provide an generation rate of this waste.
3. One container of lab waste in the hazardous waste storage area was dated 04/15/06. Was that date correct?
4. Please provided an explanation of the overfill of the kiln day tank, including the date the overfill occurred , the approximate amount of used oil spilled and final deposition of the cleanup material.
5. Would you verify if the SQL Quarry is a separate company and not covered under Cemex's EPA Identification Number FLD981758485.

Thank you for the pictures showing corrections of the items identified during the inspection on 12-19-11. For the

Universal Waste Lamps labels, you need to add the word "Lamps" or the words "Used Lamps" or "Waste Lamps". Also, I believe one small container under the line filters for the kiln day tank was label as "Waste Oil".

Thank you.

Roger E. Carman  
Environmental Specialist II, Hazardous Waste Section  
Florida Department of Environmental Protection  
Southeast District Office  
400 N. Congress Avenue , Suite 200  
West Palm Beach, FL 33304  
PH: 561.681.6720 FAX: 561.681.6770  
Email: [Roger.Carman@dep.state.fl.us](mailto:Roger.Carman@dep.state.fl.us)