

EXHIBIT E
Florida Department of Environmental Regulation
STATIONARY SOIL THERMAL TREATMENT FACILITY
INSPECTION REPORT

Name of Facility RINKER MATERIALS
Location 1200 NW 137th AVE MIAMI, FL 33182
General Permit No. SO13-195017 Date of Inspection 7/28/95
Contact Person DAVE MARPLE
Person Completing Report LEE MARTIN

Instructions: Complete the appropriate spaces for each item listed below. Use comments space to provide additional information for each item. Additional paper may be used if necessary.

Yes No SITE SURVEY

- ☒ 1. Does information provided on general permit notice of intent form coincide with actual facility?
- ☒ 2. Is soil sampling procedure correct?
- ☒ 3. Are monitoring wells properly installed (proper number and location)? *some pads damaged (SW & SE corner)*
- ☒ 4. Are monitor wells being properly sampled and analysed for required parameters?
- ☒ 5. Is untreated soil stockpiled separately from treated soil and properly identified?
- ☒ 6. Is untreated soil adequately covered by roofing?
- ☒ 7. Do floors for storage appear to be properly constructed and in good condition?
- ☒ 8. Are floors properly bermed to provide runoff control?
- ☒ 9. Is a leachate collection system provided?

Yes No REPORTING FORMS

- ☒ 10. Are untreated soil reporting forms being properly completed? starting date 3/1/95 end date 6/28/95
- ☒ 11. Are treated soil reporting forms being properly completed? starting date 2/27/95 end date 7/7/95

12. Indicate frequency clean soil criteria is being met?
- 95 % TRPH - 10 mg/kg, or
 - 5 % TRPH - 50 mg/kg, PAH - 6 mg/kg, and VOH - 50 ug/kg
13. Indicate ranges and approximate median values of untreated soil analyses for the following parameters.
- TRPH BDL mg/kg to 510000 mg/kg, median 454 mg/kg
 - VOA BDL mg/kg to 610600 mg/kg, median 1.2 mg/kg
 - Arsenic BDL mg/kg to 234 mg/kg
 - Barium BDL mg/kg to 1140 mg/kg
 - Cadmium BDL mg/kg to 33.73 mg/kg
 - Chromium BDL mg/kg to 170 mg/kg
 - Lead BDL mg/kg to 5800 mg/kg
 - Mercury BDL mg/kg to 17.24 mg/kg
 - Selenium BDL mg/kg to 130 mg/kg
 - Silver BDL mg/kg to 104 mg/kg
14. Indicate ranges and approximate median values of treated soil analyses for the following parameters.
- TRPH BDL mg/kg to 12 mg/kg, median 2.6 mg/kg
 - VOA BDL mg/kg to BDL mg/kg, median BDL mg/kg
 - Arsenic BDL mg/kg to 2.5 mg/kg
 - Barium 13 mg/kg to 180 mg/kg
 - Cadmium BDL mg/kg to 2.3 mg/kg
 - Chromium 1.6 mg/kg to 70 mg/kg
 - Lead 1.0 mg/kg to 11 mg/kg
 - Mercury BDL mg/kg to BDL mg/kg
 - Selenium BDL mg/kg to BDL mg/kg
 - Silver BDL mg/kg to BDL mg/kg
 - _____ mg/kg to _____ mg/kg
 - _____ mg/kg to _____ mg/kg

Comments: _____

William L Martin
Signature

Date

Florida Department of Environmental Regulation
Soil Treatment Facility
Treated Soil Reporting Form

Name of Facility: _____
Air Permit No.: _____
Soil Treatment Permit No.: _____
Stationary: _____ or Mobile Facility: _____

Month: _____ Year: _____

1	2	3	4	5	6	7	8	9	10	11														
Day of Mo.	Soil Batch ID#	Sample Number	Length of Run, Hours	Amount, Volume or Weight cy/tn	Analytical Results																			
					Total Metals								TCLP Metals								Totals			
					As	Ba	Cd	Cr	Pb	Hg	Se	Ag	As	Ba	Cd	Cr	Pb	Hg	Se	Ag	VOA	RPH	PAH	VOH
3-27		42	168		1.6	94	3.0	43	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0			
3-28		42	168		2.5	81	3.2	36	3.2	3.2	3.2	3.2	3.2	3.2	3.2	3.2	3.2	3.2	3.2	3.2	3.2			
3-29		42	168		2.2	116	3.0	70	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0			
3-30		42	168		1.6	71	3.0	49	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0			
3-31		42	168		1.2	112	3.0	31	1.4	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0			
4-1		42	168		3.0	85	3.0	26	2.9	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0			
4-2		42	168		3.0	76.7	3.1	18.2	3.1	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0			
4-3		42	168		1.4	98	1.1	31	4.1	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0			
4-4		42	168																					
4-5		42	168		2.2	144	3.0	44	4.2	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0			
4-6		42	168		1.4	120	3.0	34	2.9	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0			
4-7		42	168		3.0	180	3.0	48	6.2	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0			
4-8		42	168		1.0	124	3.0	50	9.9	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0			
4-9		42	168		3.0	150	3.0	30	6.3	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0			
4-10		42	168		1.1	180	2.3	49	7.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0			
4-11		42	168		1.9	150	1.6	16	6.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0			
4-12		42	168		3.0	13	3.0	4.1	1.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0			
4-13		42	168		3.0	79	3.0	44	11	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0			
4-14		42	168		1.2	97	2.2	45	4.4	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0			
4-15		42	168		1.4	70	3.0	34	10.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0			

See reverse side for instructions

Soil Thermal Treatment Facility Untreated Soil Reporting Form

Month: MARCH Year: 1995

Name of Facility: RINKER MATERIALS CORP.
Air Permit No.: A013-172154
Soil Treatment Permit No.: SW-01117-91
Stationary XXX or Mobile Facility:

DER Form # 17-775.900(2)
Soil Thermal Treatment Facility
Form Title Untreated Soil Reporting Form
Effective Date _____
DER Application No _____

1	2	3	4	5										6	7	8	9
Day of Mo.	Soil Batch ID#	Sample Number	Amount Volume or Weight cy/tn	Analytical Results										Totals			
				Metals													
				AS	BA	CD	CR	PB	HG	SE	AG	VOA	RPH	VOH	Indicate Other Analyses		
03/01/95	104-85005	1	2.48	5	62	2	44	13	BDL	BDL	2	BDL	185172	BDL			
03/01/95	114-85035	1	0.13	BDL	BDL	BDL	BDL	BDL	BDL	BDL	BDL	BDL	327	BDL			
03/01/95	114-85041	1	0.60	BDL	BDL	BDL	5	16	BDL	BDL	BDL	BDL	6100	BDL			
03/01/95	114-85034	1	3.00	BDL	1.85	BDL	BDL	5.66	BDL	BDL	BDL	BDL	3810	BDL			
03/01/95	203-85010	3	212.55	0.449	4.69	0.215	6.00	14.2	0.172	<0.050	<0.0500	1.60	479	BDL			
03/01/95	203-85020	1	0.25	10.8	8.15	1.89	21.1	166	0.128	<0.020	.16	BDL	106	BDL			
03/01/95	203-85023	10	778.53	0.78	3.48	BDL	2.97	5.82	BDL	0.25	BDL	BDL	61.28	BDL			
03/01/95	203-85029	1	0.75	0.328	4.35	0.0858	5.28	18.2	0.0588	<0.020	<0.0500	1.82	817	BDL			
03/01/95	283-85002	6	155.73	<6.0	<2.5	<4.5	<3.22	<1.50	<0.07	<6.5	<35	BDL	6411.87	BDL			
03/02/95	203-85023	10	489.93	0.78	3.48	BDL	2.97	5.82	BDL	0.25	BDL	BDL	61.28	BDL			
03/02/95	344-85004	1	5.95	28.9	200.8	BDL	57.7	118.4	0.10	BDL	BDL	142000	177000	BDL			
03/02/95	344-85005	1	5.95	2.8	73.9	1.8	35.1	114.2	BDL	BDL	BDL	6880	39100	BDL			
03/02/95	344-85008	1	5.95	182	673.1	2.5	80.1	133.6	0.07	BDL	BDL	12400	110000	BDL			
03/02/95	344-85007	1	5.95	BDL	1.7	BDL	38.9	72.7	BDL	BDL	BDL	68.72	76800	BDL			
03/02/95	344-85008	1	5.95	BDL	2.0	BDL	1.4	27.8	BDL	BDL	BDL	3.350	7980	BDL			
03/02/95	514-85010	3	19.64	0.03	2.92	BDL	3.07	4.58	BDL	1.83	0.02	28.39	1828.77	.008			
03/02/95	514-85014	5	387.63	BDL	163.40	BDL	4.20	9.25	BDL	BDL	BDL	BDL	28.68	BDL			
03/03/95	114-85034	1	6.00	BDL	1.85	BDL	BDL	5.66	BDL	BDL	BDL	BDL	3610	BDL			
03/03/95	343-85001	1	14.98	BDL	30.3	BDL	16.5	224	0.12	BDL	BDL	BDL	277	BDL			
03/03/95	437-85003	1	6.83	BDL	13.1	BDL	4.56	20.1	BDL	BDL	BDL	BDL	919	BDL			
03/06/95	114-85034	1	6.00	BDL	1.85	BDL	BDL	5.66	BDL	BDL	BDL	BDL	3610	BDL			
03/06/95	134-85002	1	4.85	BDL	2.79	BDL	4.28	1.34	BDL	BDL	BDL	838	61.8	BDL			
03/06/95	203-85021	5	814.01	BDL	42.58	BDL	5.92	17.74	BDL	BDL	0.32	BDL	68.48	BDL			
03/06/95	203-85022	1	43.18	BDL	2.90	BDL	4.30	8.60	BDL	BDL	BDL	194.70	2	BDL			
03/06/95	224-85001	1	3.37	BDL	BDL	BDL	BDL	BDL	BDL	BDL	BDL	BDL	9073	BDL			
03/07/95	134-85002	1	6.10	BDL	2.79	BDL	4.28	1.34	BDL	BDL	BDL	838	61.8	BDL			
03/07/95	203-85021	5	191.84	BDL	42.59	BDL	5.92	17.74	BDL	BDL	0.32	BDL	68.48	BDL			

775.900(2)

NOTE: VOA=ppb VOH= ppm RPH= ppm

* SEE ATTACHMENT "A"

Florida Department of Environmental Regulation

Twin Towers Office Bldg. 2800 Blair Stone Road Tallahassee, Florida 32398-2400

Soil Thermal Treatment Facility Untreated Soil Reporting Form

Month: MARCH Year: 1985

Name of Facility: RUNKER MATERIALS CORP.
Air Permit No.: A013-172154
Soil Treatment Permit No.: SW-01117-81
Stationary XXX or Mobile Facility: _____

DER Form # 17-775.900(2)
Soil Thermal Treatment Facility
Form Title Untreated Soil Reporting Form
Effective Date _____
DER Application No _____

1	2	3	4	5										6	7	8	9
Day of Mo.	Soil Batch ID #	Sample Number	Amount Volume or Weight cy/tn	Analytical Results										Totals			
				Metals													
				AS	BA	CD	CR	PB	HG	SE	AG	VOA	RPH	VOH	Indicate Other Analyses		
03/07/85	391-85002	1	49.82	1.80	8.70	BDL	2.20	23.0	BDL	BDL	3.44	BDL	40.5	BDL			
03/07/85	495-85001	3	321.03	<1.0	<2.0	<2.0	4.10	18	<0.28	<50	<2.0	11.983	158.67	BDL			
03/07/85	514-85010	3	3.00	0.03	2.82	BDL	3.07	4.58	BDL	1.83	0.02	28.39	1628.77	.006			
03/08/85	114-85034	1	6.00	BDL	1.85	BDL	BDL	5.66	BDL	BDL	BDL	BDL	3810	BDL			
03/08/85	203-85030	5	516.57	0.49	4.08	0.41	2.10	8.84	0.06	0.04	0.04	8454.88	231.38	BDL			
03/08/85	282-85002	1	0.75	BDL	6.4	BDL	10.5	3.3	BDL	BDL	BDL	1388	2940	BDL			
03/08/85	287-85006	1	1.00	BDL	22.0	BDL	1.88	3.6	BDL	BDL	0.002	BDL	251	BDL			
03/08/85	344-84008	1	0.75	1.3	39.2	1.0	21.8	31.1	BDL	BDL	BDL	3240	14700	BDL			
03/08/85	521-85001	1	74.60	BDL	9.0	1.0	12.6	4300	0.24	BDL	BDL	11.360	1230	.063			
03/08/85	114-85038	1	13.73	2.1	41	2.6	17	76	BDL	BDL	BDL	BDL	59	BDL			
03/09/85	114-85039	1	1.02	1.0	221	BDL	21.9	11.0	BDL	BDL	1.30	.038	14.1	BDL			
03/09/85	114-85034	1	3.00	BDL	1.85	BDL	BDL	5.66	BDL	BDL	BDL	BDL	3810	BDL			
03/09/85	134-85002	1	3.05	BDL	2.79	BDL	4.28	1.34	BDL	BDL	BDL	838	61.8	BDL			
03/09/85	203-85030	5	553.01	0.49	4.08	0.41	2.10	8.84	0.06	0.04	0.04	8454.88	231.38	BDL			
03/09/85	208-85004	3	282.01	BDL	3.13	BDL	BDL	6.17	BDL	BDL	BDL	BDL	444	BDL			
03/09/85	475-85001	1	71.21	.413	5.37	.176	4.51	<.0200	.00826	.0311	<.0500	2.269	531	BDL			
03/09/85	514-85010	3	3.00	0.03	2.82	BDL	3.07	4.58	BDL	1.83	0.02	28.39	1628.77	.006			
03/09/85	514-85014	5	202.07	BDL	168.40	BDL	4.20	9.25	BDL	BDL	BDL	BDL	23.68	BDL			
03/09/85	521-85001	1	10.79	BDL	9.0	1.0	12.6	4300	0.24	BDL	BDL	11.360	1230	.063			
03/10/85	108-85002	1	0.28	BDL	3.22	BDL	4.16	3.49	BDL	BDL	BDL	BDL	51.3	BDL			
03/10/85	108-85005	1	0.29	4.34	.87	BDL	6.49	25	0.641	BDL	BDL	BDL	62.2	BDL			
03/10/85	108-85007	1	0.09	1.000	358	BDL	7.83	64.7	BDL	BDL	BDL	BDL	5429	BDL			
03/10/85	108-85019	1	0.78	BDL	2.11	BDL	1.39	BDL	BDL	BDL	1.58	BDL	38.7	BDL			
03/10/85	108-85020	1	1.31	BDL	BDL	BDL	1.60	BDL	BDL	BDL	BDL	BDL	501	BDL			
03/10/85	114-85037	3	226.72	BDL	13.70	BDL	5.72	52.43	0.04	BDL	0.34	BDL	6820	BDL			
03/10/85	114-85034	1	9.00	BDL	1.85	BDL	BDL	5.66	BDL	BDL	BDL	BDL	3810	BDL			
03/10/85	134-85002	1	2.60	BDL	2.79	BDL	4.28	1.34	BDL	BDL	BDL	838	61.9	BDL			

775.900(2)

NOTE: VOA= ppb VOH=ppm RPH= ppm

* SEE ATTACHMENT "A"

Florida Department of Environmental Regulation

Twin Towers Office Bldg. 2600 Blair Stone Road Tallahassee, Florida 32309-2400

Soil Thermal Treatment Facility Untreated Soil Reporting Form

Month: **MARCH** Year: **1995**

Name of Facility: **RINKER MATERIALS CORP.**
Air Permit No.: **A013-172154**
Soil Treatment Permit No.: **SW-01117-91**
Stationary **XXX** or Mobile Facility:

DER Form # **17-775.900(2)**
Soil Thermal Treatment Facility
Form Title **Untreated Soil Reporting Form**
Effective Date
DER Application No

1	2	3	4	5										6	7	8	9
Day of Mo.	Soil Batch ID#	Sample Number	Amount Volume or Weight cy/lb	Analytical Results										Totals			
				Metals													
				AS	BA	CD	CR	PB	HG	SE	AG	VOA	RPH	VOH	Indicate Other Analyses		
03/10/95	208-95004	3	43.03	BDL	3.13	BDL	BDL	6.17	BDL	BDL	BDL	BDL	444	BDL			
03/10/95	522-95001	1	64.00	1.40	44.0	1.80	12.0	420	0.24	BDL	BDL	.003	4489	BDL			
03/13/95	108-95019	1	2.00	BDL	2.11	BDL	1.39	BDL	BDL	BDL	1.58	BDL	36.7	BDL			
03/13/95	114-95054	1	3.00	BDL	1.85	BDL	BDL	5.68	BDL	BDL	BDL	BDL	3810	BDL			
03/13/95	134-95002	1	3.05	BDL	2.78	BDL	4.28	1.34	BDL	BDL	BDL	838	61.9	BDL			
03/14/95	114-95040	1	71.85	BDL	230	BDL	1.20	1.40	BDL	BDL	BDL	BDL	26.8	BDL			
03/14/95	114-95054	1	3.00	BDL	1.85	BDL	BDL	5.68	BDL	BDL	BDL	BDL	3810	BDL			
03/14/95	134-95002	1	6.30	BDL	2.78	BDL	4.28	1.34	BDL	BDL	BDL	838	61.9	BDL			
03/14/95	203-95024	12	928.02	BDL	268.67	0.34	9.10	30.87	BDL	BDL	BDL	BDL	58.17	.001			
03/14/95	391-95002	1	52.01	1.80	9.70	BDL	2.20	23.0	BDL	BDL	3.44	BDL	40.6	BDL			
03/15/95	108-95019	1	3.28	BDL	2.11	BDL	1.39	BDL	BDL	BDL	1.58	BDL	38.7	BDL			
03/15/95	114-95040	1	13.85	BDL	230	BDL	1.20	1.40	BDL	BDL	BDL	BDL	26.8	BDL			
03/15/95	114-95042	1	0.16	BDL	8.4	BDL	4.7	3.4	BDL	BDL	BDL	BDL	23	BDL			
03/15/95	114-95043	1	0.32	BDL	BDL	9.6	37	10	BDL	BDL	BDL	BDL	5000	BDL			
03/15/95	114-95044	1	0.44	1.4	21	BDL	16	24	BDL	BDL	BDL	BDL	8500	BDL			
03/15/95	114-95054	1	3.00	BDL	1.85	BDL	BDL	5.68	BDL	BDL	BDL	BDL	3810	BDL			
03/15/95	134-95002	1	3.05	BDL	2.78	BDL	4.28	1.34	BDL	BDL	BDL	838	61.9	BDL			
03/15/95	302-95006	3	884.27	1.60	5.77	BDL	5.70	14.37	0.02	BDL	BDL	BDL	125.67	BDL			
03/15/95	302-95007	1	56.89	<1.0	<20	<2.0	4.1	27	<0.25	<50	<2.0	BDL	210	BDL			
03/15/95	514-95016	5	450.75	.34	96	.82	4.40	34.60	1.46	BDL	BDL	BDL	33.61	BDL			
03/16/95	108-95019	1	3.23	BDL	2.11	BDL	1.39	BDL	BDL	BDL	1.58	BDL	38.7	BDL			
03/16/95	114-95054	1	9.00	BDL	1.85	BDL	BDL	5.68	BDL	BDL	BDL	BDL	3810	BDL			
03/16/95	134-95002	1	9.15	BDL	2.78	BDL	4.28	1.34	BDL	BDL	BDL	838	61.9	BDL			
03/16/95	423-95005	1	1.18	2	157	5.2	29	86	<0.04	63.7	<0.5	<1700	3.400	BDL			
03/16/95	423-95006	1	2.46	1.82	12.0	BDL	3.60	1.80	BDL	BDL	BDL	.568	36.6	BDL			
03/16/95	514-95010	3	63.00	0.03	2.82	BDL	3.07	4.58	BDL	1.83	0.02	28.39	1628.77	.006			
03/16/95	514-95018	5	305.83	BDL	28.74	BDL	3.47	1.25	BDL	BDL	.29	BDL	50.40	BDL			

775.900(2)

NOTE: VOA =ppm VOH=ppm RPH=ppm

* SEE ATTACHMENT "A"

Florida Department of Environmental Regulation

Twin Towers Office Bldg. 2600 Blair Stone Road Tallahassee, Florida 32309-2400

Soil Thermal Treatment Facility Untreated Soil Reporting Form

Month: **MARCH** Year: **1995**

Name of Facility: **RINKER MATERIALS CORP.**

Air Permit No.: **A013-172154**

Soil Treatment Permit No.: **SW-01117-91**

Stationary **XXX** or Mobile Facility:

DER Form # **17-775.900(2)**
Soil Thermal Treatment Facility
 Form Title **Untreated Soil Reporting Form**
 Effective Date _____
 DER Application No. _____

1	2	3	4	5										6	7	8	9
Day of Mo.	Soil Batch ID#	Sample Number	Amount Volume or Weight cy/tn	Analytical Results													
				Metals										Totals			
				AS	BA	CD	CR	PB	HG	SE	AG	VOA	RPH	VOH	Indicate Other Analyses Attach Lab Results Only		
03/17/95	103-85008	1	2.25	BDL	125	BDL	4	34	BDL	BDL	BDL	20010	280	BDL			
03/17/95	106-85019	1	3.11	BDL	2.11	BDL	1.39	BDL	BDL	BDL	1.58	BDL	36.7	BDL			
03/17/95	114-85054	1	6.00	BDL	1.85	BDL	BDL	5.68	BDL	BDL	BDL	BDL	3810	BDL			
03/17/95	203-85033	1	0.25	1.59	3.84	1.47	7.91	4.14	0.118	.00230	0.789	BDL	<1.00	BDL			
03/17/95	302-85008	1	3.00	<0.001	<0.001	<0.001	0.003	0.007	<0.030	<0.001	<0.001	285	14,350	BDL			
03/17/95	302-85009	1	1.75	<1.0	<1.0	<1.0	<1.0	8.7	0.060	<1.0	<1.0	223	59,371	BDL			
03/17/95	475-85002	1	0.25	1.58	6.31	.0638	4.17	12.4	.0146	.0205	<.0500	BDL	26700	BDL			
03/17/95	514-85016	5	562.32	.34	96	.82	4.40	34.60	1.48	BDL	BDL	BDL	33.61	BDL			
03/17/95	514-85017	6	247.71	.25	14.11	BDL	1.62	.30	BDL	BDL	BDL	BDL	22.40	BDL			
03/17/95	822-85002	1	0.50	1.40	44.0	1.60	12.0	420	0.24	BDL	BDL	.003	4499	BDL			
03/20/95	114-85054	1	9.00	BDL	1.85	BDL	BDL	5.68	BDL	BDL	BDL	BDL	3810	BDL			
03/20/95	134-85002	1	3.05	BDL	2.79	BDL	4.28	1.34	BDL	BDL	BDL	838	61.9	BDL			
03/20/95	203-85031	3	191.87	0.369	1.79	.0132	1.78	1.74	.0916	<.0020	<.0500	320	51.1	BDL			
03/20/95	217-85001	3	328.49	2.02	13.83	BDL	3.62	50.63	BDL	BDL	2.17	2387	363.33	BDL			
03/20/95	514-85016	5	19.16	.34	96	.82	4.40	34.60	1.48	BDL	BDL	BDL	33.61	BDL			
03/20/95	823-85001	1	18.16	0.9	19.05	0.1	5.5	58	0.04	<2	<0.3	BDL	1320	BDL			
03/20/95	824-85001	1	4.41	BDL	BDL	BDL	BDL	BDL	BDL	BDL	BDL	BDL	75	BDL			
03/20/95	825-85001	1	4.33	BDL	10	BDL	9.8	17	BDL	BDL	BDL	BDL	4800	BDL			
03/21/95	114-85047	1	14.55	BDL	5.3	BDL	3.8	4.2	BDL	BDL	BDL	BDL	2200	BDL			
03/21/95	114-85054	1	3.00	BDL	1.85	BDL	BDL	5.68	BDL	BDL	BDL	BDL	3810	BDL			
03/21/95	203-85032	1	120.39	0.317	1.57	<.0500	2.00	5.11	.0272	<.0020	4.47	340	17.3	BDL			
03/21/95	217-85001	3	7.29	2.02	13.83	BDL	3.62	50.63	BDL	BDL	2.17	2387	363.33	BDL			
03/21/95	391-85003	1	41.00	BDL	2.50	BDL	4.00	BDL	BDL	BDL	BDL	BDL	384	BDL			
03/21/95	429-85002	1	15.67	<1.5	17	<1.1	11	24	<0.09	<1.3	<8.2	BDL	27400	BDL			
03/21/95	514-85016	5	142.14	.34	96	.82	4.40	34.60	1.48	BDL	BDL	BDL	33.61	BDL			
03/21/95	826-85001	3	55.93	234	20.17	11.50	28.33	46.00	0.11	130.00	<1.0	<23.33	8567	BDL			
03/22/95	111-85001	1	6.35	.0219	0.495	<.0500	.308	.850	.0234	<.0020	<.0500	BDL	51.7	BDL			

775.900(2)

NOTE: VOA=ppb VOH=ppm RPH=ppm

* SEE ATTACHMENT "A"

Florida Department of Environmental Regulation

Twin Towers Office Bldg. 2600 Blair Stone Road Tallahassee, Florida 32399-2400

Soil Thermal Treatment Facility Untreated Soil Reporting Form

Month: MARCH Year: 1995

Name of Facility: RUNKER MATERIALS CORP.

Air Permit No.: A019-172154

Soil Treatment Permit No.: SW-01117-91

Stationary XXX or Mobile Facility:

DER Form #	17-775.900(2)
Form Title	Soil Thermal Treatment Facility Untreated Soil Reporting Form
Effective Date	
DER Application No	

1	2	3	4	5										6	7	8	9
Day of Mo.	Soil Batch ID#	Sample Number	Amount Volume or Weight cy/tn	Analytical Results										Totals			
				Metals													
				AS	BA	OD	CR	PB	HG	SE	AG	VOA	RPH	VOH			
03/22/85	111-85002	3	86.07	3.54	4.05	0.10	3.80	8.95	0.00	0.11	<0.000	BDL	321.17	BDL			
03/22/85	134-85002	1	3.08	BDL	2.79	BDL	4.28	1.34	BDL	BDL	BDL	838	81.9	BDL			
03/22/85	203-85034	3	243.54	BDL	3.40	BDL	3.07	4.70	BDL	BDL	BDL	BDL	81.27	.033			
03/22/85	302-85010	1	149.77	<0.001	0.040	<0.001	0.050	0.007	<0.0020	<0.001	<0.001	2.4	385	BDL			
03/22/85	514-85016	5	124.05	.34	96	.82	4.40	34.60	1.48	BDL	BDL	BDL	33.61	BDL			
03/22/85	527-85001	3	283.23	BDL	8.63	BDL	1.09	0.54	BDL	BDL	BDL	.004	1832.33	0.24			
03/23/85	114-85048	3	165.12	BDL	3.9	BDL	3.1	2.1	BDL	BDL	BDL	BDL	10	BDL			
03/23/85	134-85002	1	5.55	BDL	2.79	BDL	4.28	1.34	BDL	BDL	BDL	838	81.9	BDL			
03/23/85	203-85035	3	169.87	.40	8.03	.17	5.07	4.37	0.08	0.01	<0.000	<3.43	3698.87	BDL			
03/23/85	203-85036	1	120.72	1.14	1.70	BDL	1.54	BDL	BDL	BDL	BDL	BDL	756.34	BDL			
03/23/85	391-85004	3	172.54	BDL	537.34	1.74	5.10	16.37	BDL	BDL	4.10	BDL	159.87	BDL			
03/23/85	514-85018	5	600.28	.20	109	.44	8.57	20.72	BDL	BDL	1.30	1.88	91.88	.002			
03/23/85	526-85001	3	138.73	234	20.17	11.50	28.33	48.00	0.11	130.00	<1.0	<23.33	9567	BDL			
03/23/85	527-85001	3	145.24	BDL	8.63	BDL	1.09	0.54	BDL	BDL	BDL	.004	1832.33	0.24			
03/24/85	114-85048	3	34.61	BDL	3.9	BDL	3.1	2.1	BDL	BDL	BDL	BDL	10	BDL			
03/24/85	114-85049	1	8.00	BDL	184	7.39	46.2	371	.258	BDL	BDL	BDL	13123	BDL			
03/24/85	114-85051	1	2.51	BDL	3.8	BDL	BDL	BDL	BDL	BDL	BDL	.103	210000	BDL			
03/24/85	526-85001	3	258.49	234	20.17	11.50	28.33	48.00	0.11	130.00	<1.0	<23.33	8567	BDL			
03/25/85	114-85054	1	1.75	BDL	1.85	BDL	BDL	5.66	BDL	BDL	BDL	BDL	3810	BDL			
03/25/85	526-85001	3	25.81	234	20.17	11.50	28.33	48.00	0.11	130.00	<1.0	<23.33	8567	BDL			
03/27/85	114-85050	1	1.65	BDL	BDL	BDL	BDL	BDL	0.31	BDL	BDL	.004	140000	BDL			
03/27/85	114-85054	1	6.00	BDL	1.85	BDL	BDL	5.66	BDL	BDL	BDL	BDL	3810	BDL			
03/27/85	526-85001	3	103.23	234	20.17	11.50	28.33	48.00	0.11	130.00	<1.0	<23.33	8567	BDL			
03/28/85	114-85054	1	7.71	BDL	1.85	BDL	BDL	5.66	BDL	BDL	BDL	BDL	3810	BDL			
03/28/85	114-85055	1	4.32	BDL	5.3	BDL	3.8	4.2	BDL	BDL	BDL	BDL	2200	BDL			
03/28/85	526-85001	3	103.43	234	20.17	11.50	28.33	48.00	0.11	130.00	<1.0	<23.33	8567	BDL			
03/28/85	526-85001	1	0.25	<0.25	4.64	<1.55	5.41	72.7	<0.05	<0.28	<0.78	57320	2440	BDL			

775.900(2)

NOTE: VOA=ppb VOH=ppm RPH=ppm

* SEE ATTACHMENT "A"

Soil Thermal Treatment Facility Untreated Soil Reporting Form

DER Form #	17-775.900(2)
Form Title	Soil Thermal Treatment Facility Untreated Soil Reporting Form
Effective Date	
DER Application No	

RINKER MATERIALS CORP.
Name of Facility: **AD13-172154**
Air Permit No.: **SW-01117-91**
Scal Treatment Permit No.: **Stationary** or Mobile Facility:
Stationary **XXX**

[illegible]

77B.900(2)

NOTE: VOA =ppb VOH=ppm RPH=ppm

*** SEE ATTACHMENT "A" ***

[illegible]

[illegible]

Name of Facility:RINKER MATERIALS CORP
Air Permit No: A013-172154
Soil Treatment Permit No: SW-01117-91
Stationary XXX or Mobile Facility:

ATTACHMENT "A"

Month	MARCH	Year	1995
-------	-------	------	------

[illegible]

PROJECT-BUILDING 1050 A
203-95020

<u>Sample</u>	<u>Source</u>	<u>AS</u> <u>PPM</u>	<u>PB</u> <u>PPM</u>	<u>DET</u> <u>LIM</u>	
<u>1</u> B1			10.8	89	10
<u>2</u> B2			17	92	
<u>4</u> CLEAN		<10	<10		
<u>5</u> CLEAN		<10	<10		
<u>7</u> MIX		<10	<10		
<u>8</u> MIX		<10	<10		

MIX:1 CONT WITH2NON CONT

PROJECT-Coastal Fuel
344-95004

<u>Sample</u>	Source	AS PPM	FB PPM	CR PPM
<u>1</u> B1		<1	<10	<10
<u>2</u> B2		<1	<10	<10
<u>4</u> CLEAN		<1	<10	<10
<u>5</u> CLEAN		<1	<10	<10
<u>7</u> MIX		<1	<10	<10
<u>8</u> MIX		<1	<10	<10

MIX:1 CONT WITH1NON CONT

PROJECT-COASTAL FUEL
344-95005

<u>Sample</u>	Source	PB PPM	DET LIM
1	B1	<10	10
2	B2	<10	
4	CLEAN	<10	
5	CLEAN	<10	
7	MIX	<10	
8	MIX	<10	

MIX:1 CONT WITH1NON CONT

PROJECT-Coastal Fuel
.344-95006

<u>Sample</u>	<u>Source</u>	<u>AS</u> <u>PPM</u>	<u>PB</u> <u>PPM</u>	<u>CR</u> <u>PPM</u>	
1	B1		8.3	67	39
2	B2		6.8	65	35
4	CLEAN	<1	<10	<10	
5	CLEAN	<1	<10	<10	
7	MIX	<1	<10	<10	
8	MIX	<1	<10	<10	

MIX:1 CONT WITH1NON CONT

MATERIALS ANALYSIS REPORT

REPORT DATE - 3-29-95

SAMPLE DATE - 3-3-95

SAMPLE SOURCE - KANSAS PACKAGING

O.K. Satellite

REFERENCE # - 348-95001

SAMPLE TYPE - SOIL

PARAMETER	RESULT	RESULT	RESULT	UNITS	METHOD	D LIMITS
	CONTAMINAT	CLEAN	BLEND			
Lead	BDL	BDL	BDL	mg/kg	239.2	10

BLEND= 1 CONTAMINATED WITH 1 CLEAN

BDL= Below detection limit

RINKER MATERIALS SUBSTITUTION

MATERIALS ANALYSIS REPORT

REPORT DATE -3-29-95

SAMPLE DATE- 3-8-95

SAMPLE SOURCE -AVRO MOTORS

REFERENCE # -521-95001

SAMPLE TYPE -SOIL

PARAMETER	RESULT	RESULT	RESULT	UNITS	METHOD	D LIMITS
	CONTAMINAT	CLEAN	BLEND			
Lead	BDL	BDL	BDL	mg/kg	239.2	10

BLEND= 1 CONTAMINATED WITH 1 CLEAN

BDL= Below detection limit

MATERIALS ANALYSIS REPORT

REPORT DATE - 3-29-95

SAMPLE DATE- 3-10-95

SAMPLE SOURCE -KANSAS PACKAGING

REFERENCE # - 522-95001

SAMPLE TYPE -SOIL

PARAMETER	RESULT	RESULT	RESULT	UNITS	METHOD	D LIMITS
	CONTAMINAT	CLEAN	BLEND			
Lead	125	BDL	BDL	mg/kg	239.2	10

BLEND= 1 CONTAMINATED WITH 1 CLEAN

BDL= Below detection limit

MATERIALS ANALYSIS REPORT

REPORT DATE - 3-29-95

SAMPLE DATE - 3-10-95

SAMPLE SOURCE - KANSAS PACKAGING

REFERENCE # - 522-95002

SAMPLE TYPE - SOIL

PARAMETER	RESULT CONTAMINAT	RESULT CLEAN	RESULT BLEND	UNITS	METHOD	D LIMITS
Lead	125	BDL	BDL	mg/kg	239.2	10

BLEND= 1 CONTAMINATED WITH 1 CLEAN

BDL= Below detection limit

MATERIALS ANALYSIS REPORT

REPORT DATE -3-29-95

SAMPLE DATE- 3-95

SAMPLE SOURCE -A-1 DURAN

REFERENCE # 526-95001

SAMPLE TYPE -SOIL

PARAMETER	RESULT CONTAMINAT	RESULT CLEAN	RESULT BLEND	UNITS	METHOD	D LIMITS
Arsenic	BDL	BDL	BDL	mg/kg	206.3	10

BLEND= 1 CONTAMINATED WITH 1 CLEAN

BDL= Below detection limit

RINKER MATERIALS SUBSTITUTION

MATERIALS ANALYSIS REPORT

REPORT DATE- 3-29-95

SAMPLE DATE- 3-95

SAMPLE SOURCE -CBI-DETH

REFERENCE # -114-95049

SAMPLE TYPE -SOIL

PARAMETER	RESULT CONTAMINAT	RESULT CLEAN	RESULT BLEND	UNITS	METHOD	D LIMITS
Lead	35	BDL	BDL	mg/kg	239.2	10

BLEND= 1 CONTAMINATED WITH 1 CLEAN

BDL= Below detection limit

LINKER MATERIALS SUBSTITUTION

MATERIALS ANALYSIS REPORT

REPORT DATE: 4-13-95

SAMPLE DATE: 3-30-95

SAMPLE SOURCE: PRESIDENTIAL GOLF COURSE

REFERENCE: 4302-95011

SAMPLE TYPE: SOIL

PARAMETER	RESULT	RESULT	RESULT	UNITS	METHOD	D. LIMITS
	CONTAMINAT	CLEAN	BLEND			
Arsenic	BDL	BDL	BDL	mg/kg	206.3	10

BLEND: CONTAMINATED WITH CLEAN

BDL: Below detection limit

[illegible]

Untreated Soil Reporting Form

Facility Rinker Materials Corporation
Air Permit No.: A013-172154
Soil Treatment Permit No.: SW-0117-91
Stationary XXX

Month March Year 1995

ATTACHMENT "B"

Date	Batch No.	Source	Soil Content PCB's	Tons	PCB Oil Concentration	Lb. PCB per Batch	YTD Lbs. PCB
Continuation from February 1995							1.5441lbs

NO ACTIVITY IN MARCH

Soil Thermal Treatment Facility Untreated Soil Reporting Form

Month: April Year: 1995

Name of Facility: RINKER MATERIALS CORP.
Air Permit No.: A013-172154
Soil Treatment Permit No.: SW-01117-91
Stationary XXX or Mobile Facility:

DER Form # 17-775.900(2)
Soil Thermal Treatment Facility
Form Title Untreated Soil Reporting Form
Effective Date _____
DER Application No _____

1	2	3	4	5										6	7	8	9
Day of Mo.	Soil Batch ID#	Sample Number	Amount Volume or Weight cy/lb	Analytical Results													
				Metals										Totals			
				AS	BA	CD	CR	PB	HG	SE	AG	VOA	RPH	VOH	Indicate Other Analyses Attach Lab Results Only		
04/03/95	106-85028	1	3.18	BDL	2.7	BDL	7.5	1.80	BDL	BDL	BDL	BDL	39	BDL			
04/03/95	180-85003	5	6.10	BDL	208	.46	10.59	338	17.24	BDL	.23	50.82	152.04	0.02			
04/03/95	203-85037	3	253.01	BDL	3.88	BDL	3.69	4.78	BDL	BDL	BDL	BDL	44.20	BDL			
04/03/95	203-85038	3	329.21	BDL	19.20	BDL	4.77	9.50	BDL	BDL	BDL	BDL	2.10	BDL			
04/03/95	203-85039	3	288.51	.54	5.44	BDL	3.60	14.24	BDL	BDL	BDL	BDL	39.34	BDL			
04/03/95	217-85002	5	165.48	BDL	3.92	BDL	3.38	5.34	BDL	BDL	BDL	BDL	707	BDL			
04/03/95	350-85003	1	32.23	BDL	BDL	1	4	BDL	BDL	BDL	BDL	144600	90	BDL			
04/03/95	388-85002	1	11.16	<10	6.7	<0.50	3.5	<5.0	<0.030	<10	<1.0	<32	4900	BDL			
04/03/95	514-85021	7	618.21	0.046	.004	.005	0.210	0.388	<0.002	0.014	<0.001	28.8	68.2	BDL			
04/04/95	180-85003	5	11.60	BDL	208	.46	10.59	338	17.24	BDL	.23	50.82	152.04	0.02			
04/04/95	203-85028	3	146.10	BDL	31.87	BDL	3.82	4.48	BDL	BDL	.60	7880	122.20	BDL			
04/04/95	203-85038	3	87.77	BDL	19.20	BDL	4.77	9.60	BDL	BDL	BDL	BDL	2.10	BDL			
04/04/95	217-85002	5	120.33	BDL	3.82	BDL	3.38	5.34	BDL	BDL	BDL	BDL	707	BDL			
04/05/95	180-85003	5	104.82	BDL	208	.46	10.59	338	17.24	BDL	.23	50.82	152.04	0.02			
04/05/95	293-85003	1	64.17	<6.0	<25	<4.5	13	400	<0.35	<5.5	<2.6	BDL	28900	BDL			
04/05/95	330-85001	1	0.11	BDL	BDL	BDL	BDL	1.87	BDL	BDL	BDL	BDL	BDL	BDL			
04/05/95	383-85001	1	0.06	1.28	2.36	BDL	3.30	BDL	BDL	BDL	BDL	BDL	3	BDL			
04/05/95	418-85002	1	3.16	1.8	27	1.7	10	820	BDL	BDL	BDL	BDL	2450	BDL			
04/05/95	478-85001	1	0.03	BDL	84	BDL	6.0	140	BDL	BDL	BDL	BDL	2300	BDL			
04/05/95	108-85015	1	3.98	BDL	53.0	BDL	12.0	10.0	BDL	BDL	BDL	BDL	63.1	BDL			
04/06/95	108-85016	1	1.39	<10	420	1.2	18	440	.06	<10	<1.0	BDL	1300	BDL			
04/06/95	114-85060	1	21.87	3.0	13	BDL	14	12	BDL	BDL	2.7	.004	1000	BDL			
04/06/95	114-85061	1	1.18	BDL	BDL	BDL	BDL	30	0.34	BDL	BDL	BDL	1000	BDL			
04/06/95	180-85003	5	8.05	BDL	208	.46	10.59	338	17.24	BDL	.23	50.82	152.04	0.02			
04/06/95	217-85002	5	173.00	BDL	3.92	BDL	3.38	5.34	BDL	BDL	BDL	BDL	707	BDL			
04/06/95	357-85003	1	42.81	BDL	3.3	BDL	4.0	5.1	BDL	BDL	BDL	.00046	540	BDL			
04/06/95	357-85004	1	53.54	BDL	2.4	BDL	2.9	13	BDL	BDL	BDL	.001	4000	BDL			

775.900(2)

NOTE: VOA=ppb VOH=ppm RPH=ppm

* SEE ATTACHMENT "A"

Florida Department of Environmental Regulation
Twin Towers Office Bldg. 2800 Blair Stone Road Tallahassee, Florida 32399-2400

**Soil Thermal Treatment Facility
Untreated Soil Reporting Form**

Month: April Year: 1995

Name of Facility: RINKER MATERIALS CORP.
Air Permit No.: A019-172154
Soil Treatment Permit No.: SW-01117-91
Stationary XXX or Mobile Facility: _____

DER Form # 17-775.900(2)
Soil Thermal Treatment Facility
Form Title Untreated Soil Reporting Form
Effective Date _____
DER Application No _____

1	2	3	4	5										6	7	8	9
Day of Mo.	Soil Batch ID#	Sample Number	Amount Volume or Weight cy/lb	Analytical Results													
				Metals										Totals			
				AS	BA	CD	CR	PB	HG	SE	AG	VOA	RPH	VOH	Indicate Other Analyses		
04/06/95	383-85003	1	25.21	1.49	3.07	BDL	BDL	3.85	BDL	BDL	BDL	BDL	48	BDL			
04/06/95	391-85005	3	74.21	BDL	537.34	1.74	6.10	16.37	BDL	BDL	4.10	BDL	199.87	BDL			
04/06/95	419-85002	1	3.18	1.8	27	1.7	10	820	BDL	BDL	BDL	BDL	2450	BDL			
04/06/95	530-85001	1	15.31	3.79	8.82	0.30	5.72	13.10	0.05	BDL	BDL	BDL	14130.57	BDL			
04/06/95	531-85001	1	81.84	BDL	16.7	BDL	3.10	3.25	BDL	BDL	BDL	.000	2256	BDL			
04/07/95	108-85004	2	0.48	BDL	28	BDL	BDL	BDL	BDL	BDL	BDL	BDL	91.1	BDL			
04/07/95	108-85009	1	0.11	BDL	2.80	BDL	1.40	6.00	.240	BDL	BDL	.002	17.4	BDL			
04/07/95	108-85010	1	0.31	BDL	1.20	BDL	BDL	6.00	BDL	BDL	BDL	.085	35	BDL			
04/07/95	108-85011	1	0.14	BDL	194	BDL	BDL	16.6	BDL	BDL	BDL	BDL	48.7	BDL			
04/07/95	108-85013	1	2.20	BDL	82.6	BDL	10.1	22.8	.120	BDL	1.02	BDL	14132	BDL			
04/07/95	114-85062	1	0.11	BDL	13	BDL	17	4.1	BDL	BDL	BDL	.096	22000	BDL			
04/07/95	180-85003	5	3.00	BDL	208	.48	10.59	336	17.24	BDL	.23	50.52	182.04	0.02			
04/07/95	203-85044	12	818.51	2.00	11	1.00	7.00	75.43	0.05	0.06	0.14	7.22	29.34	BDL			
04/07/95	353-85003	1	59.18	1.49	3.07	BDL	BDL	3.85	BDL	BDL	BDL	BDL	48	BDL			
04/07/95	391-85005	3	55.02	BDL	537.34	1.74	8.10	16.37	BDL	BDL	4.10	BDL	199.87	BDL			
04/07/95	531-85001	1	20.13	BDL	16.7	BDL	3.10	3.25	BDL	BDL	BDL	.000	2256	BDL			
04/10/95	180-85003	5	12.10	BDL	208	.48	10.59	336	17.24	BDL	.23	50.52	182.04	0.02			
04/10/95	180-85002	1	1.28	BDL	9.5	8.5	7.5	45	BDL	BDL	5.0	BDL	820	BDL			
04/10/95	180-85003	1	1.75	4.55	7.04	1.06	12.0	13.5	.00365	.0737	.0915	BDL	323	BDL			
04/10/95	302-85013	1	98.88	<1.0	<20	<2.0	8.3	<15	<0.25	<50	<2.0	52.10	5100	BDL			
04/10/95	383-85004	1	3.50	1.49	3.07	BDL	BDL	3.55	BDL	BDL	BDL	BDL	48	BDL			
04/10/95	388-85002	1	18.03	3.0	4.8	BDL	2.4	19	BDL	BDL	BDL	BDL	51000	BDL			
04/10/95	371-85002	1	22.09	BDL	50.3	2.39	10.2	105	.126	BDL	BDL	.00030	3425	0.24			
04/10/95	418-85002	1	76.49	1.8	27	1.7	10	820	BDL	BDL	BDL	BDL	2450	BDL			
04/10/95	433-85001	1	5.50	1.6	420	BDL	65	11	BDL	BDL	BDL	BDL	70	BDL			
04/10/95	532-85001	1	1.00	1.4	3.7	BDL	4.7	3.0	BDL	BDL	BDL	BDL	4040	BDL			
04/11/95	103-85009	3	43.10	BDL	7.5	0.3	3.1	269.7	BDL	BDL	BDL	189	863.60	0.11			

775.900(2)

SEE ATTACHMENT "A"

Florida Department of Environmental Regulation

Twin Towers Office Bldg. 2800 Blair Stone Road Tallahassee, Florida 32389-2400

Soil Thermal Treatment Facility Untreated Soil Reporting Form

Month: April Year: 1995

DER Form # 17-775.900(2)
 Soil Thermal Treatment Facility
 Form Title Untreated Soil Reporting Form
 Effective Date _____
 DER Application No _____

Name of Facility: RINKER MATERIALS CORP.
 Air Permit No.: A019-172154
 Soil Treatment Permit No.: SW-01117-91
 Stationary XXX or Mobile Facility: _____

1	2	3	4	5										6	7	8	9
Day of Mo.	Soil Batch ID#	Sample Number	Amount Volume or Weight cy/m	Analytical Results										Totals			
				Metals													
				AS	BA	CD	CR	PB	HG	SE	AG	VOA	RPH	VOH	Indicate Other Analyses		
				BDL	2.7	BDL	7.5	1.80	BDL	BDL	BDL	BDL	39	BDL	Attach Lab Results Only		
04/11/95	106-85026	1	2.67	BDL	13	BDL	9.0	89	BDL	BDL	BDL	2160	2300	BDL			
04/11/95	114-85036	1	0.29	BDL	7.3	BDL	4.8	5.0	BDL	BDL	BDL	BDL	37000	BDL			
04/11/95	114-85038	1	0.18	2.0	208	.46	10.89	338	17.24	BDL	.23	50.82	182.04	0.02			
04/11/95	180-85003	5	12.10	BDL	11	1.00	7.00	75.43	0.05	0.08	0.14	7.22	29.34	BDL			
04/11/95	203-85044	12	1209.24	2.00	200	13	32	620	1.3	BDL	BDL	1128	7700	BDL			
04/11/95	302-85014	1	0.25	3.7	200	BDL	18	12	BDL	BDL	BDL	BDL	0.3	BDL			
04/11/95	371-85001	1	0.60	BDL	235	BDL	7.21	18.3	BDL	BDL	BDL	BDL	883	BDL			
04/12/95	114-85046	1	0.29	BDL	BDL	BDL	BDL	BDL	BDL	BDL	BDL	BDL	198	BDL			
04/12/95	114-85059	1	1.03	BDL	BDL	BDL	BDL	BDL	BDL	BDL	BDL	BDL	2300	BDL			
04/12/95	114-85064	1	13.80	5.5	18	BDL	7.2	88	BDL	BDL	BDL	BDL	152.04	0.02			
04/12/95	180-85003	5	6.05	BDL	208	.46	10.89	338	17.24	BDL	.23	50.82	182.04	0.02			
04/12/95	203-85044	12	324.26	2.00	11	1.00	7.00	75.43	0.05	0.08	0.14	7.22	29.34	BDL			
04/12/95	217-85002	5	216.01	BDL	3.82	BDL	3.36	5.34	BDL	BDL	BDL	BDL	707	BDL			
04/12/95	278-85005	1	11.85	1.4	3.1	BDL	4.4	1.5	BDL	BDL	BDL	BDL	5.2	BDL			
04/12/95	484-85001	1	5.35	BDL	8.96	BDL	19.9	10.9	BDL	BDL	BDL	BDL	171	BDL			
04/13/95	106-85028	1	3.39	BDL	2.7	BDL	7.5	1.80	BDL	BDL	BDL	BDL	39	BDL			
04/13/95	114-85028	1	16.63	3.50	3.90	BDL	8.00	6.40	BDL	BDL	BDL	BDL	6135	BDL			
04/13/95	180-85003	5	3.00	BDL	208	.46	10.89	338	17.24	BDL	.23	50.82	182.04	0.02			
04/13/95	203-85041	3	503.85	1.5	2.83	BDL	8.69	2.54	.112	BDL	BDL	BDL	6.33	BDL			
04/13/95	203-85042	1	97.73	BDL	2.83	BDL	4.85	4.63	BDL	BDL	BDL	BDL	32	BDL			
04/13/95	203-85043	1	116.63	BDL	2.16	BDL	3.37	2.11	0.114	BDL	BDL	BDL	BDL	BDL			
04/13/95	203-85044	12	870.72	2.00	11	1.00	7.00	75.43	0.05	0.08	0.14	7.22	29.34	BDL			
04/13/95	203-85052	3	16.80	BDL	3.50	BDL	4.09	0.40	BDL	BDL	0.36	30.87	47.33	BDL			
04/13/95	419-85002	1	3.07	1.8	27	1.7	10	520	BDL	BDL	BDL	BDL	2450	BDL			
04/14/95	104-85006	1	2.40	5	62	2	44	13	BDL	BDL	2	BDL	198172	BDL			
04/14/95	106-85017	1	0.91	BDL	2.23	BDL	2.49	BDL	BDL	BDL	BDL	BDL	284	BDL			
04/14/95	106-85021	1	3.50	26	160	12	46	690	0.12	19	<1.0	696.00	270000	BDL			

270000

* SEE ATTACHMENT "A"

Florida Department of Environmental Regulation

Twin Towers Office Bldg. 2600 Blair Stone Road Tallahassee, Florida 32399-2400

Soil Thermal Treatment Facility Untreated Soil Reporting Form

Month: April Year: 1995

Name of Facility: RINKER MATERIALS CORP.
Air Permit No.: A019-172154
Soil Treatment Permit No.: SW-01117-91
Stationary XXX or Mobile Facility:

DER Form # 17-775.900(2)
Soil Thermal Treatment Facility
Form Title Untreated Soil Reporting Form
Effective Date _____
DER Application No _____

1	2	3	4	5										6	7	8	9
Day of Mo.	Soil Batch ID #	Sample Number	Amount Volume or Weight cy/tn	Analytical Results													
				Metals								Totals					
				AS	BA	OD	CR	PB	HG	SE	AG	VOA	RPH	VOH	Indicate Other Analytes Attach Lab Results Only		
04/14/95	106-85023	1	2.48	<10	6.6	<0.50	6.6	24	<0.030	<10	<1.0	22	240	BDL			
04/14/95	106-85024	1	0.21	BDL	53.0	BDL	12.0	10.0	3.68	BDL	BDL	BDL	66.1	BDL			
04/14/95	114-85063	1	15.42	BDL	66.1	BDL	6.8	5.6	17.24	BDL	13.7	21.53	84.680	BDL			
04/14/95	180-85003	5	3.00	BDL	208	.48	10.59	336	17.24	BDL	.23	50.62	152.04	0.02			
04/14/95	203-85041	3	19.63	1.5	2.83	BDL	5.69	2.54	.112	BDL	BDL	BDL	6.33	BDL			
04/14/95	203-85044	12	825.97	2.00	11	1.00	7.00	75.43	0.05	0.06	0.14	7.22	29.34	BDL			
04/14/95	203-85045	1	0.25	BDL	3.20	BDL	4.62	2.70	BDL	BDL	BDL	BDL	293	BDL			
04/14/95	302-85013	1	299.78	<1.0	<20	<2.0	8.3	<15	<0.26	<50	<2.0	52.10	5100	BDL			
04/14/95	370-85001	1	2.00	3.74	2.74	0.69	3.43	48.6	0.14	.014	0.07	BDL	66	BDL			
04/14/95	431-85001	7	850.15	BDL	1.15	BDL	2.18	BDL	BDL	BDL	BDL	BDL	764.58	BDL			
04/17/95	103-85010	1	7.37	BDL	130	7.3	3.5	390	BDL	BDL	BDL	BDL	57600	BDL			
04/17/95	293-85004	1	48.04	<8.0	<5.5	<4.5	<7.0	22	<35	<5.5	<35	BDL	25.300	BDL			
04/17/95	431-85001	7	1188.00	BDL	1.15	BDL	2.18	BDL	BDL	BDL	BDL	BDL	764.58	BDL			
04/17/95	431-85002	6	46.02	BDL	1.13	BDL	1.53	2.83	BDL	BDL	BDL	BDL	258.37	BDL			
04/18/95	103-85009	3	0.59	BDL	7.5	0.3	3.1	288.7	BDL	BDL	BDL	169	853.66	0.11			
04/18/95	180-85003	5	9.05	BDL	208	.46	10.59	336	17.24	BDL	.23	50.62	152.04	0.02			
04/18/95	203-85044	12	712.79	2.00	11	1.00	7.00	75.43	0.05	0.06	0.14	7.22	29.34	BDL			
04/18/95	239-85001	3	119.81	53.33	140	1.53	13.60	403.93	0.62	46.00	<1.33	<414.33	8533.33	BDL			
04/18/95	431-85001	7	826.48	BDL	1.15	BDL	2.18	BDL	BDL	BDL	BDL	BDL	764.58	BDL			
04/19/95	103-85011	1	7.63	BDL	BDL	BDL	BDL	BDL	BDL	BDL	BDL	BDL	73	BDL			
04/19/95	114-85065	1	1.47	3.7	6.3	BDL	2.7	8.1	BDL	BDL	BDL	BDL	11200	BDL			
04/19/95	114-85068	1	2.73	BDL	10	BDL	4.7	28	BDL	BDL	BDL	BDL	250	BDL			
04/19/95	180-85003	5	9.10	BDL	208	.46	10.59	336	17.24	BDL	.23	50.62	152.04	0.02			
04/19/95	203-85044	12	665.51	2.00	11	1.00	7.00	75.43	0.05	0.06	0.14	7.22	29.34	BDL			
04/19/95	431-85001	7	26.00	BDL	1.15	BDL	2.18	BDL	BDL	BDL	BDL	BDL	764.58	BDL			
04/19/95	533-85001	1	2.75	3.61	25.6	<0.05	13.3	19.0	<0.001	4.51	<0.05	2142	17100	BDL			
04/20/95	103-85012	1	0.25	1.9	<20	<2.0	5.6	<15	<2.0	<50	<2.0	BDL	1.7	BDL			

775.900(2)

* SEE ATTACHMENT "A"

Florida Department of Environmental Regulation

Twin Towers Office Bldg. 2600 Blair Stone Road Tallahassee, Florida 32399-2400

Soil Thermal Treatment Facility Untreated Soil Reporting Form

Month: April Year: 1995

Name of Facility: RINKER MATERIALS CORP.
Air Permit No.: A013-172154
Soil Treatment Permit No.: SW-01117-91
Stationary XXX or Mobile Facility: _____

DER Form #	17-775.900(2)
Form Title	Soil Thermal Treatment Facility
Effective Date	Untreated Soil Reporting Form
DER Application No	

Stationary XXX or Mobile Facility:				5												6	7	8	9				
1	2	3	4	Analytical Results												Indicate Other Analyses							
Day of Mo.	Soil Batch ID#	Sample Number	Amount Volume or Weight cy/tn	Metals												Totals				Attach Lab Results Only			
				AS	BA	CD	CR	PB	HG	SE	AG	VOA	RPH	VOH									
04/20/95	104-95007	1	2.48	BDL	BDL	9	BDL	24	BDL	BDL	2	83765	15940	BDL									
04/20/95	114-95072	1	107.63	BDL	2.30	BDL	1.20	1.40	BDL	BDL	BDL	BDL	28.8	BDL									
04/20/95	180-95003	5	6.05	BDL	208	.46	10.59	336	17.24	BDL	.23	50.52	162.04	0.02									
04/20/95	203-95044	12	20.14	2.00	11	1.00	7.00	75.43	0.05	0.06	0.14	7.22	28.34	BDL									
04/20/95	203-95047	5	994.23	0.218	8.3	BDL	3.15	11.87	BDL	BDL	0.728	BDL	72.16	BDL									
04/20/95	293-95005	5	989.06	<3.18	<25	<2.40	<2.76	11.24	<0.07	<2.92	<18.62	BDL	9312	BDL									
04/20/95	302-95013	1	254.70	<1.0	<20	<2.0	8.3	<15	<0.25	<30	<2.0	52.10	5100	BDL									
04/20/95	311-95001	1	1.00	<0.01	19.60	0.49	3.00	7.24	<0.01	<0.01	0.03	BDL	20	BDL									
04/20/95	344-95010	1	8.23	BDL	BDL	3.2	10	7.1	BDL	BDL	0.54	BDL	1620	BDL									
04/20/95	388-95003	1	43.99	BDL	55	1.6	14	370	0.12	BDL	BDL	BDL	2100	BDL									
04/20/95	534-95001	1	1.00	BDL	2.3	BDL	5.7	21	BDL	BDL	BDL	BDL	510000	BDL									
04/20/95	535-95001	1	3.87	1.4	33	BDL	4.2	480	0.09	BDL	BDL	BDL	5720	BDL									
04/20/95	536-95001	1	2.50	4.7	31	BDL	14	240	BDL	BDL	BDL	BDL	4400	BDL									
04/21/95	104-95003	1	0.19	5	70	14	35	2040	BDL	BDL	BDL	12157	10582	BDL									
04/21/95	180-95003	5	3.05	BDL	208	.46	10.59	336	17.24	BDL	.23	50.52	152.04	0.02									
04/21/95	203-95044	12	220.91	2.00	11	1.00	7.00	75.43	0.05	0.06	0.14	7.22	28.34	BDL									
04/21/95	203-95047	5	498.85	0.218	6.3	BDL	3.15	11.87	BDL	BDL	0.728	BDL	72.16	BDL									
04/21/95	297-95009	1	17.83	BDL	0.40	0.18	1.20	0.085	BDL	BDL	0.088	81.60	348561	BDL									
04/21/95	514-95021	7	84.07	0.048	.004	.005	0.210	0.385	<0.002	0.014	<0.001	28.8	68.2	BDL									
04/21/95	537-95001	3	144.83	1.23	6.6	0.47	6.6	15.53	BDL	BDL	BDL	2.63	203	BDL									
04/24/95	114-95067	1	1.31	BDL	48.3	BDL	9.2	33.1	16.1	BDL	9.3	BDL	10470	BDL									
04/24/95	114-95068	1	1.31	BDL	3.89	BDL	1.74	6.33	BDL	BDL	BDL	BDL	8.0	BDL									
04/24/95	114-95069	1	1.31	BDL	4.52	BDL	1.17	3.85	BDL	BDL	BDL	BDL	10900	BDL									
04/24/95	114-95070	1	1.31	BDL	5.9	BDL	5.7	8.1	BDL	BDL	BDL	BDL	2200	BDL									
04/24/95	114-95071	1	8.23	3.5	78	BDL	9.7	15	BDL	BDL	BDL	BDL	182.04	0.02									
04/24/95	180-95003	5	12.10	BDL	208	.46	10.59	336	17.24	BDL	.23	50.52	28.34	BDL									
04/24/95	203-95044	12	199.27	2.00	11	1.00	7.00	75.43	0.05	0.06	0.14	7.22	28.34	BDL									

570000

775.900(2)

* SEE ATTACHMENT "A"

Florida Department of Environmental Regulation
Twin Towers Office Bldg. 2600 Blair Stone Road Tallahassee, Florida 32399-2400

**Soil Thermal Treatment Facility
Untreated Soil Reporting Form**

Month: April Year: 1995

Name of Facility: RINKER MATERIALS CORP.
Air Permit No.: A013-172154
Soil Treatment Permit No.: SW-01117-91
Stationary XXX or Mobile Facility:

DER Form # 17-775.900(2)
Soil Thermal Treatment Facility
Form Title Untreated Soil Reporting Form
Effective Date _____
DER Application No _____

1		2		3		4		5					6	7	8	9
Day of Mo.	Soil Batch ID#	Sample Number	Amount Volume or Weight cy/lb	Analytical Results											Indicate Other Analyses Attach Lab Results Only	
				Metals								Totals				
				AS	BA	CD	CR	PB	HG	SE	AG	VOA	RPH	VOH		
04/24/95	297-85008	1	27.72	1.51	.0623	.0972	<0.100	7.92	<.0010	.218	<.0800	840.25	8410	BDL		
04/25/95	180-85003	5	12.00	BDL	.208	.46	10.59	336	17.24	BDL	.23	50.52	152.04	0.02		
04/25/95	268-85003	3	332.55	<0.19	<0.53	<1.19	2.73	8.84	<0.07	<0.12	<0.80	BDL	14.90	BDL		
04/25/95	368-85004	3	118.51	93	3.9	0.60	3.3	<0.05.0	0.02	<.0	<.10	640	13.133	BDL		
04/26/95	180-85003	5	3.05	BDL	.208	.46	10.59	336	17.24	BDL	.23	50.52	152.04	0.02		
04/26/95	203-85032	3	153.94	BDL	3.50	BDL	4.09	0.40	BDL	BDL	0.36	30.57	47.33	BDL		
04/26/95	268-85003	3	248.38	<0.19	<0.53	<1.19	2.73	8.84	<0.07	<0.12	<0.80	BDL	14.90	BDL		
04/26/95	350-85004	3	308.16	BDL	11	BDL	8	BDL	BDL	BDL	BDL	10.000	210	BDL		
04/26/95	416-85002	1	3.03	1.8	27	1.7	10	820	BDL	BDL	BDL	BDL	2450	BDL		
04/26/95	431-85002	6	1396.78	BDL	1.13	BDL	1.93	2.83	BDL	BDL	BDL	BDL	258.37	BDL		
04/27/95	106-85028	1	3.72	BDL	2.7	BDL	7.5	1.80	BDL	BDL	BDL	BDL	.39	BDL		
04/27/95	180-85003	5	6.05	BDL	.208	.46	10.59	336	17.24	BDL	.23	50.52	152.04	0.02		
04/27/95	230-85002	1	0.60	0.10	0.89	BDL	1.82	0.88	BDL	0.02	BDL	2.14	33.6	BDL		
04/27/95	302-85015	1	1.80	.008	<0.001	<0.001	5.430	<.001	<0.020	<.001	<0.001	11.7	91.67	.003		
04/27/95	344-85010	1	19.51	BDL	BDL	3.2	10	7.1	BDL	BDL	0.84	BDL	1620	BDL		
04/27/95	431-85002	6	1228.53	BDL	1.13	BDL	1.93	2.83	BDL	BDL	BDL	BDL	258.37	BDL		
04/27/95	453-85002	3	511.60	BDL	11.57	2.2	5.27	88.85	BDL	BDL	BDL	.009	269.10	BDL		
04/27/95	453-85003	1	0.80	BDL	8.1	BDL	5.9	BDL	BDL	BDL	BDL	BDL	18	BDL		
04/27/95	514-85022	6	39.01	.099	14.87	33.73	97.32	1588.33	0.07	BDL	1.96	0.16	2575	0.83		
04/28/95	106-85028	1	17.43	BDL	2.7	BDL	7.5	1.80	BDL	BDL	BDL	BDL	39	BDL		
04/28/95	180-85003	5	6.05	BDL	.208	.46	10.59	336	17.24	BDL	.23	50.52	152.04	0.02		
04/28/95	203-85052	3	184.89	BDL	3.50	BDL	4.09	0.40	BDL	BDL	0.36	30.57	47.33	BDL		
04/28/95	268-85003	3	100.12	<0.19	<0.53	<1.19	2.73	8.84	<0.07	<0.12	<0.80	BDL	14.90	BDL		
04/28/95	302-85016	1	18.47	2.46	4.73	2.47	5.31	12.2	.0419	.0369	<.0500	BDL	4200	BDL		
04/28/95	453-85002	3	307.25	BDL	11.57	2.2	5.27	88.85	BDL	BDL	BDL	.009	269.10	BDL		
04/28/95	514-85022	6	235.33	.099	14.87	33.73	97.32	1588.33	0.07	BDL	1.96	0.18	2875	0.93		

775.900(2)

* SEE ATTACHMENT "A"

Name of Facility:RINKER MATERIALS CORP
Air Permit No: A013-172154
Soil Treatment Permit No: SW-01117-01
Stationary XXX or Mobile Facility:

Month	APRIL	Year	1995
-------	-------	------	------

[illegible]

Metals Blending Report															
5															
1	2	3	4	Analytical Results										8	
Day of Mo.	Soil Batch ID#	Sample Number	Amount Volume or weight	METALS										Source	
				Totals											
				AS	BA	CD	CR	PB	HG	SE	AG	VOA	RPH		
4/6/95	106-95016														
untreated blending blended	analysis soil soil		1.38 T	<10	420	1.2	18	440	.06	<10	<1	BDL	1300	Blended 1 to 7	
4/10/95	453-95001														
untreated blending blended	analysis soil soil		5.5 T	1.6	420	BDL	65	11	BDL	BDL	BDL	BDL	70	Blended 1 to 1	
4/11/95-4/18/95	103-95009														
untreated blending blended	analysis soil soil		43.69T	BDL	7.5	.3	3.1	289.7	BDL	BDL	BDL	189	883.66	Blended 1 to 1	
4/11/95	302-95014														
untreated blending blended	analysis soil soil		.25T	3.7	200	13	32	620	1.3	BDL	BDL	1129	7700	Blended 1 to 7	

Name of Facility: RINKER MATERIALS CORP
Air Permit No: A013-172154
Soil Treatment Permit No: SW-01117-91
Stationary XXX or Mobile Facility:

ATTACHMENT "A"

Month	APRIL	Year	1995
-------	-------	------	------

[illegible]

Name of Facility: RINKER MATERIALS CORP
 Air Permit No: A013-172154
 Soil Treatment Permit No: SW-01117-91
 Stationary XXX or Mobile Facility:

ATTACHMENT "A"

Month APRIL Year 1995

Metals Blending Report

Monthly Blending Report																
1	2	3	4	5										6	7	8
Day of Mo.	Soil Batch ID#	Sample Number	Amount Volume or weight	Analytical Results												
				METALS										Totals		Source
			cy/tn	AS	BA	CD	CR	PB	HG	SE	AG	VOA	RPH			
4/14/95	160-95021															
untreated	analysis		3.5T	26	160	12	46	690	.12	19	<1	696	270000	Blended 1 to 13		
blending soil				BDL				BDL								
blended soil				BDL				BDL								
4/17/95	103-95010															
untreated	analysis		7.37T	BDL	130	7.3	3.5	390	BDL	BDL	BDL	BDL	57600	Blended 1 to 4		
blending soil								BDL								
blended soil								52								
4/18/95	239-95001															
untreated	analysis		119.81T	53.33	140	1.53	13.60	403.33	0.62	46	<1.33	<414.33	8833.33	Blended 1 to 6		
blending soil				BDL				BDL								
blended soil				BDL				BDL								
4/20/95	388-95003															
untreated	analysis		43.99T	BDL	55	1.6	14	370	0.12	BDL	BDL	BDL	2100	Blended 1 to 4		
blending soil								BDL								
blended soil								BDL								

RINKER MATERIALS SUBSTITUTION

MATERIALS ANALYSIS REPORT

REPORT DATE -4-19-95

SAMPLE DATE- 4-5-95

SAMPLE SOURCE -FLORIDA YACHT BASIN

REFERENCE # 100 05003

SAMPLE TYPE -SOIL

PARAMETER	RESULT	RESULT	RESULT	UNITS	METHOD	DLIMITS
	CONTAMINAT	CLEAN	BLEND			
LEAD	374	BDL	86	mg/kg	239.1	10

BLEND=1-CONTAMINATED WITH 4 CLEAN

BDL=Below detection limit

MATERIALS ANALYSIS REPORT

REPORT DATE -5-9-95

SAMPLE DATE- 4--95

AMPLE SOURCE -EPL Cape Canaveral Switch Yard

REFERENCE # 293-95003

SAMPLE TYPE -SOIL

PARAMETER	RESULT	RESULT	RESULT	UNITS	METHOD	DLIMITS
	CONTAMINAT	CLEAN	BLEND			
LEAD	BDL	BDL	BDL	mg/kg	239.1	10

BLEND# 1 CONTAMINATED WITH 1 CLEAN

BDL= Below detection limit

RINKER MATERIALS SUBSTITUTION

MATERIALS ANALYSIS REPORT

PORT DATE -4-19-95

SAMPLE DATE- 4-10-95

SAMPLE SOURCE - NAPA AUTO

REFERENCE # 419-95002

SAMPLE TYPE -SOIL

PARAMETER	RESULT	RESULT	RESULT	UNIT	METHOD	D LIMITS
	CONTAMINAT	CLEAN	BLEND			
LEAD	350	BDL	84	mg/kg	222.1	10

BLEND=1 CONTAMINATED WITH 4 CLEAN

BDL= Below detection limit

RINKER MATERIALS ANALYSIS REPORT

MATERIALS ANALYSIS REPORT

REPORT DATE 5-9-95

SAMPLE DATE- 4-95

SAMPLE SOURCE - Motor Vehicle

REFERENCE # - 479-95001

SAMPLE TYPE -SOIL

PARAMETER	RESULT CONTAMINAT	RESULT CLEAN	RESULT BLEND	UNITS	METHOD	D LIMITS
Lead	BDL	BDL	BDL	mg/kg	239.2	10

BLEND= 1 CONTAMINATED WITH 1 CLEAN

BDL= Below detection limit

RINKER MATERIALS SUBSTITUTION

ERIALS ANALYSIS REPORT

REPORT DATE -4-19-95

SAMPLE DATE- 4-6-95

SAMPLE SOURCE - CHEVRON

REFERENCE # 106-95016

SAMPLE TYPE -SOIL

PARAMETER	RESULT	RESULT	RESULT	UNIT	METHOD	DL LIMITS
	CONTAMINAT	CLEAN	BLEND			
LEAD	640	BDL	66	PPM	0.12.1	10

BLEND=1 CONTAMINATED WITH 70% LEAD

BDL=Below detection limit

MATERIALS ANALYSIS REPORT

REPORT DATE -5-10-95

SAMPLE DATE: 4-95

SAMPLE SOURCE - TEXACO

REFERENCE # 103-95009

SAMPLE TYPE -SOIL

PARAMETER	RESULT	RESULT	RESULT	UNITS	METHOD	D LIMITS
	CONTAMINAT	CLEAN	BLEND			
LEAD	BDL	BDL	52	mg/kg	239.1	10
BLEND= 1 CONTAMINATED WITH 1 CLEAN						
BDL= Below detection limit						

RINKER MATERIALS SUBSTITUTION

SERIALS ANALYSIS REPORT

REPORT DATE -5-10-95

SAMPLE DATE- 4-95

SAMPLE SOURCE -SHELL

REFERENCE # 302-95014

SAMPLE TYPE--SOIL

PARAMETER	RESULT	RESULT	RESULT	UNITS	METHOD	D LIMITS
	CONTAMINAT	CLEAN	BLEND			
LEAD	BDL	BDL	BDL	mg/kg	239.1	10
BLEND= 1 CONTAMINATED WITH 1 CLEAN						
BDL= Below detection limit						

MATERIALS ANALYSIS REPORT

REPORT DATE -5-9-95

SAMPLE DATE- 4--95

SAMPLE SOURCE -CHEVRON

REFERENCE # 106-95021

SAMPLE TYPE. -SOIL

PARAMETER	RESULT	RESULT	RESULT	UNITS	METHOD	D LIMITS
	CONTAMINAT	CLEAN	BLEND			
LEAD	1280	BDL	BDL	PPM		10
ARSENIC	BDL	BDL	BDL	PPM		10
BLEND= 1 CONTAMINATED WITH 13 CLEAN						
BDL= Below detection limit						

MATERIALS ANALYSIS REPORT

REPORT DATE: 5-10-95

SAMPLE DATE- 4-95

SAMPLE SOURCE - TEXACO

REFERENCE # 103-95010

SAMPLE TYPE -SOIL

PARAMETER	RESULT	RESULT	RESULT	UNITS	METHOD	D LIMITS
	CONTAMINAT	CLEAN	BLEND			
LEAD	BDL	BDL	52	mg/kg	239.1	10
BLEND= 1 CONTAMINATED WITH 1 CLEAN						
BDL= Below detection limit						

RINKER MATERIALS SUBSTITUTION

TRIALS ANALYSIS REPORT

REPORT DATE: -5-10-95

SAMPLE DATE- 4-95

SAMPLE SOURCE - TERMINAL KEY WEST

REFERENCE # 239-95001

SAMPLE TYPE -SOIL

PARAMETER	RESULT	RESULT	RESULT	UNITS	METHOD	D LIMITS
	CONTAMINAT	CLEAN	BLEND			
LEAD	370	BDL	BDL	mg/kg	239.1	10
ARSENIC	BDL	BDL	BDL	mg/kg		10
BLEND= 1 CONTAMINATED WITH 4 CLEAN						
BDL= Below detection limit						

BDL= Below detection-limit

RINKER MATERNAL & SUBSTITUTION

MATERIALS ANALYSIS REPORT

REPORT DATE 5-9-95

SAMPLE DATE: 4-7-95

AMPLE SOURCE - GATX 1500 SE 26 ST

REFERENCE # 536-9500

SAMPLE TYPE -SOIL

PARAMETER	RESULT	RESULT	RESULT	UNITS	METHOD	D LIMITS
	CONTAMINAT	CLEAN	BLEND			
LEAD	600	BDL	BDL	PPM		10
BLEND= 1 CONTAMINATED WITH 4 CLEAN						
BDL= Below detection limit						

PROJECT LINCOLN MERCURY
104-95008

<u>Sample</u>	<u>Source</u>	<u>RB</u> <u>PPM</u>	<u>DET</u> <u>PPM</u>
1 B1			341 10
2 B2			350 - -
4 CLEAN		<10	
5 CLEAN		<10	
7 MIX			55
8 MIX			60

MIX:1 CONT WITH 5 NON CONT

MATERIALS ANALYSIS REPORT

REPORT DATE 5-9-95

SAMPLE DATE- 4--95

AMPLE SOURCE - RESOURCE RECOVERY

REFERENCE # - 514-95022

SAMPLE TYPE - SOIL

PARAMETER	RESULT	RESULT	RESULT	UNITS	METHOD	D LIMITS
	CONTAMINAT	CLEAN	BLEND			
LEAD	20	BDL	BDL	mg/kg	239.1	10
CHROMIUM	BDL	BDL	BDL			10
BLEND= 1 CONTAMINATED WITH 1 CLEAN						
BDL= Below detection limit						

Name of Facility:RINKER MATERIALS CORP
Air Permit No: A013-172154
Soil Treatment Permit No: SW-01117-91
Stationary XXX or Mobile Facility:

Name of Facility:RINKER MATERIALS CORP
Air Permit No: A013-172154
Soil Treatment Permit No: SW-01117-91
Stationary XXX or Mobile Facility:

RAW MATERIALS RECEIVED

[illegible]

Untreated Soil Reporting Form

Facility Rinker Materials Corporation
Air Permit No.: A013-172154
Soil Treatment Permit No.: SW-0117-91
Stationary XXX

Month April Year 1995

ATTACHMENT "B"

Date	Batch No.	Source	Soil Content PCB's	Tons PCB Oil Concentration	Lb. PCB per Batch	YTD Lbs. PCB
Continuation from March 1995						1.5441lbs

NO ACTIVITY IN APRIL

Soil Thermal Treatment Facility Untreated Soil Reporting Form

Month: may Year: 1995

Name of Facility: RINKER MATERIALS CORP.
Air Permit No.: A013-172154
Soil Treatment Permit No.: SW-01117-91
Stationary XXX or Mobile Facility: _____

DER Form # 17-775.900(2)
Soil Thermal Treatment Facility
Form Title Untreated Soil Reporting Form
Effective Date _____
DER Application No _____

1	2	3	4	5										6	7	8	9
Day of Mo.	Soil Batch ID#	Sample Number	Amount Volume or Weight cy/tn	Analytical Results										Totals			
				Metals													
				AS	BA	CD	CR	PB	HQ	SE	AG	VOA	RPH	VOH	Indicate Other Analyses		
05/01/95	140-85005	1	3.00	BDL	70.8	BDL	2.16	392	BDL	BDL	BDL	37.39	32100	BDL			
05/01/95	203-85005	15	259.81	BDL	3.60	BDL	4.09	0.40	BDL	BDL	0.36	30.57	47.33	BDL			
05/01/95	453-85002	3	386.88	BDL	11.57	2.2	5.27	88.85	BDL	BDL	BDL	.009	288.10	BDL			
05/02/95	140-85005	1	3.00	BDL	70.8	BDL	2.16	392	BDL	BDL	BDL	37.39	32100	BDL			
05/02/95	297-85010	1	17.49	3.2	9.8	BDL	8.0	15.0	0.09	BDL	BDL	58.00	306	BDL			
05/02/95	374-85001	1	8.51	.321	3.00	<.0500	4.05	1.71	<.0010	.101	.932	<19.58	112	BDL			
05/02/95	477-85001	3	103.89	BDL	BDL	BDL	BDL	BDL	BDL	BDL	BDL	BDL	0.45	BDL			
05/02/95	485-85003	1	18.49	BDL	BDL	BDL	BDL	BDL	BDL	BDL	BDL	BDL	25400	BDL			
05/02/95	514-85023	6	347.49	0.99	14.57	33.73	97.32	1583.33	0.07	BDL	1.96	0.16	2875	0.83			
05/03/95	104-85009	1	0.76	BDL	BDL	BDL	BDL	BDL	BDL	BDL	BDL	BDL	BDL	BDL			
05/03/95	140-85005	1	6.05	BDL	70.8	BDL	2.16	392	BDL	BDL	BDL	37.39	32100	BDL			
05/03/95	180-85004	5	113.27	BDL	203	.46	10.59	338.	17.24	BDL	.23	50.82	182.04	0.02			
05/03/95	203-85005	15	430.69	BDL	3.50	BDL	4.09	0.40	BDL	BDL	0.36	30.57	47.33	BDL			
05/03/95	217-85003	5	343.80	BDL	3.92	BDL	3.98	5.34	BDL	BDL	BDL	BDL	707	BDL			
05/03/95	350-85005	3	208.72	0.76	6.2	0.32	6.8	23.39	<0.030	BDL	<1.0	BDL	454	BDL			
05/03/95	374-85001	1	6.55	.321	3.00	<.0500	4.05	1.71	<.0010	.101	.932	<18.58	112	BDL			
05/03/95	477-85001	3	89.43	BDL	BDL	BDL	BDL	BDL	BDL	BDL	BDL	BDL	0.45	BDL			
05/03/95	502-85003	3	183.91	BDL	6.03	BDL	3.67	14.30	BDL	BDL	BDL	BDL	70.67	BDL			
05/04/95	140-85005	1	3.00	BDL	70.8	BDL	2.16	392	BDL	BDL	BDL	37.39	32100	BDL			
05/04/95	203-85048	3	385.39	BDL	3.09	BDL	4.31	2.63	BDL	BDL	2.14	BDL	63.00	BDL			
05/04/95	203-85049	1	56.45	2.00	2.30	BDL	3.50	1.00	BDL	BDL	BDL	BDL	68	BDL			
05/04/95	203-85050	3	280.47	BDL	2.72	BDL	3.53	1.46	BDL	BDL	1.70	BDL	.47	BDL			
05/04/95	203-85051	1	56.10	5.00	46.0	BDL	3.40	2.50	BDL	BDL	BDL	BDL	9	BDL			
05/04/95	203-85055	15	117.40	BDL	3.50	BDL	4.09	0.40	BDL	BDL	0.36	30.57	47.33	BDL			
05/04/95	350-85005	3	48.96	0.76	6.2	0.32	6.8	23.39	<0.030	BDL	<1.0	BDL	454	BDL			
05/04/95	429-85003	1	3.15	BDL	BDL	BDL	6.7	14	BDL	BDL	BDL	BDL	20.400	BDL			
05/04/95	431-85003	13	660.69	BDL	1.13	BDL	1.53	2.63	BDL	BDL	BDL	BDL	288.37	BDL			

NOTE: VOA = PPB
VOH = PPM
RPH = PPM

* SEE ATTACHMENT "A"

Soil Thermal Treatment Facility Untreated Soil Reporting Form

Month: may Year: 1995

Name of Facility: RINKER MATERIALS CORP.

Air Permit No.: A013-172154

Soil Treatment Permit No.: SW-01117-91

Stationary XXX or Mobile Facility:

DER Form #	17-776.900(2)
Form Title	Soil Thermal Treatment Facility Untreated Soil Reporting Form
Effective Date	
DER Application No	

1	2	3	4	5										6	7	8	9
Day of Mo.	Soil Batch ID#	Sample Number	Amount Volume or Weight cy/m	Analytical Results										Totals			
				Metals													
				AS	BA	CD	CR	PB	HG	SE	AG	VOA	RPH	VOH	Indicate Other Analyses Attach Lab Results Only		
05/04/95	802-85003	3	202.79	BDL	6.03	BDL	3.67	14.30	BDL	BDL	BDL	BDL	70.67	BDL			
05/05/95	140-85005	1	6.03	BDL	70.8	BDL	2.16	382	BDL	BDL	BDL	37.39	32100	BDL			
05/05/95	203-85005	15	98.68	BDL	3.50	BDL	4.09	0.40	BDL	BDL	0.36	30.57	47.33	BDL			
05/05/95	278-85006	1	12.58	BDL	58	4.0	71	180	BDL	BDL	1.8	BDL	140	BDL			
05/05/95	350-85005	3	352.33	0.76	6.2	0.32	6.8	23.39	<0.030	BDL	<1.0	BDL	454	BDL			
05/05/95	431-85003	13	607.70	BDL	1.13	BDL	1.53	2.83	BDL	BDL	BDL	BDL	258.37	BDL			
05/05/95	485-85004	1	17.17	BDL	BDL	BDL	BDL	BDL	BDL	BDL	BDL	BDL	12.600	BDL			
05/05/95	514-85023	6	97.80	0.89	14.87	33.73	97.32	1586.33	0.07	BDL	1.95	0.16	2875	0.93			
05/05/95	108-85029	3	583.55	BDL	2.5	BDL	3.7	1.8	BDL	BDL	3.06	BDL	14.5	BDL			
05/05/95	140-85005	1	15.60	BDL	70.8	BDL	2.16	382	BDL	BDL	BDL	37.39	32100	BDL			
05/05/95	350-85005	3	117.93	0.76	6.2	0.32	6.8	23.39	<0.030	BDL	<1.0	BDL	454	BDL			
05/05/95	387-85003	1	22.00	3.8	680.1	7.1	37	210	1.0	1.0	BDL	23201	71800	.897			
05/05/95	114-85078	1	14.70	BDL	133.0	BDL	3.7	64.8	BDL	BDL	BDL	BDL	983.3	BDL			
05/05/95	140-85005	1	9.00	BDL	70.8	BDL	2.16	382	BDL	BDL	BDL	37.39	32100	BDL			
05/05/95	350-85005	3	303.68	0.76	6.2	0.32	6.8	23.39	<0.030	BDL	<1.0	BDL	454	BDL			
05/05/95	467-85001	1	1.65	BDL	4	BDL	4	17	BDL	BDL	BDL	BDL	40	BDL			
05/05/95	514-85021	7	368.52	0.046	.004	.005	0.210	0.386	<0.002	0.014	<0.001	28.8	68.2	BDL			
05/10/95	103-85013	1	1.20	<1.0	28	2.3	23	680	<0.25	<80	<2.0	BDL	1508	BDL			
05/10/95	114-85078	1	3.15	BDL	133.0	BDL	3.7	64.8	BDL	BDL	BDL	BDL	983.3	BDL			
05/10/95	140-85005	1	11.65	BDL	70.8	BDL	2.16	382	BDL	BDL	BDL	37.39	32100	BDL			
05/10/95	282-85003	1	0.20	7.3	900	38	170	5800	1.2	BDL	2.3	BDL	157000	BDL			
05/10/95	350-85003	3	103.98	0.76	6.2	0.32	6.8	23.39	<0.030	BDL	<1.0	BDL	454	BDL			
05/10/95	387-85003	1	18.28	3.8	680	7.1	37	210	1.0	1.0	BDL	23201	71800	.997			
05/10/95	514-85021	7	113.01	0.046	.004	.005	0.210	0.386	<0.002	0.014	<0.001	28.8	68.2	BDL			
05/10/95	539-85001	1	0.30	BDL	102	BDL	11.2	4.01	BDL	BDL	BDL	BDL	59.4	BDL			
05/11/95	140-85005	1	15.10	BDL	70.8	BDL	2.16	382	BDL	BDL	BDL	37.39	32100	BDL			
05/11/95	350-85005	3	235.35	0.76	6.2	0.32	6.8	23.39	<0.030	BDL	<1.0	BDL	454	BDL			

776.900(2)

* SEE ATTACHMENT "A"

NOTE: VOA = PPB
VOH = PPM
RPH = PPM

Soil Thermal Treatment Facility Untreated Soil Reporting Form

Month: may Year: 1995

DER Form # 17-775.900(2)
Soil Thermal Treatment Facility
Form Title Untreated Soil Reporting Form
Effective Date _____
DER Application No _____

Name of Facility: RINKER MATERIALS CORP.
Air Permit No.: A013-172154
Soil Treatment Permit No.: SW-01117-81
Stationary XXX or Mobile Facility: _____

1	2	3	4	5										6	7	8	9
Day of Mo.	Soil Batch ID#	Sample Number	Amount Volume or Weight cy/m	Analytical Results										Totals			
				Metals													
				AS	BA	CD	CR	PB	HG	SE	AG	VOA	RPH	VOH	Indicate Other Analyses		
05/12/85	108-85031	1	9.11	BDL	6.8	BDL	6.9	13.2	BDL	BDL	BDL	BDL	7539	BDL			
05/12/85	108-85033	1	1.00	BDL	8.0	BDL	5.7	26.7	BDL	BDL	BDL	BDL	21892	0.46			
05/12/85	114-85078	1	2.12	BDL	2.2	BDL	1.7	3.2	BDL	BDL	BDL	BDL	2700	BDL			
05/12/85	114-85077	1	2.12	BDL	38	BDL	28	47	BDL	BDL	BDL	10.31	74	BDL			
05/12/85	140-85005	1	8.05	BDL	70.8	BDL	2.18	392	BDL	BDL	BDL	37.39	32100	BDL			
05/12/85	203-85056	1	0.20	0.001	0.02	0.002	0.01	0.007	0.003	BDL	BDL	BDL	<1.0	BDL			
05/12/85	203-85057	1	0.40	1.90	25.0	8.15	27.4	93.0	.489	<.0020	61.83	1.180	573	BDL			
05/12/85	237-85001	1	3.38	BDL	BDL	1.45	5.4	15	BDL	2.48	BDL	BDL	7393	BDL			
05/12/85	273-85001	1	10.48	0.2	6.0	BDL	3.6	1.9	BDL	0.3	BDL	BDL	2030	BDL			
05/12/85	350-85005	3	55.54	0.76	6.2	0.32	6.8	23.39	<0.030	BDL	<1.0	BDL	454	BDL			
05/12/85	429-85003	1	3.15	BDL	BDL	BDL	6.7	14	BDL	BDL	BDL	BDL	20.400	BDL			
05/12/85	453-85002	3	63.28	BDL	11.57	2.2	5.27	88.85	BDL	BDL	BDL	.009	289.10	BDL			
05/12/85	543-85001	1	7.66	BDL	283	BDL	BDL	.105	BDL	BDL	BDL	BDL	10.60	BDL			
05/15/85	140-85005	1	8.60	BDL	70.8	BDL	2.16	392	BDL	BDL	BDL	37.39	32100	BDL			
05/15/85	203-85054	5	189.32	BDL	12.38	BDL	7.8	31.52	BDL	BDL	BDL	BDL	1148.44	BDL			
05/15/85	548-85001	1	4.10	.1	<1	<0.5	<1	<1	<0.05	<1	<0.5	.608	255000	BDL			
05/16/85	140-85005	1	5.50	BDL	70.8	BDL	2.16	392	BDL	BDL	BDL	37.39	32100	BDL			
05/16/85	203-85053	3	168.98	BDL	3.6	BDL	3.3	5.4	BDL	BDL	BDL	BDL	14.7	BDL			
05/16/85	350-85005	3	51.66	0.76	6.2	0.32	6.8	23.39	<0.030	BDL	<1.0	BDL	454	BDL			
05/17/85	302-85013	1	255.80	<1.0	<20	<2.0	8.3	<15	<0.25	<50	<2.0	52.10	5100	BDL			
05/17/85	350-85005	3	25.13	0.76	6.2	0.32	6.8	23.39	<0.030	BDL	<1.0	BDL	454	BDL			
05/17/85	453-85002	3	156.06	BDL	11.57	2.2	5.27	88.85	BDL	BDL	BDL	.009	289.10	BDL			
05/18/85	114-85078	1	3.33	BDL	133.0	BDL	3.7	64.8	BDL	BDL	BDL	BDL	983.3	BDL			
05/18/85	140-85005	1	6.05	BDL	70.8	BDL	2.16	392	BDL	BDL	BDL	37.39	32100	BDL			
05/18/85	203-85054	5	240.08	BDL	12.38	BDL	7.8	31.52	BDL	BDL	BDL	BDL	1148.44	BDL			
05/18/85	302-85013	1	137.48	<1.0	<20	<2.0	8.3	<15	<0.25	<50	<2.0	52.10	5100	BDL			
05/19/85	103-85014	1	3.40	1.1	43	5.4	16	180	0.16	BDL	BDL	642	45830	BDL			

257600

* SEE ATTACHMENT "A"

NOTE: VOA = PPB
VOH = PPM
RPH = PPM

Soil Thermal Treatment Facility Untreated Soil Reporting Form

Month: may Year: 1995

Name of Facility: RINKER MATERIALS CORP.
Air Permit No.: A013-172154
Soil Treatment Permit No.: SW-01117-91
Stationary XXX or Mobile Facility:

DER Form #	17-775.900(2)
Form Title	Soil Thermal Treatment Facility Untreated Soil Reporting Form
Effective Date	
DER Application No	

1	2	3	4	5										6	7	8	9
Day of Mo.	Soil Batch ID#	Sample Number	Amount Volume or Weight cy/tn	Analytical Results													
				Metals										Totals			
				AS	BA	CD	CR	PB	HG	SE	AG	VOA	RPH	VOH	Indicate Other Analyses		
				BDL	21	1.0	48	151	BDL	BDL	104	83.475	2194	BDL	Attach Lab Results Only		
05/19/85	104-85010	2	5.98	BDL	70.8	BDL	2.16	332	BDL	BDL	BDL	37.39	32100	BDL			
05/19/85	140-85003	1	3.05	BDL	12.38	BDL	7.8	31.82	BDL	BDL	BDL	BDL	1148.44	BDL			
05/19/85	203-85054	5	109.28	BDL	3.80	BDL	12	30	BDL	BDL	BDL	BDL	63	BDL			
05/19/85	203-85060	3	37.45	BDL	5	BDL	2	BDL	BDL	BDL	BDL	7	37	BDL			
05/19/85	239-85002	1	1.25	BDL	BDL	BDL	2.7	11.4	BDL	BDL	BDL	BDL	61	BDL			
05/19/85	294-85001	5	883.12	BDL	12	<1.1	7.8	0.9	<0.08	<1.3	<8.9	BDL	11700	BDL			
05/19/85	413-85003	1	20.88	<1.4	14.87	33.73	97.32	1588.33	0.07	BDL	1.86	0.16	2875	0.83			
05/19/85	514-85023	6	300.84	0.89	0.09	BDL	0.166	0.17	BDL	0.044	BDL	37.8	925	BDL			
05/19/85	548-85001	3	727.27	BDL	70.8	BDL	2.16	332	BDL	BDL	BDL	37.39	32100	BDL			
05/22/85	140-85005	1	8.05	BDL	8.20	BDL	10.4	48.0	BDL	BDL	BDL	.00931	7.0	BDL			
05/22/85	391-85006	1	36.32	BDL	14.87	33.73	97.32	1588.33	0.07	BDL	1.96	0.16	2875	0.83			
05/22/85	514-85023	6	310.68	0.89	1.85	BDL	BDL	8.68	BDL	BDL	BDL	BDL	3810	BDL			
05/23/85	114-85080	1	10.68	BDL	70.8	BDL	2.16	332	BDL	BDL	BDL	37.39	32100	BDL			
05/23/85	140-85005	1	12.05	BDL	454	.2	27.4	162	0.030	BDL	1.8	0.008	17500	BDL			
05/23/85	267-85001	1	7.54	3.0	2.30	BDL	4.00	BDL	BDL	BDL	BDL	BDL	384	BDL			
05/23/85	391-85007	1	83.61	BDL	<20	<3.6	7.2	31	<0.35	<4.4	<20	BDL	88800	BDL			
05/23/85	485-85002	1	7.59	<4.8	14.87	33.73	97.32	1588.33	0.07	BDL	1.96	0.16	2875	0.83			
05/23/85	514-85023	6	448.45	0.89	40	5.9	BDL	BDL	BDL	BDL	BDL	.018	1800	BDL			
05/24/85	114-85078	1	0.36	BDL	7.8	BDL	2.8	59	BDL	BDL	BDL	.025	140000	BDL			
05/24/85	114-85079	1	4.38	BDL	70.8	BDL	2.16	332	BDL	BDL	BDL	37.39	32100	BDL			
05/24/85	140-85005	1	17.36	BDL	44	1.3	11	19	0.63	BDL	BDL	BDL	14000	BDL			
05/24/85	243-85007	1	0.87	BDL	290	5	20	63	BDL	BDL	BDL	BDL	13000	BDL			
05/24/85	243-85008	1	1.11	BDL	228	3.8	21	62	BDL	BDL	BDL	BDL	4300	BDL			
05/24/85	243-85009	1	0.62	BDL	<20	<3.6	40	68	<0.35	<4.4	<28	BDL	3990	BDL			
05/24/85	293-85006	1	28.72	<4.8	1140	3.7	79	160	0.38	BDL	BDL	610	228000	BDL			
05/24/85	309-85001	1	43.73	99	14.87	33.73	97.32	1588.33	0.07	BDL	1.96	0.16	2875	0.83			
05/24/85	514-85023	6	681.05	0.89													

NOTE: VOA = PPB
VOH = PPM
RPH = PPM

* SEE ATTACHMENT "A"

775.900(2)

Soil Thermal Treatment Facility Untreated Soil Reporting Form

Month: may Year: 1995

Name of Facility: RINKER MATERIALS CORP.
Air Permit No.: A013-172154
Soil Treatment Permit No.: SW-01117-91
Stationary XXX or Mobile Facility:

DER Form #	17-775.900(2)
Form Title	Soil Thermal Treatment Facility Untreated Soil Reporting Form
Effective Date	
DER Application No	

1	2	3	4	5										6	7	8	9
Day of Mo.	Soil Batch ID #	Sample Number	Amount Volume or Weight cy/tn	Analytical Results										Totals			
				Metals													
				AS	BA	CD	CR	PB	HG	SE	AG	VOA	RPH	VOH	Indicate Other Analyses		
05/24/85	544-85001	1	52.34	1.6	1.8	<0.50	8.0	3.7	<0.30	<1.0	<1.0	BDL	481	BDL			
05/25/85	114-85078	1	2.93	BDL	133.0	BDL	3.7	64.8	BDL	BDL	BDL	BDL	883.3	BDL			
05/25/85	140-85005	1	6.05	BDL	70.8	BDL	2.16	392	BDL	BDL	BDL	37.39	32100	BDL			
05/25/85	203-85058	1	0.25	0.369	4.78	<0.0500	9.27	3.10	0.164	<0.0020	<0.0500	18.4	2700	BDL			
05/25/85	203-85059	1	0.25	0.679	8.39	<0.0500	21.4	8.31	<0.0010	<0.0020	<0.0500	88.4	188	BDL			
05/25/85	544-85001	1	24.65	1.8	1.8	<0.50	8.0	3.7	<0.30	<1.0	<1.0	BDL	481	BDL			
05/26/85	104-85011	1	2.47	7	221	14	89	177	BDL	BDL	8	74.140	BDL	BDL			
05/26/85	114-85078	1	2.81	BDL	133.0	BDL	3.7	64.8	BDL	BDL	BDL	BDL	883.3	BDL			
05/26/85	140-85005	1	3.00	BDL	70.8	BDL	2.16	392	BDL	BDL	BDL	37.39	32100	BDL			
05/26/85	268-85006	1	18.61	<4.8	<20	<3.8	40	68	<0.35	<4.4	<28	BDL	3990	BDL			
05/26/85	297-85011	1	5.00	0.104	4.41	0.303	0.4	0.308	BDL	<0.0020	<0.0500	4.20	345	BDL			
05/26/85	308-85001	1	23.88	99	1140	3.7	79	180	0.38	BDL	BDL	610	228000	BDL			
05/26/85	514-85023	8	94.19	0.99	14.87	33.73	97.32	1886.33	0.07	BDL	1.96	0.16	2875	0.93			
05/26/85	544-85001	1	15.38	1.8	1.8	<0.50	8.0	3.7	<0.30	<1.0	<1.0	BDL	481	BDL			
05/30/85	108-85034	3	232.84	BDL	74.5	BDL	6.38	11.3	BDL	BDL	1.19	.437	6200	BDL			
05/30/85	140-85005	1	8.08	BDL	70.8	BDL	2.16	392	BDL	BDL	BDL	37.39	32100	BDL			
05/30/85	203-85081	3	348.88	BDL	12.8	BDL	4.47	88.46	BDL	BDL	BDL	BDL	879	BDL			
05/30/85	357-85005	1	13.99	BDL	3.8	BDL	10	4.8	BDL	BDL	1.8	BDL	4300	BDL			
05/30/85	429-85003	1	9.45	BDL	BDL	BDL	6.7	14	BDL	BDL	BDL	BDL	20.400	BDL			
05/30/85	429-85005	1	18.64	BDL	BDL	BDL	7.4	19	BDL	BDL	BDL	BDL	43000	BDL			
05/30/85	435-85001	1	17.79	1	10	1	3	48	BDL	BDL	1	BDL	72	BDL			
05/30/85	542-85001	1	48.30	BDL	40.3	BDL	78.0	58.9	0.109	BDL	BDL	BDL	110	BDL			
05/30/85	547-85001	1	122.54	<10	1.5	0.61	1.6	<5.0	<0.030	<10	<1.0	745	2000	BDL			
05/31/85	302-85019	1	49.31	1.0	20	0.8	1.0	10	0.1	0.8	1.0	88	100	BDL			
05/31/85	369-85003	1	83.20	2.0	3.7	BDL	1.0	4.3	BDL	BDL	BDL	BDL	8800	BDL			
05/31/85	441-85002	1	18.20	<4.8	<20	<3.8	4.4	<5.6	<0.35	<4.4	<20	BDL	420	BDL			

775.900(2)

NOTE: VOA = PPB
VOH = PPM
RPH = PPM

* SEE ATTACHMENT "A"

Name of Facility:RINKER MATERIALS CORP
Air Permit No: A013-172154
Soil Treatment Permit No: SW-01117-91
Stationary XXX or Mobile Facility:

Month	May	Year	1995
-------	-----	------	------

[illegible]

Name of Facility:RINKER MATERIALS CORP
Air Permit No: A013-172154
Soil Treatment Permit No: SW-01117-91
Stationary XXX or Mobile Facility:

Metals Blending Report

[illegible]

Name of Facility:RINKER MATERIALS CORP
Air Permit No: A013-172154
Soil Treatment Permit No: SW-01117-91
Stationary XXX or Mobile Facility:

Month	May	Year	1995
-------	-----	------	------

[illegible]

RINKER MATERIALS SUBSTITUTION

MATERIALS ANALYSIS REPORT

REPORT DATE -6-12-95

SAMPLE DATE- 5-95

SAMPLE SOURCE - CHEVRON

REFERENCE # 140-95005

SAMPLE TYPE -SOIL

PARAMETER	RESULT	RESULT	RESULT	UNITS	METHOD	0 LIMITS
	CONTAMINAT	CLEAN	BLEND			
LEAD	400	BDL	BDL	mg/kg	239.1	10

BLEND= 1 CONTAMINATED WITH 4 CLEAN

BDL= Below detection limit

MATERIALS ANALYSIS REPORT

REPORT DATE: 5-9-95

SAMPLE DATE- 4-95

PLE SOURCE - RESOURCE RECOVERY

REFERENCE # 514-95023

SAMPLE TYPE - SOIL

PARAMETER	RESULT	RESULT	RESULT	UNITS	METHOD	D LIMITS
	CONTAMINAT	CLEAN	BLEND			
LEAD	20	BDL	BDL	mg/kg	239.1	10
CHROMIUM	BDL	BDL	BDL			10
BLEND= 1 CONTAMINATED WITH 1 CLEAN						
BDL= Below detection limit						

RINKER MATERIALS SUBSTITUTION

MATERIALS ANALYSIS REPORT

PORT DATE -4-19-95

SAMPLE DATE- 5-95

SAMPLE SOURCE -FLORIDA YACHT BASIN

REFERENCE # 180-95004

SAMPLE TYPE -SOIL

PARAMETER	RESULT	RESULT	RESULT	UNIT	METHOD	D LIMITS
	CONTAMINAT	CLEAN	BLEND			
LEAD	374	BDL	86	mg/kg	239.1	10

BLEND-1 CONTAMINATED WITH 4 CLEAN

BDL-Below detection limit

ALS ANALYSIS REPORT

REPORT DATE -5-10-95

AMPLE DATE- 5-5-95

AMPLE SOURCE - FLORIDA UNDERGROUND

REFERENCE # 278-95006

AMPLE TYPE - SOIL

PARAMETER	RESULT	RESULT	RESULT	UNITS	METHOD	D LIMITS
	CONTAMINAT	CLEAN	BLEND			
LEAD	170	BDL	52	mg/kg	239.1	10
CHROMIUM	37	BDL	BDL	mg/kg		10
BLEND = 1 CONTAMINATED WITH 1 CLEAN						
BDL = Below detection limit						

RINKER MATERIALS SUBSTITUTION

ANALYSIS REPORT

REPORT DATE - 6-8-95

SAMPLE DATE - 5-95

SAMPLE SOURCE - MOBIL

REFERENCE # 103-95013

SAMPLE TYPE - SOIL

PARAMETER	RESULT CONTAMINAT	RESULT CLEAN	RESULT BLEND	UNITS	METHOD	D LIMITS
LEAD	BDL	BDL	BDL	mg/kg	239.1	10

BLEND = 1 CONTAMINATED WITH 1 CLEAN

BDL = Below detection limit

RINKER MATERIALS SUBSTITUTION

MATERIALS ANALYSTS REPORT

REPORT DATE 3-8-95

SAMPLE DATE 5-95

SAMPLE SOURCE CORPORATE EXPRESS

REFERENCE 292-95003

SAMPLE TYPE SOIL

PARAMETER	RESULT	RESULT	RESULT	UNITS	METHOD	D. LIMIT
	CONTAMINAT	CLEAN	BLEND			
LEAD	BDL	BDL	BDL	mg/kg	239.1	10
CHROMIUM	BDL	BDL	BDL	mg/kg	218.2	10

BLEND= 1 CONTAMINATED WITH 1 CLEAN

BDL= Below detection limit

SINKER MATERIALS SUBSTITUTION

MATERIALS ANALYSIS REPORT

PORT DATE - 6-8-95

SAMPLE DATE - 5-24-95

SAMPLE SOURCE - R.S. Env.

REFERENCE # 387-95003

SAMPLE TYPE - SOIL

PARAMETER	RESULT CONTAMINAT	RESULT CLEAN	RESULT BLEND	UNITS	METHOD	D LIMITS
LEAD	561	BDL	BDL	mg/kg	239.1	10

BLEND= 1 CONTAMINATED WITH 6 CLEAN

BDL= Below detection limit

SINKER MATERIALS SUBSTITUTION

MATERIALS ANALYSIS REPORT

REPORT DATE - 6-8-95

SAMPLE DATE - 5-24-95

SAMPLE SOURCE - STAR ENTERPRISE

REFERENCE # 103-95014

SAMPLE TYPE - SOIL

PARAMETER	RESULT CONTAMINAT	RESULT CLEAN	RESULT BLEND	UNITS	METHOD	D LIMITS
LEAD	561	BDL	BDL	mg/kg	239.1	10

BLEND= 1 CONTAMINATED WITH 5 CLEAN

BDL= Below detection limit

RINKER MATERIALS SUBSTITUTION

MATERIALS ANALYSIS REPORT

REPORT DATE - 6-8-95

SAMPLE DATE - 5-19-95

SAMPLE SOURCE - OCEAN MAZDA

REFERENCE - 104-95010

SAMPLE TYPE - SOIL

PARAMETER	RESULT	RESULT	RESULT	UNITS	METHOD	DLIMITS
	CONTAMINAT	CLEAN	BLEND			
LEAD	BDL	BDL	BDL	mg/kg	239.1	10

BLEND = 1 CONTAMINATED WITH 1 CLEAN

BDL = Below detection limit

LINKER MATERIALS SUBSTITUTION

1 MATERIALS ANALYSIS REPORT

REPORT DATE - 6-8-95

SAMPLE DATE - 5-23-95

SAMPLE SOURCE - ROSE ENG

REFERENCE # 267-95001

SAMPLE TYPE - SOIL

PARAMETER	RESULT	RESULT	RESULT	UNITS	METHOD	D LIMITS
	CONTAMINAT	CLEAN	BLEND			
LEAD	BDL	BDL	BDL	mg/kg	239.1	10

BLEND= 1 CONTAMINATED WITH 1 CLEAN

BDL= Below detection limit

RINKER MATERIALS SUBSTITUTION

ANALYSIS REPORT

REPORT DATE - 6-8-95

SAMPLE DATE - 5-24-95

SAMPLE SOURCE - FPL BOCA GRAND

REFERENCE # 309-95001

SAMPLE TYPE - SOIL

PARAMETER	RESULT CONTAMINAT	RESULT CLEAN	RESULT BLEND	UNITS	METHOD	D LIMITS
LEAD	BDL	BDL	BDL	mg/kg	239.1	10
CHROMIUM	BDL	BDL	BDL	mg/kg	218.2	10
ARSENIC	BDL	BDL	BDL	mg/kg	206.3	5

BLEND = 1 CONTAMINATED WITH 1 CLEAN

BDL = Below detection limit

RINKER MATERIALS SUBSTITUTION

TRIALS ANALYSIS REPORT

REPORT DATE - 6-8-95

SAMPLE DATE - 5-8-95

SAMPLE SOURCE - RECHTEIN

REFERENCE # 104-95011

SAMPLE TYPE SOIL

PARAMETER	RESULT	RESULT	RESULT	UNITS	METHOD	D LIMITS
	CONTAMINAT	CLEAN	BLEND			
LEAD	BDL	BDL	BDL	mg/kg	239.1	10
CHROMIUM	BDL	BDL	BDL	mg/kg	218.2	10

BLEND = 1 CONTAMINATED WITH 1 CLEAN

BDL = Below detection limit

LINKER MATERIALS SUBSTITUTION

MATERIALS ANALYSIS REPORT

REPORT DATE: 6-8-95

SAMPLE DATE: 5-30-95

SAMPLE SOURCE: FIREDORR

REFERENCE: 542-95001

SAMPLE TYPE: SOIL

PARAMETER	RESULT	RESULT	RESULT	UNITS	METHOD	D LIMITS
	CONTAMINAT	CLEAN	BLEND			
CHROMIUM	BDL	BDL	BDL	mg/kg	218.2	10

BLEND=1 CONTAMINATED WITH 1 CLEAN

BDL= Below detection limit

* Name of Facility: RINKER MATERIALS CORP
Air Permit No: A013-172154
Soil Treatment Permit No: SW-01117-91
Stationary XXX or Mobile Facility:

[illegible]

**Facility Rinker Materials Corporation
Air Permit No.: A013-172154
Soil Treatment Permit No.: SW-0117-91
Stationary XXX**

Month May Year 1995

Date	Batch No.	Source	Soil Content PCB's	Tons PCB Oil Concentration	Lb. PCB per Batch	YTD Lbs. PCB
Continuation from April 1995						
					1995	1.5441lbs

NO ACTIVITY IN MAY

Soil Thermal Treatment Facility Untreated Soil Reporting Form

Month: JUNE

Year: 1995

Name of Facility: **RINKER MATERIALS CORP.**
 Air Permit No.: **A013-172164**
 Soil Treatment Permit No.: **SW-01117-91**
 Stationary **XXX** or Mobile Facility:

DER Form # **17-775.900(2)**
Soil Thermal Treatment Facility
 Form Title **Untreated Soil Reporting Form**
 Effective Date
 DER Application No

1	2	3	4	5					6	7	8	9			
Day of Mo.	Soil Batch ID#	Sample Number	Amount Volume or Weight cy/in	Analytical Results											
				Metals								Totals		Indicate Other Analyses	
				AS	BA	CD	CR	PB	HG	SE	AG	VOA	RPH	VOH	Attach Lab Results Only
06/02/95	140-95006	1	6.60	.123	4.13	.165	4.85	3.56	.0208	.0452	<.0500	6.53	15.4	BDL	
06/02/95	140-95007	1	0.50	.240	2.16	.0805	1.79	<.76	<.0010	.0666	<.0500	BDL	44.5	BDL	
06/02/95	190-95004	1	0.75	1.17	10.2	0.539	4.81	7.18	.00240	0.0374	<.0500	13.9	97.6	BDL	
06/02/95	203-95006	3	29.54	BDL	12.8	BDL	4.47	96.46	BDL	BDL	BDL	BDL	579	BDL	
06/02/95	363-95005	1	0.50	1.49	3.07	BDL	BDL	3.55	BDL	BDL	BDL	BDL	48	BDL	
06/02/95	363-95006	1	3.50	6.3	4.43	BDL	7.04	13.36	BDL	BDL	0.002	BDL	892	BDL	
06/02/95	426-95001	1	57.39	1.1	2.47	1.0	14.0	81.0	BDL	BDL	BDL	BDL	26000	BDL	
06/02/95	441-95001	1	18.32	<4.8	<20	<3.6	4.9	13	<0.35	<4.4	<20	.110	14800	BDL	
06/05/95	114-95082	1	1.70	1.58	40	1.6	9.44	8.0	0.50	0.80	3.2	36	98	BDL	
06/05/95	114-95086	1	0.88	BDL	3.8	BDL	BDL	BDL	BDL	BDL	BDL	103	210000	BDL	
06/05/95	114-95094	1	15.00	BDL	210	BDL	39	39	0.23	BDL	1.6	BDL	7000	BDL	
06/05/95	297-95012	1	4.75	0.137	16.3	0.0548	3.32	0.247	BDL	00167	<.0500	5.84	29.2	BDL	
06/05/95	551-95001	1	38.46	BDL	0.188	0.015	BDL	BDL	BDL	BDL	BDL	BDL	66.6	BDL	
06/06/95	114-95087	1	1.00	BDL	20	19	4	10	0.67	BDL	BDL	.887	1800	BDL	
06/06/95	114-95094	1	12.00	BDL	210	BDL	39	39	0.23	BDL	1.6	BDL	7000	BDL	
06/06/95	140-95006	1	3.05	.123	4.13	.165	4.95	3.56	.0208	.0452	<.0500	6.53	15.4	BDL	
06/06/95	309-95002	1	1.98	99	1140	3.7	79	150	0.38	BDL	BDL	610	228000	BDL	
06/06/95	514-95020	6	26.30	0.99	14.87	33.73	97.32	1586.33	0.07	BDL	1.96	0.16	2875	.093	
06/07/95	114-95083	1	0.08	1.91	156	22.6	49.1	327	0.567	BDL	BDL	BDL	732	BDL	
06/07/95	114-95084	1	2.66	BDL	BDL	BDL	BDL	BDL	0.31	BDL	BDL	4	140000	BDL	
06/07/95	114-95094	1	15.00	BDL	210	BDL	39	39	0.23	BDL	1.6	BDL	7000	BDL	
06/07/95	140-95006	1	2.90	.123	4.13	.165	4.95	3.56	.0208	.0452	<.0500	6.53	15.4	BDL	
06/08/95	104-95015	1	6.56	7.4	55	9	50	108	.23	BDL	1	10.550	29043	BDL	
06/08/95	114-95094	1	2.50	BDL	210	BDL	39	39	0.23	BDL	1.6	BDL	7000	BDL	
06/08/95	140-95006	1	6.10	.123	4.13	.165	4.95	3.56	.0208	.0452	<.0500	6.53	15.4	BDL	
06/08/95	278-95007	1	42.71	BDL	BDL	2.1	1.9	1.6	BDL	BDL	BDL	BDL	40	BDL	
06/08/95	475-95005	1	4.80	0.542	5.16	0.119	5.93	6.05	<.00100	<.0020	<.0500	BDL	8920	.00637	

* SEE ATTACHMENT "A"

775.900(2)

NOTE: VOA= PPM
 VOH = PPM
 RPH= PPM

228000

Soil Thermal Treatment Facility Untreated Soil Reporting Form

Name of Facility: RINKER MATERIALS CORP.
Air Permit No.: A013-472164
Soil Treatment Permit No.: SW-01117-91
Stationary XXX or Mobile Facility:

DER Form # 17-776.900(2)
Soil Thermal Treatment Facility
Form Title Untreated Soil Reporting Form
Effective Date
DER Application No

1	2	3	4	5					6	7	8	9			
Day of Mo.	Soil Batch ID#	Sample Number	Amount Volume or Weight	Analytical Results											
				Metals											
				Metals								Totals			
				AS	BA	CD	CR	PB	HG	SE	AG	VOA	RPH	VOH	Indicate Other Analyses
														Attach Lab Results Only	
06/08/95	514-95020	6	396.60	0.99	14.87	33.73	97.32	1586.33	0.07	BDL	1.96	0.16	2875	.093	
06/09/95	103-95015	1	0.50	BDL	2	BDL	3	BDL	BDL	BDL	BDL	9600	970	BDL	
06/09/95	114-95089	1	1.00	BDL	114	7.6	53	72	BDL	BDL	BDL	BDL	10000	BDL	
06/09/95	114-95094	1	3.00	BDL	210	BDL	39	39	0.23	BDL	1.6	BDL	7000	BDL	
06/09/95	203-95065	1	2.25	0.485	4.05	0.61	3.1	8.83	0.054	0.031	0.031	8458.8	110	BDL	
06/09/95	223-95002	1	0.25	<1.0	1.8	<0.50	3.1	22	0.061	<1.0	<1.0	BDL	29000	BDL	
06/10/95	114-95094	1	6.00	BDL	210	BDL	39	39	0.23	BDL	1.6	BDL	7000	BDL	
06/12/95	106-95027	1	2.75	BDL	150	BDL	6.3	BDL	BDL	BDL	BDL	BDL	219	BDL	
06/12/95	106-95032	1	0.28	BDL	1.7	BDL	4.0	21	BDL	BDL	BDL	BDL	810	BDL	
06/12/95	114-95094	1	3.00	BDL	210	BDL	39	39	0.23	BDL	1.6	BDL	7000	BDL	
06/12/95	140-95006	1	5.70	.123	4.13	.165	4.95	3.56	.0208	.0452	<.0500	6.53	15.4	BDL	
06/12/95	452-95002	1	8.61	BDL	7.0	BDL	4.4	7.0	BDL	BDL	BDL	BDL	1100	BDL	
06/13/95	114-95094	1	6.00	BDL	210	BDL	39	39	0.23	BDL	1.6	BDL	7000	BDL	
06/13/95	140-95006	1	6.10	.123	4.13	.165	4.95	3.56	.0208	.0452	<.0500	6.53	15.4	BDL	
06/13/95	203-95062	1	1.00	0.650	4.69	0.738	5.17	0.635	<.0020	<.0500	<.0500	579	2030	BDL	
06/13/95	237-95002	1	6.28	BDL	BDL	BDL	BDL	BDL	BDL	BDL	BDL	.197	15197	BDL	
06/13/95	311-95002	1	0.50	0.22	56.10	0.13	6.87	1.89	<0.01	0.03	0.03	BDL	170	BDL	
06/13/95	438-95002	1	1.50	3.3	60	2.4	169	0.56	<0.1	<0.1	0.66	.001	82000	BDL	
06/13/95	468-95005	1	0.50	BDL	BDL	BDL	15.3	BDL	BDL	BDL	BDL	BDL	BDL	BDL	
06/13/95	468-95006	1	0.25	<1.0	4.6	<0.50	3.1	<5.0	<0.030	<1.0	<1.0	1.149	210	BDL	
06/13/95	549-95001	1	11.38	BDL	2.2	BDL	1.6	4.1	BDL	BDL	BDL	BDL	4100	BDL	
06/14/95	111-95003	3	265.75	BDL	28.33	BDL	44.67	41.33	0.08	BDL	1.03	BDL	176	BDL	
06/14/95	114-95094	1	5.50	BDL	210	BDL	39	39	0.23	BDL	1.6	BDL	7000	BDL	
06/14/95	140-95006	1	6.10	.123	4.13	.165	4.95	3.56	.0208	.0452	<.0500	6.53	15.4	BDL	
06/14/95	206-95002	3	193.45	0.5	11	3	2	53	BDL	BDL	9	BDL	BDL	BDL	
06/14/95	514-95015	5	107.62	BDL	325	2.50	9.70	29.7	BDL	BDL	1.92	BDL	77.54	BDL	
06/14/95	514-95025	3	49.54	0.041	.009	.005	0.210	0.398	<0.002	0.019	<0.001	28.8	68.1	BDL	

775.900(2)

* SEE ATTACHMENT "A"

NOTE: VOA = PPB
VOH = PPM
RPH = PPM

Soil Thermal Treatment Facility Untreated Soil Reporting Form

Month: JUNE Year: 1986

Name of Facility: RINKER MATERIALS CORP.
Air Permit No.: A013-172164
Soil Treatment Permit No.: SW-01117-91
Stationary XXX or Mobile Facility: _____

DER Form # 17-776.900(2)
Soil Thermal Treatment Facility
Form Title Untreated Soil Reporting Form
Effective Date _____
DER Application No _____

1	2	3	4	5											6	7	8	9
Day of Mo.	Soil Batch ID#	Sample Number	Amount Volume or Weight cy/tn	Analytical Results														
				Metals											Totals			
AS	BA	CD	CR	PB	HG	SE	AG	VOA	RPH	VOH	Indicate Other Analyses Attach Lab Results Only							
06/14/85	522-95004	1	12.00	<.05	<1.0	.11	.71	4.38	<.05	<.01	.15	4.00	10800	.440				
06/14/85	549-95001	1	11.47	BDL	2.2	BDL	1.6	4.1	BDL	BDL	BDL	BDL	4100	BDL				
06/15/85	114-95094	1	5.50	BDL	210	BDL	39	39	0.23	BDL	1.6	BDL	7000	BDL				
06/15/85	302-95020	1	33.13	1.1	6.0	BDL	15	9.9	BDL	BDL	BDL	.295	322	BDL				
06/15/85	435-95002	3	83.51	1.00	18.67	1.33	4.67	38.67	BDL	BDL	3.00	BDL	65.67	BDL				
06/15/85	549-95001	1	29.05	BDL	2.2	BDL	1.6	4.1	BDL	BDL	BDL	BDL	4100	BDL				
06/16/85	114-95094	1	8.00	BDL	210	BDL	39	39	0.23	BDL	1.6	BDL	7000	BDL				
06/16/85	140-95006	1	6.10	.123	4.13	.165	4.85	3.56	.0208	.0452	<.0500	6.53	15.4	BDL				
06/16/85	254-95001	1	13.46	BDL	115	8.00	30.	939	BDL	BDL	BDL	BDL	2063	BDL				
06/16/85	514-95025	3	281.04	0.041	.009	.005	0.210	0.388	<.0002	0.019	<.0001	28.8	68.1	BDL				
06/16/85	549-95002	1	54.76	BDL	3.3	1.4	3.8	46	BDL	BDL	BDL	BDL	363	BDL				
06/16/85	114-95094	1	6.00	BDL	210	BDL	39	39	0.23	BDL	1.6	BDL	7000	BDL				
06/18/85	140-95006	1	2.50	.123	4.13	.165	4.85	3.56	.0208	.0452	<.0500	6.53	15.4	BDL				
06/18/85	203-95063	5	786.46	BDL	635	BDL	4.47	2.29	BDL	BDL	BDL	BDL	20.97	BDL				
06/18/85	419-95003	1	33.73	1.8	27	1.7	10	520	BDL	BDL	BDL	BDL	2450	BDL				
06/18/85	549-95002	1	17.88	BDL	3.3	1.4	3.8	46	BDL	BDL	BDL	BDL	363	BDL				
06/20/85	114-95094	1	6.00	BDL	210	BDL	39	39	0.23	BDL	1.6	BDL	7000	BDL				
06/20/85	140-95006	1	6.10	.123	4.13	.165	4.85	3.56	.0208	.0452	<.0500	6.53	15.4	BDL				
06/20/85	203-95063	5	264.97	BDL	635	BDL	4.47	2.29	BDL	BDL	BDL	BDL	20.97	BDL				
06/20/85	203-95064	5	111.97	0.82	36.33	0.29	5.55	234.33	<.0020	0.09	0.29	525.41	568.40	BDL				
06/20/85	295-95001	1	41.71	0.28	19.8	<1.42	5.66	19.8	0.13	<0.14	2.83	0.62	132	BDL				
06/20/85	475-95006	3	52.43	3.26	14.37	0.26	5.24	13.18	0.01	<.0020	0.42	<14.90	9126.67	BDL				
06/21/85	104-95012	1	2.45	2	31	4	25	165	BDL	BDL	2	BDL	200	BDL				
06/21/85	104-95013	1	5.05	5.5	44	4	130	514	BDL	BDL	4	13490	1418	BDL				
06/21/85	114-95094	1	9.00	BDL	210	BDL	39	39	0.23	BDL	1.6	BDL	7000	BDL				
06/21/85	140-95006	1	2.50	.123	4.13	.165	4.85	3.56	.0208	.0452	<.0500	6.53	15.4	BDL				
06/21/85	243-95010	1	1.14	BDL	127	6.8	41	97	0.16	BDL	1.5	0.36	74000	BDL				

776.900(2)

* SEE ATTACHMENT "A"

NOTE: VOA = PPB

VOH = PPM

RPH = PPM

Florida Department of Environmental Regulation

Twin Towers Office Bldg. 2800 Blair Stone Road Tallahassee, Florida 32399-2400

Soil Thermal Treatment Facility Untreated Soil Reporting Form

Month: JUNE

Year: 1988

Name of Facility: **RINKER MATERIALS CORP.**
Air Permit No.: **A013-172154**
Soil Treatment Permit No.: **SW-01117-91**
Stationary **XXX** or Mobile Facility: _____

DER Form #	17-776.900(2)
Form Title	Soil Thermal Treatment Facility
Effective Date	Untreated Soil Reporting Form
DER Application No	

1	2	3	4	5										6	7	8	9
Day of Mo.	Soil Batch ID#	Sample Number	Amount Volume or Weight cy/tn	Analytical Results													
				Metals										Totals			
				AS	BA	CD	CR	PB	HG	SE	AG	VOA	RPH	VOH	Indicate Other Analyses		
06/28/85	140-95006	1	6.10	.123	4.13	.165	4.95	3.56	.0208	.0452	<.0500	6.53	15.4	BDL			
06/28/85	297-95013	1	0.50	0.357	62.1	5.92	20.8	33.6	BDL	.851	.00170	11000	49400	BDL			
06/28/85	346-95002	1	1.25	4.40	49.0	1.83	22.0	58.0	BDL	BDL	BDL	BDL	701	BDL			
06/28/85	419-95004	1	6.00	1.8	27	1.7	10	520	BDL	BDL	BDL	BDL	2450	BDL			
06/28/85	489-95004	6	34.90	<10	4.45	<0.50	4.38	<5.0	<0.30	<1.0	<1.0	28700	477	BDL			
06/28/85	550-95001	8	10.18	3.70	251.88	22.14	105.33	1216.15	3.60	0.16	1.21	2630.53	7124.97	.04110			
06/28/85	111-95004	5	491.14	BDL	10	BDL	4	2	BDL	BDL	1.0	BDL	168	BDL			
06/28/85	114-95080	1	0.26	2.2	30	BDL	11	48	0.11	BDL	BDL	0.94	240	BDL			
06/28/85	114-95081	1	0.26	BDL	64	BDL	53	191	BDL	BDL	4.3	0.08	5300	0.07			
06/28/85	114-95092	1	0.26	1.8	45	5.8	15	4	0.14	BDL	BDL	0.28	4300	BDL			
06/28/85	114-95094	1	14.03	BDL	210	BDL	39	39	0.23	BDL	1.8	BDL	7000	BDL			
06/28/85	114-95095	1	16.01	BDL	1.85	BDL	BDL	5.66	BDL	BDL	BDL	BDL	3810	BDL			
06/28/85	273-95002	1	139.92	BDL	56.6	BDL	BDL	81.0	BDL	BDL	BDL	.318	998	BDL			
06/28/85	485-95005	1	15.78	<4.8	<20	<3.6	4.4	28	<0.07	<4.4	<20	BDL	32900	BDL			
06/28/85	554-95001	1	130.74	BDL	4.5	BDL	7.4	BDL	BDL	BDL	BDL	BDL	1074	BDL			
06/28/85	555-95001	1	11.75	BDL	3.60	BDL	4.50	1.95	BDL	BDL	BDL	BDL	BDL	BDL			
06/30/85	106-95041	1	61.14	BDL	BDL	BDL	5.4	4.1	BDL	1.30	BDL	3.550	12825	BDL			
06/30/85	114-95094	1	9.00	BDL	210	BDL	39	39	0.23	BDL	1.6	BDL	7000	BDL			
06/30/85	140-95006	1	6.10	.123	4.13	.165	4.95	3.56	.0208	.0452	<.0500	6.53	15.4	BDL			
06/30/85	273-95002	1	64.62	BDL	56.6	BDL	BDL	81.0	BDL	BDL	BDL	.318	998	BDL			
06/30/85	283-95007	1	8.91	<4.8	<20	<3.6	4.3	620	<0.5	<4.4	<2.9	BDL	62.4	BDL			
06/30/85	549-95001	1	3.00	BDL	2.2	BDL	1.6	4.1	BDL	BDL	BDL	BDL	4100	BDL			
06/30/85	554-95002	1	70.52	BDL	4.5	BDL	2.4	BDL	BDL	BDL	BDL	BDL	1074	BDL			

* SEE ATTACHMENT "A"

NOTE: VOA = PPB
VOH = PPM
RPH = PPM

775.900(2)

Soil Thermal Treatment Facility Untreated Soil Reporting Form

Name of Facility: RINKER MATERIALS CORP.
Air Permit No.: A013-172164
Soil Treatment Permit No.: SW-01117-91
Stationary XXX or Mobile Facility:

DER Form # 17-776.900(2)
Form Title Soil Thermal Treatment Facility
Effective Date Untreated Soil Reporting Form
DER Application No

1	2	3	4	5										6	7	8	9
Day of Mo.	Soil Batch ID#	Sample Number	Amount Volume or Weight	Analytical Results										Totals			
				Metals													
				AS	BA	CD	CR	PB	HG	SE	AG	VOA	RPH	VOH	Indicate Other Analyses		
				cy/ft	cy/ft	cy/ft	cy/ft	cy/ft	cy/ft	cy/ft	cy/ft	cy/ft	cy/ft	cy/ft	Attach Lab Results Only		
06/21/95	302-95023	5	94.56	<1.0	<2.0	<2.0	8.3	<15	<0.25	<50	<2.0	52.10	5100	BDL			
06/21/95	309-95003	1	1.18	89	1140	3.7	79	150	0.38	BDL	BDL	610	228000	BDL			
06/21/95	475-95006	3	76.62	3.26	14.37	0.26	5.24	13.18	0.01	<0.020	0.42	<14.90	9128.67	BDL			
06/21/95	489-95003	3	76.64	BDL	<0.001	<0.001	BDL	BDL	<0.001	BDL	<0.001	154.00	48.2	0314			
06/21/95	552-95001	1	32.28	BDL	104	BDL	5.91	16.5	BDL	BDL	1.22	2.71	149	BDL			
06/22/95	114-95004	1	9.00	BDL	210	BDL	39	39	0.23	BDL	1.6	BDL	7000	BDL			
06/22/95	140-95006	1	6.10	.123	4.13	.165	4.95	3.56	.0208	.0452	<.0500	6.53	15.4	BDL			
06/22/95	489-95003	3	99.44	BDL	<0.001	<0.001	BDL	BDL	<0.001	BDL	<.001	154.00	48.2	0314			
06/22/95	514-95025	3	52.48	0.041	.009	.005	0.210	0.398	<0.002	0.019	<.001	28.8	68.1	BDL			
06/23/95	114-95004	1	9.00	BDL	210	BDL	39	39	0.23	BDL	1.6	BDL	7000	BDL			
06/23/95	140-95006	1	5.55	.123	4.13	.165	4.95	3.56	.0208	.0452	<.0500	6.53	15.4	BDL			
06/23/95	524-95002	1	5.33	8.06	45	1.53	11	76	0.5	1.00	16	85	2165	BDL			
06/24/95	114-95004	1	15.00	BDL	210	BDL	39	39	0.23	BDL	1.6	BDL	7000	BDL			
06/24/95	140-95006	1	9.15	.123	4.13	.165	4.95	3.56	.0208	.0452	<.0500	6.53	15.4	BDL			
06/24/95	550-95001	8	11.32	3.70	251.88	22.14	105.33	1216.15	3.60	0.16	1.21	2630.53	7124.97	04110			
06/24/95	550-95002	8	243.55	0.14	4.42	<1.38	4.85	40.94	.001	0.15	0.76	16.86	2.10	BDL			
06/26/95	104-95014	1	0.67	BDL	BDL	9	BDL	24	BDL	BDL	2	88765	15840	BDL			
06/26/95	106-95039	1	7.43	BDL	15	BDL	BDL	BDL	BDL	BDL	BDL	1.04	79	BDL			
06/26/95	114-95004	1	2.50	BDL	210	BDL	39	39	0.23	BDL	1.6	BDL	7000	BDL			
06/26/95	140-95006	1	3.05	.123	4.13	.165	4.95	3.56	.0208	.0452	<.0500	6.53	15.4	BDL			
06/26/95	419-95003	1	6.00	1.8	27	1.7	10	520	BDL	BDL	BDL	BDL	2450	BDL			
06/26/95	489-95004	6	210.63	<10	4.45	<0.50	4.36	<5.0	<0.30	<1.0	<.001	29700	477	BDL			
06/27/95	114-95004	1	9.00	BDL	210	BDL	39	39	0.23	BDL	1.6	BDL	7000	BDL			
06/27/95	184-95001	1	167.68	BDL	2.51	BDL	3.99	9.90	BDL	BDL	BDL	BDL	78.9	BDL			
06/27/95	489-95004	6	385.67	<10	4.45	<0.50	4.36	<5.0	<0.30	<1.0	<.001	29700	477	BDL			
06/28/95	106-95040	1	0.75	5.00	20	1.31	5.0	13	0.5	2.54	1.6	610600	175226	BDL			
06/28/95	114-95004	1	9.00	BDL	210	BDL	39	39	0.23	BDL	1.6	BDL	7000	BDL			

6/10/00

776.900(2)

* SEE ATTACHMENT "A"

NOTE: VOA = PPB
VOH = PPM
RPH = PPM

Name of Facility: RINKER MATERIALS CORP
Air Permit No: A013-172154
Soil Treatment Permit No: SW-01117-91
Stationary XXX or Mobile Facility:

Month	June	Year	1995
-------	------	------	------

[illegible]

Name of Facility: RINKER MATERIALS CORP
Air Permit No: A013-172154
Soil Treatment Permit No: SW-01117-91
Stationary XXX or Mobile Facility:

Month	June	Year	1995
-------	------	------	------

[illegible]

Name of Facility:RINKER MATERIALS CORP
Air Permit No: A013-172154
Soil Treatment Permit No: SW-01117-91
Stationary XXX or Mobile Facility:

Month	June	Year	1995
-------	------	------	------

[illegible]

Name of Facility:RINKER MATERIALS CORP
Air Permit No: A013-172154
Soil Treatment Permit No: SW-01117-91
Stationary XXX or Mobile Facility:

Metals Blending Report

[illegible]

RINKER MATERIALS SUBSTITUTION

MATERIALS ANALYSIS REPORT

REPORT DATE -6-28-95

SAMPLE DATE- 6-95

SAMPLE SOURCE - FPL BOCA GRANDE

REFERENCE # 309 - 95002

SAMPLE TYPE -SOIL

PARAMETER	RESULT CONTAMINAT	RESULT CLEAN	RESULT BLEND	UNITS	METHOD	D LIMITS
LEAD	144	BDL	BDL	mg/kg	239.1	10
CHROMIUM	52	BDL	BDL	mg/kg	218.2	10
ARSENIC	BDL	BDL	BDL	mg/kg	206.3	10

BLEND= 1 CONTAMINATED WITH 10 CLEAN

BDL= Below detection limit

RINKER MATERIALS SUBSTITUTION						
MATERIALS ANALYSIS REPORT						
REPORT DATE - 6-28-95						
S. LE DATE - 6-95						
SAMPLE SOURCE - PLANTATION FORD						
REFERENCE # 114-95083 114-95083						
SAMPLE TYPE - SOIL						
PARAMETER	RESULT	RESULT	RESULT	UNITS	METHOD	D LIMITS
	CONTAMINAT	CLEAN	BLEND			
LEAD	268	BDL	36	mg/kg	239.1	10
BLEND = 1 CONTAMINATED WITH 3CLEAN						
BDL = Below detection limit						

HYDROCARBON SUBSTITUTION						
MATERIALS ANALYSIS REPORT						
REPORT DATE - 6-8-95						
SAMPLE DATE - 6-95						
SAMPLE SOURCE - RESOURCE RECOVERY						
REFERENCE # - 514-95020						
SAMPLE TYPE - SOIL						
PARAMETER	RESULT	RESULT	RESULT	UNITS	METHOD	D LIMITS
	CONTAMINAT	CLEAN	BLEND			
LEAD	20	BDL	BDL	mg/kg	239.1	10
CHROMIUM	BDL	BDL	BDL			10
BLEND= 1 CONTAMINATED WITH 1 CLEAN						
BDL= Below detection limit						

RINKER MATERIALS SUBSTITUTION						
MATERIALS ANALYSIS REPORT						
REPORT DATE -6-28-95						
SAMPLE DATE - 4-9-95						
SAMPLE SOURCE - AMOCO, JUPITER						
REFERENCE # 114-95089						
SAMPLE TYPE -SOIL						
PARAMETER	RESULT	RESULT	RESULT	UNITS	METHOD	D LIMITS
	CONTAMINAT	CLEAN	BLEND			
CHROMIUM	65	BDL	BDL	mg/kg	218.2	10
BLEND= 1 CONTAMINATED WITH 1 CLEAN						
BDL= Below detection limit.						

RINKER MATERIALS SUBSTITUTION						
MATERIALS ANALYSIS REPORT						
REPORT DATE -6-28-95						
SAMPLE DATE- 6-13-95						
SAMPLE SOURCE - CITY OF FT. LAUDERDALE						
REFERENCE # 438-95 002						
SAMPLE TYPE -SOIL						
PARAMETER	RESULT	RESULT	RESULT	UNITS	METHOD	D LIMITS
CONTAMINAT	CLEAN	CLEAN	BLENB			
CHROMIUM	214	BDL	BDL	mg/kg	218.2	10
BLEND=1 CONTAMINATED WITH 4 CLEAN						
BDL= Below detection limit						

RINKER MATERIALS SUBSTITUTION

MATERIALS ANALYSIS REPORT

REPORT DATE -6-28-95

SAMPLE DATE -6-16-95

SAMPLE SOURCE - LA DELIVERANCE AUTO

REFERENCE # 254-95001

SAMPLE TYPE -SOIL

PARAMETER	RESULT	RESULT	RESULT	UNITS	METHOD	D LIMITS
	CONTAMINAT	CLEAN	BLEND			

LEAD	249	BDL	BDL	mg/kg	239.1	10
------	-----	-----	-----	-------	-------	----

BLEND= 1 CONTAMINATED WITH 10 CLEAN

BDL= Below detection limit

SAMPLE TYPE -SOIL

PARAMETER	RESULT	RESULT	RESULT	UNITS	METHOD	D LIMITS
	CONTAMINAT	CLEAN	BLEND			
LEAD	54	BDL	BDL	mg/kg	239.1	10
BLEND= 1 CONTAMINATED WITH 3 CLEAN				-	-	
BDL= Below detection limit						

RINKER MATERIALS SUBSTITUTION					
INITIAL HIGH TAIL REPORT					
REPORT DATE -6-28-95					
SAMPLE DATE- 6-19-95					
SAMPLE SOURCE -FLAMINGO					
REFERENCE # 104-95013					
SAMPLE TYPE -SOIL					
PARAMETER	RESULT	RESULT	RESULT	UNITS	METHOD
	CONTAMINAT	CLEAN	BLEND		
LEAD	1707	BDL	37	mg/kg	239.1
CHROMIUM	BDL	BDL	BDL	mg/kg	218.2
BLEND= 1 CONTAMINATED WITH 5CLEAN					
BDL= Below detection limit					

RINKER MATERIALS SUBSTITUTION

MATERIALS ANALYSIS REPORT

REPORT DATE -6-28-95

SAMPLE DATE- 6-95

SAMPLE SOURCE - FPL BOCA GRANDE

REFERENCE # 309- 95003

SAMPLE TYPE -SOIL

PARAMETER	RESULT	RESULT	RESULT	UNITS	METHOD	D. LIMITS
	CONTAMINAT	CLEAN	BLEND			
LEAD	144	BDL	BDL	mg/kg	239.1	10
CHROMIUM	52	BDL	BDL	mg/kg	218.2	10
ARSENIC	BDL	BDL	BDL	mg/kg	206.3	10

BLEND=1 CONTAMINATED WITH 10 CLEAN

BDL = Below detection limit.

ANALYSTS REPORT

LE DATE- 6-19-95

REFERENCE # 114-95083 550-95001

SAMPLE TYPE -SOIL

PARAMETER	RESULT	RESULT	RESULT	UNITS	METHOD	D LIMITS
	CONTAMINAT	CLEAN	BLEND			
LEAD	579	BDL	30	mg/kg	239.1	10
CHROMIUM	BDL	BDL	BDL	mg/kg	218.2	10
BLEND= 1 CONTAMINATED WITH 12CLEAN						
BDL= Below detection limit						

RINKER MATERIALS SUBSTITUTION

MATERIALS ANALYSIS REPORT

REPORT DATE -6-28-95

PLE DATE- 6-19-95

SAMPLE SOURCE -NAPA AUTO

REFERENCE # 419-95004

SAMPLE TYPE -SOIL

PARAMETER	RESULT	RESULT	RESULT	UNITS	METHOD	D LIMITS
	CONTAMINAT	CLEAN	BLEND			
LEAD	446	BDL	30	mg/kg	239.1	10

BLEND= 1 CONTAMINATED WITH 5CLEAN

BDL=Below detection limit

MATERIALS ANALYSIS REPORT

SAMPLE DATE- 6-29-95

SA [redacted] SOURCE - VOC

REFERENCE # 114-95091

SAMPLE TYPE -SOIL

PARAMETER	RESULT	RESULT	RESULT	UNITS	METHOD	D LIMITS
	CONTAMINAT	CLEAN	BLEND			
LEAD	47	BDL	BDL	mg/kg	239.1	10
CHROMIUM	110	BDL	BDL	mg/kg	218.2	10
BLEND= 1 CONTAMINATED WITH 2 CLEAN						
BDL= Below detection limit						

SAMPLE TYPE -SOIL

PARAMETER	RESULT	RESULT	RESULT	UNITS	METHOD	D LIMITS
	CONTAMINAT	CLEAN	BLEND			
LEAD	150	BDL	BDL	mg/kg	239.1	10
BLEND= 1 CONTAMINATED WITH 7 CLEAN						
BDL= Below detection limit						

RAW MATERIALS RECEIVED

[illegible]

Untreated Soil Reporting Form

Facility Rinker Materials Corporation
 Air Permit No.: A013-172154
 Soil Treatment Permit No.: SM-0117-91
 Stationary XXX

Month June Year 1995

ATTACHMENT "B"

Date	Batch No.	Source	Soil Content PCB's	Tons PCB Oil Concentration	Lb. PCB per Batch	YTD Lbs. PCB
Continuation from May 1995 1.5441lbs						

NO ACTIVITY IN JUNE