

Eckoff, Michael

From: Hutchinson, Wanda M <Wanda.Hutchinson@safety-kleen.com>
Sent: Friday, February 4, 2022 11:02 AM
To: Eckoff, Michael
Cc: Curtis, Jeffery S; Bumgardner, Robin D
Subject: Safety-Kleen Ocala Inspection 2-3-2022
Attachments: DEP Inspection 2-3-22 Picture #1 Pump Used Oil Labeled.jpg; DEP Inspection 2-3-22 Picture #2 Crusher Basin Used Oil Labeled 1 of 4.jpg; DEP Inspection 2-3-22 Picture #3 Crusher Basin Used Oil Labeled 2 of 4.jpg; DEP Inspection 2-3-22 Picture #4 Crusher Basin Used Oil Labeled 3 of 4.jpg; DEP Inspection 2-3-22 Picture #5 Crusher Basin Used Oil Labeled 4 of 4.jpg; Contingency Plan Review 2-3-22.pdf

EXTERNAL MESSAGE

This email originated outside of DEP. Please use caution when opening attachments, clicking links, or responding to this email.

Good morning Michael,

It was nice to meet you yesterday, I am so very sorry for the loss of John White, he was a good man. Attached are some pictures of the corrections we are making at the facility based upon yesterday's inspection. Also attached is the signature page for recording the review of the Contingency Plan. I reviewed the plan, signed and placed this form inside the permit book. I will send additional documentation to you next week addressing the additional concerns. Thank you and have a great weekend.

Wanda

Wanda M Hutchinson Ocala/Pompano Beach Oil Terminal Manager | Safety-Kleen | A Clean Harbors Company | Wanda.hutchinson@safety-kleen.com Office 352.537.3071 Cell 352.480.7828 | safety-kleen.com



Safety Starts with Me! Live it 3-6-5





USED OIL

The image shows a complex industrial setup on the deck of a ship. In the background, a person in a blue shirt is working near a large white cylindrical tank. The foreground is dominated by a metal grating floor. A blue vertical pipe runs down from the machinery. A concrete block with two rectangular holes sits on the grating. A white label with the text 'USED OIL' is affixed to a metal structure. The machinery includes various pipes, valves, and a red component. The scene is brightly lit, suggesting daylight.



SB-60

USED OIL

DANGER
PINCH
POINT



USED OIL



USED OIL



USED OIL

SB-600

STOP
POWER ON
START
STOP
REVERSE
FORWARD
STOP

DESIGNED AND MANUFACTURED BY SHARIT EQUIPMENT INC.

DANGER
220 VOLTS
CAUTION
DO NOT ENTER
CAUTION
DO NOT ENTER
CAUTION
DO NOT ENTER
CAUTION
DO NOT ENTER

TRUCK DUMP FEEDER
SORTER

DANGER
DO NOT ENTER

Safety-Kleen Systems, Inc.
359 Cypress Road
Ocala, Florida 34472



Environmental Compliance Memorandum

To: FILE – FACILITY OPERATING RECORD

Date: February 3, 2022

Subject: Annual Review of Contingency Plan

Pursuant to Used Oil and Material Processing Facility permit 16196010-HO, Part III Subpart A, General Operating Condition 4.e, an annual review of the Safety-Kleen Systems, Inc. contingency plan was conducted. At this time there were no revisions necessary.

I certify to the best of my ability and knowledge based on the information reviewed that the required annual review was conducted.

Name: Wanda M Hutchinson

Signature: 