



**Florida Department of  
Environmental Protection  
Hazardous Waste Inspection Report**

---

**FACILITY INFORMATION:**

**Facility Name:** Cliff Berry Inc Canaveral

**On-Site Inspection Start Date:** 08/15/2023

**On-Site Inspection End Date:** 08/15/2023

**ME ID#:** 42543

**EPA ID#:** FLR000119792

**Facility Street Address:** 5855 Industrial Dr, Cocoa, Florida 32927-4608

**Contact Mailing Address:** PO Box 13079, Fort Lauderdale, Florida 33316-0100

**County Name:** Brevard

**Contact Phone:** (954) 763-3390

**NOTIFIED AS:**

Transporter, Used Oil, VSQG

**WASTE ACTIVITIES:**

**Generator:** VSQG **Transporter:** Own Waste, Commercial Waste **TSD:** Operating Non-Commercial TSD **Used Oil:** Oil Filters, Processor **Other:** Transport **Universal Waste:** Indicate types of UW generated and/or accumulated at the facility: **Generate/Accumulate:** Batteries, Mercury Containing Lamps, Mercury Containing Devices **Transport:** Mercury Containing Lamps, Mercury Containing Devices **Maximum quantity of UW handled or transported at any time:** 5000 kg or more; Large Quantity Handler (LQH)

**INSPECTION TYPE:**

Routine Inspection for Used Oil Processor Facility

**INSPECTION PARTICIPANTS:**

Principal Inspector: Gina Laddick, Inspector

Other Participants: Carly Cogburn, Inspector, Natalie Deutsch

**LATITUDE / LONGITUDE:** Lat 28° 27' 22.892" / Long 80° 46' 17.306"

**NAIC:** 562219 - Other Nonhazardous Waste Treatment and Disposal

**TYPE OF OWNERSHIP:** Private

**Introduction:**

On August 15, 2023, Gina Laddick and Carly Cogburn, Florida Department of Environmental Protection (FDEP or Department), accompanied by Natalie Deutsch, Cliff Berry, Inc., inspected Cliff Berry Inc Canaveral (CBI or Facility) for compliance with used oil processing permit number 249477-004-HO. CBI is currently operating as a used oil transporter, a hazardous waste transporter, and as a permitted used oil processor under permit number 249477-004-HO, issued April 6, 2023.

CBI has been operating at 5855 Industrial Drive, Cocoa, Florida, since 2005. The facility has seven employees and the office operating hours are Monday through Friday 8:00 AM to 4:00 PM. The facility is connected to a potable well for drinking water and a septic system for domestic wastewater. The site consists of two separate parcels totaling 4 acres in size and is owned by C-2 Holdings, Inc., Fort Lauderdale, Florida.

CBI initially notified as a used oil handler in May 2005 and was issued EPA identification number FLR000119792. On February 2, 2023, the facility's registration as a used oil and used oil filter transporter was renewed and expires on June 30, 2024. The facility's hazardous waste transporter registration also expires June 30, 2024. The facility is also currently registered as a very small quantity generator of hazardous waste.

**Inspection History (past five years):**

On August 31, 2022, CBI was inspected for compliance with used oil processing permit number 249477-003-HO and no potential violations were noted at that time.

Inspection Date: 08/15/2023

On August 26, 2020, CBI was inspected for compliance with state and federal used oil regulations and no potential violations were noted at that time.

**Process Description:**

CBI is a hazardous waste transporter, as well as a transporter and transfer facility for used oil and universal waste. Due to a used oil storage capacity in excess of 25,000 gallons, Cliff Berry, Inc. was required to obtain a used oil processing permit; however, the facility does not currently process used oil on-site. The facility's used oil operations consist of three 10,000-gallon aboveground storage tanks and two 5,000-gallon above ground storage tanks. The tank farm is located in secondary containment.

Used oil and oily water from generator locations is sampled utilizing a halogen detector (sniffer) or a Q1000 test kit. If a sample has over 1,000 parts per million (ppm) of halogens, it is not loaded onto the truck. Used oil and oily water received at the facility is screened to remove solids and transferred to storage tanks 4 and 5. Oily water is stored in tanks 2 and 3 and petroleum contact water (PCW) is stored in tank 1.

The used oil stored at the Canaveral facility is transferred to Cliff Berry, Inc.'s Miami facility for processing. According to permit condition Part II Subpart B, specific condition 9.d., analytical testing is not required if the used oil is sent to another used oil processor for further processing. Generator knowledge is applied to any petroleum contact water collected.

The tank farm was properly contained in secondary containment with no evidence of spills or releases. The floors and walls were in good condition with no visible signs of cracking. All used oil tanks were properly labeled as "Used Oil." Fire extinguishers were located on the southeast and northeast corners of the tank farm as identified in the permit application.

The training for employees consists of an initial 40-hour HAZWOPER upon hire with monthly safety meetings covering additional topics. Safety meeting topics include spill prevention and understanding of the SPCC plan. Personnel also receive on-the-job training during response to real spills as part of the company's spill response and cleanup operations.

Mark Groothouse, Assistant Facility Manager, is identified as the primary emergency coordinator with John Sandora and Steve Collins identified as alternates. The contingency plan and notifications of local authorities were reviewed on-site and no issues were found.

The 2022 Used Oil Annual Report was received on February 2, 2023. During calendar year 2022 CBI transported 2,533,528 gallons of used oil and 79,590 used oil filters. Used oil shipping and receiving documents were reviewed and found to be in compliance.

**Conclusion:**

Cliff Berry, Inc. - Canaveral was inspected on August 15, 2023, as a used oil and used oil filter transporter and as a permitted used oil processor. No potential violations were noted during this inspection.

Inspection Date: 08/15/2023

**1.0: Pre-Inspection Checklist**

## Requirements:

The requirements listed in this section provide an opportunity for the Department's inspector to indicate the conditions found at the time of the inspection. A "Not Ok" response to a requirement indicates either a potential violation of the corresponding rule or an area of concern that requires more attention. Both potential violations and areas of concern are discussed further at the end of this inspection report.

**Note: Checklist items with shaded boxes are for informational purposes only.**

Item No.	Pre-Inspection Review	Yes	No	N/A
1.1	Has the facility notified with correct status? 262.18(a)	✓		
1.2	Has the facility notified of change of status? 62-730.150(2)(b)			✓
1.3	Did the facility conduct a waste determination on all wastes generated? 262.11	✓		


Inspection Date: 08/15/2023

**Signed:**

A hazardous waste compliance inspection was conducted on this date, to determine your facility's compliance with applicable portions of Chapters 403 & 376, F.S., and Chapters 62-710, 62-730, 62-737 & 62 -740 Florida Administrative Code (F.A.C.). Portions of the United States Environmental Protection Agency's Title 40 Code of Federal Regulations (C.F.R.) 260 - 279 have been adopted by reference in the state rules under Chapters 62-730 and 62-710, F.A.C

Gina Laddick  
**Principal Investigator Name**

Inspector  
**Principal Investigator Title**

  
**Principal Investigator Signature**

DEP 08/25/2023  
**Organization** **Date**

Carly Cogburn  
**Inspector Name**

Inspector  
**Inspector Title**

DEP  
**Organization**

Natalie Deutsch  
**Representative Name**

Cliff Berry  
**Organization**

NOTE: By signing this document, the Site Representative only acknowledges receipt of this Inspection Report and is not admitting to the accuracy of any of the items identified by the Department as "Potential Violations" or areas of concern.

**Report Approvers:**

**Approver:** Daniel K. Hall

**Inspection Approval Date:** 08/28/2023