



Florida Department of Environmental Protection  
Twin Towers Office Bldg. 2600 Blair Stone Road, Tallahassee, Florida, 32399-2400  
Division of Waste Management  
Petroleum Storage Systems  
Storage Tank Facility Routine Compliance Site Inspection Report

### Facility Information:

Facility ID: 9804717 County: HIGHLANDS Inspection Date: 07/09/2024  
Facility Type: H - Local Government  
Facility Name: SEBRING CITY WWTP # of inspected ASTs: 1  
4200 CEMETERY RD USTs: 0  
SEBRING, FL 33870 Mineral Acid Tanks: 0  
Latitude: 27° 30' 28.5647"  
Longitude: 81° 25' 13.6608"  
LL Method: DPHO

### Inspection Result:

Result: In Compliance

### Signatures:

TKOKPH - OKEECHOBEE COUNTY HEALTH DEPARTMENT (863) 462-5811

### Storage Tank Program Office and Phone Number

Douglas McCoy

Mary Jane Faircloth

Inspector Name

Representative Name

No Signature

Inspector Signature

Representative Signature

Principal Inspector

Plant Operator

OKEECHOBEE COUNTY HEALTH DEPARTMENT

City of Sebring Sewer Plant

Owners of UST facilities are reminded that the Federal Energy Policy Act of 2005 and 40 CFR 280 Subpart J requires Operator Training at all facilities by October 13, 2018. For further information please visit:  
<https://floridadep.gov/waste/permitting-compliance-assistance/content/underground-storage-tank-operator-training>

### Financial Responsibility:

Financial Responsibility: INSURANCE

Insurance Carrier: COMMERCE AND INDUSTRY INSURANCE COMPANY

Effective Date: 03/22/2024

Expiration Date: 03/22/2025

## Reviewed Records

Record Category	Record type	From Date	To Date	Reviewed Record Comment
Three Years	Certificate of Financial Responsibility	03/22/2024	03/22/2025	C & I
Three Years	Monthly Maint. Visual Examinations and Results	01/02/2023	07/01/2024	missing one or two months

## Site Visit Comments

07/09/2024

Visited site with Mary Jane Faircloth for inspection.

## Inspection Comments

07/23/2024

Release Detection Methods - Visual inspection & manual Interstitial Monitoring of double wall AST.

Annual compliance inspection scheduled by email on 6/24/2024 with Maryjane Faircloth. Current registration is available. Registration information checked with facility contact. Current insurance documents D & P are available. Monthly inspections detailed and accurately reflect conditions found during inspection. Missing one or two months. Site plan, SWAP data and photos reviewed in FIRST.

Inspected 1 double wall steel tank; Tremont- sub base Gen tank (EQ-228) with dry Morrison fig 517 3.5 gallon spill containment. Rochester inventory gauge, manual overfill procedures and manual interstitial monitoring. Tank Interstitial is dry. Anti-siphon protection provided by piping configuration above tank fuel level. Regular and emergency venting on primary tank. Emergency venting on secondary basin. Tank contents identified. System needs touchup painting for corrosion protection.

Inspection reviewed with Ms. Faircloth and emailed to maryjanefaircloth@mysebring.com .

FDEP Business portal for on line registration updates: <http://www.fldeportal.com/go/submit-registration/> On Line Registration updates, Approved Equipment List, storage tank forms and other current information can be accessed from links at the FDEP Storage Tank Main Page at: [www.dep.state.fl.us/waste/categories/tanks](http://www.dep.state.fl.us/waste/categories/tanks) Storage Tank Registration section can be e-mailed at [tankregistration@dep.state.fl.us](mailto:tankregistration@dep.state.fl.us) FDEP main phone # 850-245-8839

Contact information: Douglas McCoy, phone 863-462-5811, E-mail: [Douglas.mccoy@flhealth.gov](mailto:Douglas.mccoy@flhealth.gov).

## Inspection Photos

Added Date 07/09/2024

2024-07-09-ANNUAL-DM-tank



Added Date 07/09/2024

2024-07-09-ANNUAL-DM-tank

