



**Florida Department of
Environmental Protection
Hazardous Waste Inspection Report**

FACILITY INFORMATION:

Facility Name: Coastal Oil Recovery LLC

On-Site Inspection Start Date: 09/30/2024

On-Site Inspection End Date: 09/30/2024

ME ID#: 133633

EPA ID#: FLR000231506

Facility Street Address: 1322 E University Blvd, Melbourne, Florida 32901-7242

Contact Mailing Address: 1322 E University Blvd, Melbourne, Florida 32901

County Name: Brevard

Contact Phone: (888) 892-6278

NOTIFIED AS:

Non-Handler, Used Oil

WASTE ACTIVITIES:

Generator: Non-Handler **Used Oil:** Transporter, Oil Filters

INSPECTION TYPE:

Routine Inspection for Used Oil Transporter Facility

INSPECTION PARTICIPANTS:

Principal Inspector: Michael Eckoff, Inspector

Other Participants: N/A

LATITUDE / LONGITUDE: Lat 28° 3' 50.4612" / Long 80° 35' 58.7256"

NAIC: 484220 - Specialized Freight (except Used Goods) Trucking, Local

TYPE OF OWNERSHIP: Private

Introduction:

On September 30, 2024, Michael Eckoff, Florida Department of Environmental Protection (FDEP or Department), inspected Coastal Oil Recovery, LLC (COR or Facility) for compliance with state and federal used oil transporter regulations. No one was at the Facility when the inspector arrived. The Facility received EPA identification number FLR000231506 on April 19, 2019. The Facility is currently registered as a used oil transporter and used oil filter transporter, transfer facility, and processor (expires June 30, 2025).

Process Description:

The inspector called James Moss to gain access to the Facility. While waiting for a call back from Mr. Moss an inspection of the accessible portions of the site was conducted. Two tanker trailers and a pump truck were parked outside the building. No releases were noted from the trailers or truck.

Mr. Moss called the inspector back and described the operations at the site. Mr. Moss mentioned that he was experiencing some health issues and could not meet the inspector on-site. Used oil was being stored in the tanker trailer outside and was ready for shipment to Howco Environmental in Astor, Florida. The trailer was supposed to go to Howco last week but his health issues delayed that shipment. The other tanker trailer was empty and the pump truck had engine issues and contained used antifreeze. Forty-eight to fifty 55-gallon drums of used oil filters were stored inside the building that will be shipped to EMC. Used oil is screened for halogens using a TIF XP-1A sniffer that is checked every couple weeks to ensure that it is properly working.

The inspector requested a photograph of the used oil filters stored inside the building and two weeks of used oil and two months of used oil filters disposal records be submitted. On October 3, 2024 Mr. Moss provided the requested information. Used oil was shipped to Howco Environmental Services on September 11, 2024 and September 18, 2024. Used oil filters were shipped to EMC Oil in Miami, Florida on July 15, 2024, August 6, 2024, and August 23, 2024.

Inspection Date: 09/30/2024

NOTE: It appears the Facility is storing used oil for greater than 24 hours and may need to register as a used oil transfer facility.

Conclusion:

Coastal Oil Recovery, LLC was inspected as a used oil transporter and no potential violations were noted at that time.

Inspection Date: 09/30/2024

1.0: Pre-Inspection Checklist

Requirements:

The requirements listed in this section provide an opportunity for the Department's inspector to indicate the conditions found at the time of the inspection. A "Not Ok" response to a requirement indicates either a potential violation of the corresponding rule or an area of concern that requires more attention. Both potential violations and areas of concern are discussed further at the end of this inspection report.

Note: Checklist items with shaded boxes are for informational purposes only.

Item No.	Pre-Inspection Review	Yes	No	N/A
1.1	Has the facility notified with correct status? 262.18(a)	✓		
1.2	Has the facility notified of change of status? 62-730.150(2)(b)			✓
1.3	Did the facility conduct a waste determination on all wastes generated? 262.11	✓		

Inspection Date: 09/30/2024

Signed:

A hazardous waste compliance inspection was conducted on this date, to determine your facility's compliance with applicable portions of Chapters 403 & 376, F.S., and Chapters 62-710, 62-730, 62-737 & 62 -740 Florida Administrative Code (F.A.C.). Portions of the United States Environmental Protection Agency's Title 40 Code of Federal Regulations (C.F.R.) 260 - 279 have been adopted by reference in the state rules under Chapters 62-730 and 62-710, F.A.C

Michael Eckoff**Principal Investigator Name**Inspector**Principal Investigator Title**Michael Eckoff**Principal Investigator Signature**DEP**Organization**10/24/2024**Date**N/A**Representative Name**

NOTE: By signing this document, the Site Representative only acknowledges receipt of this Inspection Report and is not admitting to the accuracy of any of the items identified by the Department as "Potential Violations" or areas of concern.

Report Approvers:**Approver:**Jill M. Farris**Inspection Approval Date:**10/25/2024