


| File Name | Date Taken | Latitude | Longitude | Camera Maker | Model | Image Size (px) |
|--------------|---------------------|-------------|--------------|--------------|-----------|-----------------|
| IMG_0294.JPG | 2024:07:30 10:09:13 | 27.85316389 | -82.63910556 | Apple | iPhone 13 | 3024 x 4032 |

Description: One of the three receipts for the purchase of perchloroethylene over the last twelve months.



File Name Date Taken Latitude Longitude Camera Maker Model Image Size (px)
 IMG_0295.JPG 2024:07:30 10:10:11 27.85315278 -82.63911389 Apple iPhone 13 3024 x 4032
 Description: Emergency spill procedure posted on the front of the machine.

Form Approved, OMB No. 2050-0047

SK SHIP# 242234085

Form Approved, OMB No. 2050-0047

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator ID Number: FLR000054338

2. Page 1 of 2

3. Emergency Response Phone: 242234085

4. Manifest Tracking Number: 008941939 SKS

5. Generator's Name and Mailing Address: Cleaners, 8840 4th St N, SAINT PETERSBURG, FL 33702-3124

6. Generator's Phone: 727-576-5193

7. Transporter 1 Company Name: SAFETY KLEEN SYSTEMS INC

8. Designated Facility Name and Site Address: SAFETY KLEEN SYSTEMS INC LEXINGTON, 130-A FRONTAGE ROAD LEXINGTON, SC 29073

9a. HM: X

9b. U.S. DOT Description: 1. UN2810 WASTE TOXIC LIQUID, ORGANIC N.O.S. (TETRACHLOROETHYLENE, TRICHLOROETHYLENE) 6.1 PGIII RQ(F002)

10. Containers: 2 DM

11. Total Quantity: 150

12. Unit Wt./Vol.: P

13. Waste Codes: F002 D002-D037 D040

14. Special Handling Instructions and Additional Information: TSD: LER 93872021 1930011 202410 CSB: 25

15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.

Generator's/Offoror's Printed/Typed Name: DINO PAZOL

Signature: [Signature]

Month Day Year: 3 8 24

16. International Shipments: Import to U.S. Export from U.S.

17. Transporter Acknowledgment of Receipt of Materials: Transporter signature (for exports only): [Signature]

Transporter 1 Printed/Typed Name: Jilly Roche

Signature: [Signature]

Month Day Year: 3 8 24

Transporter 2 Printed/Typed Name: [Signature]

Signature: [Signature]

Month Day Year: 03 24 24

18. Discrepancy: Quantity Type Residue Partial Rejection Full Rejection

18a. Discrepancy Indication Space

18b. Alternate Facility (or Generator)

19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)

1. H141

2.

3.

4.

20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a

Printed/Typed Name: [Signature]

Signature: [Signature]

Month Day Year: 13 21 24

File Name: IMG_0296.JPG Date Taken: 2024:07:30 10:11:34 Latitude: 27.85313889 Longitude: -82.63913056 Camera Maker: Apple Model: iPhone 13 Image Size (px): 3024 x 4032

Description: The receipt for the waste perchloroethylene pickup from Safety-Kleen.





| File Name | Date Taken | Latitude | Longitude | Camera Maker | Model | Image Size (px) |
|--------------|---|-------------|--------------|--------------|-----------|-----------------|
| IMG_0297.JPG | 2024:07:30 10:13:03 | 27.85306389 | -82.63910556 | Apple | iPhone 13 | 3024 x 4032 |
| Description: | The additional water separator was functioning properly and the water properly aerosolized. | | | | | |



| File Name | Date Taken | Latitude | Longitude | Camera Maker | Model | Image Size (px) |
|--------------|--|-----------|--------------|--------------|-----------|-----------------|
| IMG_0298.JPG | 2024:07:30 10:13:50 | 27.853125 | -82.63912222 | Apple | iPhone 13 | 3024 x 4032 |
| Description: | Back of dry cleaning machine; it was clean and appeared to be in good condition. | | | | | |



| File Name | Date Taken | Latitude | Longitude | Camera Maker | Model | Image Size (px) |
|--------------|---|-------------|--------------|--------------|-----------|-----------------|
| IMG_0299.JPG | 2024:07:30 10:14:33 | 27.85312778 | -82.63910556 | Apple | iPhone 13 | 3024 x 4032 |
| Description: | The perchloroethylene detector (model TIF RX-1A) was functional and no leaks were detected. | | | | | |





| File Name | Date Taken | Latitude | Longitude | Camera Maker | Model | Image Size (px) |
|--------------|--|-------------|--------------|--------------|-----------|-----------------|
| IMG_0300.JPG | 2024:07:30 10:15:24 | 27.85313889 | -82.63913056 | Apple | iPhone 13 | 3024 x 4032 |
| Description: | Waste perchloroethylene drums were properly labeled, sealed and had secondary containment. | | | | | |



File Name Date Taken Latitude Longitude Camera Maker Model Image Size (px)
 IMG_0301.JPG 2024:07:30 10:16:27 27.853125 -82.63912222 Apple iPhone 13 3024 x 4032
 Description: Dry cleaning machine model number (Union U2000).



| File Name | Date Taken | Latitude | Longitude | Camera Maker | Model | Image Size (px) |
|--------------|--|----------|--------------|--------------|-----------|-----------------|
| IMG_0302.JPG | 2024:07:30 10:21:37 | 27.8531 | -82.63911389 | Apple | iPhone 13 | 3024 x 4032 |
| Description: | Facility's additional water separator. | | | | | |