Ph: 863-453-6557

Avon Park Fire Department 98 S. Delaney Ave., Avon Park, FL 33825

Fax: 863-453-7853

Inspection Report

Page 1 of 1 Florida Tire Terminal Name: Date: 2/9/2011 Contact: Robert Reisig Inspector Name: Acting Chief David L Cloud Issued: Type of Inspection: **Courtesy Inspection** Each discrepancy detailed herein is a violation of the Fire Code and shall be corrected **Fire Code** Discrepancy / Remarks Reference See notes No major hazards found Owner is continuing to work to maintain proper separations in storage areas. It is recommended that a separating barrier be used at the north production building's west wall to maintain a 30 inch clearance to the wall for outside tire storage while keeping drive area clear. No operational changes noted. No changes noted from last inspection. Inspector Signature Site Signature