


41193  
As ✓  
man  
9/21/10



Hillsborough County  
Florida

Office of the County Administrator  
Patricia G. Bean

BOARD OF COUNTY COMMISSIONERS

- Kevin Beckner
- Rose V. Ferlita
- Ken Hagan
- Al Higginbotham
- Jim Norman
- Mark Sharpe
- Kevin White

ADMINISTRATORS

- Lucia E. Garsys
- Carl S. Harness
- Eric R. Johnson
- Michael S. Merrill
- Manus J. O' Donnell
- Edith M. Stewart

Dept. of Environmental Protection

DEC 21 2009

Southwest District

December 18, 2009

Ms. Susan J. Pelz, P.E.  
 Solid Waste Permitting  
 Florida Department of Environmental Protection  
 Southwest District  
 13051 N. Telecom Pkwy  
 Temple Terrace, Florida 33637-0926

RE: Southeast County Landfill - Gas Monitoring Report

Dear Ms. Pelz:

In accordance with Specific Conditions No. 19 and No. 20 of Permit No. 35435-006-SO, the Solid Waste Management Department (SWMD) is submitting the quarterly gas monitoring report for the Southeast County Landfill for the quarter ending January 15, 2010.

The monitoring was performed on December 15, 2009. The information includes the structure and the subsurface monitoring point gas sampling and results. No landfill gas was detected at any of the sampling locations.

Please advise should you have any questions concerning the attached submittal.

Sincerely,

Patricia V. Berry  
 Landfill Services Section Manager  
 Solid Waste Management Department

Attachment

- xc: Larry Ruiz, SWMD
- Walter Gray, SWMD
- Jason Timmons, P.E. JEA
- Ron Cope, EPC

HILLSBOROUGH COUNTY SOLID WASTE MANAGEMENT DEPARTMENT  
SOUTHEAST COUNTY LANDFILL /LFG READINGS

ADMINISTRATION BUILDING

	METHANE GAS	L.E.L.	CARBON DIOXIDE	OXYGEN	BALANCE GAS
S.P.1	0	0	0	20.9	79.1
S.P.2	0	0	0	20.9	79.1
S.P.3	0	0	0	20.9	79.1
S.P.4	0	0	0	20.9	79.1
S.P.5	0	0	0	20.9	79.1
S.P.6	0	0	0	20.9	79.1
S.P.7	0	0	0	20.9	79.1
S.P.8	0	0	0	20.9	79.1

Dept. of Environmental Protection  
**DEC 21 2009**  
Southwest District

MAINTENANCE BUILDING

	METHANE GAS	L.E.L.	CARBON DIOXIDE	OXYGEN	BALANCE GAS
S.P.9	0	0	0	20.7	79.3
S.P.10	0	0	0	20.7	79.3
S.P.11	0	0	0	20.7	79.3
S.P.12	0	0	0	20.7	79.3

LEACHATE TREATMENT PLANT

	METHANE GAS	L.E.L.	CARBON DIOXIDE	OXYGEN	BALANCE GAS
S.P.13	0	0	0	20.6	79.4
S.P.14	0	0	0	20.6	79.4
S.P.15	0	0	0	20.6	79.4

LANDFILL GAS PERIMETER MONITORING POINT

WELL	METHANE GAS	L.E.L.	CARBON DIOXIDE	OXYGEN	BALANCE GAS
LFG-1	0	0	0	20.5	79.5
LFG-2	0	0	2	18.7	79.3
LFG-3	0	0	1.7	19	79.3
LFG-4	0	0	1.5	19.2	79.3

TECHNICIAN SIGNATURE *Walter [Signature]*

SUPERVISOR SIGNATURE *Harry E. R. [Signature]*

DATE: December 15, 2009

COMMENTS \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

LEGEND S.P.= AMBIENT SAMPLE POINT