



An employee-owned company

April 1, 2011

Mr. John Morris, P.G.
Florida Department of Environmental Protection
Southwest District Office - Solid Waste Section
13051 N. Telecom Parkway
Temple Terrace, FL 33637-0926

**Re: Manatee County Lena Road Landfill
Methane Probes and Buildings Sampling
First Quarter of 2011**

Dear Mr. Morris:

The methane monitoring probes and buildings at the Lena Road Landfill were sampled for the first quarter of 2011 on March 17, 2011 using a Thermo Toxic Vapor Analyzer (TVA-1000 FID). The results are summarized on the attached table.

The readings at all the probes were zero.

If you should have any questions concerning this report, please call me at 407/806-4153.

Sincerely,

Joe Miller, P.E.
Senior Project Manager

Attachment

cc: Michael Gore, Manatee County Solid Waste Division Manager
Bryan White, Manatee County Landfill Superintendent
Anthony Detweiler, Manatee County Landfill Operations Supervisor
File – 120498.94 0200, Monitoring

u:\so\projects\manatee county\sw-05 annual monitoring\2011\march\methane points q1_2011.doc

FLORIDA DEPARTMENT OF
ENVIRONMENTAL PROTECTION
APR 05 2011
SOUTHWEST DISTRICT
TAMPA

**MANATEE COUNTY LENA ROAD LANDFILL
GAS MONITORING REPORT
FIRST QUARTER 2011
JANUARY 2011 - MARCH 2011**

METHANE GAS READINGS

Date of Readings: MARCH 17, 2011

| Gas Monitoring Probe or Building | Reading % LEL | NOTES |
|---|--------------------------|--------------|
| GMW-1 | 0.0 | |
| GMW-2 | 0.0 | |
| GMW-3 | 0.0 | |
| GMW-4 | 0.0 | |
| GMW-5 | 0.0 | |
| GMW-6 | 0.0 | |
| GMW-7 | 0.0 | |
| GMW-8 | 0.0 | |
| GMW-9 | 0.0 | |
| GMW-10 | 0.0 | |
| GMW-11A | 0.0 | |
| GMW-11B | 0.0 | |
| GMW-11C | 0.0 | |
| Administration Building | 0.0 | |
| HH Waste Drop-off Building | 0.0 | |
| Scale House Building | 0.0 | |
| Maintenance Office | 0.0 | |
| Maintenance Building | 0.0 | |
| | | |
| | | |

FIGURE K-9