

ANGELO'S RECYCLED MATERIALS

4111 Enterprise Road
Dade City, FL 33525



Dept. Of Environmental Protection

AUG 24 2011

APOPKA 407.290.8010 407.290.8115 (FAX)
DADE CITY 352.567.7676 352.567.9448 (FAX)

TAMPA 813.903.0588 813.903.9157 (FAX)
LARGO 727.581.1544 727.586.5676 (FAX)

August 18, 2011

Ms. Nancy Gaskin, Inspector
Florida Department of Environmental Protection - Southwest District
13051 North Telecom Parkway
Temple Terrace, FL 33637-0926

RE: Response to June 09, 2011 FDEP Site Inspection (Received via email August 18, 2011)
Enterprise Class III Landfill
WACS No.: 87895

Dear Ms. Gaskin:


We reviewed the referenced inspection report and provide this letter in response to selected items and/or concerns expressed by the Department. The format of this letter response is to list the applicable portion of the Department's observation with our response immediately following.

- Rule: 62-701.530(2)(c)
Explanation: Following a post inspection file review, it appears that gas monitoring results for the first quarter 2011 gas sampling event have not been submitted.
Corrective Action: Please provide information on the status of these results.

Response: The gas sampling event was included in Attachment 4 of the First Semiannual 2011 report, dated May 5, 2011. A copy of the gas sampling report is attached.
- Comment: 06/09/11 inspection - A response from the facility was received 03/31/2011. It stated that "test pits" were dug to verify cover thickness and proposed that the observed waste was a function of equipment tracking. This violation refers to exposed waste observed during an inspection. The thickness of cover in an area of exposed waste is not in question: if waste was visible then cover is inadequate. Please verify that any and all exposed waste has been addressed as this is the performance measure of any type of cover.

Response: Maintenance has already been performed on the initial cover and conditions identified in the 03/31/2011 inspection report. Additional soil cover was applied to areas to cover waste materials.

Please let me know if you have any questions or need any additional information.

Sincerely,

John Arnold, P.E.

xc: Dominic Iafrate, Angelo's Recycled Materials

**LANDFILL GAS READINGS ENTERPRISE CLASS III
LANDFILL AND RECYCLING FACILITY FIRST
QUARTER 2011**

LOCATION	% LEL	REMARKS
GP-1	-	not installed at this time
GP-2	-	not installed at this time
GP-3	-	not installed at this time
GP-4	-	not installed at this time
GP-5	-	not installed at this time
GP-6	3%	
GP-7	0%	
GP-8	0%	
GP-9	-	abandoned
GP-9R	0%	
GP-10R	0%	
GP-11	0%	
GP-12	3%	well marked 12A
GP-13	3%	well marked 13A
GP-14	0%	
GP-15	-	not installed at this time
GP-16	-	not installed at this time
SCALE HOUSE	0%	staff occupied structure

Dept. Of Environmental Protection

AUG 24 2011

Southwest District