

ANGELO'S RECYCLED MATERIALS

4111 Enterprise Road
Dade City, FL 33525



Dept. Of Environmental Protection

AUG 24 2011

Southwest District

APOPKA	407.290.8010	407.290.8115 (FAX)	TAMPA	813.903.0588	813.632.9157 (FAX)
DADE CITY	352.567.7676	352.567.9448 (FAX)	LARGO	727.581.1544	727.586.5676 (FAX)

August 18, 2011

Ms. Nancy Gaskin, Inspector
Florida Department of Environmental Protection – SW District
13051 North Telecom Parkway
Temple Terrace, FL 33637-0926

RE: Response to June 29, 2011 FDEP Site Inspection (Received via email August 16, 2011)
Enterprise Class III Landfill
WACS No.: 87895

Dear Ms. Gaskin:

We reviewed the referenced inspection report and provide this letter in response to selected items and/or concerns expressed by the Department. The format of this letter response is to list the applicable portion of the Department's observation with our response immediately following.

- Rule: 62-701.530(2)(c)
Explanation: Following a post inspection file review, it appears that gas monitoring results for the first quarter 2011 gas sampling event have not been submitted.
Corrective Action: Please provide information on the status of these results.

Response: The gas sampling event was included in Attachment 4 of the First Semiannual 2011 report, dated May 5, 2011. A copy of the gas sampling report is attached.

- Comment: During the inspection water was observed ponded on top of the areas that had been given intermediate cover in several places. According to facility staff a significant rain event had occurred the night before and they were in the process of addressing the ponded water.

Response: The incurred significant rain events and the areas identified in the pictures have since been graded to promote surface water runoff.

Please let me know if you have any questions or need any additional information.

Sincerely,

A handwritten signature in black ink that reads "John Arnold".

John Arnold, P.E.

xc: Dominic Iafate, Angelo's Recycled Materials

**LANDFILL GAS READINGS ENTERPRISE CLASS III
LANDFILL AND RECYCLING FACILITY FIRST
QUARTER 2011**

LOCATION	% LEL	REMARKS
GP-1	-	not installed at this time
GP-2	-	not installed at this time
GP-3	-	not installed at this time
GP-4	-	not installed at this time
GP-5	-	not installed at this time
GP-6	3%	
GP-7	0%	
GP-8	0%	
GP-9	-	abandoned
GP-9R	0%	
GP-10R	0%	
GP-11	0%	
GP-12	3%	well marked 12A
GP-13	3%	well marked 13A
GP-14	0%	
GP-15	-	not installed at this time
GP-16	-	not installed at this time
SCALE HOUSE	0%	staff occupied structure

FLORIDA DEPARTMENT OF
ENVIRONMENTAL PROTECTION

AUG 24 2011

SOUTHWEST DISTRICT
TAMPA