From:	Michael Kaiser
To:	Rush, Kim;
cc:	Kirk Wills; Shawn McCash; Matt Orr; Keith Lunsford;
Subject:	Replacement Report of Perimeter Gas Monitoring Probes GP-7 through GP-22 - JED Solid Waste Management Facility
Date:	Monday, December 12, 2011 10:12:13 PM
Attachments:	Report Gas Probe Monitoring Installation (Replacement of GP7-GP-22) August 2011.pdf

---

Ms. Rush:

Please find attached the final installation report documenting replacement of perimeter gas monitoring probes GP-7 through GP-22 at the JED Solid Waste Management Facility. Let me know if you would like a hard copies or have questions.

Thanks,

Mike Kaiser

WSI
A Progressive Waste Solutions Company
C: (904) 673-0446
F: (407) 831-7506
1099 Miller Drive
Altamonte Springs, Florida 32701
mkaiser@wasteservicesinc.com

CONFIDENTIALITY NOTICE: The information transmitted in this email is intended for the addressee and may contain confidential information of Waste Services Inc. or its affiliated corporations. Any unauthorized review, distribution or use or the taking of any action in reliance on the information contained in this email or any attachments is strictly

prohibited. If you have received this message in error, please delete or destroy it, all attachments and any copies, and notify the sender.