



**Atkins North America, Inc.**  
482 South Keller Road  
Orlando, Florida 32810-6101  
**Telephone: +1.407.647.7275**  
**www.atkinsglobal.com/northamerica**

January 4, 2012

Mr. John Morris, P.G.  
Florida Department of Environmental Protection  
Southwest District Office - Solid Waste Section  
13051 N. Telecom Parkway  
Temple Terrace, FL 33637-0926

**Re: Manatee County Lena Road Landfill  
Methane Probes and Buildings Sampling  
Fourth Quarter of 2011**

FLORIDA DEPARTMENT OF  
ENVIRONMENTAL PROTECTION  
JAN 05 2012  
SOUTHWEST DISTRICT  
TAMPA

Dear Mr. Morris:

The methane monitoring probes and buildings at the Lena Road Landfill were sampled for the 4th quarter of 2011 on December 23, 2011 using a Thermo Toxic Vapor Analyzer (TVA-1000 FID). The results are summarized on the attached table.

The readings at all the probes and buildings were zero.

If you should have any questions concerning this report, please call me at 407/806-4153.

Sincerely,

Joe Miller, P.E.  
Senior Project Manager

Attachment

cc: Michael Gore, Manatee County Solid Waste Division Manager  
Bryan White, Manatee County Landfill Superintendent  
Anthony Detweiler, Manatee County Landfill Operations Supervisor  
File – 120498.94 0200, Monitoring

u:\so\projects\manatee county\sw-05 annual monitoring\2011\december\methane points q4\_2011.doc

**MANATEE COUNTY LENA ROAD LANDFILL  
GAS MONITORING REPORT  
FOURTH QUARTER 2011  
OCTOBER 2011 - DECEMBER 2011**

**METHANE GAS READINGS**

**Date of Readings: DECEMBER 23, 2011**

<b>Gas Monitoring Probe or Building</b>	<b>Reading % LEL</b>	<b>NOTES</b>
GMW-1	0.0	
GMW-2	0.0	
GMW-3	0.0	
GMW-4	0.0	
GMW-5	0.0	
GMW-6	0.0	
GMW-7	0.0	
GMW-8	0.0	
GMW-9	0.0	
GMW-10	0.0	
GMW-11A	0.0	
GMW-11B	0.0	
GMW-11C	0.0	
Administration Building	0.0	
HH Waste Drop-off Building	0.0	
Scale House Building	0.0	
Maintenance Office	0.0	
Maintenance Building	0.0	

FIGURE K-9