

## Florida Department of Environmental Protection Oil & Gas Program

## MONTHLY O&G INSPECTION CHECKLIST

		W	/ELL # &	NAME		WELL	TYPE	0	G/PA NUMBER	DATE INSPE	CTED
	12	2-3	ST. F	REGIS PAPER	co.	INJE	CTOR	0	G_581/303045	8/15/20:	19
	OPERATOR			FIELD			COUNTY	API NUMBER			
PETRO OPERATING CO.					BJC			SANTA ROSA	09-113-20072		
						WELL STATUS				LAST MIT	P F
						INJE	CTING 8/15/			8/15/2019	✓
WELL SITE INSPECTION CHECKPOINTS					YES	NO		N	OTES		
			POSTE		<u> </u>	·			· ·	0120	
PAD HOUSEKEEPING SUFFICIENT PERIMETER BERM/DIKE SUFFICIENT					~						
						~					
FLOWL	INE/PIF	PELINE	ACCESI	BLE/CLEAN		<b>~</b>					
EVIDEN	NCE OF	LEAKS	/SPILLS	ON			<b>&gt;</b>				
PAD/LOCATION											
		\A/E		20		V=0	NO	NO	TEO *MAY IN IEOTI	ON PRESSURE O	
WELLHEADS					YES	NO	NO	TES-*MAX INJECTION	ON PRESSURE=2	2,500 PSI*	
PRESSURE GAUGES IN WORKING CONDITION											
TUBING* ANNULAR SURFACE											
13	25		0	0		~				PW	
HIGH/LOW FLOWLINE SHUT IN SENSORS											
LOCATED NEAR WELLHEAD						~			N/A		
HIGH:											
CELLAR CONDITION SATISFACTORY						<b>V</b>					
WELLHEAD LEAKING							<b>~</b>				
	HYDR	OGEN	SUI FIL	E DETECTION	ON SY	STFM					
	III DIX		6, FILL		<u> </u>	YES	NO		N	OTES	
DETECTION SYSTEM REQUIRED							>				
ENTRY ALARMS IN WORKING CONDITION										N/A	
SENSORS IN WORKING CONDITION										N/A	
CHEMICAL ADDITIVE SYSTEM						YES	NO	NOTES			
SYSTEM PRESENT						<b>~</b>					
SYSTEM LEAKING										N/A	
SECONDARY CONTAINMENT PROVIDED										N/A	
CHEMICALS ON LOCATION					1.)						
					2.)						
Ī											



## Florida Department of Environmental Protection Oil & Gas Program

## MONTHLY O&G INSPECTION CHECKLIST

0.77 10 01 744			
	N & WELL MAINTAINED. NO EVIDENCE OF	LEAKS OR EXCESSIVE COR	ROSION ON WELLHEAD.
Permit Number			
Oculus ID		Current Status	
API Number		Historical Status	
PA Number			16,410
	SRPC #12-3		16,410
	PETRO OPERATING COMPANY		
	BLACKJACK CREEK	Surface Casing	
	SANTA ROSA	Intermediate Casing	
Sec/Twp/Range		Production Casing	
	1190'FSL&1040'FWL	Tubing	
	SAME		15976-16066
	30.86788333	Plugs	
Longitude	-87.10358333	Issue Date	
		Spud Date	
		Completion Date	
		Plug Date	
			· · · · · · · · · · · · · · · · · · ·

I inspected the above well & premise on August 15, 2019

Signed

OIL AND GAS COORDINATOR

cc: [X]FDEP (Oil & Gas Section): Tallahassee

Form IH-1